E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC ENGINEERING • PLANNING • FIELD SERVICES **Erosion Control Specialist- Manager** E&A - P2006.135.000 Stage Inspector: Mike Jacobson, CISEC **Kennedy Town Center** NER110532 Project Name: 7/9/2011 For Week Ending: 68147 25th & Chandler Road- Bellevue, NE (Sarpy County) **Project Location:** Grading: 100% Sanitary Sewer: 100% Storm Sewer: 100% 100% Paving: Seeding: 100% **Utilities:** 100% Overall Development: 25% RAIN FALL AMOUNTS Amount in tenths Date inspected Sunday: 0.05" Monday 0.00 Tuesday 0.05" Wednesday Trace Thursday Trace Friday Trace Saturday 0.21" Sunday: Trace Monday 0.73" Tuesday 0.07" 06/22/11 Wednesday Trace Thursday Trace Friday 0.00" Saturday 1.30" 06/25/11 Sunday: 1.17" 06/26/11 Monday Trace Tuesday Trace 06/29/11 0.00" Wednesday Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: 0.34" Monday 0.00" Tuesday Wednesday 0.00" Thursday **Trace** Friday 0.00 Saturday 0.00'Sunday: N/A N/A Monday N/A N/A Tuesday N/A N/A Wednesday N/A N/A Thursday N/A N/A Friday N/A N/A Saturday N/A N/A None Complaints: Construction Sequencing: hich portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Entire Site, Grading was completed and entire site was seeded Fall 2006.

| Entire Site, Grading was c            | ompleted and entire site v      | was seeded Fall 2006            |                    |  |
|---------------------------------------|---------------------------------|---------------------------------|--------------------|--|
| Entire Oite, Grading was a            | omprotod drid oritire ofte v    |                                 |                    | <br>   |
|                                       |                                 |                                 |                    |  |
| What temporary or permanent           | stabilization measures listed i | n this section are being implem | ented?             |  |
|                                       |                                 |                                 |                    |  |
|                                       |                                 |                                 |                    | to west of SB B(4/2009); Re-<br>BB B(4/2009) |
| seeded the north east corr            |                                 |                                 |                    |  |
| seeded the north east corr  Comments: |                                 |                                 |                    |  |
| seeded the north east corr            | ner of the lot where the are    | ea inlet was installed(4/200    | 9); Re-seeded arou |  |

Findings / Corrective Actions (Date):

| Unique Name                | Туре   | Location   | Projected<br>Install Date | Status       | Maintena |  |  |
|----------------------------|--|--|---------------------------|--------------|----------|--|--|
|                            |  | N41d00m00s   |                           |              |          |  |  |
| CE A                       | Construction Entrance  | W96d00m00s   |                           | Removed      | No       |  |  |
| Current Condition:         | Removed paved entrance   | vv 90d00111003   | L                         | Removed      | 110      |  |  |
|                            | - поможно рамков симинист  | N41d00m00s   |                           |              |          |  |  |
| DD 1                       | Swale  | W96d00m00s   | In Place                  | Active       | No       |  |  |
| Current Condition:         | Good Condition - Partially rer   |  |                           | <del>'</del> |          |  |  |
|                            | Diversion ditch was redefined prior to inspection on 4/8/09 by M.E. Collins.   |  |                           |              |          |  |  |
|                            |  | N44 100 00 -   |                           |              |          |  |  |
| DD 2                       | Swale  | N41d00m00s<br>W96d00m00s   |                           | Removed      |          |  |  |
| Current Condition:         | Removed due to paving of sti   |  |                           | Removed      |          |  |  |
|                            | reasons and to passing at an   |  |                           |              |          |  |  |
| POD A                      | Misc/Other   | Lots 61-72   | 6/10/2011                 | Active       | No       |  |  |
| Current Condition:         | Good Condition-  |  |                           |              |          |  |  |
|                            | Silt fence was installed prior   | Silt fence was installed prior to inspection on 6/10/11 by Rod w/ Townhomes LLC. |                           |              |          |  |  |
|                            |  |  |                           |              |          |  |  |
| POD B                      | Misc/Other   | Lots 37-60   | 2/9/2011                  | Active       | Yes      |  |  |
| Current Condition:         | Fair Condition- Active home of   | construction in POD.   |                           |              |          |  |  |
|                            | Silt fence is down/damaged and needs to be replaced.   |  |                           |              |          |  |  |
|                            | ont lence is down/damaged and needs to be replaced.  |  |                           |              |          |  |  |
|                            | Rod w/ Townhomes LLC was informed to complete maintenance by 6/17/11. Maintenance not complete   |  |                           |              |          |  |  |
|                            | of last inspection.  |  |                           |              |          |  |  |
|                            |  | N41d00m00s   |                           |              |          |  |  |
| SB A                       | Sediment Basin   | W96d00m00s   | In Place                  | Active       | No       |  |  |
| Current Condition:         | Good Condition - 22% filled Cleaned out 10/2007 by Dave Hausman. Erosion maintenance was completed prior to inspection on 4 by M.E. Collins. |  |                           |              |          |  |  |
|                            |  | N41d00m00s   |                           |              |          |  |  |
| SB B                       | Sediment Basin   | W96d00m00s   | 10/6/2007                 | Active       | No       |  |  |
| Current Condition:         | Good Condition - 23% filled  |  |                           |              |          |  |  |
|                            | Cleanout and riser maintenance was completed on 4/1/09 by M.E. Collins.  |  |                           |              |          |  |  |
| 05.41.4                    | 0000   | East side of   | 4/07/0044                 |              |          |  |  |
| SF Al-1 Current Condition: | Silt fence- Area Inlet Pending   | Kennedy Ave  | 4/27/2011                 | Pending      | Yes      |  |  |
| Sarrent Condition.         | Chang  |  |                           |              |          |  |  |
|                            | Area inlet is partially buried and it needs to be cleaned out and silt fence needs to be installed around                                    |  |                           |              |          |  |  |
|                            | Commercial Seeding was informed to complete maintenance by 4/27/11. As of 4/21/11 Developer Mi   |  |                           |              |          |  |  |
|                            | Kucera has not paid a previous invoice to Commercial Seeding. Commercial Seeding is waiting on pa  |  |                           |              |          |  |  |
|                            | before they will complete this work. As of 6/9/11 no payment has been received per Mike Woodward v   |  |                           |              |          |  |  |
|                            | Commercial Seeding. On 6/30/11 Developer Mike Kucera was reminded that maintenance needs to b  |  |                           |              |          |  |  |
|                            | completed ASAP.  |  |                           |              |          |  |  |
|                            |  | T  | <u> </u>                  |              |          |  |  |
|                            |  | N41d00m00s   |                           | Removed      |          |  |  |
| SE A                       | Silt Eange   | Moedoomoo  |                           |              |          |  |  |
| SF A                       | Silt Fence   | W96d00m00s   | rm installed              | Removed      |          |  |  |
| SF A Current Condition:    | Silt Fence Partially removed due to good The remainder of silt fence w   | d vegetation and a ber   |                           |              | Seeding. |  |  |
|                            | Partially removed due to good  | d vegetation and a ber   |                           |              | Seeding. |  |  |

| Current Condition:               | Silt fence run was removed due to good vegetation and no activity in the area at this time prior to inspection on 3/24/10 by CS. Note: Silt fence may need to be reinstalled once there is construction activity in the area.  |                          |                             |                         |                            |  |  |
|----------------------------------|--|--------------------------|-----------------------------|-------------------------|----------------------------|--|--|
| SF C                             | Silt Fence   | N41d00m00s<br>W96d00m00s |                             | Removed                 |                            |  |  |
| Current Condition:               | Silt fence run was removed due to good vegetation prior to inspection on 3/24/10 by CS.  |                          |                             |                         |                            |  |  |
| SF D Current Condition:          | Silt Fence   | N41d00m00s<br>W96d00m00s | hia ausa                    | Removed                 |                            |  |  |
| Current Condition:               | Silt Fence removed and diversion ditch installed in this area.   |                          |                             |                         |                            |  |  |
| STR                              | Street Cleaning  | N41d00m00s<br>W96d00m00s |                             | Active                  | Yes                        |  |  |
|                                  | Fair Condition- Run off appeared to be cleaned up prior to inspection on 6/21/11 by Rod w/ Townhomes LLC.  1) Due to recent rains there is minor signs of run off along Kennedy Ave and it needs to be cleaned up.  2) The sidewalk just West of SB A along Chandler has some run off and it needs to be cleaned up.  1) Developer Mike Kucera was informed to clean up by 6/28/11. Maintenance not completed as of last inspection.  2) Developer Mike Kucera was informed to clean up by 6/28/11. Maintenance not completed as of last inspection. |                          |                             |                         |                            |  |  |
| SWPPP Sign<br>Current Condition: | SWPPP Sign Good Condition A SWPPP sign has been inst Ave entrances.  | Two signs on site.       | 8/8/2008<br>er Road, 22nd & | Active<br>Chandler Road | No<br>and 25th and Sautter |  |  |
| Inspector Signature:             | lack Jawlan  |                          |                             | Reviewed By:            | Zachany L. Jiluk           |  |  |