E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Erosion Control Specialist- Mana				
		P2006.135.000		
Inspector: Mike Jacobson, CISEC			Stage	
	Kei	nnedy Town Center	3	
Project Name:				
For Week Ending:				
	OF the O. Cheardin	12/10/2011		
Project Location:	25th & Chandle	25th & Chandler Road- Bellevue, NE (Sarpy County)		
Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	25%			
	2070			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected		
			Week	
Sunday:	0.00"		- Hook	
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	Trace		Week	
Sunday:	0.00"		Week	
Monday	0.00"	11/21/11		
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	Trace			
Saturday	0.00"		West	
Sunday:	0.00"		Week	
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	Trace			
Friday	0.03"			
Saturday	0.37"			
Country of the countr	0.00"		Week	
Sunday: Monday	0.00" Trace			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.03"			
Friday	Trace			
Saturday	0.00"			
			Week	
Sunday:	N/A	N/A		
Monday	N/A	N/A		
Tuesday Wednesday	N/A N/A	N/A N/A	-	
Thursday	N/A	N/A		
Friday	N/A	N/A		
Saturday	N/A	N/A		
-			•	
	None			
Complaints:	_			
		<u> </u>		
Construction Sequencing:				
		nent cessation of grading, earthwork, or ground di		

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:						
which portion(s) (i.e. dramage basins) or the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?						
Entire Site, Grading was completed and entire site was seeded Fall 2006.						
			ı	1		
W						
What temporary or permanent stabilization measures listed in this section are being implemented?						
Seeding (Fall 2006), stabilized entrance, Paved streets (10/2007), Paved entrance (11/2007); Re-seed part of the lot to west of SB B(4/2009); Re-						
seeded the north east corner of the lot where the area inlet was installed(4/2009); Re-seeded around the SB A and SB B(4/2009)						
		. , , , , , , , , , , , , , , , , , , ,		,	,	
Comments:						
Comments:						
Condo construction is active along 23rd and 22nd Street in the Southwest section of the site.						
Findings / Corrective Actions (Date):						
` /						
Findings / Corrective Actions (Date):						
1) Some maintenance is required in the BMP section.						

			Projected		
Unique Name	Туре	Location	Install Date	Status	Maintenan
		N41d00m00s			
CE A	Construction Entrance	W96d00m00s		Removed	No
Current Condition:	Removed paved entrance	- U		l .	
	·	N41d00m00s			
DD 1	Swale	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition - Partially ren				
	Diversion ditch was redefined				
DD 2	Swale	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed due to paving of str			Removed	
Current Condition.	Removed due to paving or str	T	ı		
POD A	Misc/Other	Lots 61-72		Removed	
Current Condition:	Good Condition-	2010 01 72		rtomovou	
	Silt fence check in the outlot of	on the North side of lot	72 was removed	d during inspectio	n on 11/22/11 by
	inspector.			0 1	ĺ
POD B	Misc/Other	Lots 37-60	2/9/2011	Active	No
Current Condition:	No BMP is installed on lots- A				
	Silt fence was removed from	the lot prior to inspecti	on on 8/12/11 by	Rod w/ Townhor	nes LLC.
		N41d00m00s			
SB A	Sediment Basin	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition - 22% filled				
	Cleaned out 10/2007 by Dave	Hausman. Erosion m	aintenance was	completed prior to	o inspection on 4
	by M.E. Collins.				
		N41d00m00s			
SB B	Sediment Basin	W96d00m00s	10/6/2007	Active	No
Current Condition:	Good Condition - 23% filled				-
	Cleanout and riser maintenan	ce was completed on	4/1/09 by M.E. C	ollins.	
		East side of			
	1 2		4/27/2011	Pending	Yes
SF AI-1	Silt fence- Area Inlet	Kennedy Ave	4/21/2011		165
SF AI-1 Current Condition:	Silt fence- Area Inlet Pending	Refinedy Ave	4/21/2011		165
	Pending				
	Pending Area inlet is partially buried a	nd it needs to be clear	ned out and silt fe	ence needs to be	installed around
	Pending Area inlet is partially buried as Commercial Seeding was info	nd it needs to be clear	ned out and silt fe	ence needs to be	installed around
	Pending Area inlet is partially buried a Commercial Seeding was info	nd it needs to be clear ormed to complete ma us invoice to Commerc	ned out and silt fe intenance by 4/2 cial Seeding. Con	ence needs to be 7/11. As of 4/21/1 nmercial Seeding	installed around 1 Developer Mily is waiting on pa
	Pending Area inlet is partially buried a Commercial Seeding was info Kucera has not paid a previous before they will complete this	ormed to complete ma is invoice to Commerc work. As of 6/9/11 no	ned out and silt fe intenance by 4/2' cial Seeding. Con payment has bee	ence needs to be 7/11. As of 4/21/1 nmercial Seeding en received per M	installed around 1 Developer Milipis waiting on pa
	Pending Area inlet is partially buried a Commercial Seeding was info	ormed to complete ma us invoice to Commero work. As of 6/9/11 no 0/11 Developer Mike k	ned out and silt fe intenance by 4/2' cial Seeding. Con payment has bee Cucera was remir	ence needs to be 7/11. As of 4/21/1 nmercial Seeding en received per M	installed around 1 Developer Mil 1 is waiting on pa
	Pending Area inlet is partially buried at Commercial Seeding was info Kucera has not paid a previou before they will complete this Commercial Seeding. On 6/30	ormed to complete ma us invoice to Commero work. As of 6/9/11 no 0/11 Developer Mike k	ned out and silt fe intenance by 4/2' cial Seeding. Con payment has bee Cucera was remir	ence needs to be 7/11. As of 4/21/1 nmercial Seeding en received per M	installed around 1 Developer Mil 1 is waiting on pa
	Pending Area inlet is partially buried at Commercial Seeding was info Kucera has not paid a previou before they will complete this Commercial Seeding. On 6/30	ormed to complete ma us invoice to Commerc work. As of 6/9/11 no 0/11 Developer Mike he not completed as of	ned out and silt fe intenance by 4/2' cial Seeding. Con payment has bee Cucera was remir	ence needs to be 7/11. As of 4/21/1 nmercial Seeding en received per M	installed around 1 Developer Milipis waiting on pa
Current Condition:	Pending Area inlet is partially buried a Commercial Seeding was info Kucera has not paid a previou before they will complete this Commercial Seeding. On 6/30 completed ASAP. Maintenand	ormed to complete ma us invoice to Commerc work. As of 6/9/11 no 0/11 Developer Mike had not completed as of N41d00m00s	ned out and silt fe intenance by 4/2' cial Seeding. Con payment has bee Cucera was remir	ence needs to be 7/11. As of 4/21/1 nmercial Seeding en received per N nded that mainten	installed around 1 Developer Mik is waiting on pa
Current Condition:	Pending Area inlet is partially buried at Commercial Seeding was info Kucera has not paid a previou before they will complete this Commercial Seeding. On 6/30 completed ASAP. Maintenance Silt Fence	ormed to complete ma us invoice to Commerc work. As of 6/9/11 no 0/11 Developer Mike he per not completed as of N41d00m00s W96d00m00s	ned out and silt for intenance by 4/2' cial Seeding. Con payment has bee (ucera was remir f last inspection.	ence needs to be 7/11. As of 4/21/1 nmercial Seeding en received per M	installed around 1 Developer Mik is waiting on pa
Current Condition:	Pending Area inlet is partially buried at Commercial Seeding was information to the Commercial Seeding was information to the Commercial Seeding. On 6/30 completed ASAP. Maintenance Silt Fence Partially removed due to good	ormed to complete maus invoice to Commerce work. As of 6/9/11 no 0/11 Developer Mike hoe not completed as of W96d00m00s divegetation and a ber	ned out and silt fe intenance by 4/2' sial Seeding. Con payment has bee kucera was remir f last inspection. m installed.	ence needs to be 7/11. As of 4/21/1 nmercial Seeding en received per M ided that mainten	installed around 1 Developer Mik 1 is waiting on pa dike Woodward v lance needs to b
Current Condition:	Pending Area inlet is partially buried at Commercial Seeding was info Kucera has not paid a previou before they will complete this Commercial Seeding. On 6/30 completed ASAP. Maintenance Silt Fence	ormed to complete ma us invoice to Commerc work. As of 6/9/11 no 0/11 Developer Mike has not completed as of N41d00m00s W96d00m00s d vegetation and a ber as removed prior to ins	ned out and silt fe intenance by 4/2' sial Seeding. Con payment has bee kucera was remir f last inspection. m installed.	ence needs to be 7/11. As of 4/21/1 nmercial Seeding en received per M ided that mainten	installed around 1 Developer Mik 1 is waiting on pa dike Woodward v lance needs to b
SF A Current Condition:	Pending Area inlet is partially buried at Commercial Seeding was information to the forest of the following seeding was information to the forest of the following seeding. On 6/30 completed ASAP. Maintenance Silt Fence Partially removed due to good The remainder of silt fence was	ormed to complete maus invoice to Commerce work. As of 6/9/11 no 0/11 Developer Mike her not completed as of W96d00m00s I vegetation and a beras removed prior to insure work.	ned out and silt fe intenance by 4/2' sial Seeding. Con payment has bee kucera was remir f last inspection. m installed.	ence needs to be 7/11. As of 4/21/1 nmercial Seeding en received per N nded that mainten Removed 1 by Commercial	installed around 1 Developer Mik 1 is waiting on pa dike Woodward v lance needs to b
SF A Current Condition:	Pending Area inlet is partially buried at Commercial Seeding was information to before they will complete this Commercial Seeding. On 6/3t completed ASAP. Maintenance Silt Fence Partially removed due to good The remainder of silt fence was Silt Fence	ormed to complete maus invoice to Commerce work. As of 6/9/11 no 0/11 Developer Mike the not completed as of W96d00m00s W96d00m00s d vegetation and a beras removed prior to in: N41d00m00s W96d00m00s	intenance by 4/2: cial Seeding. Con payment has bee fucera was remir f last inspection. m installed. spection on 4/4/1	Price needs to be 7/11. As of 4/21/1 mercial Seeding on received per Mided that mainten Removed 1 by Commercial Removed	installed around 1 Developer Mil 1 is waiting on pa 1 dike Woodward value needs to be 1 seeding.
SF A Current Condition:	Pending Area inlet is partially buried at Commercial Seeding was information to before they will complete this Commercial Seeding. On 6/3t completed ASAP. Maintenance Silt Fence Partially removed due to good The remainder of silt fence was Silt Fence Silt Fence Silt fence run was removed due.	ormed to complete maus invoice to Commerce work. As of 6/9/11 no 0/11 Developer Mike been not completed as of W96d00m00s. N41d00m00s. d vegetation and a bert as removed prior to in: N41d00m00s. W96d00m00s. ue to good vegetation	intenance by 4/2 cial Seeding. Con payment has bee success was remir f last inspection. m installed. spection on 4/4/1 and no activity in	Removed the area at this t	installed around 1 Developer Mility is waiting on particle Woodward wance needs to be seeding.
SF A Current Condition:	Pending Area inlet is partially buried at Commercial Seeding was information to before they will complete this Commercial Seeding. On 6/3t completed ASAP. Maintenance Silt Fence Partially removed due to good The remainder of silt fence was Silt Fence	ormed to complete maus invoice to Commerce work. As of 6/9/11 no 0/11 Developer Mike been not completed as of W96d00m00s. N41d00m00s. d vegetation and a bert as removed prior to in: N41d00m00s. W96d00m00s. ue to good vegetation	intenance by 4/2 cial Seeding. Con payment has bee success was remir f last inspection. m installed. spection on 4/4/1 and no activity in	Removed the area at this t	installed around 1 Developer Mility is waiting on particle Woodward wance needs to be seeding.
SF A Current Condition:	Pending Area inlet is partially buried at Commercial Seeding was information to before they will complete this Commercial Seeding. On 6/3t completed ASAP. Maintenance Silt Fence Partially removed due to good The remainder of silt fence was Silt Fence Silt Fence Silt fence run was removed due.	ormed to complete maus invoice to Commerce work. As of 6/9/11 no 0/11 Developer Mike be not completed as of w96d00m00s. N41d00m00s. d vegetation and a beras removed prior to ins N41d00m00s. W96d00m00s. ue to good vegetation ence may need to be inserted.	intenance by 4/2 cial Seeding. Con payment has bee success was remir f last inspection. m installed. spection on 4/4/1 and no activity in	Removed the area at this t	installed around 1 Developer Mik is waiting on pa fike Woodward v ance needs to b Seeding.
SF A Current Condition:	Pending Area inlet is partially buried at Commercial Seeding was information to before they will complete this Commercial Seeding. On 6/3t completed ASAP. Maintenance Silt Fence Partially removed due to good The remainder of silt fence was Silt Fence Silt Fence Silt fence run was removed due.	ormed to complete maus invoice to Commerce work. As of 6/9/11 no 0/11 Developer Mike been not completed as of W96d00m00s. N41d00m00s. d vegetation and a bert as removed prior to in: N41d00m00s. W96d00m00s. ue to good vegetation	intenance by 4/2 cial Seeding. Con payment has bee success was remir f last inspection. m installed. spection on 4/4/1 and no activity in	Removed the area at this t	installed around 1 Developer Mik is waiting on pa fike Woodward v ance needs to b Seeding.

		N41d00m00s			
SF D	Silt Fence	W96d00m00s		Removed	
Current Condition:	Silt Fence removed and diversion ditch installed in this area.				
		N41d00m00s			
STR	Street Cleaning	W96d00m00s		Active	Yes
Current Condition:	Fair Condition-				
	Run off appeared to be cleaned up prior to inspection on 9/27/11 by Rod w/ Townhomes LLC. 1) Due to recent rains there is minor signs of run off along Kennedy Ave and it needs to be cleaned up. 2) The sidewalk just West of SB A along Chandler has some run off and it needs to be cleaned up. 1) Developer Mike Kucera was informed to clean up by 6/28/11. Maintenance not completed as of last inspection. 2) Developer Mike Kucera was informed to clean up by 6/28/11. Maintenance not completed as of last inspection.				
SWPPP Sign	SWPPP Sign	Two signs on site.	8/8/2008	Active	No
Current Condition:	Good Condition A SWPPP sign has been installed at 19th & Chandler Road, 22nd & Chandler Road and 25th and Sautter Ave entrances.				
Inspector Signature: Tachany k. Reviewed By:				Zachany k. Jilde	

Inspector Signature: