E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

	E & A CONSULTING GROUP, INC.
	Engineering Answers
A - P2006.135.000	

	E&A -	P2006.135.000				
Inspector: Branson Starns				Stage		
Project Name:	K	3				
For Week Ending:		6/10/20	17			
Project Location:	25th & Char	68147				
1 Toject Location.	25th & Chandler Road- Bellevue, NE (Sarpy County) 6814					
Grading:	100%	,				
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities:	100%					
Overall Development:	30%					
•		1	1	-		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Manla		
Sunday:	0.00"			Week 1		
Monday	0.00"					
Tuesday	2.03"					
Wednesday	0.39"					
Thursday	0.18"	5/18/2017	Tstorm 64/52			
Friday	0.50"	5/19/2017	Rain 56/48			
Saturday	0.33"					
Sunday:	0.00"					
Monday	0.23"					
Tuesday	0.03"	5/23/2017	Rain 60/48			
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00" 0.42"					
Saturday	0.42					
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.01"					
Thursday	0.00"					
Friday	0.17"					
Saturday	0.00"					
	<u> </u>					
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"	-				
Wednesday						
Thursday Friday	0.00"					
Saturday	0.00"	+				
Sunday:	N/A					
Monday	N/A					
Tuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					

	None						
Complaints:							
	1						
Construction Sequencing:							
Which portion(s) (i.e. drainage basins) of the	site have had a temporary or permar	nent cessation of grading	g, earthwork, or ground disturl	bance in the las	t 14 days?		
Entire Site, Grading was completed a	Entire Site, Grading was completed and entire site was seeded Fall 2006.						
Which portion(s) (i.e. drainage basins) of the	site do not have grading, earthwork,	or ground disturbance s	scheduled in the next 14 days?	?:			
Entire Site, Grading was completed a	nd entire site was seeded Fall 2	006.					
What temporary or permanent stabilization r	neasures listed in this section are bei	ing implemented?					
Dense vegetation (2014)							
Summary Questions:							
Are approved entrances and adjacent street	s being maintained adequately?						
No-see BMP section							
Are receiving waters adjacent to the project	free of any significant signs of erosi	on or sediment that wou	ld be associated with the cons	truction activity	<i>l</i> ?		
Yes		I	1	1	1		
0. 1							
Checklist Questions: Are waste materials (concrete, construction							
No- see BMP section	material, nazardous, etc.) being mana	aged properly?					
140- See Divil Section			<u> </u>	I	l		
Are waste materials (concrete, construction	material, hazardous, etc.) being mana	aged properly?		I			
Yes							
Comments:							
Comments:							
The site is active.							
Findings / Corrective Actions (Date):						
Findings / Corrective Actions (Date):							
1) No maintenance is required.							
2) Lot 2 replat 4 and lot 74 are preser	itly undeveloped.						
	·						

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CW	Concrete Washout	TBD	5/25/2017	Pending	Yes	
Current Condition:	Pending-					
	A concrete washout needs reinstalled. Bo with 4C Construction was informed to complete by 5/25/17. Not done as of last inspection.					
DD 1	Swale	East of SB A	In Place	Active	No	
Current Condition:	Good Condition-The diversion	ditch remains in place	e on the east side of SB A	as of inspec	tion on 1/15/15.	
Lot 4 Replat 3	Silt Fence	Lot 4 Replat 3		Removed		
Current Condition:	Removed- this area is part of details.	Removed- this area is part of the Corwin Toyota SWPPP as of 7/30/16. See Corwin Toyota SWPPP for details.				
Lot 81	Concrete Washout	Lot 81		Removed		
Current Condition:	Removed- this area is part of removed.	Removed- this area is part of the Corwin Toyota SWPPP as of 7/30/16. The concrete washout has been removed.				
POD B	Silt Fence	Lots 28-44	2/9/2011	Active	Yes	
Current Condition:	Fair Condition- Bo with 4C Construction installed silt fence around the front of lots 28-30 and lot 44 prior to 4/19/17. 1) The silt fence needs entrenched around lots 28-30, and 44. 2) The silt fence is in disrepair along lot 28-30 and lot 44 and needs reinstalled/repaired. 1) Bo with 4C Construction was informed to complete by 4/26/17. Not done as of last inspection. Bo with 4C Construction was reminded on 5/3/17, 5/20/17. 2) Bo with 4C Construction was informed to complete by 5/9/17. Not done as of last inspection. Bo with 4C Construction was reminded on 5/20/17. Not done as of last inspection.					
POD C	Silt Fence	Lots 10-27	7/6/2016	Active	Yes	

Current Condition:	Fair Condition- Bo with 4C Construction installed silt fence around the sides and front of lot 24 prior to 4/20/17. Bo with 4C Construction installed silt fence in the rear of the lot prior to 5/18/17. 1) The silt fence in the rear of lot 24 and existing silt fence needs backfilled/entrenched. 2) Concrete spoils need removed from the lot. 1) Bo with 4C Construction was informed to complete by 4/26/17. Not done as of last inspection. Bo with 4C Construction was reminded on 5/3/17, 5/20/17.				
	2) Bo with 4C Construction v	vas informed to con	nplete by 5/25/17. Not do	ne as of last	inspection.
POD D	Silt Fence	Lots 1-9		Removed	
Current Condition:	Removed- Lot 2 was sodded by 4C Construction prior to inspection on 7/13/16. All lots in the Pod are now stabilized as of 7/13/16.				
SB A	Sediment Basin	Lot 75	In Place	Active	No
Current Condition:	Good Condition - 23% filled				
SB B	Sediment Basin	Outlot A	10/6/2007	Active	No
Current Condition:	Good Condition - 25% filled				
STR	Street Cleaning	In Place	In Place	Active	Yes
Current Condition:	Fair Condition- The streets need cleaned along the active lots. Bo with 4C Construction was informed to complete by 5/19/17. Not done as of last inspection.				
SWPPP Sign	SWPPP Notification Sign	One Sign	8/8/2008	Active	No
Current Condition:	on: Good Condition-22nd and Chandler Rd. The SWPPP sign at 25th and Sautter Ave could not be located and will not be reinstalled as of inspection on 12/1/15.				
Inspector Signature:	Brancon Stune		Reviewed By:	Van	