E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A .lilek CPESC CISEC

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager				Engineering Answers	
	Δ - P2006 135 000	1			
	A - 1 2000.133.000	<u>'</u>		Stage	
	Kennedy Tow	n Center			
	_				
25th & C				68147	
2011 0. 0	nunuici itouu- Benev	ruc, IL (Gurpy Gounty)			
10	00%				
10	00%				
10	00%				
10	00%				
10	00%				
10	00%				
Amount in tenths	Date inspected	Weather Conditions			
0.00"				Week	
0.01"					
0.00"					
0.12"					
	7/13/2017	Tstorm 85/69			
[0.00"					
0.00"					
0.04"					
0.00"					
0.00"					
0.00"					
0.00"					
0.92"	7/26/2017	Tstorm 77/71			
0.00"					
0.00"					
0.00					
			+		
0.00			+ +		
0.00"			+ +		
			† †		
0.04"			<u> </u>		
0.00"			 		
0.00			+		
			1		
0.00"			1		
	## E& ## 25th & C	E&A - P2006.135.000	E&A - P2006.135.000	E&A - P2006.135.000	

	None				
Complaints:					
	1				
Construction Sequencing:					
Which portion(s) (i.e. drainage basins) of th	e site have had a temporary or perma	nent cessation of gradi	ng, earthwork, or ground distu	irbance in the la	ast 14 days?
Entire Site, Grading was completed a	nd entire site was seeded Fall 2	2006.			
Which portion(s) (i.e. drainage basins) of th	e site do not have grading, earthwork	k, or ground disturbance	scheduled in the next 14 day	s?:	-
Entire Site, Grading was completed a	and entire site was seeded Fall 2	2006.			
What temporary or permanent stabilization	measures listed in this section are be	ing implemented?	•	•	
Dense vegetation (2014)					
Summary Questions:					
Are approved entrances and adjacent street	s being maintained adequately?				
No-see BMP section					
Are receiving waters adjacent to the projec	t free of any significant signs of eros	ion or sediment that wo	uld be associated with the co	nstruction activ	ity?
Yes					
Checklist Questions:					
Are waste materials (concrete, construction	material, hazardous, etc.) being man	aged properly?			
No- see BMP section	T T		ī	I	
Are waste materials (concrete, construction	material hazardous etc) being man	aged properly?	l		
Yes	material, nazardodo, etc./ being man	laged property:			
			I		
Comments:					
Comments:					
The site is active.					
Findings / Corrective Actions (Date					
Findings / Corrective Actions (Date)):	_			_
1) No maintenance is required.					
2) Lot 2 replat 4 and lot 74 are preser	ntly undeveloped.				
	<u> </u>				

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CW	Concrete Washout	TBD	5/25/2017	Pending	Yes	
Current Condition:	Pending-	•	<u>'</u>			
	A concrete washout needs reinstalled.					
		Bo with 4C Construction was informed to complete by 5/25/17. Not done as of last inspection. 4C Construction was reminded on 7/28/17.				
DD 1	Swale	East of SB A	In Place	Active	No	
Current Condition:	Good Condition-The diversion	n ditch remains in pl	ace on the east side of SB	A as of inspe	ection on 1/15/1	
Lot 4 Replat 3	Silt Fence	Lot 4 Replat 3		Removed		
Current Condition:	Removed- this area is part of the Corwin Toyota SWPPP as of 7/30/16. See Corwin Toyota SWPPP for details.					
Lot 81	Concrete Washout	Lot 81		Removed		
Current Condition:	Removed- this area is part of the Corwin Toyota SWPPP as of 7/30/16. The concrete washout has been removed.					
POD B	Silt Fence	Lots 28-44	2/9/2011	Active	Yes	
Current Condition:	Fair Condition- Bo with 4C Construction installed silt fence around the front of lots 28-30 and lot 44 pr 4/19/17. 1) The silt fence needs entrenched around lots 28-30, and 44. 2) The silt fence is in disrepair along lot 28-30 and lot 44 and needs reinstalled/repaired. 1) Bo with 4C Construction was informed to complete by 4/26/17. Not done as of last inspection. Bo with 4C Construction was informed to complete by 5/9/17. Not done as of last inspection. Bo with 4C Construction was informed to complete by 5/9/17. Not done as of last inspection. Bo with 4C Construction was reminded on 5/20/17. Not done as of last inspection. 4C Construction was reminded 7/28/17.				pection. Bo with ection. Bo with 4	

POD C	Silt Fence	Lots 10-27	7/6/2016	Active	Yes
Current Condition:	Fair Condition- Bo with 4C Co 4/20/17. Bo with 4C Construct 1) The silt fence in the rear of backfilled/entrenched/repaired 2) Concrete spoils need removable. 1) Bo with 4C Construction was Construction was reminded or 2) Bo with 4C Construction was Construction was reminded	lot 24 and silt fence d. lot 24 and silt fence d. lot 24 and silt fence d. lot 25 and silt fence d. lot 26 and silt fence	e in the rear of the lot prior along the side of the nee stee by 4/26/17. Not done a 8/17.	or to 5/18/17. ds as of last insp	pection. Bo with 4C
POD D	Silt Fence	Lots 1-9		Removed	
Current Condition:	Removed- Lot 2 was sodded by stabilized as of 7/13/16.		rior to inspection on 7/13/		the Pod are now
SB A	Sediment Basin	Lot 75	In Place	Active	No
Current Condition:	Good Condition - 23% filled	•			
SB B	Sediment Basin	Outlot A	10/6/2007	Active	No
Current Condition:	Good Condition - 25% filled				
STR	Street Cleaning	In Place	In Place	Active	Yes
Current Condition:	Fair Condition- The streets need cleaned along the active lots. Bo with 4C Construction was informed to complete by 5/19/17. Not done as of last inspection. 4C Construction was reminded on 7/28/17.				
SWPPP Sign	SWPPP Notification Sign	One Sign	8/8/2008	Active	No
Current Condition:	Good Condition-22nd and Chandler Rd. The SWPPP sign at 25th and Sautter Ave could not be located and will not be reinstalled as of inspection on 12/1/15.				
Inspector Signature:	pa luc		Reviewed By:	Posts So	