E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Environmental Services De	pr. wanayer	E & ^	- P2020.091.000	-				
Inspector: Joe Manning		EQA	- F 2020.031.000		Stage			
mapector. Jue maining		Mel	estic Pointe East		Jiaye			
		1						
Project Name:	ON	68007						
For Week Ending:		4/9/2022						
Project Location:	168th Street and State Street - Omaha, NE (Douglas County)							
			1	1	1			
Grading:	99%		_					
Sanitary Sewer:	65%		_					
Storm Sewer:	35%							
Paving:	0%							
Seeding: Utilities:	35%							
Overall Development:	30%							
overall Development.	50 / 0							
RAIN FALL AMOUNTS	Amount in tenths	Data increated	We athen Conditions	Time				
RAIN FALL AMOUNTS	Anouncintentits	Date inspected	Weather Conditions	TIME	Week 1			
Sunday	0.00"				vveek			
Sunday: Monday:	0.00"							
	0.00"				1			
Tuesday: Wednesday:	0.00"	4/6/2022	Windy/Blustery 49/38	3:25 PM	+			
		4/0/2022	winuy/blustery 49/38	3.20 FW	+			
Thursday:	0.00"				+			
Friday: Saturday:	0.00"							
Saturuay.	0.00			1	1			
<u> </u>								
Comulaintes	Nama							
Complaints:	None							
Construction Sequencing:								
	sins) of the site have had a temporary or	permanent cessation	of grading, earthwork, or ground distu	urbance in the last 14 days?				
Ground disturbance associate	ed with tree clearing at the 171st S	Street and Reynold	s Street Crossings (4/2/2021). G	round disturbance associated with	tree clearing along State			
	ding began in DEV A, DEV NT3, a							
	Street crossings (10/06/2021). Dis							
	king along the southwest portion o t N 170th Street crossing (12/29/20							
the N 170th Street box culver			i Reynolds Street Curvert. Dackin	ling for in 170th Street box curven	(2/10/2022). Grading for			
	- (
Which portion(s) (i.e. drainage bas	sins) of the site do not have grading, ear	thwork, or ground dis	turbance scheduled in the next 14 day	s?				
Ground disturbance associate	ed with tree clearing at the 171st S	Street and Reynold	s Street Crossings (4/2/2021). G	round disturbance associated with	tree clearing along State			
	ding began in DEV A, DEV NT3, a							
	Street crossings (10/06/2021). Di							
	king along the southwest portion o t N 170th Street crossing (12/29/20							
the N 170th Street box culver		JZT). EXCavation to	Reynolds Street Curvent. Backin	ling for N 170th Street box curven	(2/10/2022). Grading for			
What temporary or permanent stabilization measures listed in this section are being implemented?								
Existing vegetation (4/2/2021). Seeding and matting along the north side of the site, the western slopes along SB A, and the northeastern slopes (12/08/2021).								
Checklist Questions:								
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?								
No								
Create Corrective Action?								
No - See BMP Section.								
Have disturbed areas been	seeded or otherwise stabilized	as required? List	inactive portions of the project	t and if stabilization measure ar	e adequate or needed to			
prevent erosion.		and a second	the project					
Yes								
Create Corrective Action?								
N/A								
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?								
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?								
No Create Corrective Action?								
No - See BMP Section.								
Are construction entrances and adjacent streets being maintained adequately?								
No Create Corrective Action?								
No-See BMP Section.								

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments:

Comments:

Yes

Site was active for sanitary installation during the current inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section.

2.) CIR #15492 was received, reviewed, and sent to JC Excavation, Gene Graves, and Tab Construction on 12/03/21.

-Per CIR #15492 dirt spoils in the seeding and matting along N 168th St. should be removed. JC Excavation and Gene Graves were informed to complete by 12/10/21. Not done as of the last inspection. JC Excavation and Gene Graves were reminded on 12/09/21. Gene Graves and Susan Mortensen were reminded on 2/02/22, 2/11/22, 3/24/22, 4/07/22

Unique Name Projected Install Date Maintenance Type Location Status Removed Construction Entrance V11 CE 1 Current Condition Removed - JC Excavation graded out the site access at this location as of the inspection on 10/13/21. No CE 2 Construction Entrance S2 2/23/2021 Pending Pending - 77% effective - Legacy Homes installed a construction entrance prior to 2/23/21. Gene Graves and Legacy Homes blocked the Current Condition: construction entrance prior to the inspection on 6/08/21. JC Excavation blocked the construction entrance prior to the inspection on 10/13/21. E&A inspector will monitor and make recommendations if the entrances is used at a later date. CE 3 Construction Entrance T27 9/21/2021 Active No **Current Condition:** Good Condition - 95% effective - JC Excavation installed a construction entrance prior to the inspection on 9/21/21. JC Excavation added additional rock prior to the 9/28/21 inspection. Graves Development added a small amount of rock to the construction entrance prior to the inspection on 3/09/22. Sudbeck added rock to the construction entrance prior to the inspection on 3/29/22. Due to the density of rock added and soil composition, a liner will no longer be recommended at this time. E&A inspector will monitor. Inlet Protection CIP 1 S29 2/16/2022 Active Fair Condition - Graves Development installed curb inlet protection in the existing inlet on the north side of Potter Street prior to the inspection Current Condition: on 2/16/22. The inlet protection needs to be cleaned out Gene Graves and Susan Mortensen were informed to complete by 3/29/22. Not done as of the last inspection. Graves Development was reminded on 4/07/22. 11/16/2021 03 - 112 D 1 Diversion Active **Current Condition:** Fair Condition - JC Excavation and Gene Graves installed the diversion prior to the inspection on 11/16/21. Location of diversion was misidentified. As of 11/23/21, diversion is located at O3 to U2. The diversion was partially removed by disking prior to the inspection on 12/02/21. The diversion should be redefined into the basin. JC Excavation and Gene Graves were informed to complete by 12/15/21. Not done as of the last inspection. Gene Graves and Susan Mortensen were reminded on 2/02/22, 2/11/22, 4/07/22 D 2 Diversion J18 - S27 9/28/2021 Pending Pending - JC Excavation installed the diversion prior to the inspection on 10/25/21. JC Excavation redefined the diversion prior to the Current Condition: inspection on 11/16/21. Location of diversion was misidentified. As of 11/23/21, diversion is located at J18 to S27. Valley Corp partially removed the diversion during sanitary installation prior to the inspection on 12/02/21. The diversion should be reinstalled Valley Corp was informed to complete by 12/15/21. Not done as of the last inspection. Gene Graves and Susan Mortensen were reminded on 2/02/22, 2/11/22, 4/07/22 D 3 Diversion J15 - N6 10/28/2021 Active Fair Condition - JC Excavation installed the diversion prior to the inspection on 10/28/21. JC Excavation and Gene Graves partially redefined **Current Condition:** the diversion prior to the inspection on 11/16/21. Location of diversion was misidentified. As of 11/23/21, diversion is located at J15 to N6. The diversion was partially graded out due to disking on site prior to the inspection 12/02/21. The diversion should be redefined where filling in/removed and extended north into SB B and regraded to flow into SB B. JC Excavation and Gene Graves were informed to complete by 11/10/21. Not done as of the last inspection. JC Excavation and Gene Graves were reminded on 11/17/21 (CIR #15429), 11/24/21, 12/03/21 (CIR #15492), 12/09/21. Gene Graves and Susan Mortensen were reminded on 2/02/22, 2/11/22, 4/07/22 FM 1 E11 - S25 9/1/2021 Erosion Control Matting Pending No Pending - The matting will be installed after grading is completed in the area and weather conditions allow. Current Condition: Active FM 2 Erosion Control Matting E6 - F12 12/8/2021 No **Current Condition:** Good Condition- Gene Graves installed the erosion control matting prior to the inspection on 12/08/21. 9/1/2021 EM 3 Erosion Control Matting M6 - Z6 Pending No **Current Condition:** Pending - The matting will be installed after grading is completed in the area and weather conditions allow. EM 4 Erosion Control Matting Z5 - Z24 12/8/2021 Active No **Current Condition:** Good Condition- Gene Graves installed the erosion control matting prior to the inspection on 12/08/21. EM 5 Erosion Control Matting Active V1 - V7 12/8/2021 No **Current Condition:** Good Condition- Gene Graves installed the erosion control matting prior to the inspection on 12/08/21. Erosion Control Terrace V8 - O21 9/21/2021 Active No **Current Condition:** Good Condition - JC Excavation installed the erosion control terrace prior to the inspection on 9/21/21. Erosion Control Terrace S2 - K14 9/21/2021 No ET 2 Active **Current Condition:** Good Condition - JC Excavation installed the majority of the erosion control terrace prior to the inspection on 9/21/21 Fuel Tank On-site Removed **Current Condition:** Removed - JC Excavation and Gene Graves removed the fuel tanker and cleaned up the spills prior to the inspection on 12/16/21. Fuel Tank On-site Removed **Current Condition:** Removed - Valley Corp removed the fuel tank prior to the inspection on 11/23/21 FT 3 Fuel Tank On-site 11/23/2021 Active Vec

	Fair Condition - Tab Constru	ction placed a double	-walled fuel tank on site prior	to the inspection on 11/23/21.			
	Fair Condition - Tab Construction placed a double-walled fuel tank on site prior to the inspection on 11/23/21. Per CIR #15492, a berm should be built around the fuel tank.						
	Tab Construction was inform	ed to complete by 12	(10/21. Not done as of the las	t inspection. Tab Construction w	as reminded on 1/27/22		
FT 4	Fuel Tank	On-site		Removed			
Current Condition:	Removed - Tab Construction	removed the fuel tan	k prior to the inspection on 12	2/29/21.	•		
MS 01	Material Storage	On Site	3/2/2022	Active	No		
Current Condition:			south portion of the site as of				
PB 01	Portable Bathroom	On Site		Removed			
Current Condition:			pilet prior to the inspection on		1		
PB 02	Portable Bathroom	On Site	tailat mianta tha inana tian	Removed			
Current Condition: PB X	Portable Bathroom	On Site	e toilet prior to the inspection	Active	No		
Current Condition:				inspection on 12/29/21. Valley C			
				toilet from the site prior to the in			
SB A	Sediment Basin	E9	7/14/2021	Active	Yes		
Current Condition:				pection on 10/06/21. E&A inspe			
	painted the cleanout mark du 12/08/21. The basin should be installed JC Excavation and Gene Gra were reminded on 8/06/21, 8	ring the inspection or d per the SWPPP (inc aves were informed to /26/21, 9/02/21, 9/23/	12/08/21. Gene Graves insta luding the emergency spillwa complete by 7/14/21. Not do 21, 10/04/21 (CIR #15132), 1	ne as of the last inspection. JC E 0/14/21, 11/01/21, 11/03/21, 11/	prior to the inspection on Excavation and Gene Graves 17/21 (CIR #15429), 11/24/2		
				ninded on 2/02/22, 2/11/22 , 4/07			
SB B Current Condition:	Sediment Basin	O3	9/28/2021	Active on 10/25/21. JC Excavation rep	Yes		
	Excavation fully built up the berm prior to the inspection on 12/21/21. The basin should be installed per the SWPPP (including the emergency spillway). JC Excavation and Gene Graves were informed to complete by 9/28/21. Not completed as of 09/30/21 inspection. JC Excavation was reminded on 10/04/21 (CIR #15132), 10/14/21, 11/01/21, 11/03/21, 11/17/21 (CIR #15429), 11/24/21, 12/03/21 (CIR #15492), 12/09/21. Ger Graves and Susan Mortensen were reminded on 2/02/22, 2/11/22, 4/07/22						
	JC Excavation and Gene Gra reminded on 10/04/21 (CIR #	aves were informed to ±15132), 10/14/21, 11	complete by 9/28/21. Not con /01/21, 11/03/21, 11/17/21 (C	mpleted as of 09/30/21 inspection			
SF 1	JC Excavation and Gene Gra reminded on 10/04/21 (CIR # Graves and Susan Mortense Silt Fence	aves were informed to \$15132), 10/14/21, 11 n were reminded on 2 W27 - 120	complete by 9/28/21. Not col /01/21, 11/03/21, 11/17/21 (C //02/22, 2/11/22, 4/07/22 4/27/2021	mpleted as of 09/30/21 inspectic IR #15429), 11/24/21, 12/03/21 Active	(CIR #15492), 12/09/21. Ger 		
SF 1 Current Condition:	JC Excavation and Gene Gra reminded on 10/04/21 (CIR # Graves and Susan Mortense Silt Fence Fair Condition - JC Excavatio the silt fence prior to the insp Street crossing prior to the in 3/16/22. E&A inspector will m reinstalled the silt fence whe The silt fence should be rein JC Excavation and Gene Gra	aves were informed to #15132), 10/14/21, 11 n were reminded on 2 W27 - 120 on installed the silt fer section on 10/13/21. J isspection on 10/25/21 nonitor for completion re removed near the o installed along and o aves were informed to "CIR #15429), 11/24/2	complete by 9/28/21. Not co /01/21, 11/03/21, 11/17/21 (C /02/22, 2/11/22, 4/07/22 //27/2021 cce prior to the inspection on 4 C Excavation and Gene Grav. Sudbeck Companies was in . Sudbeck Cleaned out and re center of the run prior to the in ver the south side of the Re	mpleted as of 09/30/21 inspection IR #15429), 11/24/21, 12/03/21 Active 4/27/21. JC Excavation and Gen es installed silt fence along the sit the process of repairing the silt paired the silt fence prior to the	(CIR #15492), 12/09/21. Ger Yes e Graves partially cleaned ou south side of the Reynolds fence during the inspection o 3/22/22 inspection. Sudbeck g. Excavation and Gene Grave		
Current Condition:	JC Excavation and Gene Gra reminded on 10/04/21 (CIR # Graves and Susan Mortense Silt Fence Fair Condition - JC Excavation the silt fence prior to the insp Street crossing prior to the ir 3/16/22. E&A inspector will m reinstalled the silt fence whe The silt fence should be rein JC Excavation and Gene Gra were reminded on 11/17/21 (2/02/22, 2/11/22, 3/24/22, 4// Silt Fence	aves were informed to /15132), 10/14/21, 11 n were reminded on 2 W27 - 120 on installed the silt fer bection on 10/13/21. J ispection on 10/25/21 nonitor for completion re removed near the of installed along and o aves were informed to CIR #15429), 11/24/2 07/22 117 - K7	complete by 9/28/21. Not co /01/21, 11/03/21, 11/17/21 (C /02/22, 2/11/22, 4/07/22 4/27/2021 coce prior to the inspection on 4 C Excavation and Gene Graw. Sudbeck Companies was in . Sudbeck Companies was in . Sudbeck Cleaned out and re exenter of the run prior to the in ver the south side of the Re complete by 11/10/21. Not d 21, 12/03/21 (CIR #15492), 12 4/27/2021	mpleted as of 09/30/21 inspectic IR #15429), 11/24/21, 12/03/21 Active 4/27/21. JC Excavation and Gen es installed silt fence along the si the process of repairing the silt paired the silt fence prior to the spection on 3/29/22. Active	(CIR #15492), 12/09/21. Ger Yes e Graves partially cleaned or south side of the Reynolds fence during the inspection o 3/22/22 inspection. Sudbeck g. Excavation and Gene Grave h Mortensen were reminded of Yes		
Current Condition:	JC Excavation and Gene Graves and Susan Mortense Silt Fence Fair Condition - JC Excavation the silt fence prior to the insp Street crossing prior to the ir 3/16/22. E&A inspector will m reinstalled the silt fence whe The silt fence should be rein JC Excavation and Gene Graver were reminded on 11/17/21 (2/02/22, 2/11/22, 3/24/22, 4// Silt Fence Fair Condition - JC Excavation along the south side of the N 11 Sudbeck cleaned out and rep reinstalled the silt fence whe 1.) The silt fence should be 2.) The silt fence should be 3.) The silt fence should be 4.) JC Excavation and Gene Graves were reminded on 11/27/2022, 2/11/27, 3/24/22, 4//2021 Sudbeck cleaned out and rep reinstalled the silt fence whe 1.) JC Excavation and Gene Graves were reminded on 11/27/2022, 2/11/27, 2.) JC Excavation and Gene	aves were informed to #15132), 10/14/21, 11 n were reminded on 2 W27 - 120 on installed the silt fer section on 10/13/21, J ispection on 10/25/21 nonitor for completion re removed near the of nstalled along and o aves were informed to CIR #15429), 11/24/2 07/22 117 - K7 on installed the silt fer 170th Street culvert am paired the silt fence pr re removed near the of reinstalled along an reinstalled along an	complete by 9/28/21. Not co /01/21, 11/03/21, 11/17/21 (C /02/22, 2/11/22, 4/07/22 a/27/2021 ce prior to the inspection on 4 C Excavation and Gene Grave . Sudbeck Companies was in . Sudbeck Companies was in . Sudbeck Cleaned out and re- genter of the run prior to the in ver the south side of the Re- occmplete by 11/10/21. Not d 11, 12/03/21 (CIR #15492), 12 4/27/2021 ce prior to the inspection on 4 g and the north side of the Re- g removed the silt fence arour ior to the 3/22/22 inspection. .enter of the run prior to the in d over the south side of the d over the north side of the d to complete by 11/10/21. Not 11/24/21, 12/03/21 (CIR #15 d to complete by 11/10/21. Not d to complete by 11/10/21. Not	mpleted as of 09/30/21 inspectic IR #15429), 11/24/21, 12/03/21 Active 4/27/21. JC Excavation and Gen es installed silt fence along the silt paired the silt fence prior to the spection on 3/29/22. Active Active Active Active Active Active Active Active Active Active Active Might Street curvert crossin Sudbeck repaired the silt fence ispection on 3/29/22. N 170th Street Culvert crossin Reynolds Street Culvert crossin Sudbeck repaired the silt fence ispection on 3/29/22.	(CIR #15492), 12/09/21. Ger Yes e Graves partially cleaned or south side of the Reynolds fence during the inspection or 3/22/22 inspection. Sudbeck g. Excavation and Gene Grave n Mortensen were reminded of Yes e Graves installed silt fence e inspection on 10/25/21. Ta r to the inspection on 3/02/22 north of the SB A outfall and ng. sing. JC Excavation and Gene d Susan Mortensen were JC Excavation and Gene		
Current Condition:	JC Excavation and Gene Graves and Susan Mortense Silt Fence Fair Condition - JC Excavation the silt fence prior to the insp Street crossing prior to the ir 3/16/22. E&A inspector will m reinstalled the silt fence whe The silt fence should be rein JC Excavation and Gene Graver were reminded on 11/17/21 (2/02/22, 2/11/22, 3/24/22, 4// Silt Fence Fair Condition - JC Excavation along the south side of the N 11 Sudbeck cleaned out and rep reinstalled the silt fence whe 1.) The silt fence should be 2.) The silt fence should be 3.) The silt fence should be 4.) JC Excavation and Gene Graves were reminded on 11/27/2022, 2/11/27, 3/24/22, 4//2021 Sudbeck cleaned out and rep reinstalled the silt fence whe 1.) JC Excavation and Gene Graves were reminded on 11/27/2022, 2/11/27, 2.) JC Excavation and Gene	aves were informed to t15132), 10/14/21, 11 n were reminded on 2 W27 - 120 on installed the silt fer bection on 10/13/21. J ispection on 10/25/21 nonitor for completion re removed near the of nstalled along and o aves were informed to CIR #15429), 11/24/2 07/22 177 - K7 on installed the silt fer 170th Street culvert and baired the silt fence p re removed near the of reinstalled along an reinstalled along an Graves were informe I/17/21 (CIR #15429), 2, 3/24/22, 4/07/22 Graves were informe I/17/21 (CIR #15429),	complete by 9/28/21. Not co /01/21, 11/03/21, 11/17/21 (C /02/22, 2/11/22, 4/07/22 a/27/2021 ce prior to the inspection on 4 C Excavation and Gene Grave . Sudbeck Companies was in . Sudbeck Companies was in . Sudbeck Cleaned out and re- genter of the run prior to the in ver the south side of the Re- occmplete by 11/10/21. Not d 11, 12/03/21 (CIR #15492), 12 4/27/2021 ce prior to the inspection on 4 g and the north side of the Re- g removed the silt fence arour ior to the 3/22/22 inspection. .enter of the run prior to the in d over the south side of the d over the north side of the d to complete by 11/10/21. Not 11/24/21, 12/03/21 (CIR #15 d to complete by 11/10/21. Not d to complete by 11/10/21. Not	mpleted as of 09/30/21 inspectic IR #15429), 11/24/21, 12/03/21 Active 4/27/21. JC Excavation and Gen es installed silt fence along the s the process of repairing the silt paired the silt fence prior to the spection on 3/29/22. And Street Culvert crossin one as of the last inspection. JC 2/09/21. Gene Graves and Susar Active 4/27/21. JC Excavation and Gen ynolds Street crossing prior to the det culvert in the process prio Sudbeck repaired the silt fence is spection on 3/29/22.	(CIR #15492), 12/09/21. Ger Yes e Graves partially cleaned or south side of the Reynolds fence during the inspection or 3/22/22 inspection. Sudbeck g. Excavation and Gene Grave n Mortensen were reminded of Yes e Graves installed silt fence e inspection on 10/25/21. Ta r to the inspection on 3/02/22 north of the SB A outfall and ng. sing. JC Excavation and Gene d Susan Mortensen were JC Excavation and Gene		

Current Condition:	 Fair Condition - Legacy Homes installed the silt fence prior to E&A's first inspection on 2/23/21. JC Excavation was in the process of repairing/reinstalling the silt fence during the inspection on 4/21/21. Silt fence was formerly identified as SF 5. JC Excavation and Gene Graves installed silt fence along the north side of the N 170th Street crossing prior to the inspection on 10/25/21. JC Excavation and Gene Graves reinstalled/extended the silt fence south from the SB B outfall to the N 170th Street crossing prior to the inspection on 12/08/21. Tab Construction graded the N 170th Street cuvert and removed the silt fence along the north side of the 3/22/22 inspection. Sudbeck reinstalled the silt fence was former by a silt fence along the north of 3/22/22. Sudbeck cleaned out and trenched in the silt fence prior to the 3/22/22 inspection. Sudbeck reinstalled the silt fence was former by a silt fence along the north side of the site, and installed two checks along the north side of the site prior to the inspection on 3/29/22. 1.) The silt fence should be reinstalled along and over the north side of the N 170th Street Culvert crossing as work allows. 2.) The silt fence needs to be reinstalled below the SB B outfall or the area needs to be stabilized and silt fence needs to be installed over the outfall pipe. 1.) JC Excavation and Gene Graves were informed to complete by 11/10/21. Not done as of the last inspection. JC Excavation and Gene Graves were reminded on 11/17/21 (CIR #15429), 11/24/21, 12/03/21 (CIR #15492), 12/09/21. Gene Graves and Susan Mortensen were 						
	reminded on 2/02/22, 2/11/22, 3/24/22, 4/07/22 2.) Gene Graves and Susan Mortensen were informed to complete by 3/29/22. Not done as of the last inspection. Graves Development was						
SF 4	reminded on 4/07/22 Silt Fence	M6 - R2		Removed			
Current Condition:	Removed - JC Excavation removed the northern half of the silt fence fabric prior to the inspection on 10/06/21. JC Excavation removed the remainder of the silt fence fabric prior to the inspection on 11/11/21.						
SF 5	Silt Fence	M6 - N3		Removed			
Current Condition:	Removed - Silt fence identifi	ed as SE 3 as of 4/27/	21				
SF 6	Silt Fence	H19		Removed			
Current Condition:			n both sides of the creek prior				
SF 7	Silt Fence	K6		Removed			
Current Condition:			n both sides of the creek prior				
SF 8	Silt Fence	R2		Removed			
Current Condition:			prior to the inspection on 10/06/2				
STR	Streets	On Site	4/2/2021	Active	Yes		
Current Condition:	 Fair Condition - State Street was cleaned prior to the inspection on 6/01/21. Minor trackout was observed on N 170th Street during the inspection on 1/05/22. Potter Street should be cleaned south of the site. Graves Development was informed to complete by 2/02/22. Not done as of the last inspection. Graves Development was reminded on 2 3/24/22, 4/07/22 						
SWPPP Sign	SWPPP Signs	Adjacent to CE 3	4/21/2021	Active	No		
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign during the inspection on 4/21/21. E&A inspector moved the SWPPP sign to CE 3 during the inspection on 12/02/21.						
WO 01	Concrete Washout	On Site		Removed			
Current Condition:			waste from the site prior to the				
WS 01	Waste Storage Area	On Site	5/1/2021	Pending	No		
Current Condition:	Pending - The waste storage	area will be installed	as necessary.				
Certification Statement:	system designed to assure the person or persons who mana the best of my knowledge and	hat qualified personne age the system or thos d belief, true, accurate	l properly gathered and evaluat e persons directly responsible	ed under my direction or supervision ed the information submitted. Bass for gathering the information, the ir at there are significant penalties for ns.	ed on my inquiry of the formation submitted is, to		
nspector Signature:	Ge Main			Reviewed By:	Parto Sul		