E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A	- P2020.091.000		
Inspector: Joe Manning					Stage
Project Name:	Ol	1			
For Week Ending:		68007			
Project Location:	168				
Grading:	99%				
Sanitary Sewer:	100%				
Storm Sewer:	95%				
Paving:	98%				
Seeding:	35%				
Utilities:	57%				
Overall Development:	55%				
		1			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"	2/1/2023	Sunny 17	9:50 AM	
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				
	Ta c				
Complaints:	None				

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Ground disturbance associated with tree clearing at the 171st Street and Reynolds Street Crossings (4/2/2021). Ground disturbance associated with tree clearing along State Street (4/13/2021). Mass grading began in DEV A, DEV NT3, and the south portion of DEV NT2 (7/07/2021). Mass grading throughout the entire site. Mass grading for Reynolds Street and N 170th Street crossings (10/06/2021). Disking in the north half of the site (12/02/2021). Surcharge removal in the north portion of the site. Storm sewer installation (12/08/2021). Disking along the southwest portion of the site. Grading for N 170th Street crossing (12/16/2021). Grading at Reynolds Street crossing (12/29/2021). Construction of box culvert at N 170th Street crossing (12/29/2021). Excavation for Reynolds Street culvert. Backfilling for N 170th Street box culvert (2/16/2022). Grading for the N 170th Street box culvert (3/02/2022). Grading near Reynolds Street and 168th Street (7/19/2022). A grade stabilization structure was installed in the creek west of SB A (8/2/2022).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Ground disturbance associated with tree clearing at the 171st Street and Reynolds Street Crossings (4/2/2021). Ground disturbance associated with tree clearing along State Street (4/13/2021). Mass grading began in DEV A, DEV NT3, and the south portion of DEV NT2 (7/07/2021). Mass grading throughout the entire site. Mass grading for Reynolds Street and N 170th Street crossings (10/06/2021). Disking in the north half of the site (12/02/2021). Surcharge removal in the north portion of the site. Storm sewer installation (12/08/2021). Disking along the southwest portion of the site. Grading for N 170th Street crossing (12/16/2021). Grading at Reynolds Street crossing (12/29/2021). Construction of box culvert at N 170th Street crossing (12/29/2021). Excavation for Reynolds Street culvert. Backfilling for N 170th Street box culvert (2/16/2022). Grading for the N 170th Street box culvert (3/02/2022). Grading near Reynolds Street and 168th Street (7/19/2022). A grade stabilization structure was installed in the creek west of SB A (8/2/2022).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (4/2/2021). Seeding and matting along the north side of the site, the western slopes along SB A, and the northeastern slopes (12/08/2021). Seeding along the N 170th Street crossing (9/28/2022). Matting along the N 170th Street crossing (10/05/2022).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes					
Create Corrective Action?					
N/A					
A		lateland adaminately	2		
Are construction entrances ar	id adjacent streets being ma	iintained adequately	r		
No Create Corrective Action?					
No - See BMP Section.					
NO - See BIMF Section.					
Is dust associated with the co	Instruction activity adequate	ly controlled on the	site?		
Yes	non donon donvity daoquate	ry controlled on the	0101		
Create Corrective Action?					
N/A					
Comments:					
Comments:					
Site was active for utility installa	tion during the current inspecti	on.			
Findings / Corrective Actions					
Findings / Corrective Actions					
1.) Some maintenance is require	ed in the BMP section.				
			T		T
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	V11		Removed	
Current Condition:			ess at this location as of the insp	T .	
CE 2	Construction Entrance	S2	2/23/2021	Pending	No
Current Condition:	construction entrance prior to	the inspection on 6/0	8/21. JC Excavation blocked the	2/23/21. Gene Graves and Legace construction entrance prior to the	
			tions if the entrances is used at		
CE 3	Construction Entrance	T27		Removed	No
Current Condition:			ction entrance prior to the inspe		
CE 4	Construction Entrance	14		Removed	
Current Condition:			prior to the inspection on 9/21/22		
CIP 1	Inlet Protection	S29	2/16/2022	Active	No
Current Condition:				g inlet on the north side of Potter sorior to the inspection on 7/26/22.	Street prior to the
		South end of North			
CIP 2	Inlet Protection	169 Street	8/2/2022	Active	No
Current Condition:				spection on 8/2/22. Some dirt was	
D 1	Diversion	O3 - U2	11/16/2021	ecommend cleaning as necessary Active	y. I No
Current Condition:		00 02		he inspection on 11/16/21. Location	
Current Condition.			•	partially removed by disking prior	
			rsion into the basin prior to the i		
D 2	Diversion	J18 - S27		Removed	
Current Condition:	Removed - Valley Corp parti	ally removed the diver	rsion during sanitary installation	prior to the inspection on 12/02/2	1. Due to paving,
	reinstallation will not be reco	mmended as of 7/5/22	2.		
D 3	Diversion	J15 - N6		Removed	
Current Condition:	• • • • • • • • • • • • • • • • • • •		due to disking on site prior to th	e inspection 12/02/21. Due to pay	ring, reinstallation will not
	be recommended as of 7/5/2				T
EM 1	Erosion Control Matting	E11 - S25	9/1/2021	Pending	No
Current Condition:			g is completed in the area and v		T
EM 2	Erosion Control Matting	E6 - F12	12/8/2021	Active	No
Current Condition:	+		n control matting prior to the ins		
EM 3	Erosion Control Matting	M6 - Z6	9/1/2021	Pending	No
Current Condition:			g is completed in the area and v	T .	
EM 4	Erosion Control Matting	Z5 - Z24	12/8/2021	Active	No
Current Condition:			n control matting prior to the ins		l n.
EM 5	Erosion Control Matting	V1 - V7	12/8/2021	Active	No
Current Condition:			n control matting prior to the ins		
ET 1	Erosion Control Terrace	V8 - O21	9/21/2021	Active	No
Current Condition:	Good Condition - JC Excaval	lion installed the erosi	on control terrace prior to the in	spection on 9/21/21.	

Erosion Control Terrace

Fuel Tank

Fuel Tank

Fuel Tank

Fuel Tank

Material Storage

ET 2

Current Condition:

Current Condition:

FT 2

Current Condition:

FT 3

Current Condition:

FT 4

Current Condition: MS 01

Current Condition:

S2 - K14

On-site

On-site

On-site

On-site

On Site

Removed - Tab Construction removed the fuel tank prior to the inspection on 12/29/21.

Removed - Valley Corp removed the fuel tank prior to the inspection on 11/23/21.

9/21/2021

Removed - JC Excavation and Gene Graves removed the fuel tanker and cleaned up the spills prior to the inspection on 12/16/21.

3/2/2022

Good Condition - JC Excavation installed the majority of the erosion control terrace prior to the inspection on 9/21/21

Removed - Tab Construction removed a double-walled fuel tank on site prior to the inspection on 7/19/22.

Good Condition - Material storage is active in the south portion of the site as of the inspection on 3/02/22.

Active

Removed

Removed

Removed

Removed

Active

No

PB 01	Portable Bathroom	On Site	I	Removed				
Current Condition:			I lilet prior to the inspection on 11					
PB 02	Portable Bathroom	On Site		Removed				
Current Condition:			toilet prior to the inspection on	1/12/22.				
PB X	Portable Bathroom	On Site	12/29/2021	Active	No			
Current Condition:				pection on 12/29/21. Valley Corp				
	on site prior to the inspection on 3/16/22. Tab Construction removed a portable toilet from the site prior to the inspection on 3/29/22. Valley Corp stood up and resecured the portable toilet prior to the inspection on 4/22/22. Valley Corp removed a toilet prior to the inspection on							
			or to the inspection on 11/21/22.	valley Corp removed a tollet prior	r to the inspection on			
SB A	Sediment Basin	E9	7/14/2021	Active	No			
Current Condition:		•		ection on 10/06/21. E&A inspecto				
				tion on 11/03/21. JC Excavation wutfall pipe prior to the inspection of				
				es installed an inlet pipe into the l				
				ger be recommended as of 9/6/20				
00.0	advanced development.		0/00/0004					
SB B	Sediment Basin	03	9/28/2021	Active	No			
Current Condition:				on 10/25/21. JC Excavation repa scess of installing the riser during				
				A inspector painted the cleanout				
				berm near the riser prior to the ins				
				s was in the process of reinstalling nstalled the riser prior to the inspe				
	'			ristalled the riser prior to the mispe lendation of including the emerge				
				an began basin cleanout prior to th				
SF 1	Silt Fence	W27 - I20	4/27/2021	Active	Yes			
Current Condition:				7/21. JC Excavation and Gene Gi installed silt fence along the soutl				
				e process of repairing the silt fence				
		· ·		ired the silt fence prior to the 3/22	the state of the s			
				ection on 3/29/22. Graves Develo ion on 7/26/22. Graves Developm				
				prior to the inspection on 8/30/22.				
	backfilled and repaired the si	It fence on the north s	ide of the Reynolds Street cross	sing prior to the inspection on 10/0				
	observed in the silt fence alor	ng the south side of the	ne Reynolds Street crossing duri	ng the inspection on 10/26/22.				
	The silt fence should be clear	ned out south of the F	Revnolds Street crossing.					
	The one fortes official as creat	nou out oouth or the r	The silt fence should be cleaned out south of the Reynolds Street crossing.					
	Graves Development was informed to complete by 11/28/22. Not done as of the last inspection. Graves Development was reminded on							
		ormed to complete by	/ 11/28/22. Not done as of the la	st inspection. Graves Developme	nt was reminded on			
	Graves Development was infi 12/30/22	ormed to complete by	/ 11/28/22. Not done as of the la	st inspection. Graves Developme	nt was reminded on			
SF 2	12/30/22	·						
SF 2 Current Condition:	12/30/22 Silt Fence	l17 - K7	4/27/2021	st inspection. Graves Developme Active 7/21. JC Excavation and Gene Gr	Yes			
	Silt Fence Fair Condition - JC Excavatic along the south side of the N	I17 - K7 on installed the silt fer 170th Street crossing	4/27/2021 see prior to the inspection on 4/2	Active 7/21. JC Excavation and Gene Golds Street crossing prior to the inc	Yes raves installed silt fence spection on 10/25/21. Tab			
	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17	I17 - K7 on installed the silt fer 170th Street crossing 70th Street culvert and	4/27/2021 uce prior to the inspection on 4/2 g and the north side of the Reyno	Active 7/21. JC Excavation and Gene Golds Street crossing prior to the interest the culvert in the process prior to	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22.			
	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and rep	I17 - K7 on installed the silt fer 170th Street crossing 70th Street culvert and paired the silt fence pr	4/27/2021 ice prior to the inspection on 4/2 g and the north side of the Reyno f removed the silt fence around ior to the 3/22/22 inspection. Su	Active 7/21. JC Excavation and Gene Giolds Street crossing prior to the inthe culvert in the process prior to dbeck repaired the silt fence north	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. n of the SB A outfall and			
	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and rep reinstalled the silt fence wher	117 - K7 on installed the silt fer 170th Street crossing 70th Street culvert and paired the silt fence pr te removed near the c	4/27/2021 toe prior to the inspection on 4/2 gand the north side of the Reynord of removed the silt fence around for to the 3/22/22 inspection. Subsenter of the run prior to the inspection.	Active 7/21. JC Excavation and Gene Golds Street crossing prior to the interest the culvert in the process prior to	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and and the outfall was removed			
	Silt Fence Fair Condition - JC Excavationalong the south side of the N Construction graded the N 17 Sudbeck cleaned out and repressalled the silt fence wher during tree clearing observed reinstalled the silt fence along	I17 - K7 on installed the silt fer 170th Street crossing 70th Street culvert and aired the silt fence pr re removed near the of I during the inspectior g and over the north's	4/27/2021 see prior to the inspection on 4/2 g and the north side of the Reynord removed the silt fence around it in to the 3/22/22 inspection. Subsenter of the run prior to the inspector will ide of Reynolds Street Culvert at	Active 7/21. JC Excavation and Gene Grolds Street crossing prior to the interest the culvert in the process prior to debeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallation the N 170th Street Culvert prior	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. n of the SB A outfall and the outfall was removed ion. Graves Development or to the inspection on			
	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence wher during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground of	I17 - K7 on installed the silt fer 170th Street crossing 0th Street culvert and paired the silt fence pr e removed near the of during the inspection g and over the north s disturbance was stabi	4/27/2021 g and the north side of the Reynord removed the silt fence around it removed the run prior to the 3/22/22 inspection. Supenter of the run prior to the inspector will ide of Reynolds Street Culvert a lized by Dustin Wallis prior to the	Active 7/21. JC Excavation and Gene Giolds Street crossing prior to the inthe culvert in the process prior to dbeck repaired the silt fence northection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert price inspection on 9/21/22. A portion	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. n of the SB A outfall and the outfall was removed ion. Graves Development or to the inspection on			
	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence wher during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground of	I17 - K7 on installed the silt fer 170th Street crossing 0th Street culvert and paired the silt fence pr e removed near the of during the inspection g and over the north s disturbance was stabi	4/27/2021 see prior to the inspection on 4/2 g and the north side of the Reynord removed the silt fence around it in to the 3/22/22 inspection. Subsenter of the run prior to the inspector will ide of Reynolds Street Culvert at	Active 7/21. JC Excavation and Gene Giolds Street crossing prior to the inthe culvert in the process prior to dbeck repaired the silt fence northection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert price inspection on 9/21/22. A portion	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. n of the SB A outfall and the outfall was removed ion. Graves Development or to the inspection on			
	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence wher during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground of	117 - K7 on installed the silt fer 170th Street crossing 70th Street culvert and paired the silt fence pr re removed near the of during the inspectior g and over the north s disturbance was stabile of the Reynolds Stre	4/27/2021 toe prior to the inspection on 4/2 g and the north side of the Reynold removed the silt fence around for to the 3/22/22 inspection. Suggester of the run prior to the inspector will prior to the graph on 7/19/22. E&A inspector will prior to the graph on 7/19/22. E&A inspector will prior to the graph of Reynolds Street Culvert a lized by Dustin Wallis prior to the et crossing prior to the inspection.	Active 7/21. JC Excavation and Gene Giolds Street crossing prior to the inthe culvert in the process prior to dbeck repaired the silt fence northection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert price inspection on 9/21/22. A portion	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. n of the SB A outfall and d the outfall was removed ion. Graves Development or to the inspection on			
	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence wher during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side The silt fence should be reins	117 - K7 on installed the silt fer 170th Street crossing 10th Street culvert and paired the silt fence pr re removed near the of d during the inspection g and over the north s disturbance was stable of the Reynolds Stre	4/27/2021 ce prior to the inspection on 4/2 g and the north side of the Reynol d removed the silt fence around it ior to the 3/22/22 inspection. Su center of the run prior to the insp non 7/19/22. E&A inspector will ide of Reynolds Street Culvert a lized by Dustin Wallis prior to the et crossing prior to the inspection ynolds Street crossing.	Active 7/21. JC Excavation and Gene Giolds Street crossing prior to the interest the culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert price inspection on 9/21/22. A portion on 10/26/22.	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. h of the SB A outfall and d the outfall was removed ion. Graves Development or to the inspection on n of the silt fence was			
	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence wher during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side The silt fence should be reins	117 - K7 on installed the silt fer 170th Street crossing 10th Street culvert and paired the silt fence pr re removed near the of d during the inspection g and over the north s disturbance was stable of the Reynolds Stre	4/27/2021 ce prior to the inspection on 4/2 g and the north side of the Reynol d removed the silt fence around it ior to the 3/22/22 inspection. Su center of the run prior to the insp non 7/19/22. E&A inspector will ide of Reynolds Street Culvert a lized by Dustin Wallis prior to the et crossing prior to the inspection ynolds Street crossing.	Active 7/21. JC Excavation and Gene Giolds Street crossing prior to the inthe culvert in the process prior to dbeck repaired the silt fence northection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert price inspection on 9/21/22. A portion	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. h of the SB A outfall and d the outfall was removed ion. Graves Development or to the inspection on n of the silt fence was			
	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and rep reinstalled the silt fence wher during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground o removed along the north side The silt fence should be reins Graves Development was infe	117 - K7 on installed the silt fer 170th Street crossing 10th Street culvert and paired the silt fence pr re removed near the of d during the inspection g and over the north s disturbance was stable of the Reynolds Stre	4/27/2021 ce prior to the inspection on 4/2 g and the north side of the Reynol d removed the silt fence around it ior to the 3/22/22 inspection. Su center of the run prior to the insp non 7/19/22. E&A inspector will ide of Reynolds Street Culvert a lized by Dustin Wallis prior to the et crossing prior to the inspection ynolds Street crossing.	Active 7/21. JC Excavation and Gene Giolds Street crossing prior to the interest the culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert price inspection on 9/21/22. A portion on 10/26/22.	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. h of the SB A outfall and d the outfall was removed ion. Graves Development or to the inspection on n of the silt fence was			
Current Condition:	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence wher during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground a removed along the north side The silt fence should be reins Graves Development was infi 12/30/22 Silt Fence	117 - K7 on installed the silt fer 170th Street crossing 70th Street culvert and paired the silt fence pr re removed near the of during the inspectior g and over the north s disturbance was stable of the Reynolds Stree stalled north of the Re ormed to complete by	4/27/2021 toe prior to the inspection on 4/2 g and the north side of the Reynold removed the silt fence around it for to the 3/22/22 inspection. Supenter of the run prior to the inspector will idea of Reynolds Street Culvert a lized by Dustin Wallis prior to the te crossing prior to the inspector will idea of Reynolds Street Culvert a lized by Dustin Wallis prior to the te crossing prior to the inspection will include the prior to the inspection will be a considered the crossing prior to the inspection will be a considered the crossing prior to the inspection will be a considered the	Active 7/21. JC Excavation and Gene Gridds Street crossing prior to the interpretation of the culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating that he N 170th Street Culvert priore inspection on 9/21/22. A portion on 10/26/22. st inspection. Graves Developmental Active	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and and the outfall was removed ion. Graves Development or to the inspection on a of the silt fence was tent was reminded on			
Current Condition:	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repressalled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reins Graves Development was infection 12/30/22 Silt Fence Good Condition - Legacy Hore	117 - K7 on installed the silt fer 170th Street crossing 70th Street culvert and varied the silt fence pr re removed near the of during the inspection g and over the north s disturbance was stable of the Reynolds Stree stalled north of the Re ormed to complete by	4/27/2021 toe prior to the inspection on 4/2 g and the north side of the Reynord the removed the silt fence around it for to the 3/22/22 inspection. Suggester of the run prior to the inspector will prior to the inspector will prior to the run prior to the inspector will prior to the trossing prior to the inspector to the inspector of Reynolds Street Culvert at the trossing prior to the inspection ynolds Street crossing. 2/11/28/22. Not done as of the late 1/27/2021 4/27/2021 Ence prior to E&A's first inspection on the prior to E&A's first inspection of the prior to the prior to E&A's first inspection of the prior to t	Active 7/21. JC Excavation and Gene Grids Street crossing prior to the inthe culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert priore inspection on 9/21/22. A portion on 10/26/22. st inspection. Graves Developme Active on on 2/23/21. JC Excavation was	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and and the outfall was removed ion. Graves Development or to the inspection on a of the silt fence was ent was reminded on No s in the process of			
Current Condition:	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and reprenstalled the silt fence wher during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reins Graves Development was infected by the silt fence. Silt Fence Good Condition - Legacy Hor repairing/reinstalling the silt fence.	117 - K7 In installed the silt fer 170th Street crossing 70th Street culvert and paired the silt fence proper removed near the collection of the Reynolds Street culvert and over the north solisturbance was stable of the Reynolds Street commed to complete by M6 - R2 The sinstalled the silt fence during the inspection of the Reynolds Street commed to complete by M6 - R2 The sinstalled the silt fence during the inspection of the Reynolds Street commed to complete by M6 - R2	4/27/2021 toe prior to the inspection on 4/2 g and the north side of the Reynord of removed the silt fence around for to the 3/22/22 inspection. Support of the run prior to the inspector will ide of Reynolds Street Culvert a lized by Dustin Wallis prior to the et crossing prior to the inspection ynolds Street crossing. 1/11/28/22. Not done as of the late 4/27/2021 ence prior to E&A's first inspectication on 4/21/21. Silt fence was	Active 7/21. JC Excavation and Gene Ground	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and ind the outfall was removed ion. Graves Development or to the inspection on in of the silt fence was ent was reminded on No s in the process of scavation and Gene			
Current Condition:	Silt Fence Fair Condition - JC Excavation along the south side of the N Construction graded the N 17 Sudbeck cleaned out and representabled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinst Graves Development was infection 12/30/22. Silt Fence Good Condition - Legacy Hor repairing/reinstalling the silt for Graves installed silt fence alorgement along the silt for graves installed silt fence alorgement.	I17 - K7 In installed the silt fer 170th Street crossing 10th Street culvert and paired the silt fence pr re removed near the of during the inspection g and over the north s disturbance was stable of the Reynolds Stree stalled north of the Re ormed to complete by M6 - R2 mes installed the silt f ence during the inspe ong the north side of t	4/27/2021 g and the north side of the Reynold removed the silt fence around it removed the run prior to the inspection. Supenter of the run prior to the inspector will ide of Reynolds Street Culvert a lized by Dustin Wallis prior to the crossing prior to the inspection ynolds Street crossing. y 11/28/22. Not done as of the later of the lat	Active 7/21. JC Excavation and Gene Grids Street crossing prior to the inthe culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert priore inspection on 9/21/22. A portion on 10/26/22. st inspection. Graves Developme Active on on 2/23/21. JC Excavation was	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and and the outfall was removed ion. Graves Development or to the inspection on an of the silt fence was and the silt fence was In the process of cavation and Gene Excavation and Gene			
Current Condition:	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled the silt fence along 12/30/22 Silt Fence Good Condition - Legacy Hor repairing/reinstalling the silt fence along Graves installed silt fence along Graves reinstalled/extended Construction graded the N 17	I17 - K7 on installed the silt fer 170th Street crossing 70th Street culvert and paired the silt fence pr re removed near the of during the inspectior g and over the north s disturbance was stable of the Reynolds Stree stalled north of the Re ormed to complete by M6 - R2 mes installed the silt fence during the inspe ong the north side of t the silt fence south fix othe silt fence south fix	4/27/2021 toe prior to the inspection on 4/2 g and the north side of the Reynord removed the silt fence around it for to the 3/22/22 inspection. Superior of the run prior to the inspector will side of Reynolds Street Culvert a lized by Dustin Wallis prior to the torossing prior to the inspection of 1/12/22. Not done as of the law 1/1/28/22. Not done as of the law 1/1/28/22. Not done as of the law 1/1/28/21. Silt fence was he N 170th Street crossing prior the SB B outfall to the N 170th diremoved the silt fence around the	Active 7/21. JC Excavation and Gene Ground Street crossing prior to the instance culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert prior in in 10/26/22. A portion on 10/26/22. St inspection on 9/21/22. A portion on 10/26/22. Active On on 2/23/21. JC Excavation was formerly identified as SF 5. JC Excavation on 10/25/21. JC th Street crossing prior to the inspection on 10/25/21. The treet crossing prior to the inspection to the inspection on 10/25/21. JC th Street crossing prior to the inspection on 10/25/21. JC the culvert in the process prior to	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and ind the outfall was removed ion. Graves Development for to the inspection on in of the silt fence was sent was reminded on. No sin the process of coavation and Gene Excavation and Gene bection on 12/08/21. Tab the inspection on 3/02/22.			
Current Condition:	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repressalled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reins Graves Development was infectively a silt fence. Silt Fence Good Condition - Legacy Hor repairing/reinstalled silt fence along Graves installed silt fence along Graves reinstalled/extended to Construction graded the N 17 Sudbeck cleaned out and tree	I17 - K7 In installed the silt fer 170th Street curver and laired the silt fence proper removed near the color and laired the silt fence proper removed near the color and laired the silt fence proper removed near the color and laired the silt fence down the silt fence south from the silt fence south fro	4/27/2021 toe prior to the inspection on 4/2 g and the north side of the Reynord the removed the silt fence around to the 3/22/22 inspection. Suggester of the run prior to the inspector will side of Reynolds Street Culvert a lized by Dustin Wallis prior to the torossing prior to the inspector will sized by Dustin Wallis prior to the torossing prior to the inspection ynolds Street crossing. 4/27/2021 The case of the silt fence was the N 170th Street crossing prior on the SB B outfall to the N 170th of removed the silt fence around the prior to the 3/22/22 inspection.	Active 7/21. JC Excavation and Gene Grids Street crossing prior to the interpretation of the culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert priore inspection on 9/21/22. A portion on 10/26/22. St inspection. Graves Development of the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC to the inspection on 10/25/21. JC to the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Excavation w	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and and the outfall was removed ion. Graves Development or to the inspection on a of the silt fence was sent was reminded on the silt fence was reminded on the silt			
Current Condition:	Silt Fence Fair Condition - JC Excavation along the south side of the N Construction graded the N 17 Sudbeck cleaned out and representabled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled the silt fence along the silt fence should be reinstalled. Silt fence Graves Development was information of the silt fence along the silt fence alon	I17 - K7 In installed the silt fer 170th Street crossing 10th Street culvert and laired the silt fence pr re removed near the of d during the inspectior g and over the north s disturbance was stable of the Reynolds Street stalled north of the Re ormed to complete by M6 - R2 mes installed the silt fence south fir 10th Street culvert and nothed in the silt fence along the north side of	4/27/2021 gand the north side of the Reynold removed the silt fence around it removed the run prior to the inspection. Supenter of the run prior to the inspector will ide of Reynolds Street Culvert a lized by Dustin Wallis prior to the trossing prior to the inspection ynolds Street crossing. 4/127/2021 The control of the inspection of the set of the inspection of the inspection of the inspection of the site, and installed two chedules.	Active 7/21. JC Excavation and Gene Giolds Street crossing prior to the insthe culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert price inspection on 9/21/22. A portion on 10/26/22. St inspection. Graves Developme Active on on 2/23/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC th Street crossing prior to the inspection to the inspection on the inspe	Yes Taves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and not the outfall was removed ion. Graves Development for to the inspection on an of the silt fence was The silt fe			
Current Condition:	Silt Fence Fair Condition - JC Excavation along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled the silt fence along the silt fence should be reinstalled the silt fence should be reinstalled. Silt fence along the silt fence	I17 - K7 In installed the silt fer I70th Street crossing Oth Street culvert and Paired the silt fence pre IT eremoved near the of It during the inspection IT gand over the north side of the Reynolds Street It stalled north of the Reported to complete by M6 - R2 IT mes installed the silt fence during the inspection IT the silt fence south fro Oth Street culvert and IT the silt fence along the north side of the silt fence along the north side of the reinstalled the silt fence along the north side of the reinstalled the silt fence along the north side of the reinstalled the silt fence along the north side of the silt fence along the north side of the reinstalled the silt fence along the north side of the silt fence along the side of the silt fence along the side of the silt fence along the side of	4/27/2021 g and the north side of the Reynord removed the silt fence around it removed the run prior to the inspection. Supenter of the run prior to the inspector will ide of Reynolds Street Culvert a lized by Dustin Wallis prior to the crossing prior to the inspection ynolds Street crossing. 1/11/28/22. Not done as of the later of the sile of Reynolds Street Culvert a lized by Dustin Wallis prior to the erce prior to E&A's first inspection on 4/21/2021 fence prior to E&A's first inspectication on 4/21/21. Silt fence was the N 170th Street crossing prior on the SB B outfall to the N 170 of the moved the silt fence around the si	Active 7/21. JC Excavation and Gene Grids Street crossing prior to the interpretation of the culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert priore inspection on 9/21/22. A portion on 10/26/22. St inspection. Graves Development of the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC to the inspection on 10/25/21. JC to the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Excavation w	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and and the outfall was removed ion. Graves Development for to the inspection on an of the silt fence was sent was reminded on the process of scavation and Gene is Excavation and Gene is Excavation and Gene is excavation on 12/08/21. Tab the inspection on 3/02/22. Where removed northwest e prior to the inspection on rior to the rior to th			
Current Condition:	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled silt fence along 12/30/22 Silt Fence Good Condition - Legacy Hor repairing/reinstalling the silt for Graves installed silt fence along 12/30/22 Silt Fence Good Condition - Legacy Hor repairing/reinstalling the silt for Graves reinstalled silt fence along 12/30/22. Graves Developmer 7/26/22. Graves Developmer 7/26/22. Graves Developmer repairing the silt fence south	I17 - K7 In installed the silt fer I70th Street crossing I0th Street culvert and paired the silt fence pr re removed near the of Iduring the inspectior g and over the north s Idisturbance was stable of the Reynolds Street Installed north of the Re ormed to complete by M6 - R2 mes installed the silt fence during the inspe ong the north side of the Installed in the silt fence along the north side in It reinstalled silt fence It installed silt fence II	4/27/2021 ge prior to the inspection on 4/2 grand the north side of the Reynord removed the silt fence around it for to the 3/22/22 inspection. Supenter of the run prior to the inspector will side of Reynolds Street Culvert a lized by Dustin Wallis prior to the torossing prior to the inspection of the site, and installed two che ence along and over the north site bove and below the outfall prior to the inspection on 9/28/22. Wall	Active 7/21. JC Excavation and Gene Gridds Street crossing prior to the instet culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert priore inspection on 9/21/22. A portion on 10/26/22. St inspection. Graves Development of the silt of the inspection on 10/25/21. JC to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the culvert in the process prior to Sudbeck reinstalled the silt fence cks along the north side of the sit to the inspection on 8/30/22. Gravoord Excavating cleaned out the	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and and the outfall was removed ion. Graves Development or to the inspection on an of the silt fence was sent was reminded on. No s in the process of excavation and Gene is Excavation and Gene is Excavation and Gene is excavation on 12/08/21. Tab the inspection on 3/02/22. where removed northwest e prior to the inspection on orior to the inspection on oves Development was			
Current Condition:	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled silt fence along 12/30/22 Silt Fence Good Condition - Legacy Hor repairing/reinstalling the silt for Graves installed silt fence along 12/30/22 Silt Fence Good Condition - Legacy Hor repairing/reinstalling the silt for Graves reinstalled silt fence along 12/30/22. Graves Developmer 7/26/22. Graves Developmer 7/26/22. Graves Developmer repairing the silt fence south	I17 - K7 In installed the silt fer I70th Street crossing I0th Street culvert and paired the silt fence pr re removed near the of Iduring the inspectior g and over the north s Idisturbance was stable of the Reynolds Street Installed north of the Re ormed to complete by M6 - R2 mes installed the silt fence during the inspe ong the north side of the Installed in the silt fence along the north side in It reinstalled silt fence It installed silt fence II	4/27/2021 ge prior to the inspection on 4/2 grand the north side of the Reynord removed the silt fence around it for to the 3/22/22 inspection. Supenter of the run prior to the inspector will side of Reynolds Street Culvert a lized by Dustin Wallis prior to the torossing prior to the inspection of the site, and installed two che ence along and over the north site bove and below the outfall prior to the inspection on 9/28/22. Wall	Active 7/21. JC Excavation and Gene Grolds Street crossing prior to the instendence of the culvert in the process prior to debck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert priore inspection on 9/21/22. A portion on 10/26/22. Set inspection. Graves Development on 10/26/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC th Street crossing prior to the inspection on 10/25/21. Substitute the culvert in the process prior to Sudbeck reinstalled the silt fence cks along the north side of the sit de of the N 170th Street Culvert process of the inspection on 8/30/22. Graves and the silt fence of the N 170th Street Culvert process of the silt fence of the N 170th Street Culvert process of the inspection on 8/30/22. Graves are silted of the silt fence of the N 170th Street Culvert process of the silt fence of the N 170th Street Culvert process of the silt fence of the N 170th Street Culvert process of the silt fence of the N 170th Street Culvert process of the silt fence of the N 170th Street Culvert process of the silt fence of the N 170th Street Culvert process of the silt fence of the N 170th Street Culvert process of the silt fence of the N 170th Street Culvert process of the silt fence of the N 170th Street Culvert process of the silt fence of the N 170th Street Culvert process of the N 170th Street Culvert process of the silt fence of the N 170th Street Culvert process	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and and the outfall was removed ion. Graves Development or to the inspection on an of the silt fence was sent was reminded on. No s in the process of excavation and Gene is Excavation and Gene is Excavation and Gene is excavation on 12/08/21. Tab the inspection on 3/02/22. where removed northwest e prior to the inspection on orior to the inspection on oves Development was			
SF 3 Current Condition:	Silt Fence Fair Condition - JC Excavation along the south side of the N Construction graded the N 17 Sudbeck cleaned out and representabled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled the silt fence along the silt fence should be reinstalled. Silt Fence Good Condition - Legacy Hor repairing/reinstalled/extended to Construction graded the N 17 Sudbeck cleaned out and tree of SB B, reinstalled silt fence 3/29/22. Graves Developmer 7/26/22. Graves Developmer 7/26/22. Graves Developmer repairing the silt fence south 170th crossing and removed	I17 - K7 In installed the silt fer 170th Street crossing 10th Street culvert and paired the silt fence pr re removed near the of during the inspectior g and over the north s disturbance was stable of the Reynolds Street stalled north of the Re ormed to complete by M6 - R2 mes installed the silt fence south for 10th Street culvert and noched in the silt fence along the north side of the control of the silt fence along the north side of the crossing during the portion where the	4/27/2021 ge prior to the inspection on 4/2 grand the north side of the Reynord removed the silt fence around it for to the 3/22/22 inspection. Supenter of the run prior to the inspector will side of Reynolds Street Culvert a lized by Dustin Wallis prior to the torossing prior to the inspection of the site, and installed two che ence along and over the north site bove and below the outfall prior to the inspection on 9/28/22. Wall	Active 7/21. JC Excavation and Gene Giolds Street crossing prior to the instended of the culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert price inspection on 9/21/22. A portion on 10/26/22. St inspection. Graves Development of the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC th Street crossing prior to the inspection the culvert in the process prior to Sudbeck reinstalled the silt fence cks along the north side of the Sit de of the N 170th Street Culvert pto the inspection on 8/30/22. Gravord Excavating cleaned out the ior to the inspection on 10/05/22.	Yes raves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and and the outfall was removed ion. Graves Development or to the inspection on an of the silt fence was sent was reminded on. No s in the process of excavation and Gene is Excavation and Gene is Excavation and Gene is excavation on 12/08/21. Tab the inspection on 3/02/22. where removed northwest e prior to the inspection on orior to the inspection on oves Development was			
Current Condition:	Silt Fence Fair Condition - JC Excavation along the south side of the N Construction graded the N 17 Sudbeck cleaned out and representabled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled the silt fence along the silt fence should be reinstalled. Silt fence Graves Development was information - Legacy Hor repairing/reinstalling the silt for Graves installed silt fence along Graves reinstalled/extended to Construction graded the N 17 Sudbeck cleaned out and tree of SB B, reinstalled silt fence 3/29/22. Graves Developmen 7/26/22. Graves Developmen repairing the silt fence south 170th crossing and removed.	I17 - K7 In installed the silt fer 170th Street crossing 10th Street culvert and paired the silt fence pr re removed near the of during the inspection g and over the north sidisturbance was stable of the Reynolds Street stalled north of the Re ormed to complete by M6 - R2 mes installed the silt fence south for 10th Street culvert and 10th street culvert 10th street culve	4/27/2021 g and the north side of the Reynold removed the silt fence around it for to the 3/22/22 inspection. Superior of the run prior to the inspector will ide of Reynolds Street Culvert a lized by Dustin Wallis prior to the trossing prior to the inspection ynolds Street crossing. 4/127/2021 The service of the run prior to the inspection of the sile of Reynolds Street Culvert a lized by Dustin Wallis prior to the trossing prior to the inspection of the sile of the run of the sile of the s	Active 7/21. JC Excavation and Gene Gridds Street crossing prior to the instet culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert priore inspection on 9/21/22. A portion on 10/26/22. St inspection. Graves Development of the silt of the inspection on 10/25/21. JC to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the culvert in the process prior to Sudbeck reinstalled the silt fence cks along the north side of the sit to the inspection on 8/30/22. Gravoord Excavating cleaned out the	Yes Taves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and ad the outfall was removed ion. Graves Development for to the inspection on an of the silt fence was The silt fence was The silt fence was of the silt fence was on the process of the silt fence was on the process of the silt fence was on the silt fence was on the process of the silt fence was on the process of the silt fence was on the process of the proc			
SF 3 Current Condition:	Silt Fence Fair Condition - JC Excavation along the south side of the N Construction graded the N 17 Sudbeck cleaned out and representabled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled the silt fence along the silt fence should be reinstalled. Silt fence Graves Development was information - Legacy Hor repairing/reinstalling the silt for Graves installed silt fence along Graves reinstalled/extended to Construction graded the N 17 Sudbeck cleaned out and tree of SB B, reinstalled silt fence 3/29/22. Graves Developmen 7/26/22. Graves Developmen repairing the silt fence south 170th crossing and removed.	I17 - K7 In installed the silt fer 170th Street crossing 70th Street culvert and paired the silt fence pre removed near the of during the inspection g and over the north sidisturbance was stable of the Reynolds Street stalled north of the Reported to complete by M6 - R2 M8 - R2 M9 - R2 M9 - R2 M9 - R2 M9 - R1 M9 - R2 M9 - R1 M9 - R2 M9 - R2 M9 - R1 M9 - R2 M9 - R2 M9 - R2 M9 - R2	4/27/2021 gand the north side of the Reynord removed the silt fence around it removed the run prior to the inspection on 4/2/22 inspection. Superior of the run prior to the inspector will ide of Reynolds Street Culvert a lized by Dustin Wallis prior to the crossing prior to the inspection ynolds Street crossing. 1/11/28/22. Not done as of the later of the crossing prior to E&A's first inspectication on 4/21/21. Silt fence was the N 170th Street crossing prior on the SB B outfall to the N 170th removed the silt fence around the prior to the 3/22/22 inspection. The site, and installed two che can be considered and over the north side to the considered and over the north side over and below the outfall prior the inspection on 9/28/22. Walth crossing was seeded/matted prior to filt in the silt fence fabric prior to all for the silt fence fabric prior to	Active 7/21. JC Excavation and Gene Grodds Street crossing prior to the instee culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert price inspection on 9/21/22. A portion on 10/26/22. St inspection. Graves Developmend and the N 170th Street Culvert price in on 10/25/21. JC Excavation was formerly identified as SF 5. JC Esto the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 8/30/22. Gravel of the N 170th Street Culvert properties of the N 170th Street Culvert properties along the north side of the side of the N 170th Street Culvert properties on 8/30/22. Gravel or the inspection on 8/30/22. Gravel or the inspection on 10/05/22. Removed	Yes Taves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and ad the outfall was removed ion. Graves Development for to the inspection on an of the silt fence was In the process of the process of the inspection and Gene is excavation and Gene is excavation and Gene is excavation on 12/08/21. Tab the inspection on 3/02/22. Where removed northwest is prior to the inspection on rior to the inspection on ves Development was silt fence south of the N			
SF 3 Current Condition:	Silt Fence Fair Condition - JC Excavation along the south side of the N Construction graded the N 17 Sudbeck cleaned out and representabled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled the silt fence along 12/30/22. Silt Fence Good Condition - Legacy Hor repairing/reinstalling the silt fence along Graves reinstalled silt fence along Graves reinstalled silt fence along 12/30/22. Graves Developmen 5/26/22. Graves Developmen 7/26/22. Graves Developmen 7/26/22. Graves Developmen 7/26/22. Graves Developmen 7/26/22. Graves Developmen Removed Silt Fence Removed - JC Excavation reinemainder of the silt fence fall Silt Fence	I17 - K7 In installed the silt fer I70th Street crossing Oth Street culvert and paired the silt fence pr re removed near the of I during the inspection g and over the north sid of the Reynolds Stree stalled north of the Re ormed to complete by M6 - R2 mes installed the silt fence author of the silt fence south for Oth Street culvert and inched in the silt fence along the north side of the crossing during the portion where the M6 - R2 moved the northern h oric prior to the inspect M6 - N3	4/27/2021 gand the north side of the Reynord removed the silt fence around it for to the 3/22/22 inspection. Superter of the run prior to the inspector will ided of Reynolds Street Culvert a lized by Dustin Wallis prior to the trossing prior to the inspector ynolds Street crossing. 4/12/2021 ence prior to E&A's first inspection on 4/21/2021 ence prior to E&A's first inspection on 4/21/21. Silt fence was he N 170th Street crossing prior to the SB B outfall to the N 170 dremoved the silt fence around its prior to the 3/22/22 inspection. Of the site, and installed two che ence along and over the north singular was presented by the outfall prior the inspection on 9/28/22. Walversein crossing was seeded/matted prior to stion on 11/11/21.	Active 7/21. JC Excavation and Gene Grodds Street crossing prior to the instee culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert price inspection on 9/21/22. A portion on 10/26/22. St inspection. Graves Developmend and the N 170th Street Culvert price in on 10/25/21. JC Excavation was formerly identified as SF 5. JC Esto the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 8/30/22. Gravel of the N 170th Street Culvert properties of the N 170th Street Culvert properties along the north side of the side of the N 170th Street Culvert properties on 8/30/22. Gravel or the inspection on 8/30/22. Gravel or the inspection on 10/05/22. Removed	Yes Taves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and ad the outfall was removed ion. Graves Development for to the inspection on an of the silt fence was In the process of the process of the inspection and Gene is excavation and Gene is excavation and Gene is excavation on 12/08/21. Tab the inspection on 3/02/22. Where removed northwest is prior to the inspection on rior to the inspection on ves Development was silt fence south of the N			
SF 3 Current Condition: SF 4 Current Condition: SF 5 Current Condition:	Silt Fence Fair Condition - JC Excavation along the south side of the N Construction graded the N 17 Sudbeck cleaned out and representabled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled the silt fence along 12/30/22. Silt Fence Good Condition - Legacy Hor repairing/reinstalling the silt fence along Graves reinstalled silt fence along Graves reinstalled silt fence along 12/30/22. Graves Developmen 7/26/22. Graves Developmen 7/26/22. Graves Developmen 7/26/22. Graves Developmen 7/26/22. Graves Developmen repairing the silt fence south 170th crossing and removed Silt Fence Removed - JC Excavation reinemainder of the silt fence fall Silt Fence Removed - Silt fence identifies	I17 - K7 In installed the silt fer I70th Street crossing Oth Street culvert and paired the silt fence pr re removed near the of Iduring the inspection g and over the north side of the Reynolds Stree stalled north of the Re ormed to complete by M6 - R2 mes installed the silt fence of the silt fence south for Oth Street culvert and nothed in the silt fence along the north side of the crossing during the portion where the M6 - R2 moved the northern h oric prior to the inspect M6 - N3 ed as SF 3 as of 4/27/ ed of the crossing during the portion where the	4/27/2021 gand the north side of the Reynord removed the silt fence around it for to the 3/22/22 inspection. Superter of the run prior to the inspector will ided of Reynolds Street Culvert a lized by Dustin Wallis prior to the trossing prior to the inspector ynolds Street crossing. 4/12/2021 ence prior to E&A's first inspection on 4/21/2021 ence prior to E&A's first inspection on 4/21/21. Silt fence was he N 170th Street crossing prior to the SB B outfall to the N 170 dremoved the silt fence around its prior to the 3/22/22 inspection. Of the site, and installed two che ence along and over the north singular was presented by the outfall prior the inspection on 9/28/22. Walversein crossing was seeded/matted prior to stion on 11/11/21.	Active 7/21. JC Excavation and Gene Grolds Street crossing prior to the instendence of the culvert in the process prior to deck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert price inspection on 9/21/22. A portion on 10/26/22. St inspection. Graves Development on 10/26/22. Active on on 2/23/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the sit fence culvert in the process prior to Sudbeck reinstalled the silt fence such as along the north side of the N 170th Street Culvert p to the inspection on 8/30/22. Grayord Excavating cleaned out the ior to the inspection on 10/05/22. Removed Removed	Yes Taves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and ad the outfall was removed for to the inspection on an of the silt fence was The silt fence was The silt fence was of the silt fence was of the silt fence was on the process of the silt fence was of the silt fence wa			
SF 3 Current Condition: SF 4 Current Condition: SF 5 Current Condition: SF 6	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled the silt fence along 1/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled silt fence along 1/26/22. Silt Fence Good Condition - Legacy Hor repairing/reinstalled silt fence along 1/26/22. Graves Installed silt fence along 1/26/22. Graves Development 1	I17 - K7 In installed the silt fer 170th Street culvert and paired the silt fence pre removed near the cold during the inspection g and over the north side of the Reynolds Street culvert and the silt fence prometer the silt sturbance was stable of the Reynolds Street culvert and the silt fence south from the silt fence along the north side of the silt fence south from the silt fence south from the silt fence along the north side of the crossing during the portion where the silt fence alof the crossing during the portion where the silt fence alof the silt fence alof the crossing during the portion where the silt fence alof the silt fence alof the crossing during the portion where the silt fence alof	4/27/2021 general to the inspection on 4/2 gand the north side of the Reynord removed the silt fence around it for to the 3/22/22 inspection. Subsenter of the run prior to the inspector will idea of Reynolds Street Culvert a lized by Dustin Wallis prior to the trossing prior to the inspection of the inspection on 9/28/22. Walter of the inspection on 9/28/22. Walter of the inspection on 9/28/22. Walter of the site fence fabric prior to totion on 11/11/21.	Active 7/21. JC Excavation and Gene Grounds Street crossing prior to the instendence of the culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert prior in in 10/26/22. A portion on 10/26/22. A portion on 10/26/22. Set inspection on 9/21/22. A portion on 10/26/22. Set inspection. Graves Development on on 2/23/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the street crossing prior to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 8/30/22. Grayord Excavating cleaned out the ior to the inspection on 10/05/22. Removed Removed Removed	Yes Taves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and ad the outfall was removed for to the inspection on an of the silt fence was The silt fence was The silt fence was of the silt fence was of the silt fence was on the process of the silt fence was of the silt fence wa			
SF 3 Current Condition: SF 4 Current Condition: SF 5 Current Condition: SF 6 Current Condition:	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled the silt fence along 1/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled silt fence along 1/26/22. Silt Fence Good Condition - Legacy Hor repairing/reinstalled silt fence along 1/26/22. Graves Installed silt fence along 1/26/22. Graves Development 1	I17 - K7 In installed the silt fer 170th Street culvert and paired the silt fence pre removed near the colduring the inspectior g and over the north side of the Reynolds Street culvert and the silt fence and the silt fence south for 10th Street culvert and the silt fence south for 10th Street culvert and ched in the silt fence along the north side of the crossing during the crossing during the portion where the 10th Street culvert and the silt fence along the north side of the crossing during the portion where the 10th Street culvert and 10th Street c	4/27/2021 gand the north side of the Reynord removed the silt fence around it for to the 3/22/22 inspection. Superter of the run prior to the inspector will ided of Reynolds Street Culvert a lized by Dustin Wallis prior to the trossing prior to the inspector ynolds Street crossing. 4/12/2021 ence prior to E&A's first inspection on 4/21/2021 ence prior to E&A's first inspection on 4/21/21. Silt fence was he N 170th Street crossing prior to the SB B outfall to the N 170 dremoved the silt fence around its prior to the 3/22/22 inspection. Of the site, and installed two che ence along and over the north singular was presented by the outfall prior the inspection on 9/28/22. Walversein crossing was seeded/matted prior to stion on 11/11/21.	Active 7/21. JC Excavation and Gene Gridds Street crossing prior to the instended to the culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert prior in in 10/26/22. A portion on 10/26/22. A portion on 10/26/22. A portion on 10/26/22. A portion on 10/26/21. JC Excavation was formerly identified as SF 5. JC Exto the inspection on 10/25/21. JC th Street crossing prior to the inspection on 10/25/21. JC th Street crossing prior to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the culvert in the process prior to Sudbeck reinstalled the silt fence cks along the north side of the sit de of the N 170th Street Culvert p to the inspection on 8/30/22. Grayord Excavating cleaned out the ior to the inspection on 10/05/21. JC Example 10/05	Yes Taves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and ad the outfall was removed for to the inspection on an of the silt fence was The silt fence was The silt fence was of the silt fence was of the silt fence was on the process of the silt fence was of the silt fence wa			
SF 3 Current Condition: SF 4 Current Condition: SF 5 Current Condition: SF 6	Silt Fence Fair Condition - JC Excavatic along the south side of the N Construction graded the N 17 Sudbeck cleaned out and repreinstalled the silt fence where during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled the silt fence along 1/26/22. The area of ground or removed along the north side. The silt fence should be reinstalled for silt fence along 1/26/22. Silt Fence Good Condition - Legacy Hor repairing/reinstalling the silt fence along 1/26/22. Graves installed silt fence along 1/26/22. Graves Development of SB B, reinstalled silt fence of SB B, reinstalled silt fence 3/29/22. Graves Development repairing the silt fence south 170th crossing and removed Silt Fence Removed - JC Excavation reinermainder of the silt fence falt Silt Fence Removed - Silt fence identifies Silt Fence Removed - JC Excavation reinermainder of JC Excavation rei	I17 - K7 In installed the silt fer 170th Street culvert and paired the silt fence pre removed near the colduring the inspectior g and over the north side of the Reynolds Street culvert and the silt fence stalled north of the Reynolds Street culvert and the silt fence south from the silt fence south from the silt fence along the north side of the silt fence along the north side of the silt fence along the north side of the crossing during the portion where the silt fence south from the silt fence along the north side of the crossing during the portion where the silt fence and the silt fence south from the silt fence and the silt fence of the crossing during the portion where the silt fence to the silt fence of the si	4/27/2021 general to the inspection on 4/2 gand the north side of the Reynord removed the silt fence around it for to the 3/22/22 inspection. Subsenter of the run prior to the inspector will idea of Reynolds Street Culvert a lized by Dustin Wallis prior to the trossing prior to the inspection of the inspection on 9/28/22. Walter of the inspection on 9/28/22. Walter of the inspection on 9/28/22. Walter of the site fence fabric prior to totion on 11/11/21.	Active 7/21. JC Excavation and Gene Gridds Street crossing prior to the instendence of the culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence around monitor to recommend reinstallating the N 170th Street Culvert priore inspection on 9/21/22. A portion on 10/26/22. Strinspection. Graves Development on 10/25/21. JC Excavation was formerly identified as SF 5. JC Excavation was formerly identified as SF 5. JC Excavation on 10/25/21. JC the Street crossing prior to the inspection on 10/25/21. JC the street crossing prior to the inspection on 10/25/21. JC the culvert in the process prior to Sudbeck reinstalled the silt fence cks along the north side of the sit do of the N 170th Street Culvert produced to the inspection on 10/05/22. Removed Removed Removed Removed On the inspection on 10/06/21. JC Excavation on 10/06/21. Removed	Yes Taves installed silt fence spection on 10/25/21. Tab the inspection on 3/02/22. In of the SB A outfall and ad the outfall was removed ion. Graves Development for to the inspection on an of the silt fence was In the process of the inspection and Gene is excavation and Gene is excavation and Gene is excavation on 12/08/21. Tab the inspection on 3/02/22. Where removed northwest is prior to the inspection on ves Development was silt fence south of the N			

SF 8	Silt Fence	R2		Removed			
Current Condition:	Removed - JC Excavation removed the silt fence prior to the inspection on 10/06/21.						
SF 9	Silt Fence	W15	6/28/2022	Active	No		
Current Condition:	Good Condition - Graves Development installed a silt fence check prior to the inspection on 6/28/22.						
SF 10	Silt Fence	Along Streets	1/4/2023	Pending	Yes		
Current Condition:			curblines throughout the site as				
STR	Streets	On Site	4/2/2021	Active	Yes		
	Fair Condition - State Street was cleaned prior to the inspection on 6/01/21. Minor trackout was observed on N 170th Street during the inspection on 1/05/22. Graves Development cleaned Potter Street south of the site prior to the inspection on 6/28/22. Graves Development cleaned 171th Street prior to the inspection on 8/23/22. The street was cleaned prior to the inspection on 9/12/22. Graves Development partially cleaned the streets prior to the inspection on 2/01/23. Internal streets should be cleaned. Graves Development was informed to complete by 11/22/22. Not done as of the last inspection. Graves Development was reminded on 12/30/22						
SWPPP Sign	SWPPP Signs	Adjacent to CE 3	4/21/2021	Active	No		
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign during the inspection on 4/21/21. E&A inspector moved the SWPPP sign to CE 3 during the inspection on 12/02/21. The SWPPP sign was damaged prior to the inspection on 9/28/22. E&A inspector reinstalled the SWPPP sign during the inspection on 11/15/22.						
WO 01	Concrete Washout	On Site		Removed			
Current Condition:	Removed - Tab Construction removed all concrete waste from the site prior to the inspection on 3/02/22.						
WO 02	Concrete Washout	On Site		Removed			
Current Condition:	Removed - Tab Construction	removed the concrete	e washout prior to the inspection	n on 8/16/22.			
WO 03	Concrete Washout	Southeast of SB B		Removed			
Current Condition:	Removed- Tab Construction	removed the concrete	washout prior to the inspection	on 8/30/22.	!		
WO 04	Concrete Washout	West of SB B		Removed			
Current Condition:	Removed - Tab Construction	removed the concrete	e washout prior to the inspection	n on 8/9/22.			
WS 01	Waste Storage Area	On Site		Removed			
Current Condition:	Removed - The waste storag	e container was remo	ved from the site prior to the ins	spection on 7/26/22.			
	_						
Certification Statement:	system designed to assure the person or persons who mana the best of my knowledge and	nat qualified personne age the system or thos d belief, true, accurate	I properly gathered and evaluate se persons directly responsible f	ed under my direction or supervisi ed the information submitted. Bas- or gathering the information, the in t there are significant penalties fo ss.	ed on my inquiry of the nformation submitted is, to		
Inspector Signature:	Go ling			Reviewed By:	Set Sel		