E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

| Environmental Services De | F | F&Δ | - P2020.091.000 | | | | | |
|---------------------------|---|--|--|----------|-------|--|--|--|
| nspector: Joe Manning | | Lan | - F 2020.031.000 | | Stage | | | |
| inspector. Joe Maining | | | Otage | | | | | |
| | | - | estic Pointe East -5644-GP1 / CSW-2 | 00005050 | 1 | | | |
| Project Name: | Oi | | | | | | | |
| For Week Ending: | | 68007 | | | | | | |
| Project Location: | 168 | 168th Street and State Street - Omaha, NE (Douglas County) | | | | | | |
| | | | | | - | | | |
| Grading: | 99% | | | | | | | |
| Sanitary Sewer: | 100% | | | | | | | |
| Storm Sewer: | 95% | | | | | | | |
| Paving: | 98% | | | | | | | |
| Seeding: | 35% | | | | | | | |
| Utilities: | 60% | | | | | | | |
| Overall Development: | 55% | | | | | | | |
| | | | | | | | | |
| RAIN FALL AMOUNTS | Amount in tenths | Date inspected | Weather Conditions | Time | | | | |
| | | | | | Wee | | | |
| Sunday: | 0.00" | | | | | | | |
| Monday: | 0.00" | | | | | | | |
| Tuesday: | 0.00" | | | | | | | |
| Wednesday: | 0.00" | 5/3/2023 | Sunny 72 | 3:40 PM | | | | |
| Thursday: | 0.00" | | | | | | | |
| Friday: | 0.05" | | | | | | | |
| Saturday: | 0.05" | | | | | | | |
| | | | | | | | | |
| Complaints: | None | | | | | | | |
| Complaints. | | | | | | | | |
| Construction Sequencing: | | | | | | | | |
| | sins) of the site have had a temporary of | | | | | | | |

Ground disturbance associated with tree clearing at the 171st Street and Reynolds Street Crossings (4/2/2021). Ground disturbance associated with tree clearing along State Street (4/13/2021). Mass grading began in DEV A, DEV NT3, and the south portion of DEV NT2 (7/07/2021). Mass grading throughout the entire site. Mass grading for Reynolds Street and N 170th Street crossings (10/06/2021). Disking in the north half of the site (12/02/2021). Surcharge removal in the north portion of the site. Storm sewer installation (12/08/2021). Disking along the southwest portion of the site. Grading for N 170th Street crossing (12/16/2021). Grading at Reynolds Street crossing (12/29/2021). Construction of box culvert at N 170th Street crossing (12/29/2021). Excavation for Reynolds Street culvert. Backfilling for N 170th Street box culvert (2/16/2022). Grading for the N 170th Street box culvert (3/02/2022). Grading near Reynolds Street and 168th Street (7/19/2022). A grade stabilization structure was installed in the creek west of SB A (8/2/2022).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Ground disturbance associated with tree clearing at the 171st Street and Reynolds Street Crossings (4/2/2021). Ground disturbance associated with tree clearing along State Street (4/13/2021). Mass grading began in DEV A, DEV NT3, and the south portion of DEV NT2 (7/07/2021). Mass grading throughout the entire site. Mass grading for Reynolds Street and N 170th Street crossings (10/06/2021). Disking in the north half of the site (12/02/2021). Surcharge removal in the north portion of the site. Storm sewer installation (12/08/2021). Disking along the southwest portion of the site. Grading for N 170th Street crossing (12/16/2021). Grading at Reynolds Street crossing (12/29/2021). Construction of box culvert at N 170th Street crossing (12/29/2021). Excavation for Reynolds Street culvert. Backfilling for N 170th Street box culvert (2/16/2022). Grading for the N 170th Street box culvert (3/02/2022). Grading near Reynolds Street and 168th Street (7/19/2022). A grade stabilization structure was installed in the creek west of SB A (8/2/2022).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (4/2/2021). Seeding and matting along the north side of the site, the western slopes along SB A, and the northeastern slopes (12/08/2021). Seeding along the N 170th Street crossing (9/28/2022). Matting along the N 170th Street crossing (10/05/2022).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

/es

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action? Are construction entrances and adjacent streets being maintained adequately? Create Corrective Action? No - See BMP Section Is dust associated with the construction activity adequately controlled on the site? Create Corrective Action? N/A Comments: Site was active for utility installation during the current inspection. Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance is required in the BMP section. 2.) CIR #18899 was received, reviewed, and sent to Graves Development on 4/13/23. The City inspection was in response to a complaint regarding sediment in the streets and entering stormwater drains, as well as no visible erosion control measures. The City is requesting voluntary compliance for outstanding maintenance. The City's findings partially correspond with the E&A report. CIR #18899 stated that inlet protection was required throughout the site. All storm inlets currently drain to the sediment basins on site, so curb inlet protection is not required at this time. However, to prevent excess sediment from entering the storm inlets, the streets throughout the development should be cleaned daily and as needed, and SF 10 should be installed (See BMP Section). -Inactive portions of the site should be stabilized. Graves Development was informed to complete by 4/18/23. Not done as of the last inspection. -Concrete waste should be removed from the site and concrete washout should be installed as needed. Graves Development was informed to complete by 4/18/23. Not done as of the last inspection. Graves Development was reminded on 4/28/23. -CIR #18899 stated that SF 1, 2, and 3 were in need of maintenance. Walvoord Excavating backfilled and repaired SF 1 prior to the inspection on 10/05/22. Sudbeck cleaned out and repaired SF 2 prior to the 3/22/22 inspection. Walvoord Excavating cleaned out SF 3 prior to the inspection on 10/05/22 CIR #18899 stated that SB 2 needed to be installed. Graves Development installed the basin fully prior to the inspection on 12/08/21. CIR #18899 stated that D1 needed to be repaired. Walvoord Excavating redefined the diversion into the basin prior to the inspection on 10/18/22. Projected Install Date Unique Name Type Location Status Maintenance Construction Entrance V11 Removed **Current Condition** Removed - JC Excavation graded out the site access at this location as of the inspection on 10/13/21. Construction Entrance CF 2 S2 2/23/2021 Pendina Nο **Current Condition:** Pending - 77% effective - Legacy Homes installed a construction entrance prior to 2/23/21. Gene Graves and Legacy Homes blocked the construction entrance prior to the inspection on 6/08/21. JC Excavation blocked the construction entrance prior to the inspection on 10/13/21. E&A inspector will monitor and make recommendations if the entrances is used at a later date. T27 CE₃ Construction Entrance Removed No **Current Condition:** Removed - TAB Construction removed the construction entrance prior to the inspection on 6/10/22. CE 4 Construction Entrance 14 Removed **Current Condition:** Removed - The construction entrance was paved prior to the inspection on 9/21/22. CIP 1 S29 2/16/2022 **Current Condition:** Good Condition - Graves Development installed curb inlet protection in the existing inlet on the north side of Potter Street prior to the inspection on 2/16/22. Graves Development cleaned out the curb inlet protection prior to the inspection on 7/26/22. South end of North CIP 2 Inlet Protection 169 Street 8/2/2022 Active Fair Condition - Graves Development installed curb inlet protection prior to the inspection on 8/2/22. Some dirt was observed in front of the Current Condition: inlet protection during the inspection on 10/05/22. Per CIR #18899, the inlet protection should be cleaned out and repositioned. Graves Development was informed to complete by 4/18/23 (CIR #18899). Not done as of the last inspection. Graves Development was reminded on 4/28/23 O3 - U2 11/16/2021

Good Condition - JC Excavation and Gene Graves installed the diversion prior to the inspection on 11/16/21. Location of diversion was

misidentified. As of 11/23/21, diversion is located at O3 to U2. The diversion was partially removed by disking prior to the inspection on

Removed - Valley Corp partially removed the diversion during sanitary installation prior to the inspection on 12/02/21. Due to paving,

9/1/2021

12/8/2021

9/1/2021

12/8/2021

12/8/2021

Removed - The diversion was partially graded out due to disking on site prior to the inspection 12/02/21. Due to paving, reinstallation will not

Removed

Removed

Pendina

Active

Pending

Active

Active

No

No

No

No

No

12/02/21. Walvoord Excavating redefined the diversion into the basin prior to the inspection on 10/18/22.

Pending - The matting will be installed after grading is completed in the area and weather conditions allow.

Pending - The matting will be installed after grading is completed in the area and weather conditions allow.

Good Condition- Gene Graves installed the erosion control matting prior to the inspection on 12/08/21.

Good Condition- Gene Graves installed the erosion control matting prior to the inspection on 12/08/21.

J18 - S27

J15 - N6

E11 - S25

E6 - F12

M6 - Z6

Z5 - Z24

V1 - V7

Current Condition:

D 2+A2575

Current Condition

Current Condition:

EM 1

Current Condition:

EM 2

Current Condition:

EM 3

Current Condition:

EM 4

Current Condition:

EM 5

Diversion

Diversion

be recommended as of 7/5/22.

Erosion Control Matting

reinstallation will not be recommended as of 7/5/22.

| Current Condition: | Good Condition- Gene Grave | es installed the erosion | n control matting prior to the ins | pection on 12/08/21. | |
|--------------------------|---|---|--|---|--|
| ET 1 | Erosion Control Terrace | V8 - O21 | 9/21/2021 | Active | No |
| Current Condition: | Good Condition - JC Excavat | ion installed the erosi | on control terrace prior to the in | spection on 9/21/21. | |
| ET 2 | Erosion Control Terrace | S2 - K14 | 9/21/2021 | Active | No |
| Current Condition: | Good Condition - JC Excavat | ion installed the majo | rity of the erosion control terrace | e prior to the inspection on 9/21/2 | 1. |
| FT 1 | Fuel Tank | On-site | | Removed | |
| Current Condition: | Removed - JC Excavation an | d Gene Graves remo | ved the fuel tanker and cleaned | up the spills prior to the inspectio | n on 12/16/21. |
| FT 2 | Fuel Tank | On-site | | Removed | |
| Current Condition: | Removed - Valley Corp remo | | r to the inspection on 11/23/21. | | |
| FT 3 | Fuel Tank | On-site | | Removed | |
| Current Condition: | Removed - Tab Construction | removed a double-wa | alled fuel tank on site prior to the | e inspection on 7/19/22. | |
| FT 4 | Fuel Tank | On-site | | Removed | |
| Current Condition: | Removed - Tab Construction | removed the fuel tanl | c prior to the inspection on 12/29 | 9/21. | |
| MS 01 | Material Storage | On Site | 3/2/2022 | Active | No |
| Current Condition: | • | orage is active in the s | outh portion of the site as of the | inspection on 3/02/22. | |
| PB 01 | Portable Bathroom | On Site | | Removed | |
| Current Condition: | Removed - JC Excavation re | moved the portable to | ilet prior to the inspection on 11 | /23/21. | |
| PB 02 | Portable Bathroom | On Site | | Removed | |
| Current Condition: | Removed - Tab Construction | removed the portable | toilet prior to the inspection on | 1/12/22. | |
| PB X | Portable Bathroom | On Site | 12/29/2021 | Active | No |
| Current Condition: | Good Condition - Tab Constr | uction secured a porta | able toilet on site prior to the ins | pection on 12/29/21. Valley Corp | secured a portable toilet |
| 1 | Corp stood up and resecured 8/16/22. MUD secured a port secured a portable toilet on s | the portable toilet pri able toilet on site prio ite prior to the inspec | or to the inspection on 4/22/22. r to the inspection on 11/21/22. tion on 4/26/23. | let from the site prior to the inspect Valley Corp removed a toilet prior MUD removed the portable toilet | r to the inspection on and an unknown contractor |
| SB A Current Condition: | Sediment Basin | E9 | 7/14/2021 | Active pection on 10/06/21. E&A inspector | No |
| SB B Current Condition: | installing the riser during the inspector painted the cleanou on 12/08/21. The recommend advanced development. Sediment Basin Good Condition - 20% full - J berm of the basin prior to the JC Excavation installed the o | inspection on 11/23/2 It mark during the inside inspection on 11/03/2 Utfall pipe prior to the ind Gene Graves particulars. | 1. JC Excavation installed the opection on 12/08/21. Gene Gravemergency spillway will no long 9/28/2021 the basin prior to the inspection 1. JC Excavation was in the prinspection on 12/02/21. The E8 ially built up the low spot in the | tion on 11/03/21. JC Excavation wat fall pipe prior to the inspection of the ses installed an inlet pipe into the layer be recommended as of 9/6/20 Active Active on 10/25/21. JC Excavation repaired by the session of the session | on 12/02/21. The E&A pasin prior to the inspection 22 due to the site's No irred the erosion along the the inspection on 11/23/21. mark during the inspection on 12/16/21. JC |
| i i I SF 1 | inspection on 6/21/22. E&A ir inspector painted the cleanoube be recommended as of 9/6/2 Silt Fence | nspector will monitor f ut mark during the insp 022 due to the site's a W27 - I20 | or completion. Gene Graves rei pection on 6/28/22. The recomm dvanced development. Hausma 4/27/2021 | s was in the process of reinstalling nstalled the riser prior to the inspendendation of including the emerge an began basin cleanout prior to the Active | ection on 6/28/22. The E&A ncy spillway will no longer ne inspection on 9/12/22. Yes |
| | | | | 7/21. JC Excavation and Gene Ginstalled silt fence along the south | |
| | Street crossing prior to the in 3/16/22. E&A inspector will mreinstalled the silt fence wher fence along and over the sou and installed a J-hook north obackfilled and repaired the si observed in the silt fence alout The silt fence should be clear | spection on 10/25/21. nonitor for completion re removed near the c th side of Reynolds S of the crossing on the lt fence on the north s ng the south side of the ned out south of the R ormed to complete by | Sudbeck Companies was in the Sudbeck cleaned out and reparenter of the run prior to the inspect treet Culvert prior to the inspect eastern portion of the silt fence ide of the Reynolds Street crossing Reynolds Street crossing during teynolds Street crossing. | e process of repairing the silt fencined the silt fence prior to the 3/22 ection on 3/29/22. Graves Develoin on 7/26/22. Graves Developming to the inspection on 8/30/22. sing prior to the inspection on 10/0 | e during the inspection on /22 inspection. Sudbeck pment reinstalled the silt lent backfilled the silt fence Walvoord Excavating 05/22. Minor spoils were |
| | 0:11.5 | 147 177 | 1/07/0004 | | |
| SF 2 Current Condition: | Silt Fence | I17 - K7 | 4/27/2021 | Active 7/21. JC Excavation and Gene Gr | Yes |
| | along the south side of the N Construction graded the N 17 Sudbeck cleaned out and rep- reinstalled the silt fence wher during tree clearing observed reinstalled the silt fence along 7/26/22. The area of ground or removed along the north side The silt fence should be reins | 170th Street crossing of the Street culvert and aired the silt fence prize removed near the old during the inspection g and over the north sidisturbance was stable of the Reynolds Street alled north of the Restalled north of the | and the north side of the Reynol removed the silt fence around ior to the 3/22/22 inspection. Sue enter of the run prior to the inspector will ide of Reynolds Street Culvert alized by Dustin Wallis prior to the crossing prior to the inspection will specificate the control of the inspection of the in | olds Street crossing prior to the in- the culvert in the process prior to dbeck repaired the silt fence north ection on 3/29/22. Silt fence aroun monitor to recommend reinstallate and the N 170th Street Culvert prior ie inspection on 9/21/22. A portion on on 10/26/22. | spection on 10/25/21. Tab the inspection on 3/02/22. n of the SB A outfall and did the outfall was removed ion. Graves Development or to the inspection on n of the silt fence was |
| | 12/30/22, 4/13/23 (CIR #1889 | | 11/28/22. Not done as of the la | ist inspection. Graves Developme | nt was reminded on |

| | repairing/reinstalling the silt Graves installed silt fence al Graves reinstalled/extended Construction graded the N 1 Sudbeck cleaned out and tre of SB B, reinstalled silt fence 3/29/22. Graves Developme 7/26/22. Graves Developme repairing the silt fence south | fence during the inspe ong the north side of t the silt fence south from 70th Street culvert and enched in the silt fence along the north side int reinstalled the silt fent installed silt fence a of the crossing during | ence prior to E&A's first inspecticion on 4/21/21. Silt fence was he N 170th Street crossing prior om the SB B outfall to the N 170th dremoved the silt fence around the prior to the 3/22/22 inspection. of the site, and installed two cheence along and over the north side bove and below the outfall prior the inspection on 9/28/22. Walverseing was seeded/matted prior countries and prior the crossing was seeded/matted prior the inspection on 9/28/22. | formerly identified as SF 5. Ju to the inspection on 10/25/21 th Street crossing prior to the the culvert in the process prio Sudbeck reinstalled the silt fe cks along the north side of the de of the N 170th Street Culve to the inspection on 8/30/22. | C Excavation and Gene . JC Excavation and Gene inspection on 12/08/21. Tab r to the inspection on 3/02/22. nce where removed northwest e site prior to the inspection on ert prior to the inspection on Graves Development was the silt fence south of the N |
|--|--|--|--|--|--|
| SF 4 | Silt Fence | M6 - R2 | | Removed | |
| Current Condition: | Removed - JC Excavation re remainder of the silt fence fa | | alf of the silt fence fabric prior to ction on 11/11/21. | the inspection on 10/06/21. J | C Excavation removed the |
| SF 5 | Silt Fence | M6 - N3 | | Removed | |
| Current Condition: | Removed - Silt fence identifi | ed as SF 3 as of 4/27/ | 21. | | • |
| SF 6 | Silt Fence | H19 | | Removed | |
| Current Condition: | Removed - JC Excavation re | emoved the silt fence of | on both sides of the creek prior to | the inspection on 10/06/21. | |
| SF 7 | Silt Fence | K6 | · · | Removed | |
| Current Condition: | | - | on both sides of the creek prior to | | L |
| SF 8 | Silt Fence | R2 | l | Removed | |
| Current Condition: | | | prior to the inspection on 10/06/2 | | |
| SF 9 | Silt Fence | W15 | 6/28/2022 | Active | No |
| Current Condition: | | | silt fence check prior to the insp | | |
| SF 10 | Silt Fence | Along Streets | 1/4/2023 | Pending | Yes |
| Current Condition: | Pending - | 7 11 01 1 9 0 11 0 0 10 | 17 172020 | . s.ia.i.g | |
| CTD | | | | | |
| STR Current Condition: | | | 4/2/2021 he inspection on 6/01/21. Minor | | |
| | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets Internal streets should be cle | was cleaned prior to to be Development cleans the inspection on 8/2 prior to the inspection peaned. | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri | trackout was observed on N ² prior to the inspection on 6/2 or to the inspection on 9/12/2: | 170th Street during the 8/22. Graves Development 2. Graves Development |
| | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets Internal streets should be cle Graves Development was in | was cleaned prior to to be Development cleans the inspection on 8/2 prior to the inspection peaned. | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. | trackout was observed on N ² prior to the inspection on 6/2 or to the inspection on 9/12/2: | 170th Street during the 8/22. Graves Development 2. Graves Development |
| Current Condition: SWPPP Sign Current Condition: | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets Internal streets should be cle Graves Development was in 12/30/22, 4/13/23 (CIR #188 SWPPP Signs Good Condition - E&A inspeduring the inspection on 12/6 sign during the inspection or 12/6 sign during the 12/6 sign during the inspection or 12/6 sign during the 12/6 sign duri | was cleaned prior to the Special Prior to the Special Prior to the Inspection on 8/2 prior to the Inspection on 8/2 prior to the Inspection peaned. formed to complete by 1999, 4/28/23 Adjacent to CE 3 ctor installed the SWF 22/21. The SWPPP sign 11/15/22. | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. | trackout was observed on N of prior to the inspection on 9/12/2: or to the inspection on 9/12/2: st inspection. Graves Developed the Active of A/21/21. E&A inspection on 9/28/22. E&A inspection on 9/28/22. E&A inspection. | 2. Graves Development Development Was reminded on No red the SWPPP sign to CE 3 |
| Current Condition: SWPPP Sign Current Condition: | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets. Internal streets should be clearly cleaned to the streets. Graves Development was in 12/30/22, 4/13/23 (CIR #188 SWPPP Signs Good Condition - E&A inspeduring the inspection on 12/6 sign during the inspection or Concrete Washout | was cleaned prior to the season of the inspection on 8/2 prior to the inspection on 8/2 prior to the inspection peaned. formed to complete by 1999, 4/28/23 Adjacent to CE 3 On Site | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. 1/11/22/22. Not done as of the la 4/21/2021 PPP sign during the inspection or grow was damaged prior to the inspection of the language of th | trackout was observed on N of prior to the inspection on 9/12/2: or to the inspection of 9/12/ | poment was reminded on No No red the SWPPP sign to CE 3 |
| SWPPP Sign Current Condition: WO 01 Current Condition: | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets. Internal streets should be clearly cleaned the streets. Graves Development was in 12/30/22, 4/13/23 (CIR #188 SWPPP Signs Good Condition - E&A inspeduring the inspection on 12/0 sign during the inspection or Concrete Washout Removed - Tab Construction | was cleaned prior to the service of the inspection on 8/2 prior to the inspection on 8/2 prior to the inspection on 8/2 prior to the inspection of the inspe | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. 1/11/22/22. Not done as of the late 1/21/2021 PPP sign during the inspection of | trackout was observed on N of prior to the inspection on 9/12/2: or to the inspection of 9/12/ | 170th Street during the 8/22. Graves Development 2. Graves Development beautiful or |
| SWPPP Sign Current Condition: WO 01 Current Condition: WO 02 | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets. Internal streets should be clearly cleaned the streets. Graves Development was in 12/30/22, 4/13/23 (CIR #188 SWPPP Signs.) Good Condition - E&A inspeduring the inspection on 12/4 sign during the inspection or Concrete Washout. Removed - Tab Construction. | was cleaned prior to the service of the inspection on 8/2 prior to the inspection on 8/2 prior to the inspection on 8/2 prior to the inspection of the inspe | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. 1/11/22/22. Not done as of the late o | trackout was observed on N 2 prior to the inspection on 6/2 or to the inspection on 9/12/2: st inspection. Graves Develop Active Active Active Active 9/28/22. E&A inspection on 9/28/22. E&A inspection on 9/28/22. E&A inspection on 3/02/22. Removed | 170th Street during the 8/22. Graves Development 2. Graves Development beautiful or |
| SWPPP Sign Current Condition: WO 01 Current Condition: WO 02 Current Condition: | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets. Internal streets should be clearly cleaned the streets. Graves Development was in 12/30/22, 4/13/23 (CIR #188 SWPP Signs) Good Condition - E&A inspeduring the inspection on 12/0 sign during the inspection on Concrete Washout Removed - Tab Construction Concrete Washout Removed - Tab Construction | was cleaned prior to the service of the inspection on 8/2 prior to the inspection on 8/2 prior to the inspection on 8/2 prior to the inspection of the inspe | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. 1/11/22/22. Not done as of the la 4/21/2021 PPP sign during the inspection or grow was damaged prior to the inspection of the language of th | trackout was observed on N of prior to the inspection on 6/2 or to the inspection on 9/12/2: st inspection. Graves Develop Active A | 170th Street during the 8/22. Graves Development 2. Graves Development beautiful or |
| SWPPP Sign Current Condition: WO 01 Current Condition: WO 02 Current Condition: WO 03 | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets. Internal streets should be clearly cleaned streets should be clearly cleaned the streets. Graves Development was in 12/30/22, 4/13/23 (CIR #188 SWPPP Signs) Good Condition - E&A insped during the inspection on 12/0 sign during the inspection on Concrete Washout Removed - Tab Construction Concrete Washout Removed - Tab Construction Concrete Washout | was cleaned prior to the series of the inspection on 8/2 prior to the inspection of 8/2 prior to the inspection on 8/2 prior | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. 1/11/22/22. Not done as of the la 4/21/2021 PPP sign during the inspection or gn was damaged prior to the inspection or gn was damaged prior to the inspection to the in | trackout was observed on N of prior to the inspection on 9/12/2: or to the inspection on 9/28/22. E&A inspection on 9/28/22. E&A inspection on 9/28/22. E&A inspection on 3/02/22. Removed on 8/16/22. Removed | 170th Street during the 8/22. Graves Development 2. Graves Development beautiful or |
| SWPPP Sign Current Condition: WO 01 Current Condition: WO 02 Current Condition: WO 03 Current Condition: | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets. Internal streets should be cleaned. Graves Development was in 12/30/22, 4/13/23 (CIR #188 SWPPP Signs) Good Condition - E&A inspeduring the inspection on 12/0 sign during the inspection or Concrete Washout Removed - Tab Construction | was cleaned prior to the service of the inspection on 8/2 prior to the inspection of the inspection | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. 1/11/22/22. Not done as of the late o | trackout was observed on N of prior to the inspection on 6/2 or to the inspection on 9/12/2: st inspection. Graves Develop Active Active Active 1.4/21/21. E&A inspector move pection on 9/28/22. E&A inspection on 9/28/22. E&A inspection on 3/02/22. Removed 1.0 on 8/16/22. Removed 1.0 on 8/16/22. Removed 1.0 on 8/30/22. | 170th Street during the 8/22. Graves Development 2. Graves Development beautiful or |
| SWPPP Sign Current Condition: WO 01 Current Condition: WO 02 Current Condition: WO 03 Current Condition: WO 03 Current Condition: WO 04 | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets Internal streets should be clearly cleaned streets. Internal streets should be clearly cleaned the streets. Graves Development was in 12/30/22, 4/13/23 (CIR #188 SWPPP Signs Good Condition - E&A inspeduring the inspection on 12/6 sign during the inspection on Concrete Washout Removed - Tab Construction Concrete Washout | was cleaned prior to the Sea Development cleans the inspection on 8/2 prior to the inspection peaned. formed to complete by 1999, 4/28/23 Adjacent to CE 3 ctor installed the SWF 20/21. The SWPPP sign 11/15/22. On Site On Site On Site On Site Termoved all concrete Southeast of SB B Termoved the concrete West of SB B | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. 1/11/22/22. Not done as of the la 4/21/2021 PPP sign during the inspection or an was damaged prior to the inspection or an action of the inspection to the inspection to the inspection washout prior to the inspection washout prior to the inspection washout prior to the inspection | trackout was observed on N of prior to the inspection on 6/2 or to the inspection on 9/12/2: st inspection. Graves Develop Active 1. 4/21/21. E&A inspector move pection on 9/28/22. E&A inspection on 9/28/22. E&A inspection on 3/02/22. Removed 1. on 8/16/22. Removed On 8/30/22. Removed On 8/30/22. Removed | 2. Graves Development 2. Graves Development 2. Graves Development 2. Development 2. Graves Development 2. Grav |
| SWPPP Sign Current Condition: WO 01 Current Condition: WO 02 Current Condition: WO 03 Current Condition: WO 04 Current Condition: | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets. Internal streets should be clearly cleaned streets. Internal streets should be clearly cleaned the streets. Graves Development was in 12/30/22, 4/13/23 (CIR #188 SWPPP Signs) Good Condition - E&A inspeduring the inspection on 12/6 sign during the inspection on 12/6 sign during the inspection on Concrete Washout Removed - Tab Construction Concrete Washout | was cleaned prior to the September of the inspection on 8/2 prior to the inspection of the inspecti | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. 1/11/22/22. Not done as of the la 4/21/2021 PPP sign during the inspection or gn was damaged prior to the inspection or gn was damaged prior to the inspection to the in | trackout was observed on N of prior to the inspection on 6/2 or to the inspection on 9/12/2: st inspection. Graves Develop Active Active Active A4/21/21. E&A inspector move pection on 9/28/22. E&A inspection on 9/28/22. E&A inspection on 3/02/22. Removed An on 8/16/22. Removed Active Removed Active Removed Active Removed Active | 170th Street during the 8/22. Graves Development 2. Graves Development beautiful was reminded on No red the SWPPP sign to CE 3 |
| SWPPP Sign Current Condition: WO 01 Current Condition: WO 02 Current Condition: WO 03 Current Condition: WO 04 Current Condition: WO 04 Current Condition: WO 04 Current Condition: WS 01 | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets. Internal streets should be clearly cleaned streets should be clearly cleaned the streets. Graves Development was in 12/30/22, 4/13/23 (CIR #188 SWPPP Signs) Good Condition - E&A inspeduring the inspection on 12/0 sign during the inspection on 12/0 sign during the inspection on Concrete Washout Removed - Tab Construction Waste Storage Area | was cleaned prior to the September of the inspection on 8/2 prior to the inspection of the inspecti | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. 1/11/22/22. Not done as of the late 1/21/2021 PPP sign during the inspection or any was damaged prior to the inspection of the inspe | trackout was observed on N of prior to the inspection on 6/2 or to the inspection on 9/12/2: st inspection. Graves Develop Active 1. 4/21/21. E&A inspector move pection on 9/28/22. E&A inspection on 9/28/22. E&A inspection on 3/02/22. Removed 1. on 8/16/22. Removed 1. on 8/30/22. Removed 1. on 8/9/22. Removed 1. on 8/9/22. Removed | 170th Street during the 8/22. Graves Development 2. Graves Development beautiful was reminded on No red the SWPPP sign to CE 3 |
| SWPPP Sign Current Condition: WO 01 Current Condition: WO 02 Current Condition: WO 03 Current Condition: WO 04 Current Condition: | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets. Internal streets should be clearly cleaned streets should be clearly cleaned the streets. Graves Development was in 12/30/22, 4/13/23 (CIR #188 SWPPP Signs) Good Condition - E&A inspeduring the inspection on 12/0 sign during the inspection on 12/0 sign during the inspection on Concrete Washout Removed - Tab Construction Waste Storage Area | was cleaned prior to the September of the inspection on 8/2 prior to the inspection of the inspecti | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. 1/11/22/22. Not done as of the la 4/21/2021 PPP sign during the inspection or an was damaged prior to the inspection or an action of the inspection to the inspection to the inspection washout prior to the inspection washout prior to the inspection washout prior to the inspection | trackout was observed on N of prior to the inspection on 6/2 or to the inspection on 9/12/2: st inspection. Graves Develop Active 1. 4/21/21. E&A inspector move pection on 9/28/22. E&A inspection on 9/28/22. E&A inspection on 3/02/22. Removed 1. on 8/16/22. Removed 1. on 8/30/22. Removed 1. on 8/9/22. Removed 1. on 8/9/22. Removed | 2. Graves Development 2. Graves Development 2. Graves Development 2. Development 2. Graves Development 2. Grav |
| SWPPP Sign Current Condition: WO 01 Current Condition: WO 02 Current Condition: WO 03 Current Condition: WO 04 Current Condition: WO 04 Current Condition: WO 04 Current Condition: WO 04 | Fair Condition - State Street inspection on 1/05/22. Grave cleaned 171th Street prior to partially cleaned the streets. Internal streets should be clear in the streets. Internal streets should be clear in the streets. Graves Development was in 12/30/22, 4/13/23 (CIR #188 in 12/30/22) (CIR #18 | was cleaned prior to the September of the inspection on 8/2 prior to the inspection of the inspecti | he inspection on 6/01/21. Minor ed Potter Street south of the site 3/22. The street was cleaned pri on 2/01/23. 1/11/22/22. Not done as of the late 1/21/2021 PPP sign during the inspection or any was damaged prior to the inspection of the inspe | trackout was observed on N of prior to the inspection on 6/2 or to the inspection on 9/12/2: st inspection. Graves Develop Active 1 4/21/21. E&A inspector move pection on 9/28/22. E&A inspection on 9/28/22. E&A inspection on 3/02/22. Removed 1 on 8/16/22. Removed 1 on 8/9/22. Removed 1 on 8/9/22. Removed 2 on 8/9/22. Removed 3 on 8/9/22. Removed 4 on 1/26/22. Removed 5 or 8/9/22. Removed 6 on 8/9/22. Removed 7 on 8/9/22. Removed 8 on 8/9/22. Removed 9 on 8/9/22. | Privision in accordance with a Based on my inquiry of the he information submitted is, to |