E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Inspector: Josh Ellington			Stage
		Majestic Pointe East	
Project Name:	OMA-20201	015-5644-GP1 / CSW-202005078	1
For Week Ending:		10/21/2023	68007
Project Location:	168th Street and	d State Street - Omaha, NE (Douglas County)	
Grading:	99%		
Sanitary Sewer:	100%		
Storm Sewer:	95%		
Paving:	98%		
Seeding:	35%		
Utilities:	80%		
Overall Development:	58%		

E&A - P2020.091.000

RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time
					Week 1
Sunday:	0.00"				
Monday	0.00"	10/16/2023	Sunny 59	1:35 PM	
Tuesday	0.00"				
Wednesday	0.01"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
	ł	·	•	ł	·
	None				

Complaints:

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Ground disturbance associated with tree clearing at the 171st Street and Reynolds Street Crossings (4/2/2021). Ground disturbance associated with tree clearing along State Street (4/13/2021). Mass grading began in DEV A, DEV NT3, and the south portion of DEV NT2 (7/07/2021). Mass grading throughout the entire site. Mass grading for Reynolds Street and N 170th Street crossings (10/06/2021). Disking in the north half of the site (12/02/2021). Surcharge removal in the north portion of the site. Storm sewer installation (12/08/2021). Disking along the southwest portion of the site. Grading for N 170th Street crossing (12/16/2021). Construction of box culvert at N 170th Street crossing (12/29/2021). Excavation for Reynolds Street culvert. Backfilling for N 170th Street box culvert (2/16/2022). Grading near Reynolds Street and 168th Street (7/19/2022). A grade stabilization structure was installed in the creek west of SB A (8/2/2022).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Ground disturbance associated with tree clearing at the 171st Street and Reynolds Street Crossings (4/2/2021). Ground disturbance associated with tree clearing along State Street (4/13/2021). Mass grading began in DEV A, DEV NT3, and the south portion of DEV NT2 (7/07/2021). Mass grading throughout the entire site. Mass grading for Reynolds Street and N 170th Street crossings (10/06/2021). Disking in the north half of the site (12/02/2021). Surcharge removal in the north portion of the site. Storm sewer installation (12/08/2021). Disking along the southwest portion of the site. Grading for N 170th Street crossing (12/16/2021). Grading at Reynolds Street crossing (12/29/2021). Construction of box culvert at N 170th Street crossing (12/29/2021). Excavation for Reynolds Street culvert. Backfilling for N 170th Street box culvert (2/16/2022). Grading near Reynolds Street and 168th Street (7/19/2022). A grade stabilization structure was installed in the creek west of SB A (8/2/2022).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (4/2/2021). Seeding and matting along the north side of the site, the western slopes along SB A, and the northeastern slopes (12/08/2021). Seeding along the N 170th Street crossing (9/28/2022). Matting along the N 170th Street crossing (10/05/2022).

Checklist Questions:

Yes

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

NI/A	
IN/A	

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are	adequate or needed
to prevent erosion?	
No	
Create Corrective Action?	
No - See Findings section	
3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?	
No	
Create Corrective Action?	
No - See Findings section	
4.) Are construction entrances and adjacent streets being maintained adequately?	
No	
Create Corrective Action?	
No - See BMP section	
5.) Is dust associated with the construction activity adequately controlled on the site?	
Yes	
Create Corrective Action?	
N/A	
Comments:	
Comments:	
Site was active for home construction during the current inspection.	

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

Some maintenance is required in the BMP section.
 Waste concrete should be removed. Majestic Pointe LLC was informed to complete by 6/7/23. Not done as of last inspection. Majestic Pointe LLC was reminded on 7/18/23, 10/10/23, 10/19/23

3.) Inactive portions of the site should be stabilized. Majestic Pointe LLC was informed to complete by 6/7/23. Not done as of last inspection. Majestic Pointe LLC was reminded on 7/18/23, 10/10/23, 10/19/23

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	V11		Removed	
Current Condition:	Removed - JC Excavation gr	aded out the site acces	s at this location as of the inspe	ection on 10/13/21.	
CE 2	Construction Entrance	S2	2/23/2021	Pending	No
Current Condition:	entrance prior to the inspecti	on on 6/08/21. JC Exca		c Pointe LLC and Legacy Homes entrance prior to the inspection r date.	
CE 3	Construction Entrance	T27		Removed	No
Current Condition:	Removed - TAB Construction	n removed the construct	tion entrance prior to the inspec	tion on 6/10/22.	
CE 4	Construction Entrance	14		Removed	
Current Condition:	Removed - The construction	entrance was paved pr	ior to the inspection on 9/21/22.		
CIP 1	Inlet Protection	S29	2/16/2022	Active	No
	inlet protection prior to the 8/			, ,	
CIP 2				Removed	
CIP 2 Current Condition:	inlet protection prior to the 8/	7/23 inspection. South end of North 169 Street			
	inlet protection prior to the 8/	7/23 inspection. South end of North 169 Street			No
Current Condition:	inlet protection prior to the 8/ Inlet Protection Removed - This BMP is now Inlet Protection	7/23 inspection. South end of North 169 Street CIP 2 in CIP N 169th S Craig St	St as of 8/28/23.	Removed	
Current Condition: CIP Craig St	inlet protection prior to the 8/ Inlet Protection Removed - This BMP is now Inlet Protection	7/23 inspection. South end of North 169 Street CIP 2 in CIP N 169th S Craig St	St as of 8/28/23. 8/28/2023	Removed	
Current Condition: CIP Craig St Current Condition:	inlet protection prior to the 8/ Inlet Protection Removed - This BMP is now Inlet Protection Good Condition - Majestic Poi Inlet Protection Fair Condition - Majestic Poi 8/22/22 but is now included i Inlet filters 1 and 2 need to b	7/23 inspection. South end of North 169 Street CIP 2 in CIP N 169th S Craig St Dinte LLC installed curb N 169th St nte LLC installed curb n this BMP. e cleaned out.	St as of 8/28/23. 8/28/2023 inlet protections 1-8 prior to the 8/28/2023 inlet protections 1-6 prior to the	Removed Active inspection on 8/28/23.	Yes s installed previously o

Current Condition:	Tan Condition - Majestic Pol		inlet protection prior to the inspe		
	The inlet filter needs to be	cleaned out.			
	Majestic Pointe LLC was in	formed to complete b	oy 10/23/23.		
CIP N 170th St	Inlet Protection	N 169th St	8/28/2023	Active	Yes
Current Condition:	Fair Condition - Majestic Poi	nte LLC installed curb i	inlet protections 1-12 prior to the	e inspection on 8/28/23.	
	1.) Inlet filters 3, 4, and 6 m 2.) Erosion north of CIP 6 s 1.) Majestic Pointe LLC wa 2.) Majestic Pointe LLC wa	hould be backfilled a s informed to complet s informed to complet	nd stabilized. te by 10/23/23. te by 10/23/23.		
CIP N 170th Terrace	Inlet Protection	N 170th Terrace	8/28/2023	Active	No
Current Condition:			inlet protections 1-6 prior to th	e inspection on 8/28/23.	
CIP Reynolds St	Inlet Protection	Reynolds St	8/28/2023	Active	No
Current Condition:	,		inlet protections 1-8 prior to th	e inspection on 8/28/23.	
CIP Sheffield St	Inlet Protection	Sheffield St	8/28/2023	Active	No
Current Condition:	Good Condition - Majestic Po		o inlet protections 1-4 prior to th	e inspection on 8/28/23.	
CIP Young St	Inlet Protection	Young Street	8/28/2023	Active	No
Current Condition:	Good Condition - Majestic Po		o inlet protections 1 & 2 prior to	the inspection on 8/28/23.	
CW	Concrete Washout	On Site	8/28/2023	Active	No
Current Condition:			ncrete washout prior to the insp or to the 10/16/23 inspection.	pection on 8/28/23. DR Horton rer	noved the concrete
D 1	Diversion	O3 - U2	11/16/2021	Active	No
Current Condition:				ior to the inspection on 11/16/21.	
			: O3 to U2. The diversion was p sion into the basin prior to the ir	artially removed by disking prior to aspection on 10/18/22.	the inspection on
D 2	Diversion	J18 - S27		Removed	
Current Condition:	Removed - Valley Corp parti- reinstallation will not be reco			prior to the inspection on 12/02/21	. Due to paving,
D 3	Diversion	J15 - N6		Removed	
Current Condition:	Removed - The diversion wa be recommended as of 7/5/2	2.	lue to disking on site prior to the	e inspection 12/02/21. Due to pavir	ng, reinstallation will
EM 1	Erosion Control Matting	E11 - S25	9/1/2021	Pending	No
Current Condition:	Ç.		is completed in the area and w		
EM 2	Erosion Control Matting	E6 - F12	12/8/2021	Active	No
Current Condition:			erosion control matting prior to		No
EM 3 Current Condition:	Erosion Control Matting	M6 - Z6	9/1/2021 is completed in the area and w	Pending	No
EM 4	Erosion Control Matting	Z5 - Z24	12/8/2021	Active	No
Current Condition:	•		erosion control matting prior to t		140
EM 5	Erosion Control Matting	V1 - V7	12/8/2021	Active	No
Current Condition:	0		erosion control matting prior to t		
ET 1	Erosion Control Terrace	V8 - O21	9/21/2021	Active	No
Current Condition:	Good Condition - JC Excava		n control terrace prior to the ins	spection on 9/21/21.	
ET 2	Erosion Control Terrace	S2 - K14	9/21/2021	Active	No
Current Condition:	Good Condition - JC Excava	tion installed the major	ity of the erosion control terrace	prior to the inspection on 9/21/21	
FT 1	Fuel Tank	On-site		Removed	
Current Condition:	Removed - JC Excavation ar	nd Majestic Pointe LLC	removed the fuel tanker and cl	eaned up the spills prior to the ins	pection on 12/16/21.
FT 2	Fuel Tank	On-site		Removed	
Current Condition:	, ,		to the inspection on 11/23/21.		
FT 3	Fuel Tank	On-site		Removed	
Current Condition:	Removed - Tab Construction	removed a double-wa	lled fuel tank on site prior to the	inspection on 7/19/22.	
FT 4	Fuel Tank	On-site		Removed	
Current Condition:			prior to the inspection on 12/29		
Lot 163	Individual Lot	Lot 163	10/2/2023	Active	No
Current Condition:				on. DR Horton installed straw wa from the ROW prior to the 10/16/	
Lot 164	Individual Lot	Lot 164	10/2/2023	Active	No
Current Condition:				n. DR Horton installed and secure lot and removed the dirt pile fro	

Lot 165 Current Condition:	فما احتناء فناحدا		40/0/0000	A ativia	Ne
Current Condition.	Individual Lot	Lot 165	10/2/2023	Active n. DR Horton installed straw wa	No No
		U U	rior to the 10/16/23 inspection		atties along the nont o
Lot 166	Individual Lot	Lot 166	9/6/2023	Active	No
Current Condition:	Good Condition - DR Horton	began excavating the I	ot prior to the 9/6/23 inspection	DR Horton removed the dirt pile	s in the ROW prior to th
				prior to the 10/16/23 inspection	
Lot 167	Individual Lot	Lot 167	9/6/2023	Active	No
Current Condition:				DR Horton removed the dirt pile	
Lot 168	Individual Lot	Lot 168	9/6/2023	Active	No
Current Condition:				. D R Horton removed the dirt pile	
				prior to the 10/16/23 inspection	
Lot 169	Individual Lot	Lot 169	8/28/2023	Active	No No
Current Condition:	Horton removed the dirt piles			d installed straw wattles prior to t	ne 8/28/23 inspection. L
Lot 170	Individual Lot	Lot 170	8/28/2023	Active	No
Current Condition:			ot and installed straw wattles pr he lot prior to the 10/2/23 inspe	ior to the 8/28/23 inspection. DR ction.	Horton removed the dir
Lot 180	Individual Lot	Lot 180	8/28/2023	Active	No
Current Condition:	Good Condition - DR Horton installed straw wattles along			n. DR Horton removed the dirt pil	es in the ROW and
Lot 194	Individual Lot	Lot 194	8/28/2023	Active	No
Current Condition:		0 0	ot prior to the 8/28/23 inspectio of the lot prior to the 9/25/23 ins	n. DR Horton removed the dirt pil pection.	es in the ROW, paved
MS 01	Material Storage	On Site	3/2/2022	Active	No
Current Condition:	Good Condition - Material st	orage is active in the so	buth portion of the site as of the	inspection on 3/02/22.	
PB 01	Portable Bathroom	On Site	·	Removed	
Current Condition:	Removed - JC Excavation re	moved the portable toil	et prior to the inspection on 11/	23/21.	
PB 02	Portable Bathroom	On Site		Removed	
Current Condition:		-	toilet prior to the inspection on '		
PB X	Portable Bathroom	On Site	12/29/2021	Pending	No
Current Condition:	prior to the inspection on 3/1	6/22. Tab Construction	removed a portable toilet from	on 12/29/21. Valley Corp secured the site prior to the inspection on removed a toilet prior to the inspe	•
		the inspection on 4/26	/23. An unknown contractor rem	the portable toilet and an unknow loved the portable toilet on site p	n contractor secured a
SB A	portable toilet on site prior to	the inspection on 4/26	/23. An unknown contractor rem		n contractor secured a
SB A Current Condition:	portable toilet on site prior to inspection; E&A inspector wi Sediment Basin Good Condition - 9% full - JC JC Excavation repaired the excavation repaired the excavation repaired the cleanor inspector painted the cleanor inspection on 12/08/21. The site's advanced developmen	the inspection on 4/26, Ill monitor for its reinsta E9 C Excavation began sha erosion along the berm inspection on 11/23/21 ut mark during the insp recommendation of inc t. Minor erosion was ob	/23. An unknown contractor rem llation.	noved the portable toilet on site p	n contractor secured a rior to the 6/19/23 No r will continue to monito as in the process of n 12/02/21. The E&A to the basin prior to the s of 9/6/2022 due to the pector will continue to
	portable toilet on site prior to inspection; E&A inspector wi Sediment Basin Good Condition - 9% full - JC JC Excavation repaired the einstalling the riser during the inspector painted the cleanou inspection on 12/08/21. The site's advanced developmen monitor and recommend main	the inspection on 4/26, Ill monitor for its reinsta E9 C Excavation began sha erosion along the berm inspection on 11/23/21 ut mark during the insp recommendation of inc t. Minor erosion was ob	/23. An unknown contractor rem llation.	Active Active ection on 10/06/21. E&A inspecto on on 11/03/21. JC Excavation w itfall pipe prior to the inspection of inte LLC installed an inlet pipe in vill no longer be recommended as the 6/26/23 inspection; E&A ins	n contractor secured a rior to the 6/19/23 No r will continue to monito as in the process of n 12/02/21. The E&A to the basin prior to the s of 9/6/2022 due to the pector will continue to
Current Condition:	portable toilet on site prior to inspection; E&A inspector wi Sediment Basin Good Condition - 9% full - JC JC Excavation repaired the eleanor inspector painted the cleanor inspection on 12/08/21. The site's advanced developmen monitor and recommend main inspection. Sediment Basin Good Condition - 49% full - J berm of the basin prior to the 11/23/21. JC Excavation inst inspection on 12/08/21. JC Excavation inst inspection on 12/08/21. JC Excavation inst inspection on 12/08/21. JC Excavation fully riser during the inspection or inspection on 6/28/22. The Excert during the inspection or inspection on 6/28/22. The Excert during the inspection or inspection on 6/28/22. The Excert during the inspection or inspection on 6/28/22. The Excert during the inspection or 12/08/21. The Excert during the inspection or inspection on 6/28/22. The Excert during the inspection or inspection or 6/28/22. The Excert during the inspection or inspection on 6/28/22. The Excert during the inspection or inspection or 6/28/22. The Excert during the inspection or inspection on 6/28/22. The Excert during the inspection or inspection or 6/28/22. The Excert during the inspection or inspection or 6/28/22. The Excert during the inspection or inspection or 6/28/22. The Excert during the inspection or 6/28/22. The Excert during the inspection or 6/28/22. The Excert during the inspection or 6/28/24.	the inspection on 4/26, Ill monitor for its reinsta E9 C Excavation began sha erosion along the berm inspection on 11/23/21 ut mark during the insp recommendation of inc t. Minor erosion was ob intenance as needed. E O3 IC Excavation shaped t a inspection on 11/03/2 talled the outfall pipe pr Excavation and Gene G y built up the berm prior h 6/21/22. E&A inspector E&A inspector painted the onger be recommended	/23. An unknown contractor rem llation. 7/14/2021 aping the basin prior to the inspect of the basin prior to the inspect luding the emergency spillway to served around the barrel during SA inspector painted around the 9/28/2021 he basin prior to the inspection 1. JC Excavation was in the pro- ior to the inspection on 12/02/2 raves partially built up the low s to the inspection on 12/21/21. privile monitor for completion. M the cleanout mark during the inspection	Active Active ection on 10/06/21. E&A inspecto on on 11/03/21. JC Excavation w itfall pipe prior to the inspection o inte LLC installed an inlet pipe in vill no longer be recommended as the 6/26/23 inspection; E&A ins e remained of the riser structure	n contractor secured a rior to the 6/19/23 No r will continue to monitor as in the process of n 12/02/21. The E&A to the basin prior to the s of 9/6/2022 due to the pector will continue to during the 8/8/23 No ired the erosion along t the inspection on cleanout mark during the or to the inspection on rocess of reinstalling the riser prior to the endation of including the

Current Condition:	cleaned out the silt fence pri the Reynolds Street crossing inspection on 3/16/22. E&A inspection. Sudbeck reinstal reinstalled the silt fence alor backfilled the silt fence and i Walvoord Excavating backfil 10/05/22. Minor spoils were The silt fence was cleaned of	or to the inspection on g prior to the inspection inspector will monitor for led the silt fence where ng and over the south si installed a J-hook north lled and repaired the sil observed in the silt fenc out south of the Reynolo	10/13/21. JC Excavation and M on 10/25/21. Sudbeck Company or completion. Sudbeck cleaned removed near the center of the de of Reynolds Street Culvert p of the crossing on the eastern t fence on the north side of the	7/21. JC Excavation and Majestic ajestic Pointe LLC installed silt fe ies was in the process of repairin out and repaired the silt fence pr run prior to the inspection on 3/2 rior to the inspection on 7/26/22. portion of the silt fence prior to the Reynolds Street crossing prior to eynolds Street crossing during the spection on 5/17/23.	nce along the south side of g the silt fence during the ior to the 3/22/22 9/22. Majestic Pointe LLC Majestic Pointe LLC e inspection on 8/30/22. the inspection on
	Majestic Pointe LLC was info 10/19/23.	ormed to complete by 1	0/16/23. Not done as of last in	spection. Majestic Pointe LLC v	was reminded on
SF 2	Silt Fence	17 - K7	4/27/2021	Active	No
Current Condition:				Active 27/21. JC Excavation and Majesti	
SF 3 Current Condition:	10/25/21. Tab Construction inspection on 3/02/22. Sudb the SB A outfall and reinstal outfall was removed during the inspection on 7/26/22. The inspection on 7/26/22. The inspection on 7/26/22. The inspection on 7/26/22. The installed prior to the 5/31/2 removal in this maintenance north flared end of Reynolds Silt Fence Good Condition - Legacy Hor repairing/reinstalling the silt	graded the N 170th Streeck cleaned out and repled the silt fence where ree clearing observed or led the silt fence along the area of ground distuing the north side of the Fi23 inspection. Old portion as of 6/7/23. Majestic Fi Street crossing, and respective to the silt fermes installed the silt fermes during the inspection.	eet culvert and removed the silt paired the silt fence prior to the removed near the center of the Juring the inspection on 7/19/22 and over the north side of Reyn rbance was stabilized by Dustin Reynolds Street crossing prior to ons of SF 2 west of the creek do Pointe LLC reinstalled the silt fe emoved the old portions of SF 2 4/27/2021 nce prior to E&A's first inspectio tion on 4/21/21. Silt fence was to	Reynolds Street crossing prior to fence around the culvert in the pr 3/22/22 inspection. Sudbeck repa run prior to the inspection on 3/2 . E&A inspector will monitor to re- olds Street Culvert and the N 170 Wallis prior to the inspection on the inspection on 10/26/22. Silt for the inspection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Ex- spection on 10/25/21. JC Excavation for the second text spection on 10/25/21. JC Excavation was formerly identified as SF 5. JC Excavation was for t	ocess prior to the aired the silt fence north of 9/22. Silt fence around the commend reinstallation. th Street Culvert prior to 9/21/22. A portion of the fence was partially I not be recommended for crossing and above the 23 inspection. No in the process of cavation and Gene Graves
SF 4	Construction graded the N 1 Sudbeck cleaned out and tre of SB B, reinstalled silt fence 3/29/22. Graves Developme 7/26/22. Graves Developme repairing the silt fence south	70th Street culvert and enched in the silt fence e along the north side o nt reinstalled the silt fer nt installed silt fence ab of the crossing during	removed the silt fence around t prior to the 3/22/22 inspection. If the site, and installed two chec nee along and over the north sid pove and below the outfall prior the inspection on 9/28/22. Walv	crossing prior to the inspection o he culvert in the process prior to to Sudbeck reinstalled the silt fence cks along the north side of the site le of the N 170th Street Culvert prior to the inspection on 8/30/22. Grav roord Excavating cleaned out the or to the inspection on 10/05/22.	the inspection on 3/02/22. where removed northwest e prior to the inspection on rior to the inspection on ves Development was
Current Condition:			If of the silt fence fabric prior to	the inspection on 10/06/21. JC E	L xcavation removed the
	remainder of the silt fence fa	bric prior to the inspect	ion on 11/11/21.		
SF 5	Silt Fence	M6 - N3		Removed	
Current Condition:	Removed - Silt fence identifi		1.		1
SF 6	Silt Fence	H19		Removed	
Current Condition: SF 7	Silt Fence	K6	n both sides of the creek prior to	Removed	
Current Condition:		-	both sides of the creek prior to		
SF 8	Silt Fence	R2		Removed	
Current Condition:			I ior to the inspection on 10/06/2		
SF 9	Silt Fence	W15	6/28/2022	Active	No
Current Condition:	Good Condition - Majestic P	ointe LLC installed a sil	t fence check prior to the inspec	ction on 6/28/22. Majestic Pointe	
05.40	check and removed the tras	· · · · · · · · · · · · · · · · · · ·		A =4ius	Vee
SF 10	Silt Fence	Along Streets	1/4/2023	Active	Yes
Current Condition:	northern portion of the silt fe the southern run to the north The northern silt fence need	nce prior to the 8/7/23 i west prior to the 8/28/2 s to be repaired on the	nspection. Majestic Pointe LLC 3 inspection. corner of street.	extended the northern run of the	silt fence to the east and
		N 170th St & N 170th			
SF 11	Silt Fence	Terrace	7/24/2023	Active	No
Current Condition:	Good Condition - Majestic P	ointe LLC installed the	silt fence prior to the 8/7/23 insp	pection.	

SF 12	Silt Fence	N 170th Ave & N 170th Terrace	8/28/2023	Active	No
Current Condition:			It fence prior to the 8/28/23 in		NO
	,	South of Young Street	•	T	
SF 13	Silt Fence	& N 170th St	8/28/2023	Active	No
Current Condition:			It fence prior to the 8/28/23 in		
SF 14	Silt Fence	South of N 169th St	8/28/2023	Active	No
Current Condition:			It fence prior to the 8/28/23 in	ispection.	
SF 15	Silt Fence	South of Reynolds St and 169th St	8/28/2023	Active	No
Current Condition:	Good Condition - Majestic P	ointe LLC installed the sil	It fence prior to the 8/28/23 in	spection.	
SF 16	Silt Fence	South of Reynolds St and 170th St	8/28/2023	Active	No
Current Condition:	Good Condition - Majestic P	ointe LLC installed the sil	It fence prior to the 8/28/23 in	nspection.	
STR	Street Cleaning	Internal and Adjacent Streets	4/2/2021	Active	Yes
	 Streets need to be clean Streets should be clean Majestic Pointe LLC was 10/19/23. DR Horton was informed 	informed to complete by	10/10/23. Not done as of la	st inspection. Majestic Pointe L	LC was reminded on
WO 01	2.) Streets should be clear 1.) Majestic Pointe LLC was 10/19/23. 2.) DR Horton was informe	ed around DR Horton Ic informed to complete by d to complete by 10/17/2	10/10/23. Not done as of la		LC was reminded on
WO 01 Current Condition:	 2.) Streets should be clear 1.) Majestic Pointe LLC was 10/19/23. 2.) DR Horton was informe Concrete Washout 	ed around DR Horton ic informed to complete by d to complete by 10/17/2 On Site	10/10/23. Not done as of la: 23.	Removed	LC was reminded on
WO 01 Current Condition: WO 02	 2.) Streets should be clear 1.) Majestic Pointe LLC was 10/19/23. 2.) DR Horton was informe Concrete Washout 	ed around DR Horton ic informed to complete by d to complete by 10/17/2 On Site	10/10/23. Not done as of la	Removed	LC was reminded on
Current Condition:	2.) Streets should be clear 1.) Majestic Pointe LLC was 10/19/23. 2.) DR Horton was informe Concrete Washout Removed - Tab Construction Concrete Washout	ed around DR Horton ic informed to complete by d to complete by 10/17/7 On Site n removed all concrete wa On Site	10/10/23. Not done as of la: 23.	Removed inspection on 3/02/22. Removed	LC was reminded on
Current Condition: WO 02	2.) Streets should be clear 1.) Majestic Pointe LLC was 10/19/23. 2.) DR Horton was informe Concrete Washout Removed - Tab Construction Concrete Washout	ed around DR Horton ic informed to complete by d to complete by 10/17/7 On Site n removed all concrete wa On Site	10/10/23. Not done as of la: 23. aste from the site prior to the	Removed inspection on 3/02/22. Removed	LC was reminded on
Current Condition: WO 02 Current Condition: WO 03 Current Condition:	 2.) Streets should be clear 1.) Majestic Pointe LLC was 10/19/23. 2.) DR Horton was informed Concrete Washout Removed - Tab Construction Concrete Washout 	action DR Horton Ic informed to complete by Informed to complete by d to complete by 10/17/2 On Site n removed all concrete wa On Site n removed the concrete wa Southeast of SB B removed the concrete wa Southeast of SB B	10/10/23. Not done as of la: 23. aste from the site prior to the	Removed inspection on 3/02/22. Removed n on 8/16/22. Removed o on 8/30/22.	LC was reminded on
Current Condition: WO 02 Current Condition: WO 03 Current Condition: WO 04	2.) Streets should be clear 1.) Majestic Pointe LLC was 10/19/23. 2.) DR Horton was informed Concrete Washout Removed - Tab Construction Concrete Washout Removed - Tab Construction Concrete Washout Removed - Tab Construction Concrete Washout	action DR Horton Ic informed to complete by Informed to complete by d to complete by 10/17/7 On Site n removed all concrete wa On Site n removed the concrete wa Southeast of SB B removed the concrete wa West of SB B	10/10/23. Not done as of lat 23. aste from the site prior to the vashout prior to the inspection ashout prior to the inspection	Removed inspection on 3/02/22. Removed n on 8/16/22. Removed o on 8/30/22. Removed	LC was reminded on
Current Condition: WO 02 Current Condition: WO 03 Current Condition: WO 04 Current Condition:	2.) Streets should be clear 1.) Majestic Pointe LLC was 10/19/23. 2.) DR Horton was informed Concrete Washout Removed - Tab Construction Concrete Washout Removed - Tab Construction Concrete Washout Removed- Tab Construction Concrete Washout Removed - Tab Construction Concrete Washout Removed - Tab Construction	action DR Horton Ic informed to complete by informed to complete by d to complete by 10/17/7 On Site n removed all concrete wa On Site n removed the concrete wa Southeast of SB B removed the concrete wa West of SB B n removed the concrete wa	10/10/23. Not done as of la: 23. aste from the site prior to the vashout prior to the inspection ashout prior to the inspection	Removed inspection on 3/02/22. Removed n on 8/16/22. Removed on 8/30/22. Removed n on 8/30/22. Removed n on 8/30/22. Removed n on 8/9/22.	
Current Condition: WO 02 Current Condition: WO 03 Current Condition: WO 04	2.) Streets should be clear 1.) Majestic Pointe LLC was 10/19/23. 2.) DR Horton was informed Concrete Washout Removed - Tab Construction Concrete Washout Removed - Tab Construction Concrete Washout Removed- Tab Construction Concrete Washout Removed - Tab Construction Concrete Washout Removed - Tab Construction Waste Storage Area	ed around DR Horton ic informed to complete by d to complete by 10/17/7 On Site n removed all concrete wa On Site n removed the concrete wa Southeast of SB B removed the concrete wa West of SB B n removed the concrete wa On Site	10/10/23. Not done as of la: 23. aste from the site prior to the /ashout prior to the inspection ashout prior to the inspection /ashout prior to the inspection 10/9/2023	Removed inspection on 3/02/22. Removed n on 8/16/22. Removed o on 8/30/22. Removed	
Current Condition: WO 02 Current Condition: WO 03 Current Condition: WO 04 Current Condition: WS 01	 2.) Streets should be clear 1.) Majestic Pointe LLC was 10/19/23. 2.) DR Horton was informe Concrete Washout Removed - Tab Construction Concrete Washout 	eed around DR Horton Ic informed to complete by d to complete by 10/17/7 On Site n removed all concrete wa On Site n removed the concrete wa Southeast of SB B removed the concrete wa West of SB B n removed the concrete wa On Site or removed the concrete wa On Site or removed the concrete wa On Site on Site on Site on removed the concrete wa On Site On Site Southeast of SB B on removed the concrete wa On Site on removed the concrete wa On Site on removed the concrete wa On Site on Site	10/10/23. Not done as of la: 23. aste from the site prior to the vashout prior to the inspection ashout prior to the inspection vashout prior to the inspection 10/9/2023 emoved from the site prior to	Removed inspection on 3/02/22. Removed n on 8/16/22. Removed on 8/30/22. Removed n on 8/9/22. Active	No
Current Condition: WO 02 Current Condition: WO 03 Current Condition: WO 04 Current Condition: WS 01	 2.) Streets should be clear 1.) Majestic Pointe LLC was 10/19/23. 2.) DR Horton was informed Concrete Washout Removed - Tab Construction Waste Storage Area Good Condition - The waste storage containers prior to the system designed to assure the person or persons who man the best of my knowledge ar 	eed around DR Horton Ic informed to complete by d to complete by 10/17/2 On Site removed all concrete wa On Site removed the concrete wa Southeast of SB B removed the concrete wa West of SB B removed the concrete wa e storage container was re to 10/9/23 inspection. DR 4, that this document and hat qualified personnel pr age the system or those p nd belief, true, accurate, a	10/10/23. Not done as of las 23. aste from the site prior to the vashout prior to the inspection ashout prior to the inspection vashout prior to the inspection 10/9/2023 moved from the site prior to R Horton removed the trash all attachments were prepare roperly gathered and evaluate persons directly responsible f	Removed inspection on 3/02/22. Removed n on 8/16/22. Removed n on 8/30/22. Removed n on 8/9/22. Active the inspection on 7/26/22. D R H from the lot prior to the 10/16/2 ed under my direction or supervise ed under my direction or submitted. Base for gathering the information, the at there are significant penalties for	No No orton installed waste 23 inspection. ion in accordance with a sed on my inquiry of the information submitted is,