E&A - P2004.045.000								
Inspector: Mike Jacobson				Stage				
Project Name:	Mer		3					
For Week Ending:	2		68136					
Grading:	100%	1						
Sanitary Sewer:	90%							
Storm Sewer:	90%							
Paving:	90%							
Seeding:	100%							
Utilities:	65%							
Overall Development:	20%							
RAIN FALL AMOUNTS	Amount in inches	Date inspected						
				Week 1				
Sunday:	0.00"		1					
Monday	0.00"		1					
Tuesday	0.00"		1					
Wednesday	0.00"		+					
Thursday Friday	0.00"		+					
Saturday	0.00"		+ +					
				Week 2				
Sunday:	0.00"							
Monday	0.00"							
Tuesday	0.21"							
Wednesday	0.24"							
Thursday	0.00"							
Friday	0.04"							
Saturday	0.02"			Week 3				
Sunday:	0.04"	l	T T	week 3				
Monday	0.01"							
Tuesday	0.00"							
Wednesday	0.00"							
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
				Week 4/5				
Sunday:	0.00"; 0.11"	0/4/0040 N						
Monday	0.02"; 0.03"	2/1/2010; None						
Tuesday Wednesday	0.00"; <b>0.02"</b> 0.00": 0.00"							
Thursday	<b>0.32</b> "; 0.00"							
Friday	<b>0.24</b> "; 0.00"							
Saturday	0.00"; 0.00"							
	1		<u>,                                     </u>					
	None							
Complaints:								
Construction Sequencing:								
Which portion(s) (i.e. drainage base		orary or permanent cess	sation of grading, earth	vork, or ground				
disturbance in the last 14 days?								
Entire Site, grading complete	d and site seeded Summer/F	all 2005.						
Which portion's) (i.e. drainage bas	sins) of the site do not have gradi	ng, earthwork, or groun	d disturbance schedule	d in the next 14				
days?:								
Entire Site, grading completed and site seeded Summer/Fall 2005.								
NATIONAL ASSESSMENT OF THE PROPERTY OF THE PRO	Attination management Personal Control	and the second of the second o	manta do					
What temporary or permanent stabilization measures listed in this section are being implemented?  Site seeded Fall 2005 & 5/2007, stabilized entrances installed Summer 2005, Re-Seed 5/2007 by Geis;								
Sediment Basin E area seed			•					
(4/2009); Sediment basin E a	· ·	nere nanulcap ramp	o were moldiled Was	16-266060				
(7/2003), Ocument Dasill E a	1104 Was 16-366060(4/2009)							

## Comments:

Home construction remains active on site at this time.

During inspection on 2/1/2010 inspector walked portions of the site. Most of the BMP's are still covered with snow, but appeared to be in good working condition unless otherwise noted.

## Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

- 1) A few areas and the R.O.W. in the commercial area needs to be seeded. Developer Mike Huber was informed to seed areas by 9/3/09. Maintenance not completed as of last inspection, but due to the recent rains another seven days is given to complete maintenance until 9/10/09. Maintenance not completed as of last inspection. As of inspection on 12/7/09 seeding has not been completed and now due to frost in the ground seeding will have to take place in the spring of 2010.
- 2) A few areas of lot level silt fence is damaged in the home construction area and needs to be repaired. Mert w/ Hearthstone Production was informed that due to the ground being frozen he is to complete maintenance as soon as conditions allow.
- 3) There are a few piles of dirt in the R.O.W. in the home construction area and they need to be removed or install straw wattle around them. Mert w/ Hearthstone Production was informed to complete maintenance by 2/8/10.
- 4) There are a few full dumpsters in the home construction area and they need to be emptied or covered. Mert w/ Hearthstone Production was informed to complete maintenance by 2/8/10.
- 5) No maintenance is required in the BMP section.

			Projected			Description of
Unique Name	Туре	Location	Install Date	Status	Maintenance	Maintenance/Activity:
		N41d00m00s				Repairs
CE A	Construction Entrance	W96d00m00s		Removed		Needed/Planned:
Current Condition:	Entrance Paved					
		N41d00m00s				
SB E	Sediment Basin	W96d00m00s	ļ	Removed		
Current Condition:	Basin was removed due to I	ot development prior	to inspection on	6/12/08 by Dou	ble D	
	Excavating.	N41d00m00s	1	1		
SB F	Sediment Basin	W96d00m00s	07/01/05	Active	No	
Current Condition:	Good Condition- 20% Filled		0.70.700	7.00		
	Cleaned out 7/2008 by Bob	Roth				
	Baffle maintenance was cor	npleted prior to inspe	ection on 6/6/09 b	y Mike Stafford.		
		N41d00m00s				
SB G	Sediment Basin	W96d00m00s	08/26/05	Active	No	
Current Condition:	Good Condition- 18% Filled					
	-Cleaned 5/2007 by Dave H	ausman & riser was	repaired prior to i	nspection on 9/9	9/08.	
		N41d00m00s				
SF A	Silt Fence	W96d00m00s	07/19/05	Removed		
Current Condition:	Removed					
		N41d00m00s				
SF B	Silt Fence	W96d00m00s	<u> </u>	Removed		
Current Condition:	Removed - Not needed due					
SF C	Silt Fence	N41d00m00s	07/01/05	A -4i	NI-	
Current Condition:	Good Condition- Partially re	W96d00m00s		Active	No out lote	
Current Condition.	Maintenance was completed			0	out iots.	
		N41d00m00s	Ι			
ST A	Silt Trap	W96d00m00s		Removed		
Current Condition:	Trap Closed June 2006.					
	·	N41d14m44s				
STR	Streets	W96d12m59s	8/10/2007	Active	No	
Current Condition:	Good Condition- No major s					
SWPPP Sign	SWPPP Sign	Two signs on site	3/28/2008	Active	No	
Current Condition:	Good Condition			1		1
	On 3/28/08 a SWPPP sign	was installed at 164tl	h & Giles and 168	3th & Meridian S	t. entrance.	
	11000			Toda 1	1.L.C	1
nspector Signature: 🔟	habeel fawlow	]	Reviewed By:	Zadhany k.	yuu-	