E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager

ENGINEERING • PLANNING • FIELD SERVICES

Erosion Control Specialist- Manage							
	E&A - P	2004.045.000					
Inspector: Mike Jacobson, CISEC							
,		Meridian Pa	ark		Stage 3		
		NER11069					
Project Name:							
For Week Ending:		5/8/2010					
Project Location:	168th & Harriso	unty)	68136				
Grading:	100%						
Sanitary Sewer:	90%						
Storm Sewer:	90%						
Paving:	90%						
Seeding:	100%						
Utilities:	65%						
Overall Development:	20%						
<u> </u>		1					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected					
					Week		
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.02"						
Thursday	0.13"						
Friday	0.00"						
Saturday	0.00"						
	0.00"				Week		
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.01"						
Wednesday	0.32"						
Thursday Friday	0.00" 2.71"	04/23/10					
Saturday	0.00"	04/23/10					
Saturday	0.00				Week		
Sunday:	0.00"				Week		
Monday	0.00"						
Tuesday	0.24"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.24"						
Saturday	0.04"						
					Week 4/		
Sunday:	Trace						
Monday	0.05"						
Tuesday	0.01"						
Wednesday	0.00"						
Thursday	0.18"						
Friday	0.18"						
Saturday	0.00"						
•	1	<u>. </u>					
	None						
Complaints:							
• ** **	†						

Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Entire Site, grading completed and site seeded Summer/Fall 2005. Which portion's) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Entire Site, grading completed and site seeded Summer/Fall 2005. What temporary or permanent stabilization measures listed in this section are being implemented? Site seeded Fall 2005 & 5/2007, stabilized entrances installed Summer 2005, Re-Seed 5/2007 by Geis; Sediment Basin E area seeded (9/2008); Areas around where handicap ramps were installed was re-seeded (4/2009); Sediment basin E area was re-seeded(4/2009)

Comments:

Comments:

Home construction remains active on site at this time.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) There is some construction debris/trash in a few outlot areas around sediment basin F and needs to be cleaned up. Commercial Seeding was informed to clean up by 3/18/10. Commercial Seeding called inspector on 4/8/10 and stated that cleanup has been completed. Inspector to verify during next inspection. Maintenance was completed prior to inspection on 4/23/10 by CS.
- 2) Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
Offique Name	туре	Location	Ilistali Date	Status	Maintenance		
		N41d00m00s					
CE A	Construction Entrance	W96d00m00s		Removed			
Current Condition:	Entrance Paved						
		Commercial					
Commercial Area- Lot 3	Misc/Other	Area- Lot 3	5/4/2010	Active	Yes		
Current Condition:	Vacant lots in the commercial area.						
	 Silt fence is down/damaged and needs to be repaired or removed. On area of Meridian Street that is North of the Hearthstone office is undermining the street and it needs to be backfilled and compacted. Developer Mike Huber was informed to seed areas by 9/3/09. Maintenance not completed as of last inspection, but due to the recent rains another seven days is given to complete maintenance until 9/10/09. On 3/12/10 Developer Mike Huber was reminded that maintenance needs to be completed once seeding season begins. Maintenance not completed as of last inspection. Commercial Seeding was informed to complete maintenance by 4/14/10. Silt fence was removed prior to inspection on 4/23/10 by CS. Commercial Seeding was informed to complete maintenance by 4/14/10. Maintenance not completed as of last inspection. 						
		Commercial					
Commercial Area- Lot 4	Silt Fence/Other	Area- Lot 4	5/4/2010	Active	No		
Current Condition:	Good Condition- Vacant lot in the commercial area. A few areas of the R.O.W. needs to be seeded. Developer Mike Huber was informed to seed areas by 9/3/09. Maintenance not completed as of last inspection, but due to the recent rains another seven days is given to complete maintenance until 9/10/09. On 3/12/10 Developer Mike Huber was reminded that maintenance needs to be completed once seeding season begins. Maintenance not completed as of last inspection.						
Commercial Area- Lot 5	Misc/Other	Commercial Area- Lot 5	5/4/2010	Active	Yes		

Current Condition:	No BMP installed on lot. Vacant lot in the commercial area.				
	A few areas of the R.O.W.	needs to be seed	led.		
	Developer Mike Huber was inspection, but due to the	recent rains anoth	er seven days is	given to complet	e maintenance until
	9/10/09. On 3/12/10 Devel once seeding season begi				
Commercial Area- Lot 6	Silt Fence/Other	Commercial Area- Lot 6	5/4/2010	Active	Yes
Current Condition:	Good Condition- Silt fence	installed around a	area inlet on lot.	Vacant lot in the	commercial area.
	A few areas of the R.O.W. Developer Mike Huber was). Maintananca na	nt completed as of last
	inspection, but due to the 9/10/09. On 3/12/10 Devel	recent rains anoth	er seven days is	given to complet	e maintenance until
	once seeding season begi	ns. Maintenance r	not completed as	of last inspection	n.
0	1111 1011	Commercial	51410513		
Commercial Area- Lot 7 Current Condition:	Misc/Other No BMP installed on lot. V	Area- Lot 7	5/4/2010	Active	Yes
current condition.	A few areas of the R.O.W.				
	Developer Mike Huber was informed to seed areas by 9/3/09. Maintenance not completed as of last inspection, but due to the recent rains another seven days is given to complete maintenance until 9/10/09. On 3/12/10 Developer Mike Huber was reminded that maintenance needs to be completed once seeding season begins. Maintenance not completed as of last inspection.				
		Commercial			
Commercial Area- Lot 8	Silt Fence/Other	Area- Lot 8	<u> </u>	Removed	
Current Condition:	Lot has First National Ban	1	is sodded.		
Commercial Area- Lot 9	Misc/Other	Commercial Area- Lot 9	5/4/2010	Active	Yes
Current Condition:	No BMP installed on lot. V			Houve	100
	A few areas of the R.O.W. needs to be seeded.				
	Developer Mike Huber was informed to seed areas by 9/3/09. Maintenance not completed as of last inspection, but due to the recent rains another seven days is given to complete maintenance until 9/10/09. On 3/12/10 Developer Mike Huber was reminded that maintenance needs to be completed				
	once seeding season begins. Maintenance not completed as of last inspection.				
		Commercial			
Commercial Area- Lot 10	Misc/Other	Area- Lot 10	5/4/2010	Active	Yes
Current Condition:	No BMP installed on lot. Vacant lot in the commercial area. A few areas of the R.O.W. needs to be seeded.				
	Developer Mike Huber was informed to seed areas by 9/3/09. Maintenance not completed as of last inspection, but due to the recent rains another seven days is given to complete maintenance until 9/10/09. On 3/12/10 Developer Mike Huber was reminded that maintenance needs to be completed once seeding season begins. Maintenance not completed as of last inspection.				
0	0:14.5	Commercial	5/4/55/5	0	
Commercial Area- Lot 11 Current Condition:	Silt Fence/Other	Area- Lot 11	5/4/2010	Active	Yes
Current Condition.	No BMP installed on lot. Vacant lot in the commercial area. A few areas of the R.O.W. needs to be seeded.				
	Developer Mike Huber was inspection, but due to the 9/10/09. On 3/12/10 Devel	recent rains anoth loper Mike Huber v	er seven days is was reminded th	given to complet at maintenance n	re maintenance until leeds to be completed
	once seeding season begi	ns. Maintenance r	ior completed as	or last inspection	l.

POD A	Silt Fence	Lots 37-50	5/4/2010	Active	No		
Current Condition:	Good Condition-						
POD B	Silt Fence	Lots 63-73	5/4/2010	Active	Yes		
Current Condition:	Active home construction on varies lots. Some lots have been sodded already.						
	1) A few areas of lot level silt fence and gator guard is damaged and/or full in the home						
	construction area and needs to be repaired. A few areas needs silt fence needs to be installed. 2) As of inspection on 4/23/10 a few areas of lot level silt fence is down/damaged in the home construction area and needs to be retied/repaired, replaced if needed.						
	3) In the active home construction area there is one portable toilet that needed to be moved from on top of a curb inlet and secured down. One needs to be removed from the pavement and secured						
	down.						
	1) Mert w/ Hearthstone Prod	duction was infor	mad to complete	maintananaa hu	, 4/1.4/10		
	Maintenance was completed			•			
	2) Mert w/ Hearthstone Prod						
	3) Mert w/ Hearthstone Prod	duction was infor	med to complete	maintenance by	<i>t</i> 5/1/10.		
POD C	Silt Fence	Lots 97-122	5/4/2010	Active	Yes		
Current Condition:	Fair Condition-						
	As of inspection on 4/23/10	a few areas of lo	ot level silt fence	is down/damage	d in the home		
	construction area and need						
	installed.						
	Mert w/ Hearthstone Produc	ction was informe	ad to complete m	aintenance by 5/	/1/10		
	West w/ Ficartifistorie F Todac	I		anticharice by 5/	1,710.		
POD D	Silt Fence	Lots 123-162	5/4/2010	Active	Yes		
Current Condition:	Good Condition-						
	Maintenance was completed prior to inspection on 4/23/10 by Mert w/ Hearthstone Production. As of inspection on 4/23/10 a few areas of lot level silt fence is down/damaged in the home.						
	As of inspection on 4/23/10 a few areas of lot level silt fence is down/damaged in the home construction area and needs to be retied/repaired, replaced if needed. A few areas needs silt fence						
	installed.						
	Mert w/ Hearthstone Production was informed to complete maintenance by 5/1/10.						
	Mert w/ Hearthstone Produc	tion was informe I	ea to complete m	aintenance by 5/	/1/10. I		
POD E	Silt Fence	Lots 163-199	5/4/2010	Active	Yes		
Current Condition:	Fair Condition-	<u> </u>	3/4/2010	Active	103		
	Construction debris on emp	ty lot 173 needs	to be cleaned up				
	Mert w/ Hearthstone Produc	ction was informe	ed to complete m	aintenance by 4/	/14/10. Maintenance		
	not completed as of last ins						
		N41d00m00s					
SB E	Sediment Basin	W96d00m00s		Removed	D 11 D 5		
Current Condition:	Basin was removed due to I	ot aevelopment	prior to inspection	n on 6/12/08 by	Double D Excavating.		
		N41d00m00s					
SB F	Sediment Basin	W96d00m00s	07/01/05	Active	No		
Current Condition:	Good Condition- 20% Filled						
	Cleaned out 7/2008 by Bob Roth Baffle maintenance was completed prior to inspection on 6/6/09 by Mike Stafford.						
		N41d00m00s					
SB G	Sediment Basin	W96d00m00s	08/26/05	Active	No		
Current Condition:	Good Condition- 18% Filled						
	-Cleaned 5/2007 by Dave Hausman & riser was repaired prior to inspection on 9/9/08.						
	_	N41d00m00s		_			
SF A	Silt Fence	W96d00m00s	07/19/05	Removed			

Current Condition:	Removed					
		N41d00m00s				
SF B	Silt Fence	W96d00m00s		Removed		
Current Condition:	Removed - Not needed due to established vegetative cover in area.					
		N41d00m00s				
SF C	Silt Fence	W96d00m00s	07/01/05	Active	No	
Current Condition:	Good Condition- Partially re	moved due to de	veloped lots and	good vegetation	in out lots.	
	Maintenance was complete	d prior to inspect	on on 3/9/09 by	Tim Geis.		
		N41d00m00s				
ST A	Silt Trap	W96d00m00s		Removed		
Current Condition:	Trap Closed June 2006.					
		N41d14m44s				
STR	Streets	W96d12m59s	8/10/2007	Active	Yes	
Current Condition:	Fair Condition					
	Some minor signs of track off in the home construction area and it needs to be cleaned up.					
	Tim Geis was informed to cleaned streets by 4/24/10.					
		Two signs on				
SWPPP Sign	SWPPP Sign	site	3/28/2008	Active	No	
Current Condition:	Good Condition					
	On 3/28/08 a SWPPP sign was installed at 164th & Giles and 168th & Meridian St. entrance.					
Inspector Signature:	1 Jawlen			Reviewed By:	Zachany L. Jilek	