E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Matthew Vanicek					Stage			
mepeotor matthew valueout		Meridia	n Dark		Clayo			
					3			
Project Name:		NER1 ²	10696					
For Week Ending:		11/14	/2020					
	169	69436						
Project Location:	100	a Glies Street- Oli	aha, NE (Sarpy County)		68136			
Grading:	100%	4						
Sanitary Sewer:	1009							
Storm Sewer:	1007							
Paving:	1007							
Seeding:	1009							
Jtilities:	1009							
Overall Development:	919							
		•1		- 1 1				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time				
		·			Weel			
Sunday:	0.00"							
Nonday	0.34"							
uesday	0.00"							
Wednesday	0.00"							
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
					Weel			
Sunday:	0.01"							
Monday	0.01"							
Tuesday	0.00"							
Vednesday	0.00"							
Thursday	0.03"							
Friday	0.02"							
Saturday	0.00"							
					Weel			
Sunday:	0.01"							
Monday	0.02"							
Tuesday	0.00"							
Wednesday	0.00"							
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
					Weel			
Sunday:	0.00"							
Monday	0.00"							
Fuesday	0.00"							
Nednesday	0.00"							
Thursday	0.00"	11/5/2020	Clear 76/40	1:30 PM				
Friday	0.00"							
Saturday	0.00"							
Sunday	0.00"				Weel			
Sunday:	0.00"							
Monday	0.00"	44/40/0000	25/07 Doir	42:45 DM				
Fuesday Nednesday	1.07" 0.06"	11/10/2020	35/27 Rain	12:15 PM				
	0.00"							
Гhursday ⁻ riday	0.00"			+				
-riday Saturday	0.00"	+						
Jaturuay	10.00	-	I					
	None							
Complaints:								
pianitoi	—							
Demotrantian On manualization		1	1					
Construction Sequencing:								

0/5/11 by Double D.	l site seeded Summer/Fall 2005. E	Entire Site, grading was co	mpleted in Replat Three ar	ea Lots 1-54 prior t	to inspection on
What temporary or permanent stabiliza	tion measures listed in this section are				
	tabilized entrances installed Sumn led was re-seeded (4/2009); Sedir ded (4/2012)				
Checklist Questions:					
Yes	e project free of any significant sig	ns of erosion or sediment	that would be associated w	ith the construction	n activity?
Create Corrective Action?					
N/A					
Have disturbed areas been seeded prevent erosion.	or otherwise stabilized as required	1? List inactive portions of	the project and if stabilizati	on measures are a	dequate or needed to
Yes					
Create Corrective Action?					
N/A					
Anno 111 and a start of the formation of the	and the second state of the second state of the) haten market at the			
Are waste materials (concrete, con Yes	struction material, hazardous, etc.)) being managed properly?			
Create Corrective Action?					
N/A					
Are construction entrances and ad	jacent streets being maintained ad	equately?			
Yes					
Create Corrective Action?					
N/A					
Is dust associated with the constru Yes	ction activity adequately controlled	d on the site?			
is dust associated with the constru Yes Create Corrective Action?		a on the site?			
Yes	ction activity adequately controlled	a on the site?			
Yes <mark>Create Corrective Action?</mark> N/A		a on the site /			
Yes Create Corrective Action? N/A Comments:		a on the site /			
Yes Create Corrective Action? N/A Comments: Comments:	the last inspection. Inspector will c		vity on the undeveloped po	rtion of the site.	
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D	the last inspection. Inspector will o		vity on the undeveloped po	rtion of the site.	
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D	the last inspection. Inspector will o ate): ate):		vity on the undeveloped por	rtion of the site.	
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D	the last inspection. Inspector will o ate): ate):		vity on the undeveloped po	rtion of the site.	
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D	the last inspection. Inspector will o ate): ate): the BMP section.		vity on the undeveloped por	rtion of the site.	Maintenance
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4	the last inspection. Inspector will o ate): ate): the BMP section. Type Concrete Washout Pit	continue to monitor for acti	Projected Install Date		Maintenance
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name	the last inspection. Inspector will o ate): ate): the BMP section.	Continue to monitor for acti	Projected Install Date	Status	Maintenance
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4	the last inspection. Inspector will o ate): ate): the BMP section. Type Concrete Washout Pit	continue to monitor for acti	Projected Install Date	Status	Maintenance
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4 Current Condition:	the last inspection. Inspector will o ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was	Continue to monitor for acting to the second	Projected Install Date 15 by Celebrity Homes. 08/26/05	Status Removed	No
Yes Create Corrective Action? N/A Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in ' Unique Name CW 4 Current Condition: SB G Current Condition:	the last inspection. Inspector will o ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10.	Continue to monitor for acti Location Lot 2 removed prior to 11/18/20 Lot 9 Meridian Marketplace . The basin was partially c North of Replat three	Projected Install Date 15 by Celebrity Homes. 08/26/05	Status Removed Active as repaired by Bob	No
Yes Create Corrective Action? N/A Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4 Current Condition: SB G Current Condition:	the last inspection. Inspector will o ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10. Sediment Trap	Continue to monitor for acti Location Lot 2 removed prior to 11/18/20 Lot 9 Meridian Marketplace The basin was partially c North of Replat three Lots 1 and 2	Projected Install Date 115 by Celebrity Homes. 08/26/05 leaned out and the baffle w	Status Removed	No
Yes Create Corrective Action? N/A Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in ' Unique Name CW 4 Current Condition: SB G Current Condition:	the last inspection. Inspector will o ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10.	Continue to monitor for acti Location Lot 2 removed prior to 11/18/20 Lot 9 Meridian Marketplace . The basin was partially c North of Replat three Lots 1 and 2 ted to post construction po	Projected Install Date 115 by Celebrity Homes. 08/26/05 leaned out and the baffle w	Status Removed Active as repaired by Bob	No
Yes Create Corrective Action? N/A Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4 Current Condition: SB G Current Condition:	the last inspection. Inspector will o ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10. Sediment Trap	Continue to monitor for acti Location Lot 2 removed prior to 11/18/20 Lot 9 Meridian Marketplace The basin was partially c North of Replat three Lots 1 and 2	Projected Install Date 115 by Celebrity Homes. 08/26/05 leaned out and the baffle w	Status Removed Active as repaired by Bob	No
Yes Create Corrective Action? N/A Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D Findings / Corrective Actions (D Corrective Actions (D Corrective Actions (D Corrective Actions (D Corrective Actions (D SI 1 Current Condition: ST 1 Current Condition:	the last inspection. Inspector will o ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10. Sediment Trap Removed - Trap was conver Sediment Trap Removed - Removed by Cel	Continue to monitor for acting to the format of the format	Projected Install Date 115 by Celebrity Homes. 08/26/05 leaned out and the baffle w ond prior to 4/21/2016.	Status Removed Active as repaired by Bob Removed	No Roth prior to the
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4 Current Condition: SB G Current Condition: ST 1 Current Condition: ST 2	the last inspection. Inspector will o ate): ate): the BMP section. Concrete Washout Pit Removed - Washout Pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10. Sediment Trap Removed - Trap was conver Sediment Trap	Continue to monitor for acting the second se	Projected Install Date 115 by Celebrity Homes. 08/26/05 leaned out and the baffle w ond prior to 4/21/2016.	Status Removed Active as repaired by Bob Removed	No Roth prior to the
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4 Current Condition: SB G Current Condition: ST 1 Current Condition: ST 2	the last inspection. Inspector will o ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10. Sediment Trap Removed - Trap was conver Sediment Trap Removed - Removed by Cel	Continue to monitor for acting to the format of the format	Projected Install Date 115 by Celebrity Homes. 08/26/05 leaned out and the baffle w ond prior to 4/21/2016.	Status Removed Active as repaired by Bob Removed	No Roth prior to the
Yes Create Corrective Action? N/A Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4 Current Condition: SB G Current Condition: ST 1 Current Condition: ST 2 Current Condition:	the last inspection. Inspector will o ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10. Sediment Trap Removed - Trap was conver Sediment Trap Removed - Removed by Cel construction feature at a late	Continue to monitor for acti Location Lot 2 removed prior to 11/18/20 Lot 9 Meridian Marketplace The basin was partially c North of Replat three Lots 1 and 2 ted to post construction po Southeast corner of Replat three lot 1 lebrity Homes prior to 12/1 r time. Between Replat three Lots 26 and 27 ted to post construction po	Projected Install Date 115 by Celebrity Homes. 08/26/05 leaned out and the baffle w ond prior to 4/21/2016. 4/2015 for construction on l	Status Removed Active as repaired by Bob Removed Removed ot. Will be conver	No Roth prior to the
Yes Create Corrective Action? N/A Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4 Current Condition: SB G Current Condition: ST 1 Current Condition: ST 2 Current Condition: ST 4 Current Condition:	the last inspection. Inspector will c ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10. Sediment Trap Removed - Trap was conver Sediment Trap Removed - Removed by Cel construction feature at a late Sediment Trap Removed - Trap was conver	Continue to monitor for acti Location Lot 2 removed prior to 11/18/20 Lot 9 Meridian Marketplace The basin was partially c North of Replat three Lots 1 and 2 ted to post construction po Southeast corner of Replat three lot 1 lebrity Homes prior to 12/1 r time. Between Replat three Lots 26 and 27 ted to post construction po N41014m44s	Projected Install Date 15 by Celebrity Homes. 08/26/05 eaned out and the baffle w and prior to 4/21/2016. 4/2015 for construction on I	Status Removed Active as repaired by Bob Removed Removed Removed Removed Removed Removed	No P Roth prior to the ted to post
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4 Current Condition: SB G Current Condition: ST 1 Current Condition: ST 2 Current Condition: ST 4 Current Condition: ST 4 Current Condition:	the last inspection. Inspector will o ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10. Sediment Trap Removed - Trap was conver Sediment Trap Removed - Removed by Cel construction feature at a late Sediment Trap Removed - Trap was conver Sediment Trap Removed - Trap was conver Streets	Continue to monitor for acting to the format of the format	Projected Install Date 15 by Celebrity Homes. 08/26/05 leaned out and the baffle w ond prior to 4/21/2016. 4/2015 for construction on I ond prior to 4/21/2016. 8/10/2007	Status Removed Active as repaired by Bob Removed Removed ot. Will be conver Removed Active	No Roth prior to the
Yes Create Corrective Action? N/A Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4 Current Condition: SB G Current Condition: ST 1 Current Condition: ST 2 Current Condition: ST 4 Current Condition:	the last inspection. Inspector will c ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10. Sediment Trap Removed - Trap was conver Sediment Trap Removed - Removed by Cel construction feature at a late Sediment Trap Removed - Trap was conver	Continue to monitor for acting to the format of the format	Projected Install Date 15 by Celebrity Homes. 08/26/05 leaned out and the baffle w ond prior to 4/21/2016. 4/2015 for construction on I ond prior to 4/21/2016. 8/10/2007	Status Removed Active as repaired by Bob Removed Removed ot. Will be conver Removed Active	No P Roth prior to the ted to post
Yes Create Corrective Action? N/A Comments: Comments: No construction was active during Findings / Corrective Actions (D Findings / Corrective Actions (D 1.) No maintenance is required in Unique Name CW 4 Current Condition: SB G Current Condition: ST 1 Current Condition: ST 2 Current Condition: ST 4 Current Condition: ST 4 Current Condition:	the last inspection. Inspector will o ate): ate): the BMP section. Concrete Washout Pit Removed - Washout pit was Sediment Basin Good Condition - 25% Filled inspection on 10/12/10. Sediment Trap Removed - Trap was conver Sediment Trap Removed - Removed by Cel construction feature at a late Sediment Trap Removed - Trap was conver Sediment Trap Removed - Trap was conver Streets	Continue to monitor for action Lot 2 Temoved prior to 11/18/20 Lot 9 Meridian Marketplace The basin was partially c North of Replat three Lots 1 and 2 ted to post construction pc Southeast corner of Replat three lot 1 lebrity Homes prior to 12/1 r time. Between Replat three Lots 26 and 27 ted to post construction pc N41014m44s W96d12m59s Homes street cleaned the s S 168th and Meridian St.	Projected Install Date 115 by Celebrity Homes. 08/26/05 leaned out and the baffle w 115 by Celebrity Homes. 115 by Celebrity H	Status Removed Active as repaired by Bot Removed Removed Removed Active Status Removed Active Active Active Active Status Active 95/12/2016. Pending	No PRoth prior to the ted to post

Puttes Carm Inspector Signature:

Reviewed By: