E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

		E&A - P2021.32	21.000		
Inspector: Bryce Wright		20,7 1 2021102			Stage
Project Name:		1			
For Week Ending:					
Project Location:	Southwest corner of Ker	68007			
Grading:	80%	I	T		
Sanitary Sewer:	0%				
Storm Sewer:	0%				
Paving:	0%				
Seeding:	5%				
Utilities:	0%				
Overall Development:	10%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
	0.400				Week
Sunday: Monday	0.46" 0.27"				
Tuesday	0.56"	11/5/2024	Overcast 48	2:30 PM	
Wednesday	0.00"	11/0/2024	Over cust 40	2.001111	
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading the site (4/18/24). Grading has not started in the SW drainage basin (6/7/2024). Grubbing on southeast area of the site (7/11/24). Grading the remainder of the site began (8/13/24).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading the site (4/18/24). Grading has not started in the SW drainage basin (6/7/2024). Grubbing on southeast area of the site (7/11/24). Grading the remainder of the site began (8/13/24).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (4/18/24). Seeding and matting on the east side of the site (7/11/24).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes Create C

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

No, See BMP section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No, See BMP section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action

N/A

Comments:
Comments:
The site was active during the most recent inspection.

Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
1.) Some maintenance is needed in the BMP section.

CE 4	Туре	Location	Projected Install Date	Status	Maintenan	
CE 1	Construction Entrance	West edge of site	9/24/2024	Pending	Yes	
Current Condition:	Pending -					
	A rocked construction entrer	ce should be installed	where the site is being acce	ssed		
	A rocked construction entrance should be installed where the site is being accessed.					
	Ruff Grading was informed to	complete by 9/24/24.	Not done as of the last insp	ection. Ruff Gradin	ng was reminded on	
	10/29/24, 11/7/24	, ,	· ·		ŭ	
Berm #1	Diversion Berm	North of SB A	6/7/2024	Active	No	
Current Condition:	Good Condition- An Improve	d diversion berm was i	nstalled to the north of SB A	to control runoff to	owards 156th Street	
	Grading as of 6/7/2024.					
D 1	Diversion	SB E	4/18/2024	Active	No	
Current Condition:	Good Condition - Ruff Gradin					
	diversion for grading prior to	•	0.		on prior to the inspe	
	9/24/24. Ruff Grading finishe		· · · · · · · · · · · · · · · · · · ·			
D 2	Diversion	SB F	4/18/2024	Pending	Yes	
Current Condition:	Pending -					
	Diversion should be installed	 				
	Diversion should be installed	•				
	Ruff Grading was informed to	complete by 5/2/24. N	Not done as of last inspection	n. Ruff Grading wa	s reminded on 5/24	
	6/13/24, 7/12/24, 8/7/24, 8/1	5/24, 9/18/24, 10/29/24	, 11/7/24	ŭ		
D 3	Diversion	SB F	4/18/2024	Pending	Yes	
Current Condition:	Pending -					
	Diversion should be installed					
	Ruff Grading was informed to	o complete by 5/2/2/1 N	lot done as of last inspection	n Buff Grading wa	s reminded on 5/2/	
	6/13/24, 7/12/24, 8/7/24, 8/1			ii. Ruii Olauliig wa	3 Terrifficed Off 3/24	
EM 1	Erosion Matting	See SWPPP	7/11/2024	Active	No	
Current Condition:	Good Condition - Ruff Gradin					
Current Condition.	erosion control matting prior	•	01	77 172 1 mopodion.	. I tall Grading rollio	
EM 2		See SWPPP	4/18/2024	Pending	Yes	
Current Condition:	Erosion Matting Pending -	000 011111	1/10/2021	relialing	163	
	. Silaling					
	Erosion matting should be in	stalled when work is co	omplete in the area.			
	_					
	Ruff Grading was informed to	complete by 11/5/24.	Not done as of the last ins	spection. Ruff Gra	iding was reminde	
	11/7/24					
EM 3	Erosion Matting	See SWPPP	4/18/2024	Pending	Yes	
Current Condition:	Pending -					
	Erosion matting should be installed when work is complete in the area.					
	I rosion matting should be in	stalled when work is co				
	Erosion matting should be in	stalled when work is co	omplete in the area.			
	Ruff Grading was informed to		·	spection. Ruff Gra	ading was reminde	
			·	spection. Ruff Gra	ading was reminde	
EM 4	Ruff Grading was informed to		·	Spection. Ruff Gra	ading was reminde	
EM 4 Current Condition:	Ruff Grading was informed to	complete by 11/5/24.	Not done as of the last ins	<u> </u>		
	Ruff Grading was informed to 11/7/24 Erosion Matting Pending -	See SWPPP	Not done as of the last ins	<u> </u>		
	Ruff Grading was informed to 11/7/24 Erosion Matting	See SWPPP	Not done as of the last ins	<u> </u>		
	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in	See SWPPP	Not done as of the last ins 4/18/2024 complete in the area.	Pending	Yes	
	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to	See SWPPP	Not done as of the last ins 4/18/2024 complete in the area.	Pending	Yes	
Current Condition:	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to	See SWPPP stalled when work is co	Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins	Pending Spection. Ruff Gra	Yes	
Current Condition: EM 5	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Matting	See SWPPP	Not done as of the last ins 4/18/2024 complete in the area.	Pending	Yes	
Current Condition:	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to	See SWPPP stalled when work is co	Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins	Pending Spection. Ruff Gra	Yes	
Current Condition: EM 5	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Matting	See SWPPP stalled when work is co complete by 11/5/24. See SWPPP	Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins 4/18/2024	Pending Spection. Ruff Gra	Yes	
Current Condition: EM 5	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Matting Pending -	See SWPPP stalled when work is co complete by 11/5/24. See SWPPP	Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins 4/18/2024	Pending Spection. Ruff Gra	Yes	
Current Condition: EM 5	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Matting Pending -	See SWPPP stalled when work is co complete by 11/5/24. See SWPPP stalled when work is co	Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins 4/18/2024 complete in the area.	Pending Spection. Ruff Gra Pending	Yes ading was reminded	
Current Condition: EM 5	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24	See SWPPP stalled when work is co complete by 11/5/24. See SWPPP stalled when work is co complete by 11/5/24.	Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins	Pending Spection. Ruff Gra Pending	Yes ading was reminded	
EM 5 Current Condition:	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Control Terrace	See SWPPP stalled when work is co complete by 11/5/24. See SWPPP stalled when work is co	Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins 4/18/2024 complete in the area.	Pending Spection. Ruff Gra Pending	Yes ading was reminded	
Current Condition: EM 5 Current Condition:	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24	See SWPPP stalled when work is co complete by 11/5/24. See SWPPP stalled when work is co complete by 11/5/24.	Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins	Pending spection. Ruff Gra Pending spection. Ruff Gra	Yes Ading was reminded Yes Adding was reminded	
EM 5 Current Condition:	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Control Terrace Pending -	See SWPPP stalled when work is co complete by 11/5/24. See SWPPP stalled when work is co complete by 11/5/24. See SWPPP stalled when work is co complete by 11/5/24.	Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins	Pending spection. Ruff Gra Pending spection. Ruff Gra	Yes Ading was reminded Yes Adding was reminded	
EM 5 Current Condition:	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Control Terrace	See SWPPP stalled when work is co complete by 11/5/24. See SWPPP stalled when work is co complete by 11/5/24. See SWPPP stalled when work is co complete by 11/5/24.	Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins	Pending spection. Ruff Gra Pending spection. Ruff Gra	Yes Ading was reminded Yes Adding was reminded	
EM 5 Current Condition:	Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Matting Pending - Erosion matting should be in Ruff Grading was informed to 11/7/24 Erosion Control Terrace Pending -	See SWPPP stalled when work is co complete by 11/5/24. See SWPPP stalled when work is co complete by 11/5/24. See SWPPP stalled when work is co complete by 11/5/24.	Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins 4/18/2024 complete in the area. Not done as of the last ins 4/18/2024	Pending Pending Pending Pending Pending Pending	Yes Ading was reminded Yes Adding was reminded	

ET 2	Erosion Control Terrace	See SWPPP	4/18/2024	Pending	Yes
Current Condition:	Pending -				
	Erosion Control Terrace should be installed.				
	Ruff Grading was informed to 6/13/24, 7/12/24, 8/7/24, 8/1			n. Ruff Grading wa	is reminded on 5/24/24,
	0/13/24, //12/24, 0/1/24, 0/1				
ET 3	Erosion Control Terrace	See SWPPP	4/18/2024	Pending	Yes
Current Condition:	Pending -				
	Erosion Control Terrace sho	uld be installed.			
	Ruff Grading was informed to 6/13/24, 7/12/24, 8/7/24, 8/7			n. Ruff Grading wa	is reminded on 5/24/24,
FT X	Fuel Tank	See SWPPP	4/18/2024	Active	No
Current Condition:					ding installed a berm around
	the fuel tank prior to the 4/25	•	• .		
	inspection. Ruff Grading cleat containment berm around the				
	berm around the fuel tank pr		•	Oracing installed a	3000many containment
PB X	Portable toilet	On site	7/11/2024	Active	No
Current Condition:					24 inspection. Ruff Grading
	installed and secured two me	ore portable toilets on s	ite prior to the inspection or	n 7/16/24.	
SB E	Sediment Basin	See SWPPP	4/18/2024	Pending	Yes
Current Condition:	Pending - Ruff Grading bega	n shaping the basin pri	or to the inspection on 8/2/	724.	
	Basin should be installed (ris	er and baffle).			
	· ·				
	Ruff Grading was informed to			n. Ruff Grading wa	s reminded on 5/24/24,
	6/13/24, 7/12/24, 8/7/24, 8/1				
SB F Current Condition:	Sediment Basin Pending - Ruff Grading bega	See SWPPP	4/18/2024	Pending	Yes
Current Condition:	Pending - Rull Grading bega	n snaping the basin pri	or to the inspection on 6/2/	124.	
	Basin should be installed (ris	er and baffle).			
	_ # _ !!			5 " 6 "	
	Ruff Grading was informed to 6/13/24, 7/12/24, 8/7/24, 8/1		the state of the s	on. Ruff Grading wa	is reminded on 5/24/24,
05.4					
SF 1 Current Condition:	Silt Fence Good Condition - Ruff Gradii	Eastern Perimeter	4/18/2024 e prior to the 4/18/24 inspe	Active	No extended the silt fence
	below EM 1 prior to the inspe		o pilot to tilo 1, 10,2 i iliopo	ouo rtan Oraanig	
		Southeastern	111010001		
SF 2	Silt Fence	Perimeter	4/18/2024	Active	Yes
Current Condition:	Fair Condition - Ruff Grading				
	silt fence to the west prior to	· ·	0 1		
	fence to the southern corner prior to the inspection on 8/27/24. Ruff Grading cleaned out, backfilled, and trenched in the silt fence in multiple locations prior to the inspection on 9/24/24. Ruff Grading installed additional silt fence checks prior to the				
	inspection on 10/8/24.				
	Silt fence checks should be cleaned out and repaired. Silt fence should be repaired on the northern end and all escaped sediment cleaned up.				
				ment cleaned up.	
	3.) Silt fence in the southeast corner of the site should be cleaned out.				
	1.) Ruff Grading was inform				
	2.) Ruff Grading was inform 3.) Ruff Grading was inform				
SF 3	Silt Fence	Western Perimeter	9/24/2024	Active	No
Current Condition:	Good Condition - Ruff Gradin	ng installed the silt fence			•
		Western Perimeter	9/24/2024		
SF 4	Silt Fence			Active	No
Current Condition:	Good Condition - Ruff Gradii		<u> </u>		
MS 1	Material Storage	On Site	4/18/2024	Active	No
Current Condition: WO 1	Good Condition - Storage an Concrete Washout	on Site	Grading by the old farmster 4/18/2024	Pending	as of 6///2024. No
Current Condition:	Pending - Concrete will be p		7/10/2024	i enumy	140
WS 1	Waste Storage	On Site	4/18/2024	Pending	No
Current Condition:	Pending - Waste will be store		•		
STR	Streets	N 156th Street	4/18/2024	Active	No
Current Condition:	Good Condition - The streets				Na
SWPPP Sign Current Condition:	SWPPP Notification Sign Good Condition - E&A inspe	On Site	5/11/2023 PP sign during the 6/13/24 in	Active nspection.	No
	Jaca damanon Larrinopo		g., aag alo o/ 10/24 li		

Certification Statement:	direction or supervision in ac properly gathered and evalua persons who manage the sys the information submitted is,	v, that this document and all attachments were pre cordance with a system designed to assure that qualed the information submitted. Based on my inquistem or those persons directly responsible for gath to the best of my knowledge and belief, true, accuificant penalties for submitting false information incoming violations."	ualified personnel ry of the person or ering the information, rate, and complete. I
Inspector Signature:	Broga M Zlaght		Reviewed By: