E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A Jilek CPESC CISEC

Comments:

| Zachary A. Jilek, CPESC, CISE Environmental Services Dept. | | | En | gineering Answer | 5 | |
|---|--|---------------------------------|-----------------------------------|----------------------------|-------------------------|--|
| | T | E&A - P2021.32 | 1.000 | | Stage | |
| Inspector: Bryce Wright | | Morgan Ridge CSW-202207264 | | | | |
| Project Name: | | | | | | |
| For Week Ending: | Southwest corner of K | 10/19/ Sempten Creek Drive a | nd 156th Street - Benning | nton, NE (Douglas | | |
| Project Location: | | 68007 | | | | |
| Grading: | 95 | :0/ | | | | |
| Sanitary Sewer: | 100 | | | | | |
| Storm Sewer: | | 0% | | | | |
| Paving: | | 0% | | | | |
| Seeding: | 50 |)% | | | | |
| Utilities: | C |)% | | | | |
| Overall Development: | 5 | 5% | | | | |
| RAIN FALL AMOUNTS | Amount in tenths | Date inspected | Weather Conditions | Time | | |
| | | · | | | Wee | |
| Sunday: | 0.00" | | | | | |
| Monday Tuesday | 0.00" | 10/15/2024 | Sunny 48 | 10:40 AM | | |
| Wednesday | 0.00" | 10/15/2024 | Sunny 40 | IU.4U AIVI | | |
| Thursday | 0.00" | | | | | |
| Friday | 0.00" | | | | | |
| Saturday | 0.00" | | | | | |
| Complaints: Construction Sequencing: | | | | | | |
| Which portion(s) (i.e. drainage 14 days? | basins) of the site have had a | temporary or permane | nt cessation of grading, | earthwork, or ground | disturbance in the last | |
| Grading the site (4/20/23). Sanit | | | | | | |
| | basins) of the site do not have | grading, earthwork, o | r ground disturbance sc | heduled in the next 14 | l days? | |
| Grading the site (4/20/23). Sanit | , , | | | | | |
| | stabilization measures listed i | | | | | |
| Existing vegetation (4/20/23). No | orthwestern area seeded (7/27/23 | 3). Southern area seede | d (8/17/23). | | | |
| Checklist Questions: | | | | | | |
| Are receiving waters adjacent to the pr | roject free of any significant signs of er | osion or sediment that would | be associated with the constru | ection activity? | | |
| Yes Create Corrective Action? | | | | | | |
| N/A | | | | | | |
| | | | | | | |
| Have disturbed areas been seeded or o | otherwise stabilized as required? List in | active portions of the project | t and if stabilization measure ar | e adequate or needed to pr | event erosion. | |
| Create Corrective Action? N/A | | | | | | |
| | nation material hazardena eta \ halian | agnaged properly? | | | | |
| Are waste materials (concrete, constru Yes | uction material, hazardous, etc.) being n | пападец ргорегіу? | | | | |
| Create Corrective Action? | | | | | | |
| N/A | | | | | | |
| | ent streets being maintained adequately | ? | | | | |
| No Create Corrective Action? | | | | | | |
| No, See BMP section. | | | | | | |
| | | | | | | |
| s dust associated with the construction Yes | on activity adequately controlled on the | site? | | | | |
| Create Corrective Action? | | | | | | |
| N/A | | | | | | |

Comments:
The site was active during the most recent inspection.

Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
Some maintenance is needed in the BMP section.

| Unique Name | Туре | Location | Projected Install Date | Status | Maintenance | |
|--------------------|--|-----------------------------|---|----------------------|-----------------------------|--|
| CE 1 | Construction Entrance | 00-23 | 4/20/2023 | Active | Yes | |
| Current Condition: | Fair Condition - 10% Effective | • | | · · | | |
| | added more rock to the cons | | | onstruction entrand | ce was moved to the | |
| | Benjamin Street stub road pr | ior to the inspection on | 8/20/24. | | | |
| | | | | | | |
| | Construction entrance should have more rock added and be lengthened. | | | | | |
| | | | | | | |
| | Ruff Grading and Hubbell Ho | | | | | |
| | Hubbell Homes were remind | | 23, 3/15/24, 5/24/24, 6/13/2 ₄ | 4, 7/12/24, 7/17/24 | K2 Construction was | |
| | reminded on 8/22/24, 10/2/24 | 4 | | | | |
| D 1 | Diversion | BB-4 | 6/29/2023 | Active | No | |
| Current Condition: | Good Condition - Ruff Gradin | | | | 110 | |
| D 2 | Diversion | R-5 to Z-4 | 7/27/2023 | Active | Yes | |
| Current Condition: | Fair Condition - Ruff Grading | | | | | |
| Current Condition: | inspection on 7/23/24. | installed the diversion | prior to the 7/27/23 inspecti | on. Rololi repaired | the diversion prior to the | |
| | inspection on 7/23/24. | | | | | |
| | Francisco villa abaculal ba vancio | a al | | | | |
| | Erosion rills should be repair | ea. | | | | |
| | Duff Crading and Hubball Ha | mana uzawa imfarmanal ta a | ammiliate by 11/16/22 Net a | lana aa af laat inan | nation Daloff was informed | |
| | Ruff Grading and Hubbell Ho | | | | | |
| | to complete by 6/20/24. Hubb reminded on 8/22/24, 10/2/24 | | s reminued on 7/17/24. Hu | bbell nomes and K | az Construction was | |
| | | | | | | |
| D 3 | Diversion | R-5 to S-4 | | Removed | | |
| Current Condition: | Removed - Diversion no long | ger needed as of the 11 | 16/23 inspection. | | | |
| D 4 | Diversion | I-9 to R-3 | 8/10/2023 | Active | Yes | |
| Current Condition: | Fair Condition - Ruff Grading | installed the diversion | prior to the 8/10/23 inspecti | on. Ruff Grading re | | |
| | to the 11/9/23 inspection. Ro | loff repaired the diversion | on prior to the inspection or | n 7/23/24. | | |
| | | ' | | | | |
| | Erosion rills should be repair | ed. | | | | |
| | | | | | | |
| | Ruff Grading and Hubbell Ho | mes were informed to d | complete by 11/16/23. Not o | done as of last insp | ection. Ruff Grading and | |
| | Hubbell Homes were remind | | | | | |
| | reminded on 7/17/24. Hubbe | | | | | |
| D 5 | Diversion | I-8 to E-8 | | Removed | | |
| Current Condition: | Removed - Ruff Grading rem | | ng grading of Phase II prior | | pection Reinstallation not | |
| Curront Condition. | recommended. | iovoa ino arvoroion aan | ig grading or r ridge it prior | 10 110 0/11/21 110 | oction. I tomotanation not | |
| | | | | | | |
| D 6 | Diversion | C-8 to D-8 | | Removed | | |
| Current Condition: | Removed - Ruff Grading rem | loved the diversion duri | ng grading of Phase II prior | to the 9/17/24 insp | pection. Reinstallation not | |
| | recommended. | | | | | |
| D 7 | Diversion | BB-11 to BB-12 | 9/21/2023 | Active | Yes | |
| Current Condition: | Fair Condition - Ruff Grading | | | | res | |
| Current Condition. | rail Condition - Run Grading | installed the diversion | prior to the 9/2 1/23 inspecti | OH. | | |
| | Diversion should be re-define | od | | | | |
| | Diversion should be re-define | eu. | | | | |
| | Puff Crading and Hubball Hamas ware informed to complete by 40/08/09. Not done on filest incoming the file | | | | | |
| | Ruff Grading and Hubbell Homes were informed to complete by 10/26/23. Not done as of last inspection. Ruff Grading and Hubbell Homes were reminded on 11/10/23, 3/15/24, 5/24/24, 6/13/24, 7/17/24. Hubbell Homes and K2 Construction was | | | | | |
| | reminded on 8/22/24, 10/2/24 | | , 3/24/24, 0/13/24, 7/17/24 | . Hubbell Hollies a | nd R2 Construction was | |
| | | | | | | |
| D 8 | Diversion | BB-18 to BB-20 | 9/21/2023 | Active | No | |
| Current Condition: | Good Condition - Ruff Gradin | | | ction. | | |
| D 9 | Diversion | NN-23 | 4/25/2024 | Active | No | |
| Current Condition: | Good Condition - Ruff Gradin | ng installed the diversion | n prior to the 4/25/24 inspec | ction. | | |
| D 10 | Diversion | AA-33 | | Removed | | |
| Current Condition: | Removed - Ruff Grading rem | | ng grading of Phase II prior | | pection. Reinstallation not | |
| | recommended. | | 23 3 p.101 | | | |
| D 11 | | 0.40 +- 11.40 | <u> </u> | D ' | | |
| D 11 | Diversion | G-13 to H-13 | | Removed | Deinst " " | |
| Current Condition: | Removed - Ruff Grading rem | loved the diversion duri | ng grading of Phase II prior | to the 9/1//24 insp | pection. Reinstallation not | |
| | recommended. | | | | | |
| D 12 | Diversion | K-14 to H-14 | | Removed | | |
| Current Condition: | Removed - Ruff Grading rem | oved the diversion duri | ng grading of Phase II prior | | ection. Reinstallation not | |
| | recommended. | | 55 5 F | | | |
| | | 0 0:::=== | 4/00/005- | | | |
| EM 1 | Erosion Matting | See SWPPP | 4/20/2023 | Pending | No | |
| Current Condition: | Pending - BMP will be install | | nds in the area. E&A inspec | tor will monitor. | | |
| EM 2 | Erosion Matting | See SWPPP | 4/20/2023 | Pending | No | |
| Current Condition: | Pending - BMP will be installed | ed when work begins/er | nds in the area. E&A inspec | tor will monitor. | | |
| EM 3 | Erosion Matting | See SWPPP | | Removed | | |
| Current Condition: | Removed - Ruff Grading rem | | ı ıl matting during grading of | | e inspection on 9/17/24 | |
| | <u> </u> | | | <u>_</u> | | |
| EM 4 | Erosion Matting | See SWPPP | 4/20/2023 | Pending | No | |
| Current Condition: | Pending - BMP will be install | ed when work begins/er | nds in the area. E&A inspec | tor will monitor. | | |
| | | | | | | |

| EM 5 | Erosion Matting | See SWPPP | 6/13/2024 | Pending | Yes | |
|-------------------------|--|---------------------------|----------------------------------|-------------------------|--------------------------------|--|
| Current Condition: | Pending - | | | <u> </u> | | |
| | | | | | | |
| | Erosion should be repaired and erosion control matting should be installed around SB A. | | | | | |
| | Roloff was informed to complete by 6/20/24. Not done as of last inspection. Ruff and Hubbell Homes was reminded on | | | | | |
| | 7/17/24, 10/2/24 | 1010 by 0/20/24. 1401 doi | ic as or last inspection. Ita | ir aria riabbeli riolii | ics was reminaca on | |
| EM 6 | Erosion Matting | See SWPPP | 6/13/2024 | Pending | Yes | |
| Current Condition: | Pending - | 000 011111 | 0/10/2021 | 1 criding | 103 | |
| | 3 | | | | | |
| | Erosion should be repaired a | ind erosion control matt | ng should be installed arou | und SB B. | | |
| | Deleff was informed to some | lata by 6/00/04. Not don | o as of lost inspection. Du | ff and Hubball Hans | | |
| | Roloff was informed to comp 7/17/24, 10/2/24 | iete by 6/20/24. Not dor | le as of last inspection. Ru | ii and Hubbell Hom | les was reminded on | |
| ET 1 | Erosion Control Terrace | See SWPPP | 9/21/2023 | Active | No | |
| Current Condition: | Good Condition - Ruff Gradin | | | | No | |
| ET 2 | Erosion Control Terrace | See SWPPP | 9/21/2023 | Active | No | |
| Current Condition: | Good Condition - Ruff Gradin | | | | NO | |
| ET 3 | Erosion Control Terrace | See SWPPP | 9/21/2023 | Active | No | |
| Current Condition: | Good Condition - Ruff Gradin | | | | | |
| ET 4 | Erosion Control Terrace | See SWPPP | 9/21/2023 | Active | No | |
| Current Condition: | Good Condition - Ruff Gradin | | | | | |
| ET 5 | Erosion Control Terrace | See SWPPP | 9/21/2023 | Active | No | |
| Current Condition: | Good Condition - Ruff Gradin | · | <u>'</u> | 9/21/23 inspection. | | |
| ET 6 | Erosion Control Terrace | See SWPPP | 4/20/2023 | Pending | No | |
| Current Condition: | Pending - BMP will be install | | ends in the area. E&A ins | | | |
| ET 7 | Erosion Control Terrace | See SWPPP | | Removed | | |
| Current Condition: | Removed - Ruff Grading rem | | ol terrace during grading of | Phase II prior to the | e 4/25/24 inspection. | |
| | Reinstallation not recommen | | | | | |
| ET 8 | Erosion Control Terrace | See SWPPP | 9/21/2023 | Active | No | |
| Current Condition: | Good Condition - Ruff Gradin | , | control terrace prior to the | 9/21/23 inspection. | | |
| ET 9 | Erosion Control Terrace | See SWPPP | | Removed | -11-12-1 | |
| Current Condition: | Removed - Ruff Grading rem | | ol terrace during grading of | Phase II prior to the | e 9/17/24 inspection. | |
| | | | | | | |
| FT 1 | Fuel Tank | On site | 8/27/2024 | Active | No | |
| Current Condition: | Good Condition - K2 Constru | | | | | |
| PB 1 Current Condition: | Portable toilet Good Condition - K2 Constru | On site | 8/20/2024 | Active | No | |
| Current Condition. | the portable toilet prior to the | | e tollet on site prior to trie i | rispection on 6/20/2 | 24. K2 Construction secured | |
| | | | 4/40/0004 | · | | |
| RN 4 Current Condition: | Erosion Control Matting Pending - Erosion Control M | West of SB A | 4/18/2024 | Pending | No | |
| RN 6 | Erosion Control Matting | West of SB B | 4/18/2024 | Pendina | No | |
| Current Condition: | Pending - Erosion Control M | | | , | NO | |
| SB A | Sediment Basin | AA-4 | 4/20/2023 | Pending | Yes | |
| Current Condition: | Fair Condition - 20% Filled - | | | | | |
| | process of installing the riser | | | | | |
| | prior to the 11/16/23 inspecti | on. Ruff Grading was i | n the process of cleaning | out the basin and | d repairing the erosion | |
| | during the inspection on 1 | 0/15/24. | | | | |
| | 1) Positive bound has installed may CW/DDD (Deff) | | | | | |
| | Basin should be installed per SWPPP (Baffle, de-watering holes on riser). Basin should be cleaned out. Erosion below the outfall should be repaired. | | | | | |
| | | | | | | |
| | | | | | | |
| | 1.) Ruff Grading was informed | ed to complete by 5/25/2 | 3. Not done as of the last i | nspection. Ruff Gra | ading was reminded on | |
| | 6/1/23, 7/14/23, 8/4/23, 8/10 | | | | | |
| | 2.) Contractor will be hired to | clean the basin out in t | he Spring. E&A will evalua | te contractor and in | form them to complete | |
| CD D | ASAP as of 6/7/2024. | R-4 | 4/20/2023 | Antivo | Vac | |
| SB B Current Condition: | Sediment Basin Fair Condition - 50% Filled - | <u> </u> | | Active | Yes Ruff Grading installed the | |
| Curront Containent. | riser and outflow pipe prior to | | | | | |
| | the inspection on 10/15/24. | · · | g mas m till | | J | |
| | | | | | | |
| | 1.) Basin should be installed | | | | | |
| | 2.) Basin should be cleaned | out. | | | | |
| | 1.) Ruff Grading was informed | ed to complete by 5/25/2 | 3 Not done as of the last i | nspection Ruff Gra | ading was reminded on | |
| | 6/1/23, 7/14/23, 8/4/23, 8/10 | | | nopodion. Run Gra | aning was reminiated on | |
| | 2.) Contractor will be hired to | | | te contractor and in | form them to complete | |
| | ASAP as of 6/7/2024. | | | | | |
| SB C | Sediment Basin | D-8 | | Removed | | |
| Current Condition: | Removed - Ruff Grading rem | oved the basin during g | rading for Morgan Ridge 2 | prior to the inspect | tion on 9/3/24. | |
| SB D | Sediment Basin | HH-32 to NN-29 | 4/20/2023 | Active | Yes | |
| | | | | | | |

| Current Condition: | Fair Condition - 70% filled - Ruff Grading began excavation on the basin prior to the 12/21/23 inspection. Ruff Grading installed the riser prior to the inspection on 7/23/24. | | | | | |
|----------------------------|--|--|--|--|--|--|
| | 1.) Baffle should be installed per SWPPP. 2.) Basin should be cleaned out. | | | | | |
| | 1) Ruff Grading and Hubbel | Il Homes were informed | to complete by 11/16/23 N | lot done as of last i | inspection, Ruff Grading | |
| | 1.) Ruff Grading and Hubbell Homes were informed to complete by 11/16/23. Not done as of last inspection. Ruff Grading Hubbell Homes were reminded on 3/15/24, 5/24/24, 6/13/24, 7/17/24 | | | | | |
| | 2.) Contractor will be hired to | | | | | |
| SF 1 Current Condition: | Silt Fence Fair Condition - Ruff Grading | Western Perimeter | 4/20/2023 | Active | Yes | |
| | inspection. Ruff Grading instance prior to the 8/31/23 instance prior to the 8/31/23 instance prior to the 8/31/23 instance prior to the 8/31/24 instance pr | spection. A portion of the the west prior to the 11/1 out and repaired. so complete by 10/12/23, 20/23, 3/15/24, 5/24/24, 6/ | e silt fence was removed for 23/23 inspection. Re-insta Not done as of last inspec | r grading activity by llation not recomme stion. Ruff Grading | y Pruss Excavation for t ended. and Hubbell Homes we | |
| | Terrifficed off 6/22/24, 10/2/2 | .4 | | | | |
| | | Southeastern | | | | |
| SF 2 | Silt Fence | Perimeter | | Removed | | |
| Current Condition: | Removed - Ruff Grading ren recommended. | noved the silt fence duri | ng grading of Phase II prior | to the 4/25/24 insp | pection. Reinstallation r | |
| SF 3 | Silt Fence | Southeastern Perimeter | | Removed | | |
| Current Condition: | Removed - Ruff Grading ren | | l ng grading of Phase II prio | | l pection. Reinstallation n | |
| | recommended. | | | | | |
| SF 4 | Silt Fence | Eastern Perimeter | | Removed | | |
| Current Condition: | Removed - Ruff Grading ren recommended. | | ng grading of Phase II prior | to the 4/25/24 insp | pection. Reinstallation n | |
| SF 5 | Silt Fence | Northeastern Perimeter | | Removed | | |
| Current Condition: | Removed - Ruff Grading ren recommended. | | ng grading of Phase II prior | | pection. Reinstallation n | |
| SF 6 | Silt Fence | Northern Perimeter | 4/20/2023 | Pending | No | |
| Current Condition: | Pending - BMP will be instal | | e/ends in the area. E&A ins | pector will monitor. | T | |
| SF 7 | Silt Fonce | Northeastern Perimeter | 8/31/2023 | Activo | No | |
| Current Condition: | Silt Fence Perimeter Solution Active No Good Condition - Ruff Grading installed silt fence prior to the 8/31/23 inspection. Ruff Grading and Hubbell Homes repaire the silt fence and added an additional row of silt fence prior to the 10/10/23 inspection. Ruff Grading cleaned out and repaire the silt fence prior to the inspection on 10/1/24. | | | | | |
| ST A | Sediment Trap | H-13 | | Removed | | |
| Current Condition: | Removed - Ruff Grading ren | | | | on on 9/3/24. | |
| MS 1 | Material Storage | On Site | 4/20/2023 | Pending | No | |
| Current Condition: WO 1 | Pending - Materials will be s Concrete Washout | tored in designated area On Site | 4/20/2023 | Pending | No | |
| Current Condition: | Pending - Concrete will be p | | | | | |
| WS 1 | Waste Storage | On Site | 4/20/2023 | Pending | No | |
| Current Condition: STR | Pending - Waste will be stor Streets | ed in proper containmer N 156th Street | 4/20/2023 | Active | No | |
| Current Condition: | Good Condition - The street 8/17/23 inspection. K2 Cons | s were free of track out a | as of the 4/20/23 inspection | n. Streets were par | | |
| SWPPP Sign | SWPPP Notification Sign | On Site | 5/11/2023 | Active | No | |
| Current Condition: | Good Condition - E&A inspe | | | | | |
| Certification Statement: | "I certify, under penalty of lat direction or supervision in an properly gathered and evalu persons who manage the sy the information submitted is am aware that there are sign of fines and imprisonment for | coordance with a system ated the information sub estem or those persons of to the best of my knowl inficant penalties for sub | designed to assure that q mitted. Based on my inqui lirectly responsible for gath edge and belief, true, accu | ualified personnel ry of the person or ering the information rate, and complete | e. I | |
| | Broga M Waght | The state of the s | | | Coto Sol | |