E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

anager			Lingineering Answ	7613
	E&A- P2003.19	91.000		•
				Stage
	Ne	wport Hill		
	N	ER110499		3
10046			lac County)	68007
100011	St and NE Highway	36- Bennington NE (Doug	ias County)	00007
100%				
				I
Amount in tenths	Date inspected	Weather Conditions	Time	
	<u> </u>			Week 1
0.00"				
0.00"				
0.00"				
0.00"				
0.00"				
0.06"				
0.00"				
				Week 2
0.00"				
0.09"				
0.00"				
0.00"				
				Week 3
	8/31/2021	Partly Cloudy 70	12:35 PM	
U.UU"				- Mach 4
0.00"				Week 4
			+	
			+	
			1	
0.00				Week 5
N/A				- Week 5
				+
N/A				
N/A N/A				
	100% 100% 100% 100% 100% 100% 100% 100%	New Nite	Newport Hill NER110499 9/11/2021 180th St and NE Highway 36- Bennington NE (Doug) 100% 1	Newport Hill NER110499 9/11/2021 180th St and NE Highway 36- Bennington NE (Douglas County) 100%

O-material Communications					
Complaints:					
	None				
	N/A				
	N/A				

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site, grading was completed on 6/11/07.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire Site, grading was completed on 6/11/07.

What temporary or permanent stabilization measures listed in this section are being implemented?

Seeded (6/2007), Re-seeded (9/2007), Paving (9/2007), Seeded (4/2008), Small drainage ditch behind lot 41 was seeded and matted (4/21/15) The sidewalk by the entrance was seeded and matted (3/7/18). OL B next to lot 74 was seeded (11/4/19). River rock rip rap was installed at the flared end on OL B (12/2/19).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

Create Corrective Action?

No, See BMPs and Findings section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Is du

Yes

N/A

Comments

Comments:

The site was active for home building during the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) Maintenance is required in the BMP section.
- 2.) Outlot D has been disturbed by homeowner of Lot 36 prior to inspection on 6/27/18. E&A will monitor. Some BMPs are in place and needing maintenance.
 - a. straw wattles along outlot need cleaned out
 - b. erosion rills need backfilled and seeded

Maintenance responsibility is currently being determined by SID department. E&A will monitor. Maintenance responsibility is still being determined as of last inspection. E&A inspector is awaiting SID department's update as of April 2020. Area is currently being litigated as of 3/2021. E&A will inspector will update when more information is known.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
		South of Northern Dr.				
DS 1	Swale	between SB 1 and 2		Removed		
Current Condition:	Removed - The di	Removed - The diversion was removed prior to inspection on 5/2/17.				
		West of 182nd Cir.				
DS 9	Swale	towards SB 4		Removed		
Current Condition:	Removed - The diversion was removed prior to inspection on 5/2/17.					

		East of Northern Dr.	<u> </u>		1
		and 182nd Cir towards			
DS 12	Swale	SB 5		Removed	
Current Condition:			rior to inspection on 5/2/17.	Removed	
	Tronnerou Tino u	East of Star grass Rd			
DS 13	Swale	towards SB 6		Removed	
Current Condition:	Removed - No div		ved during the inspection on		1
		North of Star grass Rd	· · · · · · · · · · · · · · · · · · ·		
DS 14	Swale	towards SB 6		Removed	
Current Condition:	Removed - No div	ersion swale was obser	ved during the inspection on	12/8/17.	•
Lot 7	Individual Lot	Lot 7		Removed	
Current Condition:	Removed - Silvert	horn Custom Homes so	odded the lot prior to inspecti	on 12/2/19.	•
Lot 24	Silt Fence	Lot 24		Removed	
Current Condition:	Removed - Nilius	Builders sodded the lot	prior to the inspection on 7/3	1/21.	· L
Lot 28	Silt Fence	Lot 28	i İ	Removed	
Current Condition:		Designs sodded the lot r	prior to inspection on 5/20/19		
Lot 30	Silt Fence	Lot 30		Removed	
Current Condition:			sodded the lot prior to the ins		dlev Schmitt
	(homeowner) beg	an garage construction	and installed silt fence prior t	o inspection on 1/2/2019	
	homeowner sodde	ed around the garage co	onstruction area prior to inspe	ection on 7/16/19	
Lot 42	Individual Lot	Lot 42	8/17/2017	Active	No
Current Condition:	Active - D and D I	easing began construct	tion on the lot prior to the ins	pection on 8/17/17. No E	BMP's are
			or. Due to lack of disturbance		
	recommended on	the south side of the lot	. The front of the lot was soo	lded prior to inspection o	n 12/4/18 and
	the portable toilet	was removed. However	, garage construction is activ	e in the SW portion of the	ne lot.
Lot 69	Individual Lot	Lot 69		Removed	T
			at prior to inapportion on 9/12		
Current Condition:		•	ot prior to inspection on 8/13	ı	Ţ
Lot 71	Individual Lot	Lot 71		Removed	
Current Condition:			of the inspection on 9/20/201		
	10/11/2019. Minoi	silt remains in lot. E&A	A will evaluate re-seeding and	d vegetation growth in th	e Spring of 2020.
		1	T		_
Lot 73	Silt Fence	Lot 73	<u> </u>	Removed	
Current Condition:			ot prior to the inspection on 5		
Lot 74	Silt Fence	Lot 74		Removed	
Current Condition:		s sodded prior to 6/10/2	020 by Homestead Builders.	See outlot B for more in	formation.
Lot 76	Individual Lot	Lot 76		Removed	
Current Condition:			front of the lot prior to inspe		
			Construction reseeded the ba	•	ection on
	6/24/19. KRT Con	struction sodded the rei	mainder of the lot prior to ins	pection on 7/16/19.	
Lot 77	Individual Lot	Lot 77		Removed	
Current Condition:	Removed - Citade	el Signature Homes sode	ded the lot prior to inspection	on 7/16/19.	
Lot 84	Individual Lot	Lot 84		Removed	
Current Condition:	Fair Condition- Ru	iss Knapp sodded the lo	ot prior to the inspection on 7	/7/21.	
Lot 86	Individual Lot	Lot 86		Removed	
Current Condition:	Removed - Trade	mark Homes sodded the	e lot prior to inspection on 5/9	9/19.	l.
Lot 88	Individual Lot	Lot 88		Removed	
Current Condition:			prior to inspection on 4/22/21		
Outlot B	Silt Fence	Outlot B	 	Removed	
Current Condition:			were removed by the SID in		2020
SF 1	Silt Fence	South of Lot 21	Were removed by the GID in	Removed	1
Current Condition:			I ne silt fence prior to inspectio		
Current Condition.	itellioved - vvood	South of Northern Dr.		11 011 0/10/10.	
		on southwest corner			
SB 1	Sediment Basin	of site		Removed	
Current Condition:		was closed prior to insp	ection on 9/25/18.		
		South of Northern Dr.			
		between 185th St and			
SB 2	Sediment Basin	184th St.	4/9/2007	Active	No
Current Condition:			eer trees were removed from		
	Cleanout mark repainted by E&A inspector on 3/30/2020.				
		South of Northern Dr.			
		between 182th St and			
SB 3	Sediment Basin	184th St.	04/06/07	Active	No
	•				

Current Condition:	Good Condition - 39% Filled. The volunteer trees were removed from the basin prior to the 3/20/15 inspection.						
	Basin was mowed	prior to inspection on 8	/16/18. Minor riser damage v	was observed during ins	pection on		
	8/13/19. Cleanout	mark repainted by E&A	inspector on 3/30/2020.				
		South of Northern Dr.					
		between 182th St and					
SB 4	Sediment Basin	184th St.	04/06/07	Active	No		
Current Condition:	Good Condition - 4	Good Condition - 41% Filled. The volunteer trees were removed from the basin prior to the 3/20/15 inspect					
	Cleanout mark rep	painted by E&A inspecto	r on 3/30/2020.				
SB 5	Sediment Basin	East of 182nd Cir.		Removed			
Current Condition:	Removed - Basin	was closed prior to insp	ection on 8/16/18.				
		Northeast of Star					
SB 6	Sediment Basin	grass Rd.	4/9/2007	Active	No		
Current Condition:			t down volunteer trees prior	to the 2/23/16 inspection	n. Cleanout mark		
	repainted by E&A	repainted by E&A inspector on 3/30/2020.					
		North of Star grass					
SB 7	Sediment Basin	Rd. East of 182nd St.	4/9/2007	Active	No		
Current Condition:	Good Condition - 4	42% Filled - The SID cu	it down volunteer trees prior	to the 2/23/16 inspection	n. There is		
	erosion at the outfall. E&A will monitor. Cleanout mark repainted by E&A inspector on 3/30/2020.						
		North of Star grass					
		Rd. between 184th St					
SB 8	Sediment Basin	and 182nd St	4/20/2007	Active	No		
Current Condition:	Good Condition - 4	Good Condition - 49% Filled - The SID cut down volunteer trees prior to the 2/23/16 inspection. Cleanout mark					
	repainted by E&A inspector on 3/30/2020.						
STR	Streets	Entire Site	3/20/2007	Active	No		
Current Condition:	Good Condition - Streets in front of Lot 77 were cleaned prior to inspection on 9/4/18. Streets were cleaned in						
	front of lots 42, 50 and 86 prior to inspection on 10/10/18. Streets were cleaned in 182nd Circle prior to						
	inspection on 12/4/18. Streets were cleaned in 182nd Circle prior to inspection on 6/24/19. Homestead Custom						
	Builders cleaned the streets in front of Lot 74 prior to inspection on 9/10/19. Streets were cleaned by JD						
	Martinez and Knapp Custom Homes prior to 9/20/2019						
SWPPP signs	Signs	1 sign	8/19/2008	Active	No		
Current Condition:	Good Condition -	SW corner of 180th St a	nd Northern Hills Dr.				
	· ·		<u> </u>		2		
	a m 7/m tot			7	littes Van		
Inspector Signature:	Braga M Wantet			Reviewed By:	- V com		
mapecioi oignature.	/			itevieweu by.			