Inspector: Mike Jacobson Project Name: For Week Ending:				Stage
				Clago
For Week Ending:			3	
		Palisades 2/13/2010		
Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	39%	6		
		1		
RAIN FALL AMOUNTS	Amount in inches	Date inspected		
Sunday:	0.00"			Week 1
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
	0.00"			
Saturday	0.00			Week 2
Sunday:	0.00"			WCCR 2
Monday	0.00"			
Tuesday	0.21"			
Wednesday	0.24"			
Thursday	0.00"			
Friday	0.04"			
Saturday	0.02"			
				Week 3
Sunday:	0.04"			
Monday	0.01"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
,		•		Week 4 / 5
Sunday:	0.00"; 0.11 "			
Monday	0.02"; 0.03"	2/1/2010; None		
Tuesday	0.00"; 0.02 "			
Wednesday	0.00"; 0.00"			
Thursday	0.32 "; 0.00"			
Friday	0.24 "; 0.00"			
Saturday	0.00"; 0.00"			
•		1	I .	
Complaints:	None			

Construction Sequencing:
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and site seeded Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site; grading completed and site seeded Spring 2005.

Paving, seeding (Spring 05), dense vegetative cover; Drainage way west of sediment basin 3 was re-graded and seeded/matt (9/2008); Area around SB 3 and where silt was placed was re-seeded (4/2009)

Comments:

Comments:

Home construction is active in varies areas on site.

During inspection on 2/1/2010 inspector walked portions of the site. Most of the BMP's are is still covered with snow, but appeared to be in good working condition unless otherwise noted.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some required maintenance in the BMP section.

			Projected Install			Description of		
Unique Name	Туре	Location	Date	Status	Maintenance	Maintenance/Activity		
		N41d00m00s				Repairs		
CE 1	Construction Entrance	W96d00m00s		Removed		Needed/Planned:		
Current Condition:	Removed; 2 paved entra	Removed; 2 paved entrances exist on site.						
		N41d00m00s						
SB 1 Current Condition:	Sediment Basin Good Condition - 31% Fi	W96d00m00s	In Place	Active	No			
Current Condition.	Cleaned out 06/05	lieu						
		N41d00m00s						
SB 2	Sediment Basin	W96d00m00s	In Place	Active	No			
Current Condition:	This has been convert to							
SB 3	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No			
Current Condition:	Good Condition - 13% Fi		III I lace	Active	110	1		
	Clean out was completed prior to inspection on 1/22/09 by M.E. Collins.							
		N41d00m00s				1		
SB 4	Sediment Basin	W96d00m00s	In Place	Active	No			
Current Condition:	Good Condition - 37% Fi	lled						
	Cleaned out 07/05	N41d00m00s	1	I	1			
SF 1	Silt Fence	W96d00m00s		Removed				
Current Condition:	The remainder of silt fen		to inspection on 8/8/09		due to good			
	vegetation. The builder v	vill be responsible for re	e-installation of silt fend	e prior to activity	home			
	construction in this area. Lot 293 was sodded prio	r to inspection on 9/28	/00 by Jeff w/ McCaul F	Homes therefore	the cilt fence is			
	no longer needed.	i to inspection on 9/20	709 by Jell W/ McCaul I	iomes, mereiore	ine siii ierice is			
		N41d00m00s						
SF 2	Silt Fence	W96d00m00s	8/18/2009	Active	No			
Current Condition:	Good Condition-The rem							
	due to good vegetation. home construction in this	·	onsible for re-installation	on of silt fence pri	or to activity			
	Silt fence was re-installed		4 by builder due to activ	e home construct	ion.			
		N41d00m00s						
SF 3		W96d00m00s		Removed				
Current Condition:	Removed; permanent ve	<u> </u>	i	ı	,			
SF 4	Cilt Fance	N41d00m00s W96d00m00s		Domoved				
Current Condition:	Silt Fence Removed due to good ve		to be reinstalled once	Removed home construction	n begin in this			
	area.	. 9						
		N41d00m00s						
SF 5	Silt Fence	W96d00m00s		Removed				
Current Condition:	Removed due to good ve	egetation, but will need	to be reinstalled once	home construction	n begin in this			
	area.	N41d00m00s			1	-		
SF 6	Silt Fence	W96d00m00s		Removed				
Current Condition:	Removed due to good ve	egetation, but will need	to be reinstalled once	home construction	n begin in this	1		
	area.		i	T	_			
05.7	Cilt Fance	N41d00m00s		Damassad				
SF 7 Current Condition:	Silt Fence The remainder of silt fen	W96d00m00s	to inspection on 8/8/09	Removed by Boyer Young o	lue to good	-		
	vegetation. The builder v							
	construction in this area.							
07.0	a =	N41d00m00s						
SF 8 Current Condition:	Silt Fence The remainder of silt fence	W96d00m00s	to increation on 9/9/00	Pending	Yes			
Current Condition.								
	vegetation. The builder will be responsible for re-installation of silt fence prior to activity home construction in this area.							
	Lot 79 has active home construction and the silt fence needs to be installed on the back of the lot.							
	Lot 79 has active home of	construction and the si	it tence needs to be ins	stalled on the back	of the lot.			
	Sherwood Homes was in	formed to complete m	aintenance by 8/15/09.	Maintenance not	completed as of			
	last inspection.	•						
05.5	074 =	N41d00m00s	0/40/2222		l			
SF 9	Silt Fence	W96d00m00s	8/18/2009	Active	No	J		

Current Condition:	Good Condition- The remainder of silt fence was removed prior to inspection on 8/8/09 by Boyer Young							
Current Condition.	due to good vegetation. The builder will be responsible for re-installation of silt fence prior to activity							
	home construction in this area.							
	Silt fence was re-installed on the back of lot 100 prior to inspection on 8/18/09 by Builder. N41d00m00s							
05.40	0.11. E		. 5:					
SF 10	Silt Fence	W96d00m00s	In Place	Active	Yes			
Current Condition:	Good Condition- Partially removed due to lot development.							
	Lot 213 has active home construction and silt fence needs to be re-installed on the back of the lot.							
	McCaul Homes was inf	McCaul Homes was informed to complete maintenance by 12/14/09. Maintenance not completed as of						
	last inspection.	last inspection.						
		N41d00m00s						
ST 1	Silt Trap	W96d00m00s		Removed				
Current Condition:	Removed; berm constructed and area matted and seeded.							
		N41d00m00s						
STR	Streets	W96d00m00s	In Place	Active	No			
Current Condition:	Good Condition- No major signs of track off.							
SWPPP Sign	SWPPP Sign	Three signs on site	3/28/2008	Active	No			
Current Condition:	Good Condition	-						
	On 3/28/08 inspector install SWPPP a sign at 172nd & Cornhusker Rd., 168th & Chutney Dr and 168th							
	& Palisades Drive entrance.							
	, , , , ,				11.			
Inspector Signature:	bed Jawson		Reviewed By:	Zadnany L. Ji	LUC			