E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



E&A CONSULTING GROUP, INC. ENGINEERING • PLANNING • FIELD SERVICES

Erosion Control Specialist- Manage		E&A - P2004.020	000		
N'I	1	E&A - P2004.020	.000		Chara
nspector: Mike Jacobson, CISEC					Stage 3
		Palis	ades		3
Project Name:		NER1	10500		
For Week Ending:	7/10/2010				
Project Location:	169			4 1)	68136
	168th & Cornhusker Road- Omaha, NE (Sarpy County)				00100
RAIN FALL AMOUNTS	Amount in tenths	Date inspected			
Sunday:	0.42"				Weel
Monday	0.83"	06/14/10			
Tuesday	0.00"	00,11,10			
Vednesday	0.00"	06/16/10			
Thursday	0.10"				
Friday	0.72"	06/18/10			
Saturday	0.14"				
					Weel
Sunday:	0.92"	0/04/06 10			
Monday	0.85"	6/21/2010			
Fuesday Vednesday	0.38" 0.00"	06/22/10			
Vednesday Fhursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Wee
Sunday:	0.00"				
Monday	0.00"				
luesday	0.00"				
Vednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.08"				Wee
Sunday:	1.90"				Wee
Aonday	0.02"	07/05/10			
luesday	0.00"	01700/10			
Vednesday	0.50"	07/07/10			
Thursday	0.00"				
Friday	0.00"				
Saturday	Trace				
					Wee
Sunday:	N/A	N/A			
Ionday	N/A	N/A			
Tuesday Mednesday	N/A N/A	N/A N/A			
Vednesday	N/A N/A	N/A N/A			
Thursday Friday	N/A N/A	N/A N/A			
Saturday	N/A	N/A			
	None				
Complaints:]				
Construction Sequencing:					
Vhich portion(s) (i.e. drainage basins) of the	e site have had a tempo	orary or permanent cessatio	n of grading, earthwork, or gro	und disturbance in the	ast 14 days?
		-			
Entire site; grading completed and sit	e seeded Spring 200	5.			
Vhich portion(s) (i.e. drainage basins) of th	e site do not have grad	ing, earthwork, or ground di	sturbance scheduled in the ne	xt 14 days?	
Entire site; grading completed and sit	e seeded Sprina 200	5.			
		-			
	1				
What temporary or permanent stabilization					
What temporary or permanent stabilization Paving, seeding (Spring 05), dense vo	egetative cover; Drai	nage way west of sedim		and seeded/matt (9/2	2008); Area
/hat temporary or permanent stabilization	egetative cover; Drai	nage way west of sedim		and seeded/matt (9/2	2008); Area

Comments:

Home construction is active in varies areas on site. Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): 1) Some required maintenance in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenanc		
Lot 21	Silt Fence	Lot 21	4/29/2010	Active	Yes		
Current Condition:	Lot level silt fence needs trenched in correctly and across the front of the lo installed on the North sic On 5/11/10, 6/2/10, 6/22	Fair Condition-Active home construction on lot. Lot level silt fence needs to be installed. As of inspection 5/11/10 silt fence was installed, but it was not trenched in correctly and it needs to be trenched in correctly. As of inspection on 7/5/10 silt fence on the across the front of the lot has been partially removed and it needs to be reinstalled. Silt fence needs to be installed on the North side of the lot. On 5/11/10, 6/2/10, 6/22/10 and again on 7/5/10 Urban Homes was called and left a message informing them that silt fence needs to be installed correctly ASAP. Maintenance not completed as of last inspection.					
Lot 51	Misc/Other	Lot 51	6/9/2010	Active	No		
Current Condition:	Misc/Other Lot 51 6//2/10 Active No BMP's needed on lot. Active home construction on lot. Ditt piles in the R.O.W. was removed and construction debris/trash was cleaned up prior to ins 6/9/10 by Timberline Homes. Section 1000000000000000000000000000000000000						
Lot 62 Current Condition:	Silt Fence Pending- Active home co	Lot 62 Distruction on lot.	7/12/2010	Active	Yes		
	Lot level silt fence needs Builder is unknow. Inspe builder is determined the	ctor has emailed Nic w	/ Boyer Young asking h	nim who the builde	r is on this lot. Or		
Lot 80	Silt Fence	Lot 80	7/12/2010	Active	Yes		
	Part of the outlot behind Sherwood Homes was in	nformed to complete m			completed as of la		
	until 7/15/10.	d muddy conditions, the	erefore another seven o				
Lot 81	until 7/15/10. Silt Fence	Lot 81	erefore another seven of 7/12/2010				
Lot 81 Current Condition:	until 7/15/10.	Lot 81 postruction on lot. stalled on back of lot. ctor has emailed Nic w	7/12/2010 / Boyer Young asking h	days is given to co	mplete maintena		
	until 7/15/10. Silt Fence Pending- Active home co Silt fence needs to be in: Builder is unknow. Inspe builder is determined the Silt Fence	Lot 81 onstruction on lot. stalled on back of lot. ctor has emailed Nic w n maintenance will ado	7/12/2010 / Boyer Young asking h	days is given to co	mplete maintena		
Current Condition: Lot 101	until 7/15/10. Silt Fence Pending- Active home co Silt fence needs to be in: Builder is unknow. Inspe builder is determined the	Lot 81 Distruction on lot. stalled on back of lot. ctor has emailed Nic w in maintenance will add Lot 100 lot. i/10 construction debris e debis on lot from the eds to be re-seeded. as informed to clean up led to complete mainte as informed to clean up	7/12/2010 / Boyer Young asking F ress accordly. 4/9/2010 s was cleaned up by Mu active home construction by 5/26/10. On 6/22/10 nance ASAP. Maintenan by 5/26/10. On 6/22/10	days is given to co Active im who the builder Active uhle Construction. ion on lot 100 and 0 and again on 7/5 ince not completed 0 and again on 7/5	mplete maintena Yes r is on this lot. Or Yes it needs to be /10 Muhle d as of last /10 Muhle		
Lot 101 Current Condition:	until 7/15/10. Silt Fence Pending- Active home of Silt fence needs to be in: Builder is unknow. Inspe- builder is determined the Silt Fence Good Condition- Vacant Prior to inspection on 7/5 1) Empty lot has concret cleaned up. 2) Disturb area of lot need 1) Muhle construction was Construction was remined inspection.	Lot 81 Distruction on lot. stalled on back of lot. ctor has emailed Nic w n maintenance will add Lot 100 lot. /10 construction debris e debis on lot from the adds to be re-seeded. as informed to clean up led to complete mainten as informed to clean up led to completent as informed to clean up led to completent as informed to clean up the cle	7/12/2010 / Boyer Young asking h ress accordly. 4/9/2010 s was cleaned up by Mu active home construction by 5/26/10. On 6/22/10 nance ASAP. Maintenan by 5/26/10. On 6/22/10	days is given to co Active im who the builder Active uhle Construction. ion on lot 100 and 0 and again on 7/5 ance not completed 0 and again on 7/5 ance not completed	r is on this lot. Or Yes it needs to be /10 Muhle d as of last /10 Muhle		
Current Condition: Lot 101	until 7/15/10. Silt Fence Pending- Active home or Silt fence needs to be in: Builder is unknow. Inspe builder is unknow. Inspe builder is determined the Silt Fence Good Condition- Vacant Prior to inspection on 7/5 1) Empty lot has concret cleaned up. 2) Disturb area of lot need 1) Muhle construction was construction was remined inspection. 2) Muhle construction was	Lot 81 Distruction on lot. stalled on back of lot. ctor has emailed Nic winth n maintenance will add Lot 100 lot. //10 construction debris e debis on lot from the eds to be re-seeded. as informed to clean up led to complete maintenant as informed to clean up led to complete maintenant Lot 113 check installed on lot. ged and needs to be re-	7/12/2010 / Boyer Young asking h ress accordly. 4/9/2010 s was cleaned up by Mu active home constructi by 5/26/10. On 6/22/10 nance ASAP. Maintena by 5/26/10. On 6/22/10 nance ASAP. Maintena 5/4/2010 Vacant lot. paired, replaced if need	days is given to co Active im who the builded Active uhle Construction. ion on lot 100 and 0 and again on 7/5 ince not completed 0 and again on 7/5 ince not completed Active Active	mplete maintena Yes r is on this lot. Or Yes it needs to be /10 Muhle d as of last /10 Muhle d as of last Yes		

Current Condition:	Good Condition- Silt fence check installed on lot. Vacant lot. Silt fence was tied up by inspection during inspection on 6/22/10.						
Lot 207	Silt Fence	Lot 207	In Place	Active	Yes		
Current Condition:	Fair Condition- Vacant lot. Silt fence is down/damaged in a few areas and needs to be repaired, replaced if needed or silt fence can be removed, but will need to be reinstalled by the builder prior to active home construction on these lots. Boyer Young was informed to complete maintenance by 3/18/10. Maintenance not completed as of last inspection.						
Lot 213	Silt Fence/Other	Lot 213	12/14/2009	Pending	Yes		
Current Condition:	Silt Fence/Other Lot 213 12/14/2009 Pending Yes Pending- Active home construction on lot.						
	Silt fence needs to be re-installed on the back of the lot. McCaul Homes was informed to complete maintenance by 12/14/09. On 3/11/10 and again on 6/22/10 McCaul Homes was reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection.						
Lot 225	Silt Fence/Other	Lot 225		Removed			
Current Condition:	Silt fence was removed of	due to the lot being sod	ded prior to inspection	on 7/5/10 by Rege	ncy Homes.		
Lot 990	Silt Enner/Other	Lot 220	7/5/0040	Active	No		
Lot 226 Current Condition:	Silt Fence/Other Good Condition- Active h			Active	No		
	Silt fence was installed o	on West side of lot prior	to inspection on 7/5/10) by Regency Hom	es.		
Lot 245	Silt Fence	Lot 245	7/5/2010	Active	Yes		
Current Condition:	Fair Condition- Active ho	ome construction on lot.	Diverison ditch installe	ed along lot.			
	Diverison ditch is blown out and needs to be redefined. Jim w/ Charleston Homes was informed to complete maintenance by 7/12/10. Maintenance not completed as of last inspection due to wet and muddy conditions, therefore another seven days is given to complete maintenance until 7/15/10.						
Lot 257 Current Condition:	Silt Fence	Lot 257	6/30/2010	Pending	Yes		
	 Pending- Active home construction on lot. 1) Dirt piled in the R.O.W. and it needs to be removed or silt fence needs to be installed around it. 2) Lot level silt fence needs to be installed on the lot. 1) Sudbeck construction was informed to clean up by 6/29/10. Maintenance not completed as of last inspection. 2) Sudbeck construction was informed to clean up by 6/29/10. Maintenance not completed as of last inspection. 						
Lat 202	Silt Conco	Lat 202	4/20/2010	A otivio	Vac		
Lot 303 Current Condition:	Silt Fence Fair Condition- Silt fence						
	Additional section of lot level silt fence installed prior to inspection on 6/16/10 by HBC Construction. Dumpsters was emptied prior to inspection on 7/5/10 by HBC Construction. Silt fence on the back of the lot is full and down/damaged in a few areas and it needs to be cleaned out and repaired. Additional silt fence needs to be installed on the back of the lot. HBC Construction was informed to complete maintenance by 6/29/10. Maintenance not completed as of last inspection.						
Lot 304	Silt Fence	Lot 304		Removed			
Current Condition:	Silt fence was removed of		ded prior to inspection		Construction.		
Lot 313	Silt Fence	Lot 313	4/29/2010	Active	Yes		
Current Condition:	Silt Fence Lot 313 4/29/2010 Active Yes Good Condition- Silt fence installed on the back of the lot. Active home construction on lot. Sand and gravel in the street and R.O.W. and the dirt in the R.O.W. was removed prior to inspection on 5/11/10 by Horizon Homes. Lot level silt fence needs to be installed on the front of the lot. Horizon Homes was informed to install silt fence by 4/29/10. Maintenance not completed as of last inspection. Preside						
Lot 402	Silt Fence	Lot 402	4/29/2010	Active	Yes		

Current Condition:	good Condition- Silt fenc	e installed on the back	of the lot. Active hom	e construction on lot			
		Silt is leaving the lot and going into the playground area, therefore additional silt fence needs to be installed i the Southwest corner of the lot and the play ground needs to be cleaned up.					
	Zych Construction was informed to complete maintenance by 6/29/10. Additional silt fence was installed price to inspection on 7/5/10 by Zych Construction.						
Lot 418	Silt Fence	Lot 418	4/2/2010	Active	No		
Current Condition:	Good Condition- Active h Gator Guard was installe			4/2/10 by Sherwood	d Homes.		
Lot 423 Current Condition:	Silt Fence	Lot 423	5/4/2010	Active	Yes		
	to be repaired. As of insp needs to removed.	Fair Condition- Commercial lot along Cornhusker Road. The silt fence on the back of the lot were the daycare is along Cornhusker Road is down/damaged and nee to be repaired. As of inspection on 6/22/10 the area was seeded/matted therefore silt fence is no longer and needs to removed.					
	inspection on 4/7/10, but as of last inspection. On	Developer Bill Torczon was informed to complete maintenance by 4/9/10. Maintenance not completed as of inspection on 4/7/10, but developer still has two days to complete maintenance. Maintenance not completer as of last inspection. On 6/22/10 Developer Bill Torczon was called and left a message informed to remove silt fence ASAP. Maintenance not completed as of last inspection.					
SB 1	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 31% Fi Cleaned out 06/05			<u>. </u>	-		
SB 2	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No		
Current Condition:	This has been convert to	permanent pond for th	e school site.				
SB 3	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No		
Current Condition:		Good Condition - 16% Filled Clean out was completed prior to inspection on 1/22/09 by M.E. Collins.					
SB 4 Current Condition:	Sediment Basin Good Condition - 39% Fi	N41d00m00s W96d00m00s illed	In Place	Active	No		
	Cleaned out 07/05		i	· · · ·			
SF 1	Silt Fence	N41d00m00s W96d00m00s		Removed			
Current Condition:	The remainder of silt fen vegetation. The builder v this area.	The remainder of silt fence was removed prior to inspection on 8/8/09 by Boyer Young due to good vegetation. The builder will be responsible for re-installation of silt fence prior to activity home construction this area. Lot 293 was sodded prior to inspection on 9/28/09 by Jeff w/ McCaul Homes, therefore the silt fence is no					
ST 1	Silt Trap	N41d00m00s W96d00m00s		Removed			
Current Condition:	Removed; berm constru		ind seeded.				
STR	Streets	N41d00m00s W96d00m00s	In Place	Active	Yes		
Current Condition:	Fair Condition- Some minor signs of run Boyer Young was inform				nspection.		
SWPPP Sign	SWPPP Sign	Three signs on site	3/28/2008	Active	No		
Current Condition:	Good Condition On 3/28/08 inspector ins Palisades Drive entrance	stall SWPPP a sign at 7	•	•			
pector Signature:	I Jawlom			Reviewed By:	Ednary K. Gil		