E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



E&A CONSULTING GROUP, INC. ENGINEERING • PLANNING • FIELD SERVICES

Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager

		E&A - P2004.020.0	00		
Inspector: Mike Jacobson, CISEC	;				Stage
		Palisa	des		3
Project Name:		NER11	0500		
For Week Ending:		4/14/2	012		
Project Location:	168	Bth & Cornhusker Road- C	-	ntv)	68136
RAIN FALL AMOUNTS	Amount in tenths	Date inspected			
					Week
Sunday:	0.15"				
Monday Tuesdav	0.05"			-	
Wednesday	0.00"				
Thursday	Trace				
Friday	0.00"				
Saturday	0.00"				
Sunday	0.00"				Week
Sunday: Monday	0.00"		+		
Tuesday	0.48"		1	1	
Wednesday	0.20"				
Thursday	0.06"				
Friday Saturday	0.00"		+		
Jalui Udy	0.00				Week
Sunday:	0.00"				Heck
Monday	0.00"				
Tuesday	Trace				
Wednesday	Trace				
Thursday Friday	Trace 0.03"				
Saturday	0.00"				
•					Week
Sunday:	0.00"				
Monday	0.00"				
Tuesday Wednesday	0.00" Trace				
Thursday	0.02"				
Friday	0.00"				
Saturday	Trace				
Oran dana	0.00"				Week
Sunday: Monday	0.00" Trace	04/09/12			
Tuesday	0.00"	04/00/12			
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.30"		+		
Saturday	1.21"		1	1	
	None				
Complaints:					
Construction Regulation			1	1	
Construction Sequencing: Which portion(s) (i.e. drainage basins) of f	the site have had a tempora	ry or permanent cessation of gra	ding, earthwork, or ground	disturbance in the last 1	4 days?
mich portion(s) (i.e. drainage basilis) of	ane site nave nau a tempora	ry or permanent dessation of gre	lang, caramork, or ground		4 uuysi
Entire site; grading completed and	site seeded Spring 200	5.			
				1	
Which portion(s) (i.e. drainage basins) of t	the site do not have grading	earthwork, or ground disturban	ce scheduled in the next 14	davs?	
Entire site; grading completed and	site seeded Spring 200				
What temporary or permanent stabilizatio			havin 2 was to are to t	and anoded/mett (2	(2008). Area area
Paving, seeding (Spring 05), dense SB 3 and where silt was placed was					
So o and where siit was placed was	3 15-366ucu (4/2009); 1	ne uramaye area just Wes		and seeded/mailed(10/2011)
Comments:					

Comments:

Home construction is active in various areas on site.

On April 2, 2012 @ 1pm Jeff Elliott and Zach Jilek of E&A met with Robert Dailey an attorney at McGrath North which was the representative for the Hearthstone Homes, Inc. Bankruptcy Chapter 11 Trustee. During this meeting E&A notified the Trustee's representative that there where deficiencies/violations at almost all of the properties that Hearthstone Homes owned. The deficiencies ranged from silt fence maintenance/installation, seeding, and miscellaneous items. At this time the Trustee requested a proposal for the time and materials to get the sites into compliance. On April 5, 2012 E&A provide a proposal/estimate for maintenance to the Trustee. On April 13, 2012 a signed proposal was supplied. E&A will supply Commercial Seeding with the maintenance plans to get hard bids and get the maintenance completed as soon as possible if funds are available. This was supplied as an update to the Hearthstone Homes, Inc. Bankruptcy and maintenance status. **Findings / Corrective Actions (Date)**:

Findings / Corrective Actions (Date):

1) Some required maintenance in the BMP section.

			Projected Install				
Unique Name	Туре	Location	Date	Status	Maintenance		
Lot 77	Silt Fence	Lot 76	6/25/2011	Active	No		
Current Condition:	Good Condition-	20170	0/20/2011	7 louve	110		
	The disturbed area was Maintenance was comple						
Lot 217	Silt Fence	Lot 217	11/10/2011	Pending	Yes		
Current Condition:	Pending-						
	Lot level silt fence needs to be installed on the back of the lot.						
	Newport Homes was info overdue maintenance on was reminded that maint inspection.	11/21/11 and to comp	lete ASAP . On 1/9/12 a	and again on 3/6/1	2 Newport Homes		
1 -1 252	Olly France	1 -1 050		Demonst			
Lot 352 Current Condition:	Silt Fence Lot was sodded prior to i	Lot 352	v Frontier Construction	Removed			
Current Contailon.	Lot was souded prior to t			•			
L et 206	Silt Fence	Lot 306	4/16/2012	Dending	Vee		
Lot 306 Current Condition:	Pending	LOI 306	4/16/2012	Pending	Yes		
	 2) Silt fence needs to be installed on the back of the lot. 1) Dave Hausman was informed to complete maintenance by 4/16/12. 2) Dave Hausman was informed to complete maintenance by 4/16/12. 						
Lot 307	Silt Fence	Lot 307	4/16/2012	Pendina	Yes		
Current Condition:	Pending	Lot 307	4/10/2012	Pending	165		
	 There is dirt piled in the contract of the contra	installed on the back of	of the lot.	silt fence around di	rt pile.		
	 Dave Hausman was ir Dave Hausman was ir 						
Lot 404	Silt Fence	Lot 404	11/10/2011	Active	No		
Current Condition:	Good Condition- A silt fence check was in Homes.	stalled on the Southea	st corner of the lot prior	to inspection on 3	/6/12 by Newport		
Lot 420	Silt Fence	Lot 420	4/9/2012	Active	Yes		
Current Condition:	Fair Condition	L0("#20	4/3/2012	Active	105		
	The silt fence on the bac	k of the lot is down/dar	naged and it needs to b	e replaced.			
	Newport Homes was info	ormed to complete mair	ntenance by 4/16/12.				
	a u, =						
POD A	Silt Fence	Lots 103-133	4/20/2011	Active	Yes		

Current Condition:	Fair Condition- Silt fence installed on a Portable toilet was remo		b inspection on 4/9/12	by toilet company								
	 Portable toilet was removed from lot 112 prior to inspection on 4/9/12 by toilet company. The dirt in the R.O.W. on Lot 112 and lot 121 was removed prior to inspection on 4/9/12 by Hearthstone. 3) Lot 111,lot 120 and lot 123 has silt fence that is damaged on the lots and it needs to be repaired, replaneeded. 2) Scott w/ Hearthstone was informed to complete maintenance by 3/14/12. Maintenance not completed a last inspection. See Comments on update on maintenance by 3/14/12. Maintenance not completed a 3) Scott w/ Hearthstone was informed to complete maintenance by 3/14/12. Maintenance not completed a 											
									mments on update on m			
							POD B	Silt Fence	Lots 134-159	4/20/2011	Active	Yes
Current Condition:	Good Condition- Active home construction on a few lots. The outlot behind lot 142 was re-graded and re-seeded prior to inspection on 4/9/12 the home owner of lot 142. Lots 143-146 was re-graded prior to inspection on 4/9/12 by the home owner of lot 142. The down/damaged silt fence on lot 142-146 was removed prior to inspection on 4/9/12 by the home owner of lot 142. The down/damaged silt fence on lot 142-146 was removed prior to inspection on 4/9/12 by the home owner of lot 142. The Outlot area behind lots 142-146 was damaged due to the home construction being active in the area it needs to be re-seeded. As of inspection on 11/21/11 maintenance was not completed. On 11/21/11 Jeff w/ Hearthstone Producti was reminded that maintenance needs to be completed ASAP. On 11/30/11 Mert w/ Hearthstone Producti sinspection due to winter conditions. Maintenance was reminded that maintenance needs to be completed ASAP. Maintenance not completed as of last inspection due to winter conditions. Maintenance was reminded that maintenance needs to be completed ASAP. Maintenance not completed ASAP. Maintenance not completed as OF last inspection due to winter conditions. Maintenance was reminded that maintenance needs to be completed ASAP. Maintenance not completed ASAP.											
								N41d00m00s				
SB 1 Current Condition:	Sediment Basin	W96d00m00s or to inspection on 5/12/1	1 by O'Brian Crading	Removed								
Current Condition:		ne lots and outlot was se			bv CS.							
					.,							
		N41d00m00s			.,							
SB 2	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No							
SB 2 Current Condition:				Active								
Current Condition:	This has been convert t	W96d00m00s o permanent pond for th N41d00m00s	e school site.		No							
		W96d00m00s o permanent pond for th N41d00m00s W96d00m00s		Active								
Current Condition: SB 3	This has been convert t Sediment Basin Good Condition - 23% F	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled ed prior to inspection on	e school site. In Place	Active	No							
Current Condition: SB 3	This has been convert t Sediment Basin Good Condition - 23% F	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled	e school site. In Place	Active	No							
Current Condition: SB 3 Current Condition:	This has been convert t Sediment Basin Good Condition - 23% f Clean out was complete Sediment Basin Good Condition - 39% f	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled oprior to inspection on N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collir	Active	No							
Current Condition: SB 3 Current Condition: SB 4	This has been convert t Sediment Basin Good Condition - 23% f Clean out was complete Sediment Basin	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled ed prior to inspection on N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collir	Active	No No							
Current Condition: SB 3 Current Condition: SB 4 Current Condition:	This has been convert t Sediment Basin Good Condition - 23% f Clean out was complete Sediment Basin Good Condition - 39% f Cleaned out 07/05	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled ad prior to inspection on N41d00m00s W96d00m00s Filled option to inspection on N41d00m00s W96d00m00s Filled N41d00m00s	e school site. In Place 1/22/09 by M.E. Collir	Active	No No							
Current Condition: SB 3 Current Condition: SB 4	This has been convert t Sediment Basin Good Condition - 23% R Clean out was complete Sediment Basin Good Condition - 39% R Cleaned out 07/05 Silt Fence	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled ed prior to inspection on N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collir In Place	Active Is. Active Removed	No No No							
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SF 1	This has been convert t Sediment Basin Good Condition - 23% R Clean out was complete Sediment Basin Good Condition - 39% R Cleaned out 07/05 Silt Fence	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled d prior to inspection on N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s W96d00m00s Filled N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collir In Place	Active Is. Active Removed	No No No							
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SF 1 Current Condition:	This has been convert t Sediment Basin Good Condition - 23% f Clean out was complete Sediment Basin Good Condition - 39% f Cleaned out 07/05 Silt Fence The remainder of silt fer Silt Trap	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled ad prior to inspection on N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s W96d00m00s N41d00m00s W96d00m00s N41d00m00s	e school site. In Place 1/22/09 by M.E. Collir In Place p inspection on 8/8/09	Active Is. Active Removed by Boyer Young due	No No No							
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SF 1 Current Condition: ST 1	This has been convert t Sediment Basin Good Condition - 23% f Clean out was complete Sediment Basin Good Condition - 39% f Cleaned out 07/05 Silt Fence The remainder of silt fer Silt Trap	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled ad prior to inspection on N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s rcce was removed prior to N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collir In Place p inspection on 8/8/09	Active Is. Active Removed by Boyer Young due	No No No							
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SF 1 Current Condition: ST 1 Current Condition: ST 1 Current Condition:	This has been convert t Sediment Basin Good Condition - 23% f Clean out was complete Sediment Basin Good Condition - 39% f Cleaned out 07/05 Silt Fence The remainder of silt fei Silt Trap Removed; berm constru Streets	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled ed prior to inspection on N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s nce was removed prior to N41d00m00s W96d00m00s ucted and area matted an N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collir In Place p inspection on 8/8/09	Active Is. Active Removed by Boyer Young due	No No No							
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SF 1 Current Condition: ST 1 Current Condition:	This has been convert t Sediment Basin Good Condition - 23% f Clean out was complete Sediment Basin Good Condition - 39% f Cleaned out 07/05 Silt Fence The remainder of silt fen Silt Trap Removed; berm constru	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled ed prior to inspection on N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s nce was removed prior to N41d00m00s W96d00m00s ucted and area matted an N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collir In Place p inspection on 8/8/09 nd seeded.	Active Is. Active Removed by Boyer Young due Removed	No No No to good vege							
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SF 1 Current Condition: ST 1 Current Condition: ST 1 Current Condition:	This has been convert t Sediment Basin Good Condition - 23% f Clean out was complete Sediment Basin Good Condition - 39% f Cleaned out 07/05 Silt Fence The remainder of silt fei Silt Trap Removed; berm constru Streets	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s Filled ed prior to inspection on N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s Filled N41d00m00s W96d00m00s nce was removed prior to N41d00m00s W96d00m00s ucted and area matted an N41d00m00s W96d00m00s	e school site. In Place 1/22/09 by M.E. Collir In Place D inspection on 8/8/09 d seeded. In Place	Active Is. Active Removed by Boyer Young due Removed	No No No to good vege							
Current Condition: SB 3 Current Condition: SB 4 Current Condition: SF 1 Current Condition: ST 1 Current Condition: STR Current Condition:	This has been convert t Sediment Basin Good Condition - 23% f Clean out was complete Sediment Basin Good Condition - 39% f Cleaned out 07/05 Silt Fence The remainder of silt fer Silt Trap Removed; berm constru Streets Good Condition- No ma SWPPP Sign Good Condition	W96d00m00s o permanent pond for th N41d00m00s W96d00m00s iilled ed prior to inspection on N41d00m00s W96d00m00s iilled N41d00m00s W96d00m00s iilled N41d00m00s W96d00m00s nce was removed prior to N41d00m00s W96d00m00s inceed and area matted and N41d00m00s W96d00m00s inceed and area matted and N41d00m00s W96d00m00s install SWPPP a sign at formula sign a	e school site. In Place 1/22/09 by M.E. Collir In Place p inspection on 8/8/09 nd seeded. In Place 3/28/2008	Active IS. Active Removed by Boyer Young due Removed Active Active	No No No No No No No							