E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A - P2004.020	0.000				
Inspector: Shaun McGuire					Stage		
		Cluge					
	iect Name: Palisades NER110500						
Project Name:							
For Week Ending:		3/11/2023					
Project Location:	16	168th & Cornhusker Road- Omaha, NE (Sarpy County)					
			· · · · · · · · · · · · · · · · · · ·		68136		
Grading:	100	%					
Sanitary Sewer:	100						
Storm Sewer:	100						
Paving:	100						
Seeding:	100						
Utilities:	100						
Overall Development:	99	%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Martin		
Sunday:	0.00"				Week 1		
Monday	0.00"			+	+		
Tuesday	0.00 0.78"			+	Rain 8 AM - 5 PM		
Wednesday	0.00"	2/15/2023	Overcast 37/19	2:10 PM			
Thursday	0.60"	L: 10/2020		2.1011	Snow 3 AM - 12 PM		
Friday	0.02"	2/17/2023	Sunny 27/20	10:00 AM			
Saturday	0.00"	2,11,2020	0	10.00 / 44			
	0.00				Week 2		
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00"						
					Week 3		
Sunday:	0.25"				Rain 9 PM - 12 AM		
Monday	0.12"	2/27/2023	Overcast 52/32	11:30 AM	Rain 12 AM - 7 AM		
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"	-					
Friday	0.00"						
Saturday	0.00"				Week 4		
Sunday:	0.00"				Week 4		
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"			1	1		
Thursday	0.14"		1	1			
Friday	0.00"		1	1	1		
Saturday	0.24"			1			
					Week 5		
Sunday:	N/A						
Monday	N/A						
Tuesday	N/A						
Wednesday	N/A						
Thursday	N/A			1			
Friday	N/A						
Saturday	N/A		1				
	NUM						
Comulainte	None						
Complaints:							
				1			
Construction Sequencing:			1	1			
construction sequencing:							

Which portion(s) (i.e. drainage basins) of		normanont coccation of gradin	a parthwork or around dicturba	neo in the last 14 day	c?
	the site have had a temporary or	permanent cessation of gradin	g, earthwork, or ground disturba	nce in the last 14 days	51
ntire site; grading completed and s					
/hich portion(s) (i.e. drainage basins) of		hwork, or ground disturbance	scheduled in the next 14 days?		
ntire site; grading completed and s					
Vhat temporary or permanent stabilizatio			in 2 was to graded and soos	lad/matt (0/2008).	Area around CD 2
Paving, seeding (Spring 05), dense	.	-	0		Area around SB 3
nd where silt was placed was re-so					2015) The outlet
Swale down to basin #3 was regrad adjacent to lot 204 and the outlot ad			s, mailing was installed on a	56 3 Slopes (6/26/	2015). The outlot
	ijacent to tot oo were seeded	u anu maileu (4/25/16).			
Checklist Questions:					
Are receiving waters adjacent to the	project free of any significant	signs of erosion or sedime	nt that would be associated w	vith the constructio	n activity?
/es					
Create Corrective Action?					
J/A					
lave disturbed areas been seeded or	otherwise stabilized as requ	ired? List inactive portions	of the project and if stabilizat	ion measures are a	dequate or needed
revent erosion.					
/es					
Create Corrective Action?					
//A					
re waste materials (concrete, consti	ruction material, hazardous.	etc.) being managed properl	y?		
'es	,	, 6	•		
Create Corrective Action?					
/A					
re construction entrances and adjac	cent streets being maintained	adequately?			
′es					
Create Corrective Action?					
J/A					
s dust associated with the construct	ion activity adequately control	olled on the site?			
Yes					
Create Corrective Action?					
J/A					
N/A					
Comments: Comments:					
Comments: Comments: Home construction was inactive as					
Comments: Comments: Home construction was inactive as Findings / Corrective Actions (Da	te):				
Comments: Comments: Home construction was inactive as Findings / Corrective Actions (Da Findings / Corrective Actions (Da	te): te):				
Comments: Comments: Home construction was inactive as Findings / Corrective Actions (Da	te): te):				
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da .) No maintenance is required in th	te): te): ne BMP section.	Location	Projected Install Date	Status	Maintenance
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da	te): te):	Location South end of Outlet C	Projected Install Date	Status	Maintenance
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da .) No maintenance is required in th	te): te): ne BMP section.		Projected Install Date	Status Removed	Maintenance
Comments: Comments: Iome construction was inactive as Context indings / Corrective Actions (Da Corrective Actions (Da No maintenance is required in th Unique Name	te): te): le BMP section. Type Concrete Washout	South end of Outlet C along Palisades Drive was removed by Celebrity	Projected Install Date Homes prior to 11/12/2015.		Maintenance
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da .) No maintenance is required in th Unique Name CW 1 Current Condition:	te): te): ne BMP section. Type Concrete Washout Removed - Washout pit	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C		Removed	Maintenance
Comments: Comments: Nome construction was inactive as Contractive Actions (Da Contractive Actions (Da Contractive Actions (Da Contractive Actions (Da CW 1 Current Condition: CW 2	te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive	Homes prior to 11/12/2015.		Maintenance
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da .) No maintenance is required in th Unique Name CW 1 Current Condition:	te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo	Homes prior to 11/12/2015.	Removed	Maintenance
Comments: Comments: Jome construction was inactive as Findings / Corrective Actions (Da Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition:	te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout pit	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C	Homes prior to 11/12/2015.	Removed Removed	Maintenance
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da .) No maintenance is required in th Unique Name CW 1 CW 1 Current Condition: CW 2 Current Condition: CW 3	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout pit Removed - Washout pit Concrete Washout pit	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive	Homes prior to 11/12/2015. ung prior to 11/12/2015.	Removed Removed Removed	
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da .) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition:	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout pit Removed - Washout pit Concrete Washout pit Concrete Washout pit	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive	Homes prior to 11/12/2015.	Removed Removed Removed	
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da .) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition:	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout Removed - Washout pit Concrete Washout Removed - Celebrity Ho need to re-install.	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yoo South end of Outlet C along Palisades Drive mes removed the washout	Homes prior to 11/12/2015. ung prior to 11/12/2015.	Removed Removed Removed 2003. The inspecto	
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout Removed - Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24	Homes prior to 11/12/2015. ung prior to 11/12/2015.	Removed Removed Removed	
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da .) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition:	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout Removed - Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Story Homes	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 sLLC sodded the lot prior for	Homes prior to 11/12/2015. ung prior to 11/12/2015.	Removed Removed Removed 203. The inspecto Removed	
omments: omments: ome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 24 Current Condition:	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout Removed - Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Story Homes Individual lot	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 LLC Sodded the lot prior the Lot 387	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection.	Removed Removed Removed 2003. The inspecto	
omments: omments: ome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 CUrrent Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 24 Current Condition:	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout pit Removed - Celebrity Ho need to re-install. Individual lot Removed - Story Homes Individual lot Removed - Celebrity Ho	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 s LLC sodded the lot prior to Lot 387 mes sodded the lot prior to	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection. to the 8/16/22 inspection.	Removed Removed 203. The inspecto Removed Removed	pr will monitor the
omments: omments: ome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da .) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3	te): te): te BMP section. Concrete Washout Removed - Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Story Homes Individual lot Removed - Celebrity Ho Sediment Basin	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 s LLC sodded the lot prior to Lot 387 mes sodded the lot prior to Commercial Lot #5	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection. to the 8/16/22 inspection. In Place	Removed Removed 203. The inspecto Removed Removed Active	or will monitor the
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 CUrrent Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition:	te): te): te BMP section. Concrete Washout Removed - Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Story Homes Individual lot Removed - Celebrity Ho Sediment Basin	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 s LLC sodded the lot prior to Lot 387 mes sodded the lot prior to Commercial Lot #5	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection. to the 8/16/22 inspection.	Removed Removed 203. The inspecto Removed Removed Active	or will monitor the
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3	te): te): te BMP section. Concrete Washout Removed - Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Story Homes Individual lot Removed - Celebrity Ho Sediment Basin	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 LLC sodded the lot prior to Lot 387 mes sodded the lot prior to Commercial Lot #5 illed - Cleaned out was con	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection. to the 8/16/22 inspection. In Place	Removed Removed 203. The inspecto Removed Removed Active	or will monitor the
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da .) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition:	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Celebrity Ho Sediment Basin Good Condition - 15% F Sediment Basin	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 LLC sodded the lot prior to Lot 387 mes sodded the lot prior to Commercial Lot #5 illed - Cleaned out was con 173rd Street and	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection. to the 8/16/22 inspection. In Place mpleted prior to inspection on	Removed Removed 2003. The inspecto Removed Removed Active n 7/31/15 by Dusty	or will monitor the
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition:	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Celebrity Ho Sediment Basin Good Condition - 15% F Sediment Basin	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 LLC sodded the lot prior to Lot 387 mes sodded the lot prior to Commercial Lot #5 illed - Cleaned out was con 173rd Street and Palisades Drive	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection. to the 8/16/22 inspection. In Place mpleted prior to inspection on	Removed Removed 2003. The inspecto Removed Removed Active n 7/31/15 by Dusty	or will monitor the
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition:	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout Removed - Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Story Homes Individual lot Removed - Celebrity Ho Sediment Basin Good Condition - 15% F Sediment Basin Removed - Basin was re Streets	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 LC sodded the lot prior to Lot 387 mes sodded the lot prior to Commercial Lot #5 illed - Cleaned out was con 173rd Street and Palisades Drive emoved prior to the inspect Cornhusker, 168th, and Interior Streets	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection. In Place mpleted prior to inspection on tion on 3/24/16. In Place	Removed Removed 203. The inspecto Removed Removed Active n 7/31/15 by Dusty Removed Active	or will monitor the No Roth. No
Comments: Comments: Comme construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 CUrrent Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition: SB 4 Current Condition:	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout Removed - Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Story Homes Individual lot Removed - Celebrity Ho Sediment Basin Good Condition - 15% F Sediment Basin Removed - Basin was re Streets	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 LC sodded the lot prior to Lot 387 mes sodded the lot prior to Commercial Lot #5 illed - Cleaned out was con 173rd Street and Palisades Drive emoved prior to the inspect Cornhusker, 168th, and Interior Streets	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection. to the 8/16/22 inspection. In Place mpleted prior to inspection o tion on 3/24/16.	Removed Removed 203. The inspecto Removed Removed Active n 7/31/15 by Dusty Removed Active	or will monitor the No Roth. No
omments: omments: ome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition: SB 4 Current Condition:	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout pit Concrete Washout Removed - Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Story Homes Individual lot Removed - Celebrity Ho Sediment Basin Good Condition - 15% F Sediment Basin Removed - Basin was re Streets Good Condition - The st streets around lot 24 priot	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 LC sodded the lot prior to Lot 387 mes sodded the lot prior to Commercial Lot #5 illed - Cleaned out was con 173rd Street and Palisades Drive emoved prior to the inspect Cornhusker, 168th, and Interior Streets	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection. In Place mpleted prior to inspection on tion on 3/24/16. In Place ean as of the inspection on	Removed Removed 203. The inspecto Removed Removed Active n 7/31/15 by Dusty Removed Active	or will monitor the No Roth. No
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition: SB 4 Current Condition: STR	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout pit Concrete Washout Removed - Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Celebrity Ho Sediment Basin Good Condition - 15% F Sediment Basin Removed - Basin was re Streets Good Condition - The st streets around lot 24 priot	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 Lot 24 LLC sodded the lot prior to Lot 387 mes sodded the lot prior to Commercial Lot #5 illed - Cleaned out was cor 173rd Street and Palisades Drive emoved prior to the inspect Cornhusker, 168th, and Interior Streets reets around lot 35 were cl or to the 4/26/22 inspectior	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection. In Place mpleted prior to inspection on tion on 3/24/16. In Place ean as of the inspection on 7 1. 3/28/2008	Removed Removed 2003. The inspecto Removed Removed Active n 7/31/15 by Dusty Removed Active 12/5/19. Story Hon Active	r will monitor the No Roth. No nes LLC cleaned t
Comments: Comments: Iome construction was inactive as indings / Corrective Actions (Da indings / Corrective Actions (Da) No maintenance is required in th Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: SB 3 Current Condition: SB 4 Current Condition: STR Current Condition:	te): te): te BMP section. Type Concrete Washout Removed - Washout pit Concrete Washout pit Concrete Washout Removed - Washout pit Concrete Washout Removed - Celebrity Ho need to re-install. Individual lot Removed - Celebrity Ho Sediment Basin Good Condition - 15% F Sediment Basin Removed - Basin was re Streets Good Condition - The st streets around lot 24 priot	South end of Outlet C along Palisades Drive was removed by Celebrity South end of Outlet C along Palisades Drive was removed by Boyer Yo South end of Outlet C along Palisades Drive mes removed the washout Lot 24 Lot 24 LLC sodded the lot prior t Lot 387 mes sodded the lot prior to Commercial Lot #5 illed - Cleaned out was cor 173rd Street and Palisades Drive emoved prior to the inspect Cornhusker, 168th, and Interior Streets reets around lot 35 were cl or to the 4/26/22 inspectior Three signs on site 8/08 inspector installed SV	Homes prior to 11/12/2015. ung prior to 11/12/2015. t in preparation for sod on lot to the 8/16/22 inspection. to the 8/16/22 inspection. In Place mpleted prior to inspection on tion on 3/24/16. In Place ean as of the inspection on file.	Removed Removed 2003. The inspecto Removed Removed Active n 7/31/15 by Dusty Removed Active 12/5/19. Story Hon Active	r will monitor the No Roth. No nes LLC cleaned t

Certification Statement:	direction or supervision in properly gathered and ev persons who manage the the information submitted am aware that there are	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."				
Inspector Signature:	Sm MsGin		Reviewed By:			