E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A - P200	4.020.000		
Inspector: Shaun McGuire					Stage
Project Name:		3			
For Week Ending:		6/	10/2023		
Project Location:	1	68136			
One dia as		000/			
Grading: Sanitary Sewer:		00% 00%			
Storm Sewer:		00%			
Paving:		00%			
Seeding:	1	00%			
Utilities:		00%			
Overall Development:		99%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	
					Week 1
Sunday:	0.00"				
Monday	0.01"				
Tuesday	0.00"		0 •••/=-		
Wednesday	0.00"	5/17/2023	Sunny 82/50	2:35 PM	
Thursday Friday	0.00"				
Friday Saturday	0.00"				
	0.00				Week 2
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				Week 2
Sunday:	0.00"				Week 3
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.43"				Rain 12:00 pm - 4:00 pm
Friday	0.09"	6/2/2023	Sunny 84/66	8:20 AM	
Saturday	0.03"				Week 4
Sunday:	0.00"				Week 4
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.02"				Week 5
Sunday:	N/A				week 3
Monday	N/A				1
Tuesday	N/A				
Wednesday	N/A				
Thursday	N/A				
Friday	N/A				
Saturday	N/A				
Complaints:	None				
Construction Seguencing:					
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a tempor	ary or permanent cessation	of grading, earthwork, or ground d	isturbance in the last 14	days?
Entire site; grading completed a Which portion(s) (i.e. drainage basins			urbance scheduled in the next 14 o	lays?	

where silt was placed was re-see Swale down to basin #3 was regr	raded, seeded and matted p	area just West of SB 3 war ior to inspection on 9/11/	as repaired and seeded/ma 2013; Matting was installed	tted(10/2011)	
adjacent to lot 204 and the outlot	adjacent to lot 88 were seed	ded and matted (4/25/18).			
Checklist Questions:					
Are receiving waters adjacent to the	e project free of any significar	t signs of erosion or sedim	ent that would be associated	with the constructi	on activity?
Yes					
Create Corrective Action? N/A					
Have disturbed areas been seeded	or otherwise stabilized as req	uired? List inactive portion	s of the project and if stabiliz	ation measures are	adequate or needed to
prevent erosion.					
Yes Create Corrective Action?					
N/A					
Are waste materials (concrete, con	struction material, hazardous,	etc.) being managed prope	erly?		
Yes Create Corrective Action?					
N/A					
1 1/7 1					
Are construction entrances and adj	jacent streets being maintaine	d adequately?			
Yes Create Corrective Action?					
N/A					
Is dust associated with the constru	ction activity adequately cont	olled on the site?			
Yes					
Create Corrective Action?					
N/A					
Comments:					
Comments: Comments:	as of the last inspection.				
Comments: Comments: Home construction was inactive a					
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I	Date): Date):				
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I	Date): Date):				
Comments: Home construction was inactive a	Date): Date): n the BMP section.	Location	Projected Install Date	Status	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in	Date): Date): In the BMP section. Type	Location South end of Outlet C	Projected Install Date		Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in Unique Name CW 1	Date): Date): the BMP section. Type Concrete Washout	South end of Outlet C along Palisades Drive		Removed	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required ir Unique Name	Date): Date): the BMP section. Type Concrete Washout	South end of Outlet C along Palisades Drive t was removed by Celebri	Projected Install Date	Removed	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in Unique Name CW 1 Current Condition:	Date): Date): the BMP section. Type Concrete Washout Removed - Washout pi	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C		Removed 5.	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in Unique Name CW 1	Date): Date): The BMP section. Concrete Washout Removed - Washout pi Concrete Washout	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive	ty Homes prior to 11/12/201	Removed	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required ir Unique Name CW 1 Current Condition: CW 2 Current Condition:	Date): Date): Type Concrete Washout Removed - Washout pi Concrete Washout pi	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C		Removed 5. Removed	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3	Date): Date): Date): Date BMP section. Type Concrete Washout pi Concrete Washout pi Concrete Washout pi Concrete Washout pi	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive t was removed by Boyer South end of Outlet C along Palisades Drive	ty Homes prior to 11/12/201 Young prior to 11/12/2015.	Removed 5. Removed Removed	
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required ir Unique Name CW 1 Current Condition: CW 2 Current Condition:	Date): Date:: Date): Date): Date:: Date): Date:: Date): Date::	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive t was removed by Boyer South end of Outlet C along Palisades Drive	ty Homes prior to 11/12/201	Removed 5. Removed Removed	
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition:	Date): Date):	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive t was removed by Boyer South end of Outlet C along Palisades Drive omes removed the washo	ty Homes prior to 11/12/201 Young prior to 11/12/2015.	Removed 5. Removed Removed lot 203. The inspe	
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24	Date): Date): Date): Date): Concrete Washout Removed - Washout pi Concrete Washout Removed - Washout pi Concrete Washout Removed - Celebrity He to re-install. Individual lot	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. uut in preparation for sod on	Removed 5. Removed Removed	
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition:	Date): Date): Date): Date): Concrete Washout Removed - Washout pi Concrete Washout Removed - Washout pi Concrete Washout Removed - Celebrity He to re-install. Individual lot	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo	ty Homes prior to 11/12/201 Young prior to 11/12/2015.	Removed 5. Removed Removed lot 203. The inspe	
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition:	Date): Date): Date): Date): Concrete Washout pi Concrete Washout pi	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive t was removed by Boyer N South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior mes sodded the lot prior	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection.	Removed 5. Removed lot 203. The inspe Removed Removed	cctor will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required ir Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3	Date): Date):	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive t was removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior Lot 387 omes sodded the lot prior Commercial Lot #5	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection. In Place	Removed 5. Removed lot 203. The inspe Removed Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition:	Date): Date):	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior Lot 387 omes sodded the lot prior Commercial Lot #5 Filled - Cleaned out was co	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection.	Removed 5. Removed lot 203. The inspe Removed Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 24 Current Condition: SB 3 Current Condition:	Date): Date): Type Concrete Washout Removed - Washout pi Concrete W	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive was removed by Boyer Y South end of Outlet C along Palisades Drive Drive South end of Outlet C along Palisades Drive Lot 24 s LLC sodded the lot prior Lot 387 Drives sodded the lot prior Commercial Lot #5 Filled - Cleaned out was c 173rd Street and	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection. In Place	Removed 5. Removed lot 203. The inspe Removed Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required ir Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3	Date): Date): Date): Date): Concrete Washout Removed - Washout pi Concrete Washout pi	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior Lot 387 omes sodded the lot prior Commercial Lot #5 Filled - Cleaned out was co	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection. In Place completed prior to inspectior	Removed 5. Removed lot 203. The inspe Removed Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition:	Date): Date): Date): Date): Concrete Washout Removed - Washout pi Concrete Washout pi	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior Lot 387 omes sodded the lot prior Commercial Lot #5 Filled - Cleaned out was of 173rd Street and Palisades Drive	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection. In Place completed prior to inspectior	Removed 5. Removed lot 203. The inspe Removed Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 4	Date): Date): n the BMP section. Type Concrete Washout Removed - Washout pi Concrete Wa	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive the transformer of the term Lot 24 s LLC sodded the lot prior Commercial Lot #5 Filled - Cleaned out was c 173rd Street and Palisades Drive emoved prior to the inspe Cornhusker, 168th, and Interior Streets	ty Homes prior to 11/12/201 foung prior to 11/12/2015. To the preparation for sod on to the 8/16/22 inspection. In Place completed prior to inspectior action on 3/24/16. In Place	Removed 5. Removed lot 203. The inspe Removed Removed Active n on 7/31/15 by Du Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (Findings / Corrective Actions (1.) No maintenance is required ir Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition: SB 4 Current Condition:	Date): Date): Type Concrete Washout Removed - Washout pi Concrete Washout pi Sediment Basin Removed - Basin was n Streets Good Condition - The s	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive twas removed the state to 24 s LLC sodded the lot prior Lot 24 s LLC sodded the lot prior Commercial Lot #5 cilled - Cleaned out was of 173rd Street and Palisades Drive emoved prior to the inspe Cornhusker, 168th, and Interior Streets treets around lot 35 were	ty Homes prior to 11/12/201 (oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. In Place completed prior to inspection ction on 3/24/16. In Place clean as of the inspection of	Removed 5. Removed lot 203. The inspe Removed Removed Active n on 7/31/15 by Du Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 4 Current Condition: STR Current Condition:	Date): Date): Date): Type Concrete Washout Removed - Washout pi Concrete Story Home Individual lot Removed - Celebrity Home Individual lot Removed - Story Home Individual lot Removed - Celebrity Home Sediment Basin Good Condition - 15% I Sediment Basin Removed - Basin was n Streets Good Condition - The s streets around lot 24 pr	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive was removed by Boyer Y South end of Outlet C along Palisades Drive Drive Termoved the washo to the state of Courter C along Palisades Drive twas removed the washo to 24 s LLC sodded the lot prior Lot 387 Drives sodded the lot prior Commercial Lot #5 Filled - Cleaned out was c 173rd Street and Palisades Drive emoved prior to the inspe Cornhusker, 168th, and Interior Streets treets around lot 35 were ior to the 4/26/22 inspecti	ty Homes prior to 11/12/201 foung prior to 11/12/2015. To the 8/16/22 inspection. In Place prior to inspectior in Place In Place clean as of the inspection of on.	Removed 5. Removed lot 203. The inspe Removed Removed Active n on 7/31/15 by Dt Removed Active n on 2/5/19. Story H	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 4	Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Concrete Washout pi Concrete Washout pi Concret	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior Lot 387 omes sodded the lot prior Commercial Lot #5 Filled - Cleaned out was c 173rd Street and Palisades Drive emoved prior to the inspe Cornhusker, 168th, and Interior Streets treets around lot 35 were ior to the 4/26/22 inspecti	ty Homes prior to 11/12/201 (oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. In Place completed prior to inspection ction on 3/24/16. In Place clean as of the inspection of	Removed 5. Removed Iot 203. The inspe Removed Removed Active n on 7/31/15 by Du Removed Active n on 2/5/19. Story H Active	Contemporation of the net sector will monitor the net sect

Certification Statement:	direction or supervision properly gathered and e persons who manage th the information submitte am aware that there are	of law, that this document and all attachments were p in accordance with a system designed to assure that valuated the information submitted. Based on my inc the system or those persons directly responsible for ga- ed is, to the best of my knowledge and belief, true, ac significant penalties for submitting false information int for knowing violations."	t qualified personnel quiry of the person or athering the information, ccurate, and complete. I
Inspector Signature:	Sm Magin		Reviewed By: