E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A - P2004.	020.000				
Inspector: Shaun McGuire					Stage		
Project Name:		3					
For Week Ending:							
Project Location:	1	68136					
Grading:	1	00%					
Sanitary Sewer:		00%			-		
Storm Sewer:	1	00%					
Paving:		00%					
Seeding:		00%					
Utilities:		00%					
Overall Development:		99%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Storm Event Duration		
					Week 1		
Sunday:	0.71"			44 19 19	Rain 12:00 AM - 5:00 AM		
Monday	0.00"	6/12/2023	Sunny 78/55	11:40 AM			
Tuesday Wednesday	0.00"						
wednesday Thursday	0.00"						
Friday	0.00"				+		
Saturday	0.00"						
Sunday	0.00"				Week 2		
Sunday: Monday	0.00"				_		
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"				-		
Friday	0.00"						
Saturday	0.00"						
					Week 3		
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.01"	0/00/0000		0.05 BM			
Thursday	0.25"	6/29/2023	Sunny 92/67	3:25 PM	Rain 7:30 AM - 9:00 AM		
Friday	0.49" 0.54"	6/30/2023	Partly Cloudy 86/68	11:05 AM	Rain 3:00 AM - 10:00 AM Rain 4:45 AM - 10:00 PM		
Saturday	0.54				Week 4		
Sunday:	0.25"				Rain 12:30 AM - 1:00 PM		
Monday	0.04"	7/3/2023	Sunny 92/67	10:45 AM			
Tuesday	0.03"						
Wednesday	0.19"			-			
Thursday Friday	0.00" 0.65"				Rain 6:45 AM - 11:00 PM		
Saturday	0.05				Rain 6.45 AW - 11.00 PW		
	0.00				Week 5		
Sunday:	N/A						
Monday	N/A						
Tuesday	N/A						
Wednesday	N/A						
Thursday Friday	N/A						
Friday Saturday	N/A N/A						
Jatarday		1	I				
Complaints:	None						
Construction Commencie							
Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?							
Entire site; grading completed a Which portion(s) (i.e. drainage basins			pance scheduled in the next 14 day	s?			
	,	o,		-			

where silt was placed was re-see Swale down to basin #3 was regr	raded, seeded and matted p	area just West of SB 3 war for to inspection on 9/11/	as repaired and seeded/ma 2013; Matting was installed	tted(10/2011)	
adjacent to lot 204 and the outlot	adjacent to lot 88 were seed	ded and matted (4/25/18).			
Checklist Questions:					
Are receiving waters adjacent to the	e project free of any significar	t signs of erosion or sedim	ent that would be associated	with the constructi	on activity?
Yes					
Create Corrective Action? N/A					
Have disturbed areas been seeded	or otherwise stabilized as req	uired? List inactive portion	s of the project and if stabiliz	ation measures are	adequate or needed to
prevent erosion.					
Yes Create Corrective Action?					
N/A					
Are waste materials (concrete, con	struction material, hazardous,	etc.) being managed prope	erly?		
Yes Create Corrective Action?					
N/A					
1 1/7 1					
Are construction entrances and adj	jacent streets being maintaine	d adequately?			
Yes Create Corrective Action?					
N/A					
Is dust associated with the constru	ction activity adequately cont	olled on the site?			
Yes					
Create Corrective Action?					
N/A					
Comments:					
Comments: Comments:	as of the last inspection.				
Comments: Comments: Home construction was inactive a					
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I	Date): Date):				
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I	Date): Date):				
Comments: Home construction was inactive a	Date): Date): n the BMP section.	Location	Projected Install Date	Status	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in	Date): Date): In the BMP section. Type	Location South end of Outlet C	Projected Install Date		Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in Unique Name CW 1	Date): Date): the BMP section. Type Concrete Washout	South end of Outlet C along Palisades Drive		Removed	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required ir Unique Name	Date): Date): the BMP section. Type Concrete Washout	South end of Outlet C along Palisades Drive t was removed by Celebri	Projected Install Date	Removed	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in Unique Name CW 1 Current Condition:	Date): Date): the BMP section. Type Concrete Washout Removed - Washout pi	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C		Removed 5.	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in Unique Name CW 1	Date): Date): The BMP section. Concrete Washout Removed - Washout pi Concrete Washout	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive	ty Homes prior to 11/12/201	Removed	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required ir Unique Name CW 1 Current Condition: CW 2 Current Condition:	Date): Date): Type Concrete Washout Removed - Washout pi Concrete Washout pi	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C		Removed 5. Removed	Maintenance
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3	Date): Date): Date): Date BMP section. Type Concrete Washout pi Concrete Washout pi Concrete Washout pi Concrete Washout pi	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive t was removed by Boyer South end of Outlet C along Palisades Drive	ty Homes prior to 11/12/201 Young prior to 11/12/2015.	Removed 5. Removed Removed	
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required ir Unique Name CW 1 Current Condition: CW 2 Current Condition:	Date): Date:: Date): Date): Date:: Date): Date:: Date): Date::	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive t was removed by Boyer South end of Outlet C along Palisades Drive	ty Homes prior to 11/12/201	Removed 5. Removed Removed	
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition:	Date): Date):	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive t was removed by Boyer South end of Outlet C along Palisades Drive omes removed the washo	ty Homes prior to 11/12/201 Young prior to 11/12/2015.	Removed 5. Removed Removed lot 203. The inspe	
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24	Date): Date): Date): Date): Concrete Washout Removed - Washout pi Concrete Washout Removed - Washout pi Concrete Washout Removed - Celebrity He to re-install. Individual lot	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. uut in preparation for sod on	Removed 5. Removed Removed	
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition:	Date): Date): Date): Date): Concrete Washout Removed - Washout pi Concrete Washout Removed - Washout pi Concrete Washout Removed - Celebrity He to re-install. Individual lot	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo	ty Homes prior to 11/12/201 Young prior to 11/12/2015.	Removed 5. Removed Removed lot 203. The inspe	
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition:	Date): Date): Date): Date): Concrete Washout pi Concrete Washout pi	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive t was removed by Boyer N South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior mes sodded the lot prior	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection.	Removed 5. Removed lot 203. The inspe Removed Removed	cctor will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required ir Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3	Date): Date):	South end of Outlet C along Palisades Drive t was removed by Celebri South end of Outlet C along Palisades Drive t was removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior Lot 387 omes sodded the lot prior Commercial Lot #5	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection. In Place	Removed 5. Removed lot 203. The inspe Removed Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition:	Date): Date):	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior Lot 387 omes sodded the lot prior Commercial Lot #5 Filled - Cleaned out was co	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection.	Removed 5. Removed lot 203. The inspe Removed Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (I Findings / Corrective Actions (I 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 24 Current Condition: SB 3 Current Condition:	Date): Date): Type Concrete Washout Removed - Washout pi Concrete W	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive was removed by Boyer Y South end of Outlet C along Palisades Drive Drive South end of Outlet C along Palisades Drive Lot 24 s LLC sodded the lot prior Lot 387 Drives sodded the lot prior Commercial Lot #5 Filled - Cleaned out was c 173rd Street and	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection. In Place	Removed 5. Removed lot 203. The inspe Removed Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required ir Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3	Date): Date): Date): Date): Concrete Washout Removed - Washout pi Concrete Washout pi	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior Lot 387 omes sodded the lot prior Commercial Lot #5 Filled - Cleaned out was co	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection. In Place completed prior to inspectior	Removed 5. Removed lot 203. The inspe Removed Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition:	Date): Date): Date): Date): Concrete Washout Removed - Washout pi Concrete Washout pi	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior Lot 387 omes sodded the lot prior Commercial Lot #5 Filled - Cleaned out was of 173rd Street and Palisades Drive	ty Homes prior to 11/12/201 /oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. to the 8/16/22 inspection. In Place completed prior to inspectior	Removed 5. Removed lot 203. The inspe Removed Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 4	Date): Date): n the BMP section. Type Concrete Washout Removed - Washout pi Concrete Wa	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive the transformer of the term Lot 24 s LLC sodded the lot prior Commercial Lot #5 Filled - Cleaned out was c 173rd Street and Palisades Drive emoved prior to the inspe Cornhusker, 168th, and Interior Streets	ty Homes prior to 11/12/201 foung prior to 11/12/2015. To the preparation for sod on to the 8/16/22 inspection. In Place completed prior to inspectior action on 3/24/16. In Place	Removed 5. Removed lot 203. The inspe Removed Removed Active n on 7/31/15 by Du Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (Findings / Corrective Actions (1.) No maintenance is required ir Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition: SB 4 Current Condition:	Date): Date): Type Concrete Washout Removed - Washout pi Concrete Washout pi Sediment Basin Removed - Basin was n Streets Good Condition - The s	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive twas removed the state to 24 s LLC sodded the lot prior Lot 24 s LLC sodded the lot prior Commercial Lot #5 cilled - Cleaned out was of 173rd Street and Palisades Drive emoved prior to the inspe Cornhusker, 168th, and Interior Streets treets around lot 35 were	ty Homes prior to 11/12/201 (oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. In Place completed prior to inspection ction on 3/24/16. In Place clean as of the inspection of	Removed 5. Removed lot 203. The inspe Removed Removed Active non 7/31/15 by Du Removed Active	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 4 Current Condition: STR Current Condition:	Date): Date): Date): Type Concrete Washout Removed - Washout pi Concrete Story Home Individual lot Removed - Celebrity Home Individual lot Removed - Story Home Individual lot Removed - Celebrity Home Sediment Basin Good Condition - 15% I Sediment Basin Removed - Basin was n Streets Good Condition - The s streets around lot 24 pr	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive was removed by Boyer Y South end of Outlet C along Palisades Drive Drive Termoved the washo to the standard the construction Lot 24 s LLC sodded the lot prior Commercial Lot #5 Filled - Cleaned out was co 173rd Street and Palisades Drive emoved prior to the inspe Cornhusker, 168th, and Interior Streets treets around lot 35 were ior to the 4/26/22 inspecti	ty Homes prior to 11/12/201 foung prior to 11/12/2015. To the 8/16/22 inspection. In Place prior to inspectior in Place In Place clean as of the inspection of on.	Removed 5. Removed lot 203. The inspe Removed Removed Active n on 7/31/15 by Dt Removed Active n on 2/5/19. Story H	ector will monitor the ne
Comments: Comments: Home construction was inactive a Findings / Corrective Actions (i Findings / Corrective Actions (i 1.) No maintenance is required in Unique Name CW 1 Current Condition: CW 2 Current Condition: CW 3 Current Condition: Lot 24 Current Condition: Lot 387 Current Condition: SB 3 Current Condition: SB 4 Current Condition: SB 4	Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Date): Concrete Washout pi Concrete Washout pi Concret	South end of Outlet C along Palisades Drive twas removed by Celebri South end of Outlet C along Palisades Drive twas removed by Boyer Y South end of Outlet C along Palisades Drive omes removed the washo Lot 24 s LLC sodded the lot prior Lot 387 omes sodded the lot prior Commercial Lot #5 Filled - Cleaned out was c 173rd Street and Palisades Drive emoved prior to the inspe Cornhusker, 168th, and Interior Streets treets around lot 35 were ior to the 4/26/22 inspecti	ty Homes prior to 11/12/201 (oung prior to 11/12/2015. ut in preparation for sod on r to the 8/16/22 inspection. In Place completed prior to inspection ction on 3/24/16. In Place clean as of the inspection of	Removed 5. Removed Iot 203. The inspe Removed Removed Active n on 7/31/15 by Du Removed Active n on 2/5/19. Story H Active	Contemporation of the net sector will monitor the net sect

Certification Statement:	direction or supervision properly gathered and e persons who manage th the information submitte am aware that there are	of law, that this document and all attachments were p in accordance with a system designed to assure that valuated the information submitted. Based on my inc the system or those persons directly responsible for gr ed is, to the best of my knowledge and belief, true, ac significant penalties for submitting false information int for knowing violations."	t qualified personnel quiry of the person or athering the information, ccurate, and complete. I
Inspector Signature:	Sm Magin		Reviewed By: