E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Site was active during the current inspection.
Findings / Corrective Actions (Date):

Environmental Services Dep	t. Manager			Engineering Al	nswers
	E&	A- P2022.261.001			
Inspector: Rhett DeLay					Stage
	Plattsmouth Historic				
Drainet Name		1			
Project Name:			68003		
For Week Ending: Project Location:	814 Ma	00003			
		011	- (Guos Gourry)		<u>l</u>
Grading:	50%				
Sanitary Sewer:	50%	+			
Storm Sewer:	50%				
Paving: Seeding:	50%				
Utilities:	50%				
Overall Development:	50%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Weel
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"	10		4	
Wednesday:	0.00"	12/7/2022	Sunny 25/37	1:25 PM	
Thursday:	0.00"				
Friday: Saturday:	0.00"				
Saturday.	0.00				<u> </u>
	None				
Complaints:					
	ns) of the site do not have grading, earthwork, or ground				
Grading work active northwest	side of site, utility installation, footings poured (9/28/22). Framing for pay	ving roadways (11/9/22). P	aving roadways (11/1	6/22).
What temporary or permanent stabi	lization measures listed in this section are being implen	nented?			
Existing Vegetation (9/21/22).					
Checklist Questions:					
Are receiving waters adjacer	t to the project free of any significant signs	of erosion or sediment	that would be associate	d with the construct	ion activity?
Yes Create Corrective Action?					
N/A					
Have disturbed areas been s	eeded or otherwise stabilized as required?	List inactive portions o	f the project and if stabil	ization measure are	adequate or needed
No Create Corrective Action?					
See Findings Section					
Are waste materials (consent	e, construction material, hazardous, etc.) be	ing managed properly	2		
No	e, construction material, nazardous, etc.) be	ang manageu property	r		
Create Corrective Action?					
See BMP Section					
	and adjacent streets being maintained adequ	uately?			
Yes Create Corrective Action?					
Create Corrective Action? N/A					
	onstruction activity adequately controlled o	n the site?			
Yes Create Corrective Action?					
N/A					
		·			
Comments:					

- Findings / Corrective Actions (Date):
 1.) Some maintenance required in the BMP Section
 2.) Disturbed area to the south east should be stabilized. Lund Ross was informed to complete by 11/16/22. Not done as of last inspection.

Unique Name	Type	Location	Projected Install Date	Status	Maintena	
ČE 01	Construction Entrance	D2		Removed		
Current Condition:	Removed- Lund Ross paved the constru	ction entrance prior to the in	spection on 11/16/22.			
CE 02	Construction Entrance	M11		Removed		
Current Condition:	Removed- Lund Ross paved the rest cor				1	
IF 01	Inlet Filter	A7	11/16/2022	Pending	Yes	
Current Condition:	Pending-					
	Inlet filter should be installed.	11/16/22 Not done as of la	et inconcition Lund Poss	was rominded on 13	V2/22	
15.00	Lund Ross was informed to complete by					
IF 02 Current Condition:	Inlet Filter	A9	11/16/2022	Pending	Yes	
current condition:	Pending- Inlet filter should be installed. Lund Ross was informed to complete by	44/40/00 New Jersey or of le	at is a satisfact Lund December		W0/00	
IF 03	Inlet Filter	B10	11/16/2022	Pending	Yes	
Current Condition:	Pending-	210	11/10/2022	1 oriding	100	
	Inlet filter should be installed. Lund Ross was informed to complete by	11/16/22. Not done as of la	st inspection. Lund Ross	was reminded on 12	/2/22.	
MS 01	Material Storage	On Site	9/30/2022	Active	No	
Current Condition:	Active - Lund Ross stored material is org					
PB 01	Portable Toilet	On Site	9/30/2022	Active	Yes	
Current Condition:	Fair Condition - Lund Ross installed and	secured a set of portable to	lets prior to the 10/05/22	inspection		
	Portable toilets should be secured with our Lund Ross was informed to complete by		st inspection. Lund Ross	was reminded on 12	2/2/22.	
SB A Current Condition:	Sediment Basin Pending -	B3	9/30/2022	Pending	Yes	
	The sediment basin should be installed per SWPPP.					
	Lund Ross was informed to complete by					
SB B Current Condition:	Sediment Basin Pending -	G14	9/30/2022	Pending	Yes	
	The sediment basin should be installed p		st inspection Lund Ross	was reminded on 11	/10/22 12/2/2:	
SF 01	Silt Fence	A2-D2	9/28/2022	Active	Yes	
Current Condition:	Fair Condition- Lund Ross installed silt fence prior to the 9/28/22 inspection. 1.) Silt fence should be extended to the south. 2.) Additional silt fence check is needed to the north. 1.) Lund Ross was informed to complete by 11/16/22. Not done as of last inspection. Lund Ross was reminded on 12/2/22.					
		by 11/16/22. Not done as o				
SF 02	2.) Lund Ross was informed to complete	by 11/16/22. Not done as o by 11/16/22. Not done as o	f last inspection. Lund Ro	ss was reminded or	12/2/22.	
SF 02 Current Condition:	2.) Lund Ross was informed to complete Silt Fence	by 11/16/22. Not done as o				
Current Condition:	2.) Lund Ross was informed to complete Silt Fence Pending - Silt fence should be installed. Lund Ross was informed to complete by	by 11/16/22. Not done as o by 11/16/22. Not done as o A3-H12	f last inspection. Lund Ro 9/30/2022	ss was reminded or Pending was reminded on 12	12/2/22. Yes	
Current Condition:	2.) Lund Ross was informed to complete Silt Fence Pending - Silt fence should be installed. Lund Ross was informed to complete by Silt Fence	by 11/16/22. Not done as o by 11/16/22. Not done as o A3-H12 11/16/22. Not done as of later G12-N15	f last inspection. Lund Ro 9/30/2022 st inspection. Lund Ross 9/30/2022	ss was reminded or Pending was reminded on 12 Pending	12/2/22. Yes	
SF 03 Current Condition:	2.) Lund Ross was informed to complete Silt Fence Pending - Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Pending - The silt fence will be installed of Silt fence should be installed. Lund Ross was informed to complete by	by 11/16/22. Not done as o by 11/16/22. Not done as o A3-H12 11/16/22. Not done as of late G12-N15 on site when machinery is av	st inspection. Lund Ross 9/30/2022 st inspection. Lund Ross 9/30/2022 vailable as of 9/28/22 a dir	was reminded on 12 Pending was reminded on 12 Pending t berm is in place.	12/2/22. Yes //2/22. Yes	
SF 03 Current Condition:	2.) Lund Ross was informed to complete Silt Fence Pending - Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Pending - The silt fence will be installed of Silt fence should be installed. Lund Ross was informed to complete by Silt Fence	by 11/16/22. Not done as or by 11/16/22. Not done as or A3-H12 11/16/22. Not done as of later of the state o	st inspection. Lund Ross 9/30/2022 st inspection. Lund Ross 9/30/2022 railable as of 9/28/22 a dia	was reminded on 12 Pending Was reminded on 12 Pending t berm is in place. Was reminded on 12 Removed	12/2/22. Yes 1/2/22. Yes	
SF 03 Current Condition: SF 04 Current Condition:	2.) Lund Ross was informed to complete Silt Fence Pending - Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Pending - The silt fence will be installed of Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Removed- Silt fence is uphill of disturbed	by 11/16/22. Not done as of by 11/16/22. Not done as of A3-H12 11/16/22. Not done as of later and the state of the state	st inspection. Lund Ross 9/30/2022 st inspection. Lund Ross 9/30/2022 vailable as of 9/28/22 a direction. Lund Ross st inspection. Lund Ross at inspection. Lund Ross inspection as of 9/28/22 a direction.	was reminded on 12 Pending was reminded on 12 Pending t berm is in place. was reminded on 12 Removed f the 11/30/22 inspe	12/2/22. Yes 1/2/22. Yes 1/2/22.	
SF 03 Current Condition: SF 04 Current Condition: STR	2.) Lund Ross was informed to complete Silt Fence Pending - Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Pending - The silt fence will be installed of Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Removed- Silt fence is uphill of disturbed Streets	by 11/16/22. Not done as of by 11/16/22. Not done as of last G12-N15 on site when machinery is available. E1-E4 area. There is no recomme ADJ and Internal Streets	st inspection. Lund Ross 9/30/2022 st inspection. Lund Ross 9/30/2022 railable as of 9/28/22 a dia	was reminded on 12 Pending Was reminded on 12 Pending t berm is in place. Was reminded on 12 Removed	12/2/22. Yes 1/2/22. Yes	
SF 03 Current Condition: SF 04 Current Condition: STR Current Condition:	2.) Lund Ross was informed to complete Silt Fence Pending - Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Pending - The silt fence will be installed of Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Removed- Silt fence is uphill of disturbed Streets Good Condition- No major signs of track	by 11/16/22. Not done as of by 11/16/22. Not done as of last G12-N15 on site when machinery is available. E1-E4 area. There is no recomme ADJ and Internal Streets	st inspection. Lund Ross 9/30/2022 st inspection. Lund Ross 9/30/2022 vailable as of 9/28/22 a direction. Lund Ross st inspection. Lund Ross at inspection. Lund Ross inspection as of 9/28/22 a direction.	was reminded on 12 Pending was reminded on 12 Pending t berm is in place. was reminded on 12 Removed f the 11/30/22 inspe	12/2/22. Yes //2/22. Yes //2/22. //2/22.	
SF 03 Current Condition: SF 04 Current Condition: STR Current Condition: STR Current Condition:	2.) Lund Ross was informed to complete Silt Fence Pending - Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Pending - The silt fence will be installed of Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Removed- Silt fence is uphill of disturbed Streets Good Condition- No major signs of track SWPPP Signs	by 11/16/22. Not done as or by 11/16/22. Not done as of late A3-H12 11/16/22. Not done as of late G12-N15 on site when machinery is available area. There is no recommed ADJ and Internal Streets off. South of CE 1	st inspection. Lund Ross 9/30/2022 st inspection. Lund Ross 9/30/2022 railable as of 9/28/22 a direction. Lund Ross of 9/28/22 a direction. Lund Ross of 9/30/2022 9/30/2022	was reminded on 12 Pending was reminded on 12 Pending t berm is in place. was reminded on 12 Removed f the 11/30/22 insper Active	/2/22. /2/22. Yes //2/22. /2/22. //2/22. Pection. No	
SF 03 Current Condition: SF 04 Current Condition: STR Current Condition: SWPPP Sign Current Condition:	2.) Lund Ross was informed to complete Silt Fence Pending - Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Pending - The silt fence will be installed of Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Removed- Silt Fence is uphill of disturbed Streets Good Condition- No major signs of track SWPPP Signs Good Condition - E&A inspector will in	by 11/16/22. Not done as or by 11/16/22. Not done as or A3-H12 11/16/22. Not done as of later G12-N15 on site when machinery is as a site when machinery is a site when m	st inspection. Lund Ross 9/30/2022 st inspection. Lund Ross 9/30/2022 vailable as of 9/28/22 a direction. Lund Ross st inspection. Lund Ross endation for this BMP as of 9/30/2022 9/30/2022 of the south of CE 1 duri	was reminded on 12 Pending Was reminded on 12 Pending To berm is in place. Was reminded on 12 Removed f the 11/30/22 inspendent in the 11/30/22 inspenden	/2/22. //2/22. //2/22. //2/22. //2/22. //2/22. No No No No	
SF 03 Current Condition: SF 04 Current Condition: STR Current Condition: STR Current Condition:	2.) Lund Ross was informed to complete Silt Fence Pending - Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Pending - The silt fence will be installed of Silt fence should be installed. Lund Ross was informed to complete by Silt Fence Removed- Silt fence is uphill of disturbed Streets Good Condition- No major signs of track SWPPP Signs	by 11/16/22. Not done as or by 11/16/22. Not done as or A3-H12 11/16/22. Not done as of late G12-N15 on site when machinery is available of the G12-N15 on site when machinery is available of the G12-N15 on site when machinery is available of the G12-N15 area. There is no recomme ADJ and Internal Streets off. South of CE 1 onstalled the SWPPP sign to On site	st inspection. Lund Ross 9/30/2022 st inspection. Lund Ross 9/30/2022 vailable as of 9/28/22 a direction. Lund Ross of 9/28/22 a direction. Lund Ross of 9/30/2022 9/30/2022 othe south of CE 1 duri 9/30/2022	was reminded on 12 Pending was reminded on 12 Pending t berm is in place. was reminded on 12 Removed f the 11/30/22 inspr Active Active Active Active Active	12/2/22. Yes 1/2/22. Yes 1/2/22. Pection. No No No No No No No No	

	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."				
Inspector Signature:	no ble		Reviewed By:		