E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

	E	&A- P2022.261.001				
Inspector: Ethan Anderson	on					
Project Name:	Plattsmouth Historic	1				
For Week Ending:		68003				
Project Location:	814 N					
					<del></del>	
Grading:	50					
Sanitary Sewer:	50					
Storm Sewer:	50					
Paving:	50					
Seeding:		%				
Utilities:	50					
Overall Development:	50	%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Times	
					Week 1	
Sunday:	0.00"					
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"	5/24/2023	Sunny 85/58	2:20 PM		
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.00"					

## Construction Sequencing:

Complaints:

asins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturb

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22).

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22).

hat temporary or permanent stabilization measures listed in this section are being implemented?

None

Existing Vegetation (9/21/22).

## **Checklist Questions:**

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

**Create Corrective Action?** 

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?
No, See BMP Section

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

**Create Corrective Action?** 

Site was active during the current inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) Some maintenance required in the BMP Section.

			T		1
Unique Name CE 01	Type  Construction Entrance	Location D2	Projected Install Date	Status Removed	Maintenance
Current Condition:	Removed- Lund Ross paved the construction	ction entrance prior to the ins	spection on 11/16/22.	•	•
CE 02	Construction Entrance	M11		Removed	
Current Condition:	Removed- Lund Ross paved the rest con	·	_ '	1	T
IF 01 Current Condition:	Inlet Filter Good Condition - Lund Ross cleaned off	A7 inlet prior to inspection on 5	5/17/2023 /10/23. Lund Ross installe	Active ed silt fence around t	No he inlet prior to
	inspection on 5/17/23.				
IF 02	Inlet Filter	A9	5/17/2023	Active	No
Current Condition:	Good Condition - Lund Ross cleaned off inspection on 5/17/23.	inlet prior to inspection on 5	10/23. Lund Ross installe	ed silt fence around t	he inlet prior to
IF 03	Inlet Filter	B10	5/17/2023	Active	No
Current Condition:	Good Contition - Lund Ross installed a si	It fence wrap on the inlet pri	or to the inspection on 5/3	3/23. Lund Ross insta	alled a silt fence in
	front of the inlet prior to inspection on 5/1	7/23.			
MS 01	Material Storage	On Site	9/30/2022	Active	No
Current Condition:	Good Condition- Lund Ross stored mater lot near SB A used as material storage, in			on on 11/9/22.Lund	Ross is using parki
PB 01	Portable Toilet	On Site	9/30/2022	Active	No
Current Condition:	Good Condition - Lund Ross installed and were adequately secured with pallets again	d secured a set of portable t	oilets prior to the 10/05/22		
PB 02	Portable Toilet	On Site	5/10/2023	Active	Yes
Current Condition:	Fair Condition - Lund Ross installed a se	· ·		Active	162
	PT needs to be secured.  Lund Ross was informed to complete by				
SB A	Sediment Basin	B3	9/30/2022	Pending	Yes
Current Condition:	Pending - Inlet and outfall for the basin a inlet and outfall prior to the inspection on The sediment basin should be installed p	5/3/23. Lund Ross installed	silt fence around the inle	/26/23. Lund Ross fi	
	Lund Ross was informed to complete by 4/5/23, 5/10/23			vas reminded on 11/	10/22, 12/5/22, 2/3
SB B	Sediment Basin	C44	9/30/2022	Pending	Yes
		l G14			
Current Condition:	Pending - The sediment basin should be installed p				
	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by 4/5/23, 5/10/23	er SWPPP. 11/02/22. Not done as of las	st inspection. Lund Ross w	vas reminded on 11/	10/22, 12/5/22, 2/3
SF 01 Current Condition:	Pending - The sediment basin should be installed p Lund Ross was informed to complete by 4/5/23, 5/10/23 Silt Fence Fair Condition- Lund Ross installed silt fe	er SWPPP.  11/02/22. Not done as of las  A2-D2 ence prior to the 9/28/22 insp	ot inspection. Lund Ross w 9/28/2022 pection. Lund Ross extend	vas reminded on 11/ Active led the silt fence up	10/22, 12/5/22, 2/3 Yes the CE and installe
SF 01	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by 4/5/23, 5/10/23  Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.	er SWPPP.  11/02/22. Not done as of las  A2-D2  Ince prior to the 9/28/22 insp  f the CE prior to the inspecti	of inspection. Lund Ross w 9/28/2022 pection. Lund Ross extendion on 5/10/23. Lund Ross	vas reminded on 11/ Active led the silt fence up a also installed SF or	10/22, 12/5/22, 2/3  Yes the CE and installe the other side of the
SF 01 Current Condition:	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by 4/5/23, 5/10/23  Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.  Lund Ross was informed to complete by	er SWPPP.  11/02/22. Not done as of las  A2-D2  Ince prior to the 9/28/22 inspection from the inspection of the inspection of the second of last	st inspection. Lund Ross w 9/28/2022 section. Lund Ross extendion on 5/10/23. Lund Ross inspection. Lund Ross wa	Active Led the silt fence up a also installed SF or a less reminded on 5/3/2	10/22, 12/5/22, 2/3  Yes the CE and installenthe other side of the others.
SF 01 Current Condition:  SF 02 Current Condition:	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by 4/5/23, 5/10/23  Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.	er SWPPP.  11/02/22. Not done as of las  A2-D2  ence prior to the 9/28/22 insp  f the CE prior to the inspect  4/12/23. Not done as of last  A3-H12  h of SB A was correctly desi	st inspection. Lund Ross was 19/28/2022 Dection. Lund Ross extendion on 5/10/23. Lund Ross was 19/30/2022 Inspection. Lund Ross was 19/30/2022 Inspection SF 02 for future of the section	vas reminded on 11/  Active led the silt fence up is also installed SF or also installed SF or as reminded on 5/3/2  Pending e reports, SWPPP m	Yes the CE and installe the other side of the ot
SF 01 Current Condition:  SF 02 Current Condition:	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by  4/5/23, 5/10/23  Silt Fence  Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.  Lund Ross was informed to complete by  Silt Fence  Pending - For consistency, silt fence nort maintenance plans on 2/3/23.  Silt fence should be installed.  Lund Ross was informed to complete by  5/3/23  Silt Fence	er SWPPP.  11/02/22. Not done as of last  A2-D2  Ince prior to the 9/28/22 insp  f the CE prior to the inspect  4/12/23. Not done as of last  A3-H12 In of SB A was correctly desi  11/16/22. Not done as of last  G12-N15	9/28/2022 section. Lund Ross was section on 5/10/23. Lund Ross was 9/30/2022 gnated as SF 02 for future st inspection. Lund Ross was 9/30/2022	vas reminded on 11/  Active led the slit fence up s also installed SF or as reminded on 5/3/2  Pending e reports, SWPPP no vas reminded on 12/  Pending	10/22, 12/5/22, 2/3  Yes the CE and installe in the other side of  23,  Yes hap updates and  5/22, 2/3/23, 4/5/23
SF 01 Current Condition:  SF 02 Current Condition:	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by 4/5/23, 5/10/23  Silt Fence  Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.  Lund Ross was informed to complete by Silt Fence  Pending - For consistency, silt fence nort maintenance plans on 2/3/23.  Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence  Pending - The silt fence will be installed of across future reports, SWPPP maps, and	er SWPPP.  11/02/22. Not done as of last  A2-D2  Price prior to the 9/28/22 inspection of the CE prior to the inspection of the CE prior to the inspection of SB A was correctly designed by the CE prior to the inspection of SB A was correctly designed by the CE prior to the inspection of SB A was correctly designed by the CE prior to the inspection of SB A was correctly designed by the CE prior to the inspection of SB A was correctly designed by the CE prior to the inspection of SB A was correctly designed by the CE prior to the inspection of SB A was correctly designed by the CE prior to the inspection of SB A was correctly designed by the inspection of SB A was cor	st inspection. Lund Ross w 9/28/2022 pection. Lund Ross extendion on 5/10/23. Lund Ross inspection. Lund Ross wa 9/30/2022 gnated as SF 02 for future st inspection. Lund Ross w	vas reminded on 11/  Active led the silt fence up a also installed SF or a least reminded on 5/3/2  Pending a reports, SWPPP may a reminded on 12/  Pending dirt berm is in place.	Yes the CE and installe the other side of  Yes  Yes Tyes Tyes Tyes Tyes Tyes Tyes Tyes Ty
SF 01 Current Condition:  SF 02 Current Condition:	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by 4/5/23, 5/10/23  Silt Fence  Fair Condition- Lund Ross installed silt fethe remaining section on the south side centrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.  Lund Ross was informed to complete by  Silt Fence  Pending - For consistency, silt fence nort maintenance plans on 2/3/23.  Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence  Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed.	er SWPPP.  11/02/22. Not done as of last A2-D2 ence prior to the 9/28/22 inspection of the prior to the inspection of the cell prior to the cell prior to the inspection of the cell prior to th	st inspection. Lund Ross w 9/28/2022 section. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa 9/30/2022 gnated as SF 02 for future st inspection. Lund Ross w 9/30/2022 /ailable. As of 9/28/22, a of silt fence will be design	Active led the silt fence up as reminded on 5/3/2 Pending reports, SWPPP nowas reminded on 12/ Pending dirt berm is in place, gnated as SF 03, as	Yes the CE and installed in the other side of 23, Yes nap updates and 5/22, 2/3/23, 4/5/2: Yes For consistency of 2/3/23.
SF 01 Current Condition:  SF 02 Current Condition:  SF 03 Current Condition:	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by  4/5/23, 5/10/23  Silt Fence  Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.  Lund Ross was informed to complete by Silt Fence  Pending - For consistency, silt fence nort maintenance plans on 2/3/23.  Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence  Pending - The silt fence will be installed of across future reports, SWPPP maps, and Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23	er SWPPP.  11/02/22. Not done as of last A2-D2 Ince prior to the 9/28/22 insp if the CE prior to the inspect  4/12/23. Not done as of last A3-H12 h of SB A was correctly desi  11/16/22. Not done as of last G12-N15 on site when machinery is an it maintenance plans, this rui	st inspection. Lund Ross w 9/28/2022 section. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa 9/30/2022 gnated as SF 02 for future st inspection. Lund Ross w 9/30/2022 /ailable. As of 9/28/22, a of silt fence will be design	vas reminded on 11/  Active led the silt fence up s also installed SF or as reminded on 5/3/2  Pending e reports, SWPPP n  vas reminded on 12/  Pending dirt berm is in place, gnated as SF 03, as  vas reminded on 12/	Yes the CE and installed in the other side of in th
SF 01 Current Condition:  SF 02 Current Condition:  SF 03 Current Condition:	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by 4/5/23, 5/10/23  Silt Fence  Fair Condition- Lund Ross installed silt fet the remaining section on the south side of entrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.  Lund Ross was informed to complete by  Silt Fence  Pending - For consistency, silt fence nort maintenance plans on 2/3/23.  Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence  Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence	er SWPPP.  11/02/22. Not done as of last A2-D2 ence prior to the 9/28/22 inspection to the 9/28/22 inspection to the inspection of the cell prior to the cell prior to the cell prior to the inspection of the cell prior to the cell prior to the inspection of the cell prior to the cel	st inspection. Lund Ross w 9/28/2022 section. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa 9/30/2022 gnated as SF 02 for future st inspection. Lund Ross w 9/30/2022 vailable. As of 9/28/22, a of silt fence will be designed as st inspection. Lund Ross w	vas reminded on 11/  Active led the silt fence up as also installed SF or also installed SF or also reminded on 5/3/2  Pending as reminded on 12/  Pending dirt berm is in place, anated as SF 03, as a vas reminded on 12/  Removed	10/22, 12/5/22, 2/3  Yes the CE and installe the other side of in  23,  Yes hap updates and  5/22, 2/3/23, 4/5/23  Yes For consistency of 2/3/23.
SF 01 Current Condition:  SF 02 Current Condition:  SF 03 Current Condition:  SF 04 Current Condition:	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by  4/5/23, 5/10/23  Silt Fence  Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.  Lund Ross was informed to complete by Silt Fence  Pending - For consistency, silt fence nort maintenance plans on 2/3/23.  Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence  Pending - The silt fence will be installed of across future reports, SWPPP maps, and Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23	er SWPPP.  11/02/22. Not done as of last A2-D2 Price prior to the 9/28/22 inspection to the 9/28/22 inspection to the inspection of the CE prior to the CE prior to the inspection of the CE prior to the CE prior to the inspection of the CE prior to the CE prior to the inspection of the CE prior to the CE	st inspection. Lund Ross w 9/28/2022 section. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa 9/30/2022 gnated as SF 02 for future st inspection. Lund Ross w 9/30/2022 vailable. As of 9/28/22, a of silt fence will be designed as st inspection. Lund Ross w	vas reminded on 11/  Active led the silt fence up as also installed SF or also installed SF or also reminded on 5/3/2  Pending as reminded on 12/  Pending dirt berm is in place, anated as SF 03, as a vas reminded on 12/  Removed	10/22, 12/5/22, 2/3  Yes the CE and installe the other side of  23,  Yes nap updates and  5/22, 2/3/23, 4/5/2  Yes For consistency of 2/3/23.
SF 01 Current Condition:  SF 02 Current Condition:  SF 03 Current Condition:	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by 4/5/23, 5/10/23  Silt Fence  Fair Condition- Lund Ross installed silt fet the remaining section on the south side of entrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.  Lund Ross was informed to complete by  Silt Fence  Pending - For consistency, silt fence nort maintenance plans on 2/3/23.  Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence  Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence	er SWPPP.  11/02/22. Not done as of last A2-D2 Price prior to the 9/28/22 inspection of the CE prior to the	st inspection. Lund Ross w 9/28/2022 pection. Lund Ross extend inspection. Lund Ross wa 9/30/2022 gnated as SF 02 for future st inspection. Lund Ross w 9/30/2022 vailable. As of 9/28/22, a of silt fence will be designed to the silt inspection. Lund Ross w 10/2022 vailable. As of 9/28/22, a of silt fence will be designed to silt fence will be designed to silt inspection. Lund Ross w 10/2022 vailable of silt fence will be designed to silt fence will be designed t	vas reminded on 11/  Active led the silt fence up a also installed SF or a also installed SF or a as reminded on 5/3/2  Pending e reports, SWPPP may a reminded on 12/  Pending dirt berm is in place, anated as SF 03, as a serification of the 11/30/22 inspections of the 11/30/22 insp	10/22, 12/5/22, 2/3  Yes the CE and installe in the other side of  23,  Yes nap updates and  5/22, 2/3/23, 4/5/2  Yes For consistency of 2/3/23.
SF 01 Current Condition:  SF 02 Current Condition:  SF 03 Current Condition:  SF 04 Current Condition:  STR	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by 4/5/23, 5/10/23  Silt Fence  Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.  Lund Ross was informed to complete by Silt Fence  Pending - For consistency, silt fence nort maintenance plans on 2/3/23.  Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence  Pending - The silt fence will be installed of across future reports, SWPPP maps, and Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence  Removed- Silt fence is uphill of disturbed Streets  Fair Condition- A trail of escaped sedime Ave.  The interior and exterior streets should be	er SWPPP.  11/02/22. Not done as of last  A2-D2 ence prior to the 9/28/22 inspection of the Plant of the CE prior to the inspection of the CE prior to the inspection of the CE prio	st inspection. Lund Ross was placed as SF 02 for future st inspection. Lund Ross was placed as SF 02 for future st inspection. Lund Ross was placed as SF 02 for future st inspection. Lund Ross was placed as SF 02 for future st inspection. Lund Ross was placed as SF 02 for future st inspection. Lund Ross was placed as placed	vas reminded on 11/  Active led the silt fence up is also installed SF or also installed SF o	Yes the CE and installe the other side of  Yes the CE and installe the other side of  Yes ap updates and  Yes For consistency of 2/3/23.  5/22. 2/3/23, 4/5/23  5/22. 2/3/23, 4/5/23  ction. Yes own to Washingtor
SF 01 Current Condition:  SF 02 Current Condition:  SF 03 Current Condition:  SF 04 Current Condition:  STR	Pending -  The sediment basin should be installed p  Lund Ross was informed to complete by 4/5/23, 5/10/23  Silt Fence  Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23.  Areas above SF 01 should be stabilized.  Lund Ross was informed to complete by Silt Fence  Pending - For consistency, silt fence nort maintenance plans on 2/3/23.  Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence  Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence  Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed.  Lund Ross was informed to complete by 5/3/23  Silt Fence  Removed- Silt fence is uphill of disturbed Streets  Fair Condition- A trail of escaped sedime Ave.	er SWPPP.  11/02/22. Not done as of last  A2-D2 ence prior to the 9/28/22 inspection of the Plant of the CE prior to the inspection of the CE prior to the inspection of the CE prio	st inspection. Lund Ross was placed as SF 02 for future st inspection. Lund Ross was placed as SF 02 for future st inspection. Lund Ross was placed as SF 02 for future st inspection. Lund Ross was placed as SF 02 for future st inspection. Lund Ross was placed as SF 02 for future st inspection. Lund Ross was placed as placed	vas reminded on 11/  Active led the silt fence up is also installed SF or also installed SF o	Yes the CE and installe the other side of the ot

Current Condition:	Good Condition - Lund Ross installed straw wattles along the south side of property along Main St. prior to the inspection on 5/10/23.						
SWPPP Sign	SWPPP Signs	South of CE 1	9/30/2022	Active	No		
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign to the south of CE 1 during the inspection on 12/7/22. E&A inspector updated the SWPPP sign with the correct permit information website during the 12/21/22 inspection.						
WO 01	Concrete Washout	On site	9/30/2022	Active	Yes		
Current Condition:	Fair Condition - Lund Ross cleaned up concrete waste prior to the inspection on 11/9/22. Lund Ross installed a concrete washout onsite prior to the inspection on 11/16/22. Lund Ross removed concrete washouts prior to the inspection on 11/123/22. Lund Ross installed 1 concrete washout bin onsite prior to the inspection on 11/30/22. More concrete waste was observed during the 2/8/23 inspection. More effort to utilize the concrete washout bin onsite is needed. More concrete waste was observed escaping designated areas during the 2/22/23 inspection. Concrete mixing bucket was removed prior to the 3/8/23 inspection.  1.) Concrete waste near the material storage (H13) should be cleaned up. 2.) A concrete washout should be installed on site.  1.) Lund Ross was informed to complete by 2/8/23. Not done as of the last inspection. Lund Ross was reminded on 4/5/23, 5/3/23 2.) Lund Ross was informed to complete by 3/1/23. Not done as of the last inspection. Lund Ross was reminded on 4/5/23, 5/3/23						
WS 01	Waste storage	On site	3/22/2023	Active	No		
Current Condition:	Active - Additional waste storage on site was observed during the inspection on 3/22/23.						
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
Inspector Signature:	En Carlon			Reviewed By:	to See		