E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E8	A- P2022.261.001			
Inspector: Ethan Anderson						Stage
Project Name:	Plattsmouth	Plattsmouth Historic High School Housing and New Apartments CSW-202207329				
For Week Ending:		6/10/2023				
Project Location:		814 Main St Plattsmouth, NE (Cass County)				
Grading:	T	50%	I			
Sanitary Sewer:		50%				
Storm Sewer:		50%				
Paving:		50%				
Seeding:		0%				
Utilities:		50%				
Overall Development:		50%				
RAIN FALL AMOUNTS	Amount in tenths		Date inspected	Weather Conditions	Time	Storm Event Times
						Week '
Sunday:	1.22"					2:00 AM - 6:00 AM
Monday:	0.00"					

Tuesday:	0.00"					
Wednesday:	0.00"	6/14/2023	Sunny 83/59	11:30 AM		
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.00"					
	None					

Complaints:

Construction Sequencing:

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22).

orary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (9/21/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?
No, See BMP Section

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments:

1.) Site was active during the current inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): Some maintenance required in the BMP Section.

Unique Name CE 01 Current Condition: CE 02 Current Condition:	Type					
Current Condition: CE 02		Location	Projected Install Date	Status	Maintenance	
CE 02	Construction Entrance	D2		Removed		
	Removed- Lund Ross paved the construction Entrance	M11		Removed		
	Removed- Lund Ross paved the rest con		e inspection on 11/16/22	Ttomoved		
IF 01	Inlet Filter	A7	5/17/2023	Active	No	
Current Condition:	Good Condition - Lund Ross cleaned off					
	inspection on 5/17/23.				'	
IF 02	Inlet Filter	A9	5/17/2023	Active	No	
Current Condition:	Good Condition - Lund Ross cleaned off	inlet prior to inspection on 5/	10/23. Lund Ross installe	d silt fence around t	the inlet prior to	
	inspection on 5/17/23.					
IF 03	Inlet Filter	B10	5/17/2023	Active	No	
Current Condition:	Good Condition - Lund Ross installed a s		ior to the inspection on 5/3	3/23. Lund Ross ins	talled a silt fence in	
	front of the inlet prior to inspection on 5/1				_	
MS 01	Material Storage	On Site	9/30/2022	Active	No No	
Current Condition:	Good Condition- Lund Ross stored mater			on on 11/9/22.Lund	Ross is using parking	
	lot near SB A used as material storage, in	ncluding lumber prior to the	nspection on 2/8/23.			
PB 01	Portable Toilet	On Site	9/30/2022	Active	No	
Current Condition:	Good Condition - Lund Ross installed and			inspection. The po	rtable toilets on site	
	were adequately secured with pallets aga					
PB 02	Portable Toilet	On Site	5/10/2023	Active	Yes	
Current Condition:	Fair Condition - Lund Ross installed a se	t of portable toilets prior to the	ne 5/10/23 inspection.			
	Deutskie teilete waard te ka aan ward					
	Portable toilets need to be secured.					
	Lund Ross was informed to complete by	5/18/23 Not done as of last	inspection Lund Ross wa	s reminded on 5/31	123 6/7/23	
SB A	Sediment Basin	B3	9/30/2022	Pending	Yes	
Current Condition:	Pending - Inlet and outfall for the basin a					
	inlet and outfall prior to the inspection on					
	Ross repaired the erosion at the inlet					
	The sediment basin should be installed p	er SWPPP, including outfall	cleanout and repair.			
	·····osamon securiorista de mentre per octivir i mentre grande de securiorista					
	Lund Ross was informed to complete by	11/02/22. Not done as of las	t inspection. Lund Ross w	as reminded on 11/	<mark>/10/22, 12/5/22, 2/3/2</mark>	
	4/5/23, 5/10/23, 5/31/23, 6/7/23					
	0 11 12 1	1 011	0/00/0000			
SB B Current Condition:	Sediment Basin Pending - Lund Ross was actively working	G14	9/30/2022	Pending Pending	Yes	
Current Condition.	to the inspection on 6/14/23.	ing on the basin during the in	specifori or 0/1/23. Lunu	NUSS Started Ilista		
	to the inspection on 6/14/23.				illing the basin prio	
					ming the basin prio	
	The sediment hasin should be installed n	er SWPPP			aning the basin pric	
	The sediment basin should be installed p	er SWPPP.			ming the basin pric	
			t inspection. Lund Ross w	as reminded on 11/		
	The sediment basin should be installed p Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23		t inspection. Lund Ross w	/as reminded on 11/		
SF 01	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence	11/02/22. Not done as of las	9/28/2022	Active	/10/22, 12/5/22, 2/3/2 Yes	
SF 01 Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe	11/02/22. Not done as of las A2-D2 ence prior to the 9/28/22 insp	9/28/2022 ection. Lund Ross extend	Active led the silt fence up	10/22, 12/5/22, 2/3/ Yes the CE and installed	
	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of	11/02/22. Not done as of las A2-D2 ence prior to the 9/28/22 insp	9/28/2022 ection. Lund Ross extend	Active led the silt fence up	110/22, 12/5/22, 2/3/3 Yes the CE and installed	
	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe	11/02/22. Not done as of las A2-D2 ence prior to the 9/28/22 insp	9/28/2022 ection. Lund Ross extend	Active led the silt fence up	10/22, 12/5/22, 2/3/ Yes the CE and installed	
	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23.	11/02/22. Not done as of las A2-D2 ence prior to the 9/28/22 insp of the CE prior to the inspection	9/28/2022 ection. Lund Ross extend	Active led the silt fence up	110/22, 12/5/22, 2/3/3 Yes the CE and installed	
	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of	11/02/22. Not done as of las A2-D2 ence prior to the 9/28/22 insp of the CE prior to the inspection	9/28/2022 ection. Lund Ross extend	Active led the silt fence up	110/22, 12/5/22, 2/3/2 Yes the CE and installed	
	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized.	11/02/22. Not done as of las A2-D2 noce prior to the 9/28/22 insp if the CE prior to the inspecti	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross	Active led the silt fence up a also installed SF o	Yes the CE and installed n the other side of the	
	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23.	11/02/22. Not done as of las A2-D2 noce prior to the 9/28/22 insp if the CE prior to the inspecti	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross	Active led the silt fence up a also installed SF o	Yes the CE and installed n the other side of the	
Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by	11/02/22. Not done as of las A2-D2 ance prior to the 9/28/22 inspection of the CE prior to the inspection of the cell of the CE prior to the inspection of the cell of the CE prior to the inspection of the cell of the cel	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa	Active led the silt fence up s also installed SF o	Yes the CE and installed in the other side of the	
Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fethe remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence	A2-D2 Price prior to the 9/28/22 inspection of the CE prior to the the CE prio	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa	Active led the silt fence up salso installed SF of as reminded on 5/3/2	Yes Yes the CE and installed in the other side of the country of	
Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence north	A2-D2 Price prior to the 9/28/22 inspection of the CE prior to the the CE prio	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa	Active led the silt fence up salso installed SF of as reminded on 5/3/2	Yes Yes the CE and installed on the other side of the case of the	
Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fethe remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence	A2-D2 Price prior to the 9/28/22 inspection of the CE prior to the the CE prio	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa	Active led the silt fence up salso installed SF of as reminded on 5/3/2	Yes Yes the CE and installed on the other side of the case of the	
Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23.	A2-D2 Price prior to the 9/28/22 inspection of the CE prior to the the CE prio	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa	Active led the silt fence up salso installed SF of as reminded on 5/3/2	Yes Yes the CE and installed on the other side of the case of the	
Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence north	A2-D2 Price prior to the 9/28/22 inspection of the CE prior to the the CE prio	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa	Active led the silt fence up salso installed SF of as reminded on 5/3/2	Yes The CE and installed in the other side of the other side of the case of t	
Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23.	11/02/22. Not done as of last A2-D2 ence prior to the 9/28/22 inspection of the CE prior to the the CE prior	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross was 9/30/2022 gnated as SF 02 for future	Active led the silt fence up s also installed SF o as reminded on 5/3/2 Pending e reports, SWPPP n	Yes the CE and installed in the other side of the centre o	
Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23. Silt fence should be installed.	11/02/22. Not done as of last A2-D2 ence prior to the 9/28/22 inspection of the CE prior to the the CE prior	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross was 9/30/2022 gnated as SF 02 for future	Active led the silt fence up s also installed SF o as reminded on 5/3/2 Pending e reports, SWPPP n	Yes the CE and installed in the other side of the centre o	
Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by	11/02/22. Not done as of last A2-D2 ence prior to the 9/28/22 inspection of the CE prior to the the CE prior	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross was 9/30/2022 gnated as SF 02 for future	Active led the silt fence up s also installed SF o as reminded on 5/3/2 Pending e reports, SWPPP n	Yes the CE and installed in the other side of the case	
SF 02 Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed.	11/02/22. Not done as of last A2-D2 Proce prior to the 9/28/22 inspection of the CE prior to the CE prior to the CE prior to the CE prior to the inspection of the CE prior to the inspection of the CE prior to the CE prior to the inspection of the CE prior to t	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa 9/30/2022 gnated as SF 02 for future trinspection. Lund Ross was 9/30/2022 railable. As of 9/28/22, a callable. As of 9/28/22, a callable.	Active led the silt fence up a also installed SF of a seriminded on 5/3/2 Pending reports, SWPPP news reminded on 12/2 Pending dirt berm is in place.	Yes Tyes Tyes Tyes Tyes Tyes Tyes Tyes Ty	
SF 02 Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence	11/02/22. Not done as of last A2-D2 Proce prior to the 9/28/22 inspection of the CE prior to the CE prior to the CE prior to the CE prior to the inspection of the CE prior to the inspection of the CE prior to the CE prior to the inspection of the CE prior to t	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa 9/30/2022 gnated as SF 02 for future trinspection. Lund Ross was 9/30/2022 railable. As of 9/28/22, a callable. As of 9/28/22, a callable.	Active led the silt fence up a also installed SF of a seriminded on 5/3/2 Pending reports, SWPPP news reminded on 12/2 Pending dirt berm is in place.	Yes Tyes Tyes Tyes Tyes Tyes Tyes Tyes Ty	
SF 02 Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and	11/02/22. Not done as of last A2-D2 Proce prior to the 9/28/22 inspection of the CE prior to the CE prior to the CE prior to the CE prior to the inspection of the CE prior to the inspection of the CE prior to the CE prior to the inspection of the CE prior to t	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa 9/30/2022 gnated as SF 02 for future trinspection. Lund Ross was 9/30/2022 railable. As of 9/28/22, a callable. As of 9/28/22, a callable.	Active led the silt fence up a also installed SF of a seriminded on 5/3/2 Pending reports, SWPPP news reminded on 12/2 Pending dirt berm is in place.	Yes Tyes Tyes Tyes Tyes Tyes Tyes Tyes Ty	
SF 02 Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side of entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed.	11/02/22. Not done as of last A2-D2 Proce prior to the 9/28/22 inspection of the CE prior to the CE prior to the CE prior to the CE prior to the inspection of the CE prior to the inspection of the CE prior to the CE prior to the inspection of the CE prior to t	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross inspection. Lund Ross wa 9/30/2022 gnated as SF 02 for future trinspection. Lund Ross was 9/30/2022 railable. As of 9/28/22, a callable. As of 9/28/22, a callable.	Active led the silt fence up a also installed SF of a seriminded on 5/3/2 Pending reports, SWPPP news reminded on 12/2 Pending dirt berm is in place.	Yes Tyes Tyes Tyes Tyes Tyes Tyes Tyes Ty	
SF 02 Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed.	A2-D2 Ince prior to the 9/28/22 inspection of the CE prior to the the	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross was 9/30/2022 gnated as SF 02 for future trinspection. Lund Ross was 9/30/2022 railable. As of 9/28/22, a of silt fence will be designed.	Active led the silt fence up a also installed SF of also installed SF of a reminded on 5/3/2 Pending a reports, SWPPP nowas reminded on 12/2 Pending dirt berm is in place, anated as SF 03, as	Yes Tyes The CE and installed in the other side of the CE and installed in the other side of the CE and installed in the other side of the CE and installed in the other side of the CE and CE	
SF 02 Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt for the remaining section on the south side of entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed. Lund Ross was informed to complete by across future reports, SWPPP maps, and Silt fence should be installed.	A2-D2 Ince prior to the 9/28/22 inspection of the CE prior to the the	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross was 9/30/2022 gnated as SF 02 for future trinspection. Lund Ross was 9/30/2022 railable. As of 9/28/22, a of silt fence will be designed.	Active led the silt fence up a also installed SF of also installed SF of a reminded on 5/3/2 Pending a reports, SWPPP nowas reminded on 12/2 Pending dirt berm is in place, anated as SF 03, as	Yes Tyes The CE and installed in the other side of the CE and installed in the other side of the CE and installed in the other side of the CE and installed in the other side of the CE and CE	
SF 02 Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed.	A2-D2 Ince prior to the 9/28/22 inspection of the CE prior to the the	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross was 9/30/2022 gnated as SF 02 for future trinspection. Lund Ross was 9/30/2022 railable. As of 9/28/22, a of silt fence will be designed.	Active led the silt fence up a also installed SF of also installed SF of a reminded on 5/3/2 Pending a reports, SWPPP nowas reminded on 12/2 Pending dirt berm is in place, anated as SF 03, as	Yes Tyes The CE and installed in the other side of the CE and installed in the other side of the CE and installed in the other side of the CE and installed in the other side of the CE and CE	
SF 02 Current Condition: SF 03 Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt fe the remaining section on the south side centrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23	A2-D2 Ince prior to the 9/28/22 inspection of the CE prior to the the inspection of the CE prior to the	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross was 9/30/2022 gnated as SF 02 for future trinspection. Lund Ross was 9/30/2022 railable. As of 9/28/22, a of silt fence will be designed.	Active led the silt fence up is also installed SF or as reminded on 5/3/2 Pending as reminded on 12/ Pending dirt berm is in place. Instead as SF 03, as as reminded on 12/ Pass reminded on 12/ Pending Pending	Yes Tyes The CE and installed in the other side of the CE and installed in the other side of the CE and installed in the other side of the CE and installed in the other side of the CE and CE	
SF 02 Current Condition:	Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt for the remaining section on the south side of entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized. Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence nort maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed. Lund Ross was informed to complete by across future reports, SWPPP maps, and Silt fence should be installed.	A2-D2 Ince prior to the 9/28/22 inspection of the CE prior to the the inspection of the CE prior to the	9/28/2022 ection. Lund Ross extend on on 5/10/23. Lund Ross was 9/30/2022 gnated as SF 02 for future trinspection. Lund Ross was 9/30/2022 railable. As of 9/28/22, a of of silt fence will be design trinspection. Lund Ross was 1 silt fence will be design to fine trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection. Lund Ross was 1 silt fence will be design trinspection.	Active led the silt fence up is also installed SF or also installed SF or also reminded on 5/3/2 Pending is reminded on 12/ Pending dirt berm is in place, anated as SF 03, as a reminded on 12/ Removed	Yes the CE and installed in the other side of the CE and installed in the other side of the CE and installed in the other side of the CE and installed in the other side of the CE and C	

Current Condition:	Fair Condition- A trail of escaped sedimer Ave.	nt was observed along the s	treet curb on N 10th st tra	aveling all the way do	own to Washington		
	The interior and exterior streets should be cleaned. Lund Ross was informed to complete by 4/26/23. Not done as of last inspection. Lund Ross was reminded on 5/10/23, 5/31/23, 6/7/23						
SW 1	Straw Wattles	Main St	5/10/2023	Active	No		
Current Condition:	Good Condition - Lund Ross installed straw wattles along the south side of property along Main St. prior to the inspection on 5/10/23. Lund Ross cleaned out the wattles and repositioned them prior to the inspection on 6/14/23.						
SWPPP Sign	SWPPP Signs	South of CE 1	9/30/2022	Active	No		
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign to the south of CE 1 during the inspection on 12/7/22. E&A inspector updated the SWPPP sign with the correct permit information website during the 12/21/22 inspection.						
WO 01	Concrete Washout	On site	9/30/2022	Active	Yes		
	 2/22/23 inspection. Concrete mixing bucket was removed prior to the 3/8/23 inspection. Lund Ross removed the concrete waste near the material storage prior to the inspection on 6/7/23. A concrete washout should be installed on site. Lund Ross was informed to complete by 3/1/23. Not done as of the last inspection. Lund Ross was reminded on 4/5/23, 5/3/23, 5/31/23, 6/7/23 						
WS 01	Waste storage	On site	3/22/2023	Active	No		
Current Condition:	Active - Additional waste storage on site was observed during the inspection on 3/22/23.						
Certification Statement	"I certify, under penalty of law, that this do with a system designed to assure that qua inquiry of the person or persons who man information submitted is, to the best of my penalties for submitting false information	alified personnel properly ga age the system or those per y knowledge and belief, true	athered and evaluated the rsons directly responsible , accurate, and complete.	e information submitte e for gathering the info . I am aware that the	ed. Based on my ormation, the re are significant		
Inspector Signature:	En Carlon			Reviewed By:	to Sur		