E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	E&	A- P2022.261.001			
Inspector: Ethan Anderson					Stage
Project Name:	Plattsmouth Historic High School Housing and New Apartments CSW-202207329				1
For Week Ending:	6/24/2023				68003
Project Location:	814 Ma	814 Main St Plattsmouth, NE (Cass County)			
Grading:	50%				
Sanitary Sewer:	50%				
Storm Sewer:	50%				
Paving:	50%				
Seeding:	0%				
Utilities:	50%				
Overall Development:	50%				
DAIN FALL AMOUNTS	Amount in tenths	Data bases at all	144 - 44 0 414	T	Ot F Ti

RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Times
					Week 1
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"	6/21/2023	Cloudy 86/67	10:55 AM	
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.00"				

	None
Complaints:	
	i

Construction Sequencing:

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22).

orary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (9/21/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to

Create Corrective Action?

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?
No, See BMP Section

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments:

1.) Site was active during the current inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): Some maintenance required in the BMP Section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenan
CE 01 Current Condition:	Construction Entrance Removed- Lund Ross paved the constru	D2	nepection on 11/16/22	Removed	
CE 02	Construction Entrance	M11	nspection on 11/10/22.	Removed	
Current Condition:	Removed- Lund Ross paved the rest co		the inspection on 11/16/22.	rtomovou	1
IF 01	Inlet Filter	A7	5/17/2023	Active	No
Current Condition:	Good Condition - Lund Ross cleaned of	f inlet prior to inspection on	5/10/23. Lund Ross installe	d silt fence around t	he inlet prior to
	inspection on 5/17/23.				
IF 02	Inlet Filter	A9	5/17/2023	Active	No
Current Condition:	Good Condition - Lund Ross cleaned of	f inlet prior to inspection on	5/10/23. Lund Ross installe	d silt fence around t	he inlet prior to
IF 00	inspection on 5/17/23.	1 240	5470000		
IF 03	Inlet Filter	B10	5/17/2023	Active	No No
Current Condition:	Good Condition - Lund Ross installed a front of the inlet prior to inspection on 5/		orior to the inspection on 5/3	3/23. Luna Ross insi	talled a slit lence
MS 01	Material Storage	On Site	9/30/2022	Active	No
Current Condition:	Good Condition- Lund Ross stored mate				
	lot near SB A used as material storage,				. 1000 to dog po
PB 01	Portable Toilet	On Site	9/30/2022	Active	No
Current Condition:	Good Condition - Lund Ross installed a				
Current Condition.	were adequately secured with pallets ag		•	. mapeodon. The poi	TRADIC TOILCES OFF
PB 02	Portable Toilet	On Site	5/10/2023	Active	Yes
Current Condition:	Fair Condition - Lund Ross installed a s			Active	163
	Portable toilets need to be secured.				
	Lund Ross was informed to complete by				
SB A	Sediment Basin	B3	9/30/2022	Pending	Yes
Current Condition:	Pending - Inlet and outfall for the basin				
	inlet and outfall prior to the inspection or repaired the erosion at the inlet and out				on 5/17/23. Lund
	repaired the erosion at the inlet and out	iet and moved the iniet luith	er away phor to the inspecti	1011 011 6/14/23.	
	The sediment basin should be installed	ner SWPPP_including outfa	all cleanout and renair		
	The sediment basin should be installed	per ovvi i i , including odde	an orcanout and repair.		
	Lund Ross was informed to complete by	y 11/02/22. Not done as of la	ast inspection. Lund Ross w	as reminded on 11/	10/22, 12/5/22, 2
	4/5/23, 5/10/23, 5/31/23, 6/7/23	•			
SB B	Sediment Basin	G14	9/30/2022	Pending	Yes
Current Condition:	Pending - Lund Ross was actively work	ring on the basin during the	inapposition on 6/7/22 Lund [ng the bacin pric
	the inspection on 6/14/23. The sediment basin should be installed		inspection on 6/7/23. Lund r	Ross started installii	ng the basin pho
	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by	per SWPPP.			
SF 01	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23	per SWPPP.	ast inspection. Lund Ross w	as reminded on 11/	
SF 01 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by	per SWPPP. y 11/02/22. Not done as of la	ast inspection. Lund Ross w	as reminded on 11/	10/22, 12/5/22, 2
	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side	per SWPPP. y 11/02/22. Not done as of la A2-D2 fence prior to the 9/28/22 ins	ast inspection. Lund Ross w 9/28/2022 spection. Lund Ross extend	as reminded on 11/ Active ed the silt fence up	10/22, 12/5/22, 2 Yes the CE and insta
	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt	per SWPPP. y 11/02/22. Not done as of la A2-D2 fence prior to the 9/28/22 ins	ast inspection. Lund Ross w 9/28/2022 spection. Lund Ross extend	as reminded on 11/ Active ed the silt fence up	10/22, 12/5/22, 2 Yes the CE and insta
	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23.	per SWPPP. y 11/02/22. Not done as of la A2-D2 fence prior to the 9/28/22 ins of the CE prior to the inspec	ast inspection. Lund Ross w 9/28/2022 spection. Lund Ross extend	as reminded on 11/ Active ed the silt fence up	10/22, 12/5/22, 2 Yes the CE and insta
	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side	per SWPPP. y 11/02/22. Not done as of la A2-D2 fence prior to the 9/28/22 ins of the CE prior to the inspec	ast inspection. Lund Ross w 9/28/2022 spection. Lund Ross extend	as reminded on 11/ Active ed the silt fence up	10/22, 12/5/22, 2 Yes the CE and insta
	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized.	per SWPPP. y 11/02/22. Not done as of la A2-D2 fence prior to the 9/28/22 ins of the CE prior to the inspect	ast inspection. Lund Ross w 9/28/2022 spection. Lund Ross extend tion on 5/10/23. Lund Ross	Active ed the silt fence up also installed SF or	10/22, 12/5/22, 2 Yes the CE and insta n the other side
	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23.	per SWPPP. y 11/02/22. Not done as of la A2-D2 fence prior to the 9/28/22 ins of the CE prior to the inspect	ast inspection. Lund Ross w 9/28/2022 spection. Lund Ross extend tion on 5/10/23. Lund Ross	Active ed the silt fence up also installed SF or	10/22, 12/5/22, 2 Yes the CE and insta n the other side
	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized.	per SWPPP. y 11/02/22. Not done as of la A2-D2 fence prior to the 9/28/22 ins of the CE prior to the inspect	ast inspection. Lund Ross w 9/28/2022 spection. Lund Ross extend tion on 5/10/23. Lund Ross	Active ed the silt fence up also installed SF or	10/22, 12/5/22, 2 Yes the CE and insta
Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by	per SWPPP. y 11/02/22. Not done as of late	9/28/2022 spection. Lund Ross extend obtion on 5/10/23. Lund Ross extend strinspection. Lund Ross was inspection. Lund Ross was 19/30/2022	Active ed the silt fence up also installed SF or	Yes Yes the CE and insta n the other side of
Current Condition: SF 02	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence	per SWPPP. y 11/02/22. Not done as of late	9/28/2022 spection. Lund Ross extend obtion on 5/10/23. Lund Ross extend strinspection. Lund Ross was inspection. Lund Ross was 19/30/2022	Active ed the silt fence up also installed SF or	Yes The CE and instant the other side of the CE, 5/31/23, 6/7/2 Yes
Current Condition: SF 02	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23.	per SWPPP. y 11/02/22. Not done as of late	9/28/2022 spection. Lund Ross extend obtion on 5/10/23. Lund Ross extend strinspection. Lund Ross was inspection. Lund Ross was 19/30/2022	Active ed the silt fence up also installed SF or	Yes The CE and instant the other side of the CE, 5/31/23, 6/7/2 Yes
Current Condition: SF 02	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no	per SWPPP. y 11/02/22. Not done as of late	9/28/2022 spection. Lund Ross extend obtion on 5/10/23. Lund Ross extend strinspection. Lund Ross was inspection. Lund Ross was 19/30/2022	Active ed the silt fence up also installed SF or	Yes The CE and instant the other side of the CE, 5/31/23, 6/7/2 Yes
Current Condition: SF 02	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed.	per SWPPP. y 11/02/22. Not done as of late	9/28/2022 spection. Lund Ross was tinspection. Lund Ross extend ction on 5/10/23. Lund Ross was tinspection. Lund Ross was 9/30/2022 signated as SF 02 for future	Active ed the silt fence up also installed SF or as reminded on 5/3/2 Pending e reports, SWPPP m	Yes the CE and insta n the other side 23, 5/31/23, 6/7/2 Yes nap updates and
Current Condition: SF 02	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by	per SWPPP. y 11/02/22. Not done as of late	9/28/2022 spection. Lund Ross was tinspection. Lund Ross extend ction on 5/10/23. Lund Ross was tinspection. Lund Ross was 9/30/2022 signated as SF 02 for future	Active ed the silt fence up also installed SF or as reminded on 5/3/2 Pending e reports, SWPPP m	Yes the CE and insta n the other side 23, 5/31/23, 6/7/2 Yes nap updates and
Current Condition: SF 02	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23	per SWPPP. y 11/02/22. Not done as of last A2-D2 fence prior to the 9/28/22 insof the CE prior to the inspect of the CE prio	9/28/2022 spection. Lund Ross w 9/28/2022 spection. Lund Ross extend ction on 5/10/23. Lund Ross st inspection. Lund Ross wa 9/30/2022 signated as SF 02 for future	Active ed the silt fence up also installed SF or as reminded on 5/3/2 Pending e reports, SWPPP n	10/22, 12/5/22, 2 Yes the CE and instant the other side 23, 5/31/23, 6/7/2 Yes hap updates and
SF 02 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by	per SWPPP. y 11/02/22. Not done as of last per support to the 9/28/22 instance of the CE prior to the inspect of the CE prior to the inspect st. y 4/12/23. Not done as of last per support	9/28/2022 spection. Lund Ross was tinspection. Lund Ross extend stion on 5/10/23. Lund Ross was 9/30/2022 signated as SF 02 for future ast inspection. Lund Ross was 19/30/2022	Active ed the silt fence up also installed SF or also installed SF or also reminded on 5/3/2 Pending e reports, SWPPP mass reminded on 12/	10/22, 12/5/22, 2 Yes the CE and insta n the other side 23, 5/31/23, 6/7/2 Yes nap updates and
SF 02 Current Condition: SF 02 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence	per SWPPP. y 11/02/22. Not done as of last and a series of the CE prior to the inspect of the CE prior to the CE prior to the inspect of the CE prior to the CE prior to the inspect of the CE prior to the CE prior	ast inspection. Lund Ross w 9/28/2022 spection. Lund Ross extend on 5/10/23. Lund Ross extend on 5/10/23. Lund Ross wast inspection. Lund Ross was p/30/2022 signated as SF 02 for future extended as signated as signated as signated as signated extended as signated extended as signated extended as signated extended ex	Active ed the silt fence up also installed SF or as reminded on 5/3/2 Pending e reports, SWPPP n	10/22, 12/5/22, 2 Yes the CE and insta n the other side 23, 5/31/23, 6/7/2 Yes nap updates and 5/22, 2/3/23, 4/5 Yes For consistency
SF 02 Current Condition: SF 02 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and	per SWPPP. y 11/02/22. Not done as of last and a series of the CE prior to the inspect of the CE prior to the CE prior to the inspect of the CE prior to the CE prior to the inspect of the CE prior to the CE prior	ast inspection. Lund Ross w 9/28/2022 spection. Lund Ross extend on 5/10/23. Lund Ross extend on 5/10/23. Lund Ross wast inspection. Lund Ross was p/30/2022 signated as SF 02 for future extended as signated as signated as signated as signated extended as signated extended as signated extended as signated extended ex	Active ed the silt fence up also installed SF or as reminded on 5/3/2 Pending e reports, SWPPP n	10/22, 12/5/22, 2 Yes the CE and insta n the other side 23, 5/31/23, 6/7/2 Yes nap updates and 5/22, 2/3/23, 4/5 Yes For consistency
SF 02 Current Condition: SF 02 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed.	per SWPPP. y 11/02/22. Not done as of last and a series of the CE prior to the inspect of the CE prior to the CE prior to the inspect of the CE prior to the CE prior to the inspect of the CE prior to the CE prior	ast inspection. Lund Ross w 9/28/2022 spection. Lund Ross extend on 5/10/23. Lund Ross extend on 5/10/23. Lund Ross wast inspection. Lund Ross was p/30/2022 signated as SF 02 for future extended as signated as signated as signated as signated extended as signated extended as signated extended as signated extended ex	Active ed the silt fence up also installed SF or as reminded on 5/3/2 Pending e reports, SWPPP n	10/22, 12/5/22, 2 Yes the CE and insta n the other side of 23, 5/31/23, 6/7/2 Yes nap updates and 5/22, 2/3/23, 4/5 Yes For consistency
SF 02 Current Condition: SF 02 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed.	per SWPPP. y 11/02/22. Not done as of last and a second s	9/28/2022 spection. Lund Ross was tinspection. Lund Ross was strinspection. Lund Ross was 9/30/2022 signated as SF 02 for future ast inspection. Lund Ross was inspection. Lund Ross was 19/30/2022 signated as SF 02 for future ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22.	Active ed the silt fence up also installed SF or also installed SF or reminded on 5/3/2 Pending reports, SWPPP nr reas reminded on 12/ Pending litt berm is in place, nated as SF 03, as	10/22, 12/5/22, 2 Yes the CE and instant the other side of the control of the co
SF 02 Current Condition: SF 02 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt fence should be installed.	per SWPPP. y 11/02/22. Not done as of last and a second s	9/28/2022 spection. Lund Ross was tinspection. Lund Ross was strinspection. Lund Ross was 9/30/2022 signated as SF 02 for future ast inspection. Lund Ross was inspection. Lund Ross was 19/30/2022 signated as SF 02 for future ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22.	Active ed the silt fence up also installed SF or also installed SF or reminded on 5/3/2 Pending reports, SWPPP nr reas reminded on 12/ Pending litt berm is in place, nated as SF 03, as	10/22, 12/5/22, 2 Yes the CE and insta n the other side 23, 5/31/23, 6/7/2 Yes nap updates and 5/22, 2/3/23, 4/5 Yes For consistency of 2/3/23.
SF 02 Current Condition: SF 02 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed.	per SWPPP. y 11/02/22. Not done as of last and a second s	9/28/2022 spection. Lund Ross was tinspection. Lund Ross was strinspection. Lund Ross was 9/30/2022 signated as SF 02 for future ast inspection. Lund Ross was inspection. Lund Ross was 19/30/2022 signated as SF 02 for future ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22.	Active ed the silt fence up also installed SF or also installed SF or reminded on 5/3/2 Pending reports, SWPPP nr reas reminded on 12/ Pending litt berm is in place, nated as SF 03, as	10/22, 12/5/22, 2 Yes the CE and instant the other side of the control of the co
SF 02 Current Condition: SF 02 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23	per SWPPP. y 11/02/22. Not done as of last and a series of the GE prior to the inspect of the inspect of the GE prior to the GE prior to the GE prior to the inspect of the GE prior to the GE prior to the GE prior to	9/28/2022 spection. Lund Ross was tinspection. Lund Ross was strinspection. Lund Ross was 9/30/2022 signated as SF 02 for future ast inspection. Lund Ross was inspection. Lund Ross was 19/30/2022 signated as SF 02 for future ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22, a cun of silt fence will be designated as 19/28/22.	Active ed the silt fence up also installed SF or also installed SF or as reminded on 5/3/2 Pending e reports, SWPPP m ras reminded on 12/ Pending dirt berm is in place. nated as SF 03, as	10/22, 12/5/22, 2 Yes the CE and insta n the other side 23, 5/31/23, 6/7/2 Yes nap updates and 5/22, 2/3/23, 4/5 Yes For consistency of 2/3/23.
SF 02 Current Condition: SF 02 Current Condition: SF 03 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt fence should be installed.	per SWPPP. y 11/02/22. Not done as of last A2-D2 fence prior to the 9/28/22 instruction of the CE prior to the inspect of t	9/28/2022 spection. Lund Ross was tinspection. Lund Ross extend attorn on 5/10/23. Lund Ross was 9/30/2022 signated as SF 02 for future ast inspection. Lund Ross was inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a coun of silt fence will be designant inspection. Lund Ross was 19/30/2022	Active ed the silt fence up also installed SF or also installed SF or as reminded on 5/3/2 Pending e reports, SWPPP re ras reminded on 12/ Pending lift berm is in place, nated as SF 03, as as reminded on 12/ Removed	10/22, 12/5/22, 2 Yes the CE and instant the other side of the ot
SF 02 Current Condition: SF 02 Current Condition: SF 03 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, at Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Removed- Silt fence is uphill of disturbed	per SWPPP. y 11/02/22. Not done as of later and the prior to the 9/28/22 into of the CE prior to the inspect of the cE prior to the inspect of the cE prior to the cE prio	9/28/2022 spection. Lund Ross was tinspection. Lund Ross was strinspection. Lund Ross was 19/30/2022 signated as SF 02 for future ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a cun of silt fence will be designant inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a cun of silt fence will be designant inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a cun of silt fence will be designant inspection. Lund Ross was 19/30/2022	Active ed the silt fence up also installed SF or al	10/22, 12/5/22, 2 Yes the CE and instant the other side of the ot
SF 02 Current Condition: SF 03 Current Condition: SF 04 Current Condition: STR	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Removed- Silt fence is uphill of disturbed Streets	per SWPPP. y 11/02/22. Not done as of later A2-D2 fence prior to the 9/28/22 insoft the CE prior to the inspect of the CE p	ast inspection. Lund Ross was 19/28/2022 spection. Lund Ross extend tion on 5/10/23. Lund Ross was 19/30/2022 signated as SF 02 for future ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a coun of silt fence will be designed ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a coun of silt fence will be designed ast inspection. Lund Ross was 19/30/2022	Active ed the silt fence up also installed SF or also installed SF or also installed SF or also reminded on 5/3/2 Pending experts, SWPPP m reas reminded on 12/ Pending lift berm is in place, nated as SF 03, as as reminded on 12/ Removed the 11/30/22 inspections	10/22, 12/5/22, 2 Yes the CE and instant the other side of the ot
SF 02 Current Condition: SF 02 Current Condition: SF 03 Current Condition:	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, at Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Removed- Silt fence is uphill of disturbed	per SWPPP. y 11/02/22. Not done as of later A2-D2 fence prior to the 9/28/22 insoft the CE prior to the inspect of the CE p	ast inspection. Lund Ross was 19/28/2022 spection. Lund Ross extend tion on 5/10/23. Lund Ross was 19/30/2022 signated as SF 02 for future ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a coun of silt fence will be designed ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a coun of silt fence will be designed ast inspection. Lund Ross was 19/30/2022	Active ed the silt fence up also installed SF or also installed SF or also installed SF or also reminded on 5/3/2 Pending experts, SWPPP m reas reminded on 12/ Pending lift berm is in place, nated as SF 03, as as reminded on 12/ Removed the 11/30/22 inspections	10/22, 12/5/22, 2 Yes the CE and instant the other side of the ot
SF 02 Current Condition: SF 03 Current Condition: SF 04 Current Condition: STR	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Removed- Silt fence is uphill of disturbed Streets Fair Condition- A trail of escaped sedim	per SWPPP. y 11/02/22. Not done as of later A2-D2 fence prior to the 9/28/22 insoft the CE prior to the inspect of the CE p	ast inspection. Lund Ross was 19/28/2022 spection. Lund Ross extend tion on 5/10/23. Lund Ross was 19/30/2022 signated as SF 02 for future ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a coun of silt fence will be designed ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a coun of silt fence will be designed ast inspection. Lund Ross was 19/30/2022	Active ed the silt fence up also installed SF or also installed SF or also installed SF or also reminded on 5/3/2 Pending experts, SWPPP m reas reminded on 12/ Pending lift berm is in place, nated as SF 03, as as reminded on 12/ Removed the 11/30/22 inspections	10/22, 12/5/22, 2 Yes the CE and insta n the other side of 23, 5/31/23, 6/7/2 Yes nap updates and 5/22, 2/3/23, 4/5 Yes For consistency of 2/3/23. 5/22, 2/3/23, 4/5
SF 02 Current Condition: SF 03 Current Condition: SF 04 Current Condition: STR	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Removed- Silt fence is uphill of disturbed Streets Fair Condition- A trail of escaped sedim	per SWPPP. y 11/02/22. Not done as of last of the CE prior to the 9/28/22 insoft the CE prior to the inspect of the inspect of the CE prior to the inspect of the inspect of the CE prior to the inspect of the inspect of the CE prior to the inspect of the inspect of the CE prior to the inspect of the inspect of the CE prior to the inspect of the inspect of the CE prior to the inspect of the inspect of the CE prior to the inspect of	ast inspection. Lund Ross was 19/28/2022 spection. Lund Ross extend tion on 5/10/23. Lund Ross was 19/30/2022 signated as SF 02 for future ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a coun of silt fence will be designed ast inspection. Lund Ross was 19/30/2022 available. As of 9/28/22, a coun of silt fence will be designed ast inspection. Lund Ross was 19/30/2022	Active ed the silt fence up also installed SF or also installed SF or also installed SF or also reminded on 5/3/2 Pending experts, SWPPP m reas reminded on 12/ Pending lift berm is in place, nated as SF 03, as as reminded on 12/ Removed the 11/30/22 inspections	10/22, 12/5/22, 2 Yes the CE and instant the other side of the control of the co
SF 02 Current Condition: SF 03 Current Condition: SF 04 Current Condition: STR	the inspection on 6/14/23. The sediment basin should be installed Lund Ross was informed to complete by 4/5/23, 5/10/23, 5/31/23, 6/7/23 Silt Fence Fair Condition- Lund Ross installed silt the remaining section on the south side entrance prior to inspection on 5/10/23. Areas above SF 01 should be stabilized Lund Ross was informed to complete by Silt Fence Pending - For consistency, silt fence no maintenance plans on 2/3/23. Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Pending - The silt fence will be installed across future reports, SWPPP maps, and Silt fence should be installed. Lund Ross was informed to complete by 5/3/23, 5/31/23, 6/7/23 Silt Fence Removed- Silt fence is uphill of disturbed Streets Fair Condition- A trail of escaped sedim Ave.	per SWPPP. y 11/02/22. Not done as of later A2-D2 fence prior to the 9/28/22 insoft the CE prior to the inspect of the CE p	ast inspection. Lund Ross was placed as the process of the process	Active ed the silt fence up also installed SF or also installed SF or also installed SF or as reminded on 5/3/2 Pending exas reminded on 12/ Pending lift berm is in place, nated as SF 03, as as reminded on 12/ Removed the 11/30/22 insperies Active veling all the way de	10/22, 12/5/22, 2 Yes the CE and instant the other side of the ot

SW 1	Straw Wattles	Main St	5/10/2023	Active	No	
Current Condition:	Good Condition - Lund Ross installed stra Lund Ross cleaned out the wattles and re			n St. prior to the insp	ection on 5/10/23.	
SWPPP Sign	SWPPP Signs	South of CE 1	9/30/2022	Active	No	
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign to the south of CE 1 during the inspection on 12/7/22. E&A inspector updated the SWPPP sign with the correct permit information website during the 12/21/22 inspection.					
WO 01	Concrete Washout	On site	9/30/2022	Active	Yes	
	prior to the inspection on 11/16/22. Lund concrete washout bin onsite prior to the ir effort to utilize the concrete washout bin of 2/22/23 inspection. Concrete mixing buck material storage prior to the inspection or A concrete washout should be installed of Lund Ross was informed to complete by 6/7/23	nspection on 11/30/22. More onsite is needed. More concided was removed prior to the n 6/7/23.	concrete waste was observed aste waste was observed 3/8/23 inspection. Lund F	erved during the 2/8/ escaping designated Ross removed the co	23 inspection. More I areas during the ncrete waste near the	
WS 01	Waste storage	On site	3/22/2023	Active	No	
Current Condition:	Active - Additional waste storage on site	was observed during the ins	pection on 3/22/23.	!	!	
Certification Statement	"I certify, under penalty of law, that this do with a system designed to assure that qu inquiry of the person or persons who mar information submitted is, to the best of my penalties for submitting false information	alified personnel properly ga nage the system or those per y knowledge and belief, true	athered and evaluated the rsons directly responsible , accurate, and complete.	information submitte for gathering the inf I am aware that the	ed. Based on my ormation, the re are significant	
Inspector Signature:	En Carla			Reviewed By:	to Sie	