E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

	Εδ	&A- P2022.261.001					
nspector: Ethan Anderson	tor: Ethan Anderson						
Project Name:	Plattsmouth Historic High School Housing and New Apartments CSW-202207329						
For Week Ending:		68003	13				
Project Location:	814 Mai	3/16/2024 814 Main St Plattsmouth, NE (Cass County)					
Grading:	95%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	99%						
Seeding:	50%						
Utilities:	99%						
Overall Development:	85%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Times	is	
						Week	
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.03"	3/13/2024	Sunny 72/40	2:05 PM		11:35 PM	
Thursday:	0.31"		,		10:55 AM		
Friday:	0.00"						
Saturday:	0.00"						
•				_			
Complaints:	None						

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22). Silt basin B grading and shaping (8/2/23). Storm sewer was being installed near silt basin B (9/6/23). Storm installation completed (9/27/23). Fine grading on all disturbed areas of site (12/27/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22). Silt basin B grading and shaping (8/2/23). Storm sewer was being installed near silt basin B (9/6/23). Storm installation completed (9/27/23). Fine grading on all disturbed areas of site (12/27/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (9/21/22). Sod installation around north building (11/8/23). Seed and matting installed in SB A (11/8/23). Seed and matting installed along the west entrance and adjacent slope (11/15/23). Seed and matting installed along the north perimeter and west entrance parking lot edges (11/22/23).

Checklist Questions:

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

No, See BMP Section.

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to

Create Corrective Action?

No, See BMP Section and Findings Section.

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

4.) Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

No, See BMP Section.

5.) Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:
1.) Site was active during the current inspection.

- Findings / Corrective Actions (Date):

 Findings / Corrective Actions (Date):

 1.) Some maintenance required in the BMP Section.

 2.) Disturbed areas should be stabilized per SWPPP. Lund Ross was informed to complete by 12/27/23. Not done as of last inspection. Lund Ross was reminded on 2/22/24

			1		
Unique Name CE 01	Type Construction Entrance	Location D2	Projected Install Date	Status Removed	Maintenance
Current Condition:	Removed- Lund Ross paved the constru	ction entrance prior to the ins	spection on 11/16/22.		
CE 02	Construction Entrance	M11		Removed	
Current Condition:	Removed- Lund Ross paved the rest cor	nstruction entrance prior to th	ne inspection on 11/16/22.		
CW 1	Concrete washout	West entrance	11/22/2023	Active	No
Current Condition:	Good Condition - Lund Ross installed 2 p	oortable concrete washouts p	prior to the inspection on 1	/22/23. Lund Ross r	moved all the concrete
	washouts to one location near the west e washout on N 10th St prior to the inspect				
	to the inspection on 12/20/23.				
CW 2	Concrete washout	N 10th St		Removed	
Current Condition:	Removed - Lund Ross removed the cond				
EM 01	Erosion Control Matting	West entrance	11/15/2023	Active	No
Current Condition:	Good Condition - Lund Ross installed ma inspection on 2/21/24.	atting prior to the inspection o	on 11/15/23. Lund Ross se	cured the matting are	ound the outfall prior to
IF 01	Inlet Filter	A7		Removed	
Current Condition:	Removed - Lund Ross installed sod arou	and the inlet prior to the inspe	ection on 11/8/23.		
IF 02	Inlet Filter	A9		Removed	
Current Condition:	Removed - Lund Ross installed sod arou	and the inlet prior to the inspe	ection on 11/8/23.		
IF 03	Inlet Filter	B10		Removed	
Current Condition:	Removed - Lund Ross installed sod arou	and the inlet prior to the inspe	ection on 11/8/23.		
IF 04	Inlet Filter	H11		Removed	
Current Condition:	Removed - Lund Ross paved around the		on 12/6/23.		
IF 05	Inlet Filter	H12		Removed	
Current Condition:	Removed - Lund Ross paved around the		on 12/6/23.		
IF 06	Inlet Filter	K13	11/29/2023	Active	No
Current Condition:	Active- Lund Ross installed the inlet and				110
IF 07	Inlet Filter	K13	12/6/2023	Active	No
Current Condition:	Active- Lund Ross installed the inlet and				110
IF 08	Inlet Filter	K13	12/6/2023	Active	No
Current Condition:	Active- Lund Ross installed the inlet and				110
MS 01	Material Storage	On Site	9/30/2022	Active	No
Current Condition:	Good Condition- Lund Ross stored mater				
Current Condition.	near SB A used as material storage, incli			11 O11 11/3/22. Lund 11	loss is using parking i
PB 01	Portable Toilet	On Site		A ating	No
Current Condition:	Good Condition - Lund Ross installed and		9/30/2022	Active	No No spiloto en eite wer
PB 02	12/20/23. Lund Ross moved the portable Portable Toilet	On Site	le street along the lence p	Removed	on 2/28/24.
Current Condition:	Removed - Lund Ross removed the porta		tion on 12/6/23	Removed	
SB A	Sediment Basin/swale/drainage ditch	B3	12/0/20:	Removed	
Current Condition:	Removed - Lund Ross installed matting a		nage ditch prior to the insc		
SB B	Sediment Basin/swale/drainage ditch	G14	9/30/2022	Pending	Yes
Current Condition:	Pending - Lund Ross was actively working	ng on the basin/swale/draina	ge ditch during the inspect	ion on 6/7/23. Luna F	Ross started installing
		spection on 6/14/23. Lund Ro aping the sides and bottom o on clean out ports in the basi litch should be installed per S ound inlet or area stabilized. by 11/02/22. Not done as of 8/9/23, 9/7/23, 10/19/23, 11/	oss was shaping and gradi of the basin/swale/drainage in/swale/drainage ditch prices SWPPP or area stabilized to flast inspection. Lund Ross 16/23, 12/21/23, 2/22/24	ng the basin/swale/d ditch prior to the ins or to the inspection o o plan.	rainage ditch prior to to to pection on 10/4/23. Lun 11/1/23.
	Pending - Lund Ross was actively working basin/swale/drainage ditch prior to the insinspection 8/2/23. Lund Ross finished share Ross began installing the post construction. The sediment basin/swale/drainage documents. In the sediment basin/swale/drainage documents. In Lund Ross was informed to complete 4/5/23, 5/10/23, 5/31/23, 6/7/23, 7/5/23, 2.) Lund Ross was informed to complete variety.	spection on 6/14/23. Lund Ro aping the sides and bottom o on clean out ports in the basi litch should be installed per S ound inlet or area stabilized. by 11/02/22. Not done as of 8/9/23, 9/7/23, 10/19/23, 11/	oss was shaping and gradi of the basin/swale/drainage in/swale/drainage ditch prices SWPPP or area stabilized to flast inspection. Lund Ross 16/23, 12/21/23, 2/22/24	ng the basin/swale/d ditch prior to the ins or to the inspection o o plan.	rainage ditch prior to to pection on 10/4/23. Lin 11/1/23.
Current Condition:	Pending - Lund Ross was actively working basin/swale/drainage ditch prior to the insinspection 8/2/23. Lund Ross finished share Ross began installing the post construction. 1.) The sediment basin/swale/drainage documents. In the sediment basin/swale/drainage documents. In the sediment basin/swale/drainage documents. In Lund Ross was informed to complete 4/5/23, 5/10/23, 5/31/23, 6/7/23, 7/5/23, 12.) Lund Ross was informed to complete 11/16/23, 12/21/23, 2/22/24	spection on 6/14/23. Lund Roaping the sides and bottom con clean out ports in the basilitch should be installed per Sound inlet or area stabilized. by 11/02/22. Not done as of 8/9/23, 9/7/23, 10/19/23, 11/ by 7/12/23. Not done as of line and the stability of t	oss was shaping and gradi of the basin/swale/drainage in/swale/drainage ditch prices. SWPPP or area stabilized to last inspection. Lund Ross 16/23, 12/21/23, 2/22/24 ast inspection. Lund Ross	ng the basin/swale/deditch prior to the insor to the inspection of o plan. s was reminded on 1 was reminded on 8/5	rainage ditch prior to pection on 10/4/23. Ln 11/1/23.
Current Condition: SF 01 Current Condition:	Pending - Lund Ross was actively working basin/swale/drainage ditch prior to the insinspection 8/2/23. Lund Ross finished shares began installing the post construction. The sediment basin/swale/drainage documents. In the s	spection on 6/14/23. Lund Ro aping the sides and bottom o on clean out ports in the basi litch should be installed per S bund inlet or area stabilized. by 11/02/22. Not done as of 8/9/23, 9/7/23, 10/19/23, 11/ by 7/12/23. Not done as of little A2-D2 fence prior to the inspection of	oss was shaping and gradif the basin/swale/drainage in/swale/drainage ditch prices. SWPPP or area stabilized to the stabilized of the sta	ng the basin/swale/d ditch prior to the ins or to the inspection of o plan. s was reminded on 1 was reminded on 8/s Removed	rainage ditch prior to pection on 10/4/23. Ln 11/1/23. 1/1/0/22, 12/5/22, 2/3/ 1/3, 9/7/23, 10/19/23
Current Condition:	Pending - Lund Ross was actively working basin/swale/drainage ditch prior to the insinspection 8/2/23. Lund Ross finished share Ross began installing the post construction. 1.) The sediment basin/swale/drainage documents. In the sediment basin/swale/drainage documents.	spection on 6/14/23. Lund Ro aping the sides and bottom o on clean out ports in the basi litch should be installed per S ound inlet or area stabilized. by 11/02/22. Not done as of 8/9/23, 9/7/23, 10/19/23, 11/ by 7/12/23. Not done as of land A2-D2 fence prior to the inspection of A3-H12	oss was shaping and gradi of the basin/swale/drainage in/swale/drainage ditch prices. WPPP or area stabilized in SWPPP or area stabilized in	ng the basin/swale/d e ditch prior to the insor to the inspection of o plan. s was reminded on 1 was reminded on 8/s Removed Pending	rainage ditch prior to pection on 10/4/23. Ln 11/1/23. 1/10/22, 12/5/22, 2/3/9/23, 9/7/23, 10/19/23 Yes
SF 01 Current Condition: SF 02	Pending - Lund Ross was actively working basin/swale/drainage ditch prior to the insinspection 8/2/23. Lund Ross finished share Ross began installing the post construction. 1.) The sediment basin/swale/drainage documents. In the sediments with sediments. In the sediments with the sediments of the sediments. In the sediments with the sediments of the sediments. In the sediments with the sediments with the sediments of the sediments. In the sediments with the sediments with the sediments with the sediments. In the sediments with the sedim	spection on 6/14/23. Lund Roaping the sides and bottom con clean out ports in the basilitch should be installed per Sound inlet or area stabilized. by 11/02/22. Not done as of 8/9/23, 9/7/23, 10/19/23, 11/12/23. Not done as of 8/9/23, 9/7/23. Not done as of 8/9/23. Hot SB A was correctly designation of 1/9/22. Not done as of las	oss was shaping and gradi of the basin/swale/drainage in/swale/drainage in/swale/dra	ng the basin/swale/d ditch prior to the ins or to the inspection o o plan. s was reminded on 1 was reminded on 8/s Removed Pending reports, SWPPP ma	rainage ditch prior to to to pection on 10/4/23. Lin 11/1/23. 1/10/22, 12/5/22, 2/3/20/23, 9/7/23, 10/19/23. Yes ap updates and
SF 01 Current Condition: SF 02 Current Condition:	Pending - Lund Ross was actively working basin/swale/drainage ditch prior to the insinspection 8/2/23. Lund Ross finished share Ross began installing the post construction. 1.) The sediment basin/swale/drainage documents. In the sediments with sediments. In the sediments with the sediments of the sediments. In the sediments with the sediments of the sediments. In the sediments with the sediments with the sediments of the sediments. In the sediments with the sediments with the sediments with the sediments. In the sediments with the sedim	spection on 6/14/23. Lund Roaping the sides and bottom of on clean out ports in the basilitch should be installed per Sound inlet or area stabilized. By 11/02/22. Not done as of 8/9/23, 9/7/23, 10/19/23, 11/ By 7/12/23. Not done as of like the stability of the inspection of A3-H12 the of SB A was correctly designated. 11/16/22. Not done as of las 0/19/23, 11/16/23, 12/21/23, 10/19/23, 11/16/23, 12/21/24/23, 12/21/24/24, 12/24/24, 12/24/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24, 12/24/24/24, 12/2	Siss was shaping and gradiof the basin/swale/drainage ditch priority wale/drainage ditch wale/drainage	ng the basin/swale/dictic prior to the insor to the inspection of oplan. s was reminded on 1 was reminded on 8/s Removed Pending reports, SWPPP masses reminded on 12/5/s	rainage ditch prior to to pection on 10/4/23. Lun 11/1/23. 1/10/22, 12/5/22, 2/3/. 1/23, 9/7/23, 10/19/23, Yes ap updates and
SF 01 Current Condition: SF 02 Current Condition: SF 02 SF 03	Pending - Lund Ross was actively working basin/swale/drainage ditch prior to the insinspection 8/2/23. Lund Ross finished share Ross began installing the post construction. 1.) The sediment basin/swale/drainage documents. In the sediments was informed to complete 4/5/23, 5/10/23, 5/31/23, 6/71/23, 7/3/22/24 Silt Fence Removed - Lund Ross removed the silt for Silt Fence Pending - For consistency, silt fence north maintenance plans on 2/3/23. Silt fence should be installed or area state Lund Ross was informed to complete by 5/31/23, 6/7/23, 7/5/23, 8/9/23, 9/7/23, 1/5/23, 8/9/23, 9/7/23,	spection on 6/14/23. Lund Roaping the sides and bottom con clean out ports in the basi litch should be installed per Sound inlet or area stabilized. by 11/02/22. Not done as of 8/9/23, 9/7/23, 10/19/23, 11/ by 7/12/23. Not done as of law in the property of San Was correctly desired. A2-D2 fence prior to the inspection of A3-H12 th of SB A was correctly desired. 11/16/22. Not done as of las 0/19/23, 11/16/23, 12/21/23, 11/16/23, 11/16/23, 12/21/23, 11/16/23, 11/16/23, 12/21/23, 11/16/23, 1	Siss was shaping and gradiof the basin/swale/drainage in/swale/drainage in/swale/drainage in/swale/drainage ditch prices. SWPPP or area stabilized to swap the stabilized to say the say the say the swap the swa	ng the basin/swale/d ditch prior to the ins or to the inspection of o plan. s was reminded on 1 was reminded on 8/s Removed Pending reports, SWPPP ma as reminded on 12/5/	rainage ditch prior to to pection on 10/4/23. Lin 11/1/23. 1/10/22, 12/5/22, 2/3/ 1/23, 9/7/23, 10/19/23 Yes Yes Yes Yes
SF 01 Current Condition: SF 02 Current Condition:	Pending - Lund Ross was actively working basin/swale/drainage ditch prior to the insinspection 8/2/23. Lund Ross finished share Ross began installing the post construction. 1.) The sediment basin/swale/drainage documents. In the sediments with sediments. In the sediments with the sediments of the sediments. In the sediments with the sediments of the sediments. In the sediments with the sediments with the sediments of the sediments. In the sediments with the sediments with the sediments with the sediments. In the sediments with the sedim	spection on 6/14/23. Lund Roaping the sides and bottom con clean out ports in the basi litch should be installed per Sound inlet or area stabilized. by 11/02/22. Not done as of 8/9/23, 9/7/23, 10/19/23, 11/16/24. Not done as of late in the basi litch should be by 7/12/23. Not done as of late in the inspection of A3-H12 in first should be a sound in the inspection of A3-H12 in first should be a sound in the inspection of A3-H12. 11/16/22. Not done as of late in the inspection of SB A was correctly desirated in the inspection of SB A was co	in/swale/drainage ditch priority and gradiof the basin/swale/drainage ditch priority and gradion and g	ng the basin/swale/deditch prior to the insor to the inspection of oplan. s was reminded on 1 was reminded on 8/9 Removed Pending reports, SWPPP mass reminded on 12/5/0 Pending t berm is in place. For	rainage ditch prior to pection on 10/4/23. Ln 11/1/23. 1/10/22, 12/5/22, 2/3/ 1/23, 9/7/23, 10/19/23 Yes ap updates and Yes or consistency across
SF 01 Current Condition: SF 02 Current Condition: SF 02 SF 03	Pending - Lund Ross was actively working basin/swale/drainage ditch prior to the insinspection 8/2/23. Lund Ross finished shares began installing the post construction. The sediment basin/swale/drainage displayed and the post construction of the complete and the protection should be installed and the post complete and the protection should be installed and the protection should be installed and the protection should be installed or and the protection should be installed and the protection should be installed and the protection should be installed or area stated that the protection of the protection	spection on 6/14/23. Lund Roaping the sides and bottom of on clean out ports in the basi litch should be installed per Sound inlet or area stabilized. By 11/02/22. Not done as of 8/9/23, 9/7/23, 10/19/23, 11/16 by 7/12/23. Not done as of litch l	in/swale/drainage ditch priority and gradiof the basin/swale/drainage ditch priority and gradion and g	ng the basin/swale/deditch prior to the insor to the inspection of oplan. s was reminded on 1 was reminded on 8/9 Removed Pending reports, SWPPP mass reminded on 12/5/0 Pending t berm is in place. For	rainage ditch prior to pection on 10/4/23. Ln 11/1/23.

SF 04	Silt Fence	E1-E4		Removed		
Current Condition:	Removed- Silt fence is uphill of disturbed area. There is no recommendation for this BMP as of the 11/30/22 inspection.					
STR	Streets	ADJ and Internal Streets	9/30/2022	Active	Yes	
Current Condition:	Fair Condition- A trail of escaped sedimer Lund Ross cleaned the interior streets pri 8/23/23. Lund Ross was in the process or sidewalk prior to the inspection on 1/17/2. Street and sidewalk should be cleaned at Lund Ross was informed to complete by	or to the inspection on 7/5/23 f cleaning the eastern streets 4. Main St and 8th St.	3. Lund Ross cleaned the aduring the inspection on	internal streets prior 10/18/23. Lund Ross	to the inspection on scraped the streets and	
SW 1	Straw Wattles	Main St	podudiii Zuiiu i tood iiud	Removed		
Current Condition:	Removed - Lund Ross removed the wattl		alk prior to the inspection (
SW 2	Straw Wattles	N 10th St	11/22/2023	Active	No	
Current Condition:	Good Condition - Lund Ross installed stra	aw wattles along the western	slope of property along S	10th St prior to the in	nspection on 11/22/23.	
SWPPP Sign	SWPPP Signs	South of CE 1	9/30/2022	Active	No	
Current Condition:	Active - E&A inspector installed the SWPPP sign to the south of CE 1 during the inspection on 12/7/22. E&A inspector updated the SWPPP sign with the correct permit information website during the 12/21/22 inspection. SWPPP sign was recovered but will not be reinstalled at this time due to project near completion as of the inspection on 3/13/24.					
WO 01	Concrete Washout	On site		Removed		
Current Condition:	Removed - Lund Ross installed a concrete washout on site prior to the inspection on 12/6/23. All recommendations will be under CW 1.					
WS 01	Waste storage	On site	3/22/2023	Active	No	
Current Condition:	Active - Additional waste storage on site was observed during the inspection on 3/22/23.					
Certification Statement	"I certify, under penalty of law, that this do system designed to assure that qualified person or persons who manage the syste the best of my knowledge and belief, true information including the possibility of fine	personnel properly gathered em or those persons directly of accurate, and complete. I a	and evaluated the informative responsible for gathering to maware that there are signs.	ation submitted. Base the information, the ir	d on my inquiry of the formation submitted is, to	
Inspector Signature:	In Carlon			Reviewed By:	t Sil	