E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

**Engineering Answers** 

	E	E&A- P2022.261.00	1				
Inspector: Ethan Anderson					Stage		
Project Name:	Plattsmouth Historic	Plattsmouth Historic High School Housing and New Apartments CSW-202207329					
For Week Ending:							
Project Location:	814 Mai	68003					
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	100%						
Seeding:	90%						
Utilities:	100%						
Overall Development:	85%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Times		
					Wed		
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.03"	4/3/2024	Cloudy 55/37	12:05 PM			
Thursday:	0.00"		_				
Friday:	0.00"						
Saturday:	0.06"						
Complaints:	None						

## onstruction Sequencing:

n(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22). Silt basin B grading and shaping (8/2/23). Storm sewer was being installed near silt basin B (9/6/23). Storm installation completed (9/27/23). Fine grading on all disturbed areas of site (12/27/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days

Grading work active northwest side of site, utility installation, footings poured (9/28/22). Framing for paving roadways (11/9/22). Paving roadways (11/16/22). Silt basin B grading and shaping (8/2/23). Storm sewer was being installed near silt basin B (9/6/23). Storm installation completed (9/27/23). Fine grading on all disturbed areas of site (12/27/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing Vegetation (9/21/22). Sod installation around north building (11/8/23). Seed and matting installed in SB A (11/8/23). Seed and matting installed along the west entrance and adjacent slope (11/15/23). Seed and matting installed along the north perimeter and west entrance parking lot edges (11/22/23). Seeding and matting installed on and around the eastern building (3/20/24). <mark>Additional seeding and matting installed on and around the eastern basin/swale (4/3/24).</mark>

## **Checklist Questions:**

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to

Create Corrective Action?

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

4.) Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?
No, See BMP Section.

5.) Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments:

Comments:
1.) Site was active during the current inspection.
Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
1.) Some maintenance required in the BMP Section.

Unique Name CE 01	Type Construction Entrance	Location D2	Projected Install Date	Status Removed	Maintenance
Current Condition:	Removed- Lund Ross paved the construction		pection on 11/16/22.	rtemoved	
CE 02	Construction Entrance	M11		Removed	
Current Condition:	Removed- Lund Ross paved the rest con		e inspection on 11/16/22.	_	I
CW 1	Concrete washout	West entrance	n increation on 4/2/24	Removed	
Current Condition: CW 2	Removed - Lund Ross removed the co Concrete washout	N 10th St	e inspection on 4/3/24.	Removed	
Current Condition:	Removed - Lund Ross removed the conc		pection on 11/29/23.		
EM 01	Erosion Control Matting	West entrance	11/15/2023	Active	No
Current Condition:	Good Condition - Lund Ross installed mainspection on 2/21/24.		n 11/15/23. Lund Ross se		ound the outfall prior to the
IF 01	Inlet Filter	A7		Removed	
Current Condition: IF 02	Removed - Lund Ross installed sod arour		ction on 11/8/23.	Damana	1
Current Condition:	Inlet Filter Removed - Lund Ross installed sod arou	A9	ction on 11/8/23	Removed	
IF 03	Inlet Filter	B10	1,0,20	Removed	
Current Condition:	Removed - Lund Ross installed sod arou		ction on 11/8/23.		
IF 04	Inlet Filter	H11	10/0/00	Removed	
Current Condition: IF 05	Removed - Lund Ross paved around the Inlet Filter	inlet prior to the inspection of H12	n 12/6/23.	Removed	
Current Condition:	Removed - Lund Ross paved around the		n 12/6/23	Removed	
IF 06	Inlet Filter	K13	112/0/20.	Removed	
Current Condition:	Removed - Lund Ross installed seed and	matting around the inlet prio	r to the inspection on 3/20	)/24.	•
IF 07	Inlet Filter	K13		Removed	
Current Condition: IF 08	Removed - Lund Ross installed landscap		o the inspection on 3/20/2	4. Removed	
Current Condition:	Removed - Lund Ross installed landscape	K13	o the inspection on 3/20/2		
MS 01	Material Storage	On Site	o ano mopocalom on orzurz	4. Removed	
Current Condition:	Removed - Lund Ross removed the sto		rom the site prior to the		24.
PB 01	Portable Toilet	On Site	9/30/2022	Active	No
Current Condition:	Fair Condition - Lund Ross installed and s				
	adequately secured with pallets against the prior to the inspection on 12/6/23. Lund R				
	Lund Ross moved the portable toilets to t				
	removing the portable toilets when work in				
	3/27/24. Lund Ross will be removing the			,	
PB 02	Portable Toilet	On Site		Removed	
Current Condition:	Removed - Lund Ross removed the porta		tion on 12/6/23.		
SB A Current Condition:	Sediment Basin/swale/drainage ditch Removed - Lund Ross installed matting a	B3	ago ditab prior to the inen	Removed	
SB B	Sediment Basin/swale/drainage ditch	G14	9/30/2022	Active	No
Current Condition:	Good Condition - Lund Ross was active				
	installing the basin/swale/drainage ditch p				
	prior to the inspection 8/2/23. Lund Ross				
	10/4/23. Lund Ross began installing the p				
	Lund Ross installed matting around the comatting around the inlet of the basin/s				und Ross Installed
	matting around the iniet of the basin's	wateraramage unteri prior t	o the inspection on 4/3/2	-4.	
SF 01	Silt Fence	A2-D2		Removed	
Current Condition:	Removed - Lund Ross removed the silt for	ence prior to the inspection or	n 11/29/23.		
SF 02	Silt Fence	A3-H12		Removed	
Current Condition:	Removed - Due to the seed and matting i		Ross the silt fence is no lo		
SF 03	Silt Fence	G12-N15	Dono the cit for	Removed	
Current Condition:	Removed - Due to the seed and matting i Silt Fence	installed in the area by Lund I E1-E4	NUSS THE SHT TENCE IS NO IC		
Current Condition:	Removed- Silt fence is uphill of disturbed	area. There is no recommen	dation for this BMP as of	the 11/30/22 inspec	tion.
STR	Streets	ADJ and Internal Streets	9/30/2022	Active	Yes
Current Condition:	Fair Condition- A trail of escaped sedimer				
	Ross cleaned the interior streets prior to t				
	Ross was in the process of cleaning the e	eastern streets during the ins	pection on 10/18/23. Lund	Ross scraped the s	treets and sidewalk prior to
	the inspection on 1/17/24.				
		M : 01 1011 01			
	Street and sidewalk should be cleaned at	iviain St and 8th St.			
	Lund Ross was informed to complete by	2/1/24 Not done as of last in	spection Lund Ross was	reminded on 2/22/2/	1
SW 1	Straw Wattles	Main St	- Doublin Edita 11000 Was	Removed	
Current Condition:	Removed - Lund Ross removed the wattl				
SW 2	Straw Wattles	N 10th St	11/22/2023	Active	No
Current Condition:	Good Condition - Lund Ross installed stra	aw wattles along the western	slope of property along S	10th St prior to the i	nspection on 11/22/23.
CWDDD Ci	OMBDD O	0			
SWPPP Sign	SWPPP Signs	South of CE 1	l of this time also t	Removed	n an of the increase:
Current Condition:	Removed - SWPPP sign was recovered 4/3/24.	a but will not be reinstalled	at this time due to proj	ect near completio	n as of the inspection on
WO 01	Concrete Washout	On site		Removed	
Current Condition:	Removed - Lund Ross installed a concret		e inspection on 12/6/23 A		will be under CW 1.
WS 01	Waste storage	On site	,	Removed	
	Tradio diorage	OT SILO		1.cmovcu	

Current Condition:	Removed - Lund Ross removed the waste storage from the site prior to the inspection on 4/3/24.				
Certification Statement	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."				
Inspector Signature:	En Carla		Reviewed By:		