E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Environmental Services Dep	t. Manager	F&A - P20	21.167.005				
nspector: Jason Brackett					Stage		
Project Name:	Ponderosa Place (Seventy-Two Place South) PAP-20230221-6811-GP1 CSW-202307567				1		
For Week Ending:							
Project Location:	10/19/2024 SE of Ponderosa Drive and S 72nd Street, Papillion, Sarpy County, Nebraska				68133		
-							
Grading: Sanitary Sewer:	60% 0%						
Storm Sewer:	0%						
Paving:	0%						
Seeding:	0%						
Utilities:	0%						
Overall Development:	6%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
		Date inspected	Weather Conditions	Time	Week 1		
Sunday:	0.00"				Week I		
Monday:	0.00"						
Tuesday:	0.00"			1			
Wednesday:	0.00"						
Thursday:	0.00"	10/17/2024	Sunny/Wind 75/49	11:15 AM			
Friday:	0.00"						
Saturday:	0.00"						
Complaints: None. Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?							
Rough grading in the northeast corner site (9/26/24). Which portion(s) (i.e. drainage basin Bauch grading in the portheast express	ns) of the site do not have grad	ing, earthwork, or ground	disturbance scheduled in the next	14 days?			
site (9/26/24).	Rough grading in the northeast corner began (12/6/23). Grading ceased (12/21/23). Grading started east side of site (7/17/24). Rough grading and excavation of sediment basins on all portions of site (9/26/24). What temporary or permanent stabilization measures listed in this section are being implemented?						
Existing vegetation (12/6/23).							
Checklist Questions: Are receiving waters adjacent to the	e project free of any significant	signs of erosion or sedim	ent that would be associated with	the construction activity?	•		
Yes Create Corrective Action?							
N/A							
Have disturbed areas been seeded Yes	or otherwise stabilized as requ	ired? List inactive portion	s of the project and if stabilization	measure are adequate or	needed to prevent erosion.		
N/A							
Are waste materials (concrete, cons	struction material, hazardous, o	etc.) being managed prope	riy?				
Yes Create Corrective Action? N/A							
Ave construction entrances and adjacent streets being maintained adequately?							
No							
Create Corrective Action?							
No, see BMPs section. Is dust associated with the construction activity adequately controlled on the site?							
Yes							
Create Corrective Action?							
N/A							
Comments:							
Comments: Site was active for grading.							
Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):							
 Some maintenance is required in the BMP section of this report. CIR 22909 was received, reviewed, and forwarded to Ruff Grading on 10/10/24. CIR is consistent with E&A inspector's report. 							

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
AI 01	Area Inlet Protection	NW Corner along 72nd Street	9/26/2024	Active	No
Current Condition:	Good Condition - The area		as been moved from the Seve	nty-Two Place report	as of the 9/26/24.
CE 01	Construction Entrance	NW Corner	8/16/2024	Active	Yes
Current Condition:		alling the construction e	ing an entrance prior to the 8/ entrance prior to the 8/16/24 ir		nspector will continue
			. Not done as of the last inspe	ection. Ruff Grading v	was reminded on 9/2
D TEMP	Diversion	Western Portion		Removed	
Current Condition:	Removed - Temporary div		or grading prior to the 10/10/2	24 inspection.	
D TEMP 2	Diversion	Old Farm Pond S Central		Removed	
Current Condition:	Removed - The pond was				
D 01	Diversion	SW of SB A	3/3/2024	Pending	Yes
Current Condition:	Pending - The diversion should be in Ruff Grading was informed		asin installation. . Not done as of the last inspe	ection. Ruff Grading v	was reminded on 9/2
	It should be noted that sig Grading will install as work		removed from the west side of	of the site before diver	sion can be installed
D 02	Diversion	SE of SB A	3/3/2024	Pending	Yes
Current Condition:	Pending - The diversion w	ill be installed with SB A	A. D 02 is not specifically insta	alled; however, the sw	vale is graded as of t
	It should be noted that sig	d to complete by 9/6/24. nificant cut needs to be	. Not done as of the last inspe removed from the west side of		
	Grading will install as work	callows.			
D 03	D ¹				
Current Condition:	Diversion Pending - The diversion should be in	N of SB B1	3/3/2024 asin installation.	Pending	Yes
	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig	stalled with sediment bad back of the sediment back of the sediment by 9/6/24. Inificant cut needs to be		ection. Ruff Grading v	was reminded on 9/2
Current Condition:	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work	stalled with sediment by d to complete by 9/6/24. nificant cut needs to be c allows.	asin installation. . Not done as of the last inspe removed from the west side o	ection. Ruff Grading v	was reminded on 9/2 sion can be installed
Current Condition: D 04	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion	to complete by 9/6/24. nificant cut needs to be callows. SB B1 to SB B2	asin installation. . Not done as of the last insperence of the last insperence of the west side of the west side of 10/10/2024	ection. Ruff Grading v of the site before diver Active	was reminded on 9/2
Current Condition: D 04 Current Condition:	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra	astalled with sediment by d to complete by 9/6/24. nificant cut needs to be callows. SB B1 to SB B2 ding installed a tempora	asin installation. . Not done as of the last inspe removed from the west side o	ection. Ruff Grading of the site before diver Active	was reminded on 9/2 sion can be installed
D 04 Current Condition: D 04 Current Condition: D 05	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra	astalled with sediment by d to complete by 9/6/24. nificant cut needs to be callows. SB B1 to SB B2 ding installed a tempora SE of SB B2	asin installation. Not done as of the last insperere removed from the west side of 10/10/2024 10/10/2024 ary version of D 04 prior to the	ection. Ruff Grading v of the site before diver Active	was reminded on 9/2 sion can be installed
D 04 Current Condition: D 04 Current Condition: D 05 Current Condition:	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra Diversion Removed - Revision remo	stalled with sediment by d to complete by 9/6/24. nificant cut needs to be c allows. SB B1 to SB B2 ding installed a tempora SE of SB B2 ved diversion as of 5/16	asin installation. Not done as of the last insperence of the last insperence of the west side of 10/10/2024 10/10/2024 ary version of D 04 prior to the	ection. Ruff Grading v of the site before diver Active e 10/10/24 inspection. Removed	was reminded on 9/2 sion can be installed No
D 04 Current Condition: D 04 Current Condition: D 05	Pending - The diversion should be in Ruff Grading was informer It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra Diversion Removed - Revision remo Diversion	stalled with sediment by d to complete by 9/6/24. nificant cut needs to be c allows. SB B1 to SB B2 ding installed a tempora SE of SB B2 ved diversion as of 5/16 E of SB A ding installed portions c	asin installation. Not done as of the last insperemoved from the west side of 10/10/2024 any version of D 04 prior to the S/24. 8/23/2024 of the diversion prior to the ins	ection. Ruff Grading v of the site before diver Active 10/10/24 inspection. Removed Active	was reminded on 9/2 rsion can be installed No No
D 04 Current Condition: D 05 Current Condition: D 05 Current Condition: D 06	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra Diversion Removed - Revision remo Diversion Good Condition - Ruff Gra majority of the rest of the o Diversion	stalled with sediment by d to complete by 9/6/24. nificant cut needs to be c allows. SB B1 to SB B2 ding installed a tempora SE of SB B2 ved diversion as of 5/16 E of SB A ding installed portions c	asin installation. Not done as of the last insperemoved from the west side of 10/10/2024 any version of D 04 prior to the S/24. 8/23/2024 of the diversion prior to the ins	ection. Ruff Grading v of the site before diver Active 10/10/24 inspection. Removed Active	was reminded on 9/2 rsion can be installed No
D 04 Current Condition: D 05 Current Condition: D 06 Current Condition:	Pending - The diversion should be in Ruff Grading was informer It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra Diversion Removed - Revision remo Diversion Good Condition - Ruff Gra majority of the rest of the o	astalled with sediment by d to complete by 9/6/24. nificant cut needs to be c allows. SB B1 to SB B2 ding installed a tempora SE of SB B2 ved diversion as of 5/16 E of SB A ding installed portions c diversion prior to the 10/ NE Corner of Site	asin installation. Not done as of the last insperemoved from the west side of the last insperemoved from the west side of the ary version of D 04 prior to the last of the diversion prior to the ins (10/24 inspection.) 6/1/2024	ection. Ruff Grading v of the site before diver Active 10/10/24 inspection. Removed Active pection on 8/23/24. R	was reminded on 9/2 rsion can be installed No Mo uff Grading installed
D 04 Current Condition: D 05 Current Condition: D 06 Current Condition: D 06 Current Condition: D 07	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra Diversion Removed - Revision remo Diversion Good Condition - Ruff Gra majority of the rest of the o Diversion Pending - The diversion should be in Ruff Grading was informed	Istalled with sediment by d to complete by 9/6/24. nificant cut needs to be callows. SB B1 to SB B2 ding installed a tempora SE of SB B2 ved diversion as of 5/16 E of SB A ding installed portions of diversion prior to the 10/ NE Corner of Site	asin installation. Not done as of the last insperemoved from the west side of the last insperemoved from the west side of the ary version of D 04 prior to the last of the diversion prior to the ins (10/24 inspection.) 6/1/2024	ection. Ruff Grading v of the site before diver Active 10/10/24 inspection. Removed Active pection on 8/23/24. R Pending	was reminded on 9/2 sion can be installed No Mo uff Grading installed Yes
D 04 Current Condition: D 05 Current Condition: D 06 Current Condition: D 07 Current Condition: D 07 Current Condition:	Pending - The diversion should be in Ruff Grading was informer It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra Diversion Removed - Revision remo Diversion Good Condition - Ruff Gra majority of the rest of the o Diversion Pending - The diversion should be in Ruff Grading was informer It should be noted that sig Grading will install as work Diversion	Istalled with sediment by d to complete by 9/6/24. nificant cut needs to be callows. SB B1 to SB B2 ding installed a tempora SE of SB B2 ved diversion as of 5/16 E of SB A ding installed portions of diversion prior to the 10/ NE Corner of Site	asin installation. Not done as of the last insperence of the last insperence of the last insperence of the last insperence of the last inspection of D 04 prior to the last inspection. 8/24. 8/23/2024 10/24 inspection. 6/1/2024 asin installation. Not done as of the last inspection.	ection. Ruff Grading v of the site before diver Active 10/10/24 inspection. Removed Active pection on 8/23/24. R Pending	was reminded on 9/2 sion can be installed No Mo uff Grading installed Yes
D 04 Current Condition: D 05 Current Condition: D 06 Current Condition: D 07 Current Condition: D 07 Current Condition:	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra Diversion Removed - Revision remo Diversion Good Condition - Ruff Gra majority of the rest of the o Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work	astalled with sediment by d to complete by 9/6/24. nificant cut needs to be c allows. SB B1 to SB B2 ved diversion as of 5/16 E of SB A ding installed portions c diversion prior to the 10/ NE Corner of Site stalled with sediment be d to complete by 9/6/24. nificant cut needs to be c allows. SE of SB B1	asin installation. Not done as of the last insperemoved from the west side of the last insperemoved from the west side of the last inspection. 3/24. 8/23/2024 10/24 inspection. 6/1/2024 asin installation. Not done as of the last insperemoved from the west side of the last inspection.	ection. Ruff Grading v of the site before diver Active 10/10/24 inspection. Removed Active pection on 8/23/24. R Pending ection. Ruff Grading v of the site before diver	was reminded on 9/2 sion can be installed No Unif Grading installed Yes was reminded on 9/2
D 04 Current Condition: D 05 Current Condition: D 06 Current Condition: D 07 Current Condition:	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra Diversion Removed - Revision remo Diversion Good Condition - Ruff Gra majority of the rest of the o Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Pending - The diversion should be in Ruff Grading was informed	Istalled with sediment by d to complete by 9/6/24. nificant cut needs to be c allows. SB B1 to SB B2 ding installed a tempora SE of SB B2 ved diversion as of 5/16 E of SB A ding installed portions of diversion prior to the 10/ NE Corner of Site stalled with sediment by c allows. SE of SB B1 SE of SB B1 stalled with sediment by c allows. SE of SB B1	asin installation. Not done as of the last insperemoved from the west side of the last insperemoved from the west side of the last inspection. 3/24. 8/23/2024 10/24 inspection. 6/1/2024 asin installation. Not done as of the last insperemoved from the west side of the last inspection.	ection. Ruff Grading v of the site before diver Active 10/10/24 inspection. Removed Active pection on 8/23/24. R Pending ection. Ruff Grading v of the site before diver Pending	was reminded on 9/2 sion can be installed No Was reminded on 9/2 sion can be installed Yes Was reminded on 9/2 sion can be installed
D 04 Current Condition: D 05 Current Condition: D 06 Current Condition: D 07 Current Condition: D 07 Current Condition: D 08 Current Condition:	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Grad Diversion Removed - Revision remo Diversion Good Condition - Ruff Grad Diversion Good Condition - Ruff Grad Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work	Istalled with sediment by d to complete by 9/6/24. nificant cut needs to be callows. SB B1 to SB B2 ved diversion as of 5/10 E of SB A ding installed a tempora SE of SB A diversion prior to the 10/ NE Corner of Site stalled with sediment by d to complete by 9/6/24. nificant cut needs to be callows. SE of SB B1	asin installation. Not done as of the last insperence of the last insperence of the last insperence of the last insperence of the last inspection. (10/10/2024) (10/10/2024) (10/24	ection. Ruff Grading v of the site before diver Active e 10/10/24 inspection. Removed Active pection on 8/23/24. R Pending Pending Pending Pending ection. Ruff Grading v of the site before diver Active	was reminded on 9/2 sion can be installed No UMA NO UMA STATES Was reminded on 9/2 sion can be installed Yes Was reminded on 9/2 sion can be installed No
D 04 Current Condition: D 05 Current Condition: D 06 Current Condition: D 07 Current Condition: D 07 Current Condition:	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Grad Diversion Removed - Revision remo Diversion Good Condition - Ruff Grad Diversion Good Condition - Ruff Grad Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Diversion Good Condition - Ruff Grading was informed It should be noted that sig Grading will install as work	Istalled with sediment by d to complete by 9/6/24. nificant cut needs to be c allows. SB B1 to SB B2 ved diversion as of 5/16 E of SB A ding installed portions of diversion prior to the 10/ NE Corner of Site stalled with sediment be c allows. SE of SB B1 stalled with sediment be c allows. SE of SB B2 ding installed a tempora 24 inspection. The div	asin installation. Not done as of the last insperemoved from the west side of any version of D 04 prior to the solution of the diversion prior to the ins /10/24 inspection. 6/1/2024 asin installation. Not done as of the last insperemoved from the west side of 6/1/2024 asin installation. Not done as of the last insperemoved from the west side of 6/1/2024 asin installation. Not done as of the last insperemoved from the west side of 6/1/2024 asin installation.	ection. Ruff Grading v of the site before diver Active e 10/10/24 inspection. Removed Active pection on 8/23/24. R Pending ection. Ruff Grading v Pending Pending ection. Ruff Grading v f the site before diver Active 24 inspection. Ruff Grading v	was reminded on 9/2 resion can be installed No UMB Grading installed Yes was reminded on 9/2 resion can be installed Yes was reminded on 9/2 resion can be installed No rading extended the
D 04 Current Condition: D 05 Current Condition: D 06 Current Condition: D 07 Current Condition: D 07 Current Condition: D 08 Current Condition:	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Grading will install as work Diversion Removed - Revision remo Diversion Good Condition - Ruff Grading vill install as work Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra diversion prior to the 9/26/ Grading for grading, the Diversion	Istalled with sediment by d to complete by 9/6/24. nificant cut needs to be callows. SB B1 to SB B2 ding installed a tempora SE of SB B2 ved diversion as of 5/16 E of SB A ding installed portions of diversion prior to the 10/ NE Corner of Site stalled with sediment ba d to complete by 9/6/24. nificant cut needs to be callows. SE of SB B1 stalled with sediment ba callows. SE of SB B1 stalled with sediment ba callows. SE of SB B2 ding installed a tempora 24 inspection. The div inspector will monito E of SB B2	asin installation. Not done as of the last insperemoved from the west side of 10/10/2024 ary version of D 04 prior to the side of 10/24 prior to the last insperemoved from the west side of 6/1/2024 asin installation. Not done as of the last insperemoved from the west side of 6/1/2024 asin installation. Not done as of the last insperemoved from the west side of 10/2024 asin installation. Not done as of the last insperemoved from the west side of 10/2024 asin installation. Not done as of the last insperemoved from the west side of 10/2024 asin installation. Not done as of the last insperemoved from the west side of 10/2024 asin installation. Not done as of the last insperemoved from the west side of 10/2024 asin installation. Not done as of the last insperemoved from the west side of 10/2024 asin installation. Not done as of the last insperemoved from the west side of 10/2024 asin installation. Not done as of the last insperemoved from the west side of 10/2024 asin installation. Not done as of the last insperemoved from the west side of 10/2024 asin just done as of the last insperemoved from the west side of 10/2024 asin just done as of the last insperemoved from the west side of 10/2024 asin just done as of the last insperemoved from the west side of 10/2024 asin just done as of the last insperemoved from the west side of 10/2024 asin just done as of the last insperemoved from the west side of 10/2024 asin just done as of the last insperemoved from the west side of 10/2024 asin just done as of the last insperemoved from the 10/2024 asin just done as of the last insperemoved from the 10/2024 asin just done as of the last insperemoved from the 10/2024 asin just done as of the last insperemoved from the 10/2024 asin just done as of the last insperemoved from the 10/2024 asin just done as of the 10/2024 asin just done as o	ection. Ruff Grading v of the site before diver Active 10/10/24 inspection. Removed Active pection on 8/23/24. R Pending ection. Ruff Grading v of the site before diver Pending ection. Ruff Grading v of the site before diver Active 24 inspection. Ruff Grading v Active 24 inspection. Ruff Grading v Active	was reminded on 9/2 resion can be installed No UMB Grading installed Yes was reminded on 9/2 resion can be installed Yes was reminded on 9/2 resion can be installed No rading extended the
D 04 Current Condition: D 05 Current Condition: D 06 Current Condition: D 07 Current Condition: D 07 Current Condition: D 08 Current Condition:	Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Grading will install as work Diversion Removed - Revision remo Diversion Good Condition - Ruff Grading vill install as work Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Pending - The diversion should be in Ruff Grading was informed It should be noted that sig Grading will install as work Diversion Good Condition - Ruff Gra diversion prior to the 9/26/ Grading for grading, the Diversion	Istalled with sediment by d to complete by 9/6/24. nificant cut needs to be callows. SB B1 to SB B2 ding installed a tempora SE of SB B2 ved diversion as of 5/16 E of SB A ding installed portions of diversion prior to the 10/ NE Corner of Site stalled with sediment ba d to complete by 9/6/24. nificant cut needs to be callows. SE of SB B1 stalled with sediment ba callows. SE of SB B1 stalled with sediment ba callows. SE of SB B2 ding installed a tempora 24 inspection. The div inspector will monito E of SB B2	asin installation. Not done as of the last insperence of the diversion of D 04 prior to the installation. Not done as of the last insperence of the last insperence of the last inspection. Not done as of the last insperence of	ection. Ruff Grading v of the site before diver Active 10/10/24 inspection. Removed Active pection on 8/23/24. R Pending ection. Ruff Grading v of the site before diver Pending ection. Ruff Grading v of the site before diver Active 24 inspection. Ruff Grading v Active 24 inspection. Ruff Grading v Active	was reminded on 9/2 sion can be installed No uff Grading installed Yes was reminded on 9/2 sion can be installed Yes was reminded on 9/2 sion can be installed No rading extended the 24 inspection by Rt

EN 00	En sin Os da IMatilia		0/0/0004	Decilient	NI.			
EM 02 Current Condition:	Erosion Control Matting	N and E of SB A	3/3/2024 alled after the area reaches fir	Pending	No			
FT 01	Vehicle Fueling	Staging Area	7/17/2024	Active	No			
Current Condition:			k and berm on site prior to the		I NU			
MS 01	Material Storage	On Site	3/3/2024	Pending	No			
Current Condition:	Pending - Materials will be			1 onding	110			
PB XX	Portable Bathroom	On Site	8/30/2024	Active	No			
Current Condition:	Good Condition - Ruff Gra	ading installed a portable	e toilet in the staging area prio	r to the 8/30/24 inspe	ction. Ruff Grading sta			
	down the portable toilet p	Good Condition - Ruff Grading installed a portable toilet in the staging area prior to the 8/30/24 inspection. Ruff Grading stake down the portable toilet prior to the 9/26/24 inspection.						
SB A	Sediment Basin	NW	10/10/2024	Active	No			
Current Condition:	Good Condition - 5% Fille	ed - Ruff Grading began	digging out the basin prior to	the 9/6/24 inspection.	Riser was delivered to			
	Good Condition - 5% Filled - Ruff Grading began digging out the basin prior to the 9/6/24 inspection. Riser was delivered to the site prior to the 10/3/24 inspection. Ruff Grading was in the process of installing the riser and outlet pipe during the 10/10/24 inspection. Ruff Grading finished installing the basin prior to the 10/17/24 inspection. The E&A inspector painted the cleanout mark prior to the 10/17/24 inspection.							
SB B1	Sediment Basin	W Central	3/3/2024	Pending	Yes			
Current Condition:	Pending - Riser was deliv	ered to the site prior to t	he 10/3/24 inspection, the ins	pector will monitor for	installation.			
	The basin should be insta Ruff Grading was informe		ency spillway). 4. Not done as of the last insp	pection. Ruff Grading	was reminded on 9/27			
SB B2	Sediment Basin	SW Corner	3/3/2024	Bonding	Yes			
Current Condition:			3/3/2024 in prior to the 9/13/24 inspect	Pending	Tes			
Surrent Condition.	rending - Run Grading be	egan algging out the bas	in phor to the 3/13/24 inspect					
	Ruff Grading was informe		4. Not done as of the last insp	pection. Ruff Grading	was reminded on 9/2			
SF 01	Silt Fence	Western Perimeter N of Mass Road	4/3/2024	Active	No			
Current Condition:	Good Condition - An unid		ed the silt fence prior to the 4	/3/24 inspection.				
SF 02	Silt Fence	Western Perimeter S of Mass Road	4/3/2024	Active	No			
Current Condition:			ed the silt fence prior to the 4					
SF 03	Silt Fence	Northeast Corner		Removed				
Current Condition: SF 04	Silt Fence	Southern Perimeter W	e were removed prior to the 8 9/26/2024	Active	Yes			
		of S 69th Street			Tes			
Current Condition:	Fair Condition - Ruff Grac	ling installed the silt fend	e prior to the 9/26/24 inspecti	on.				
	J-hooks should be installe Ruff Grading was informe		4. Not done as of the last insp	pection.				
05.05		Southern Perimeter E			Nee			
SF 05	Silt Fence	of S 69th Street	10/3/2024	Pending	Yes			
Current Condition:	Pending -							
	Ŭ		ling where draining the old far					
	Ruit Grading was informe		 Not done as of the last insp 	bection.				
SF 06	Silt Fence	Drainage at SB A	8/16/2024	Active	Yes			
		outfall						
Current Condition:	Fair Condition - The silt fe	ence has been transferre	d from the Seventy-Two Plac	e SWPPP due to acti	ve ground disturbance			
	Ponderosa Place. Silt fence in the area will include downgradient silt fence in the Ponderosa Drive swale to the west as of the							
	9/26/24 inspection. Ruff Grading repaired the silt fence prior to the 9/26/24 inspection. Ruff Grading installed silt fence on the east side of the Ponderosa Culvert prior to the 10/17/24 inspection.							
	J-hooks along the south side of Ponderosa Drive need to be installed.							
			4. Not done as of the last insp					
SWPPP Sign	SWPPP Sign	At CE 01	12/20/2023	Active	No			
Current Condition:		•	SWPPP sign at the central st thwest corner of the property	•				
WO 01	Concrete Washout	On Site	3/3/2024	Pending	No			
			3/3/2024 en concrete work begins on s	Pending	UVI			
Current Condition								
Current Condition:					No			
Current Condition: WS 01 Current Condition:	Waste Storage Pending - Waste will be p	On Site	3/3/2024	Pending	No			

Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."				
Inspector Signature:	Jon le Mart		Reviewed By:	Cato Sul	