E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A- P2017.	.463.001						
Inspector: Avery Dresser					Stage				
	Prairie Ho	ollow (aka Hidd	en Hollow per NDE	Q NOI)					
Project Name:			01802726		2				
					00007				
For Week Ending:	1-011-01		/2020		68007				
Project Location: 156th Street and Highway 36 (Bennington Ne, Douglas County)									
Grading:	95%	ı							
Sanitary Sewer:	75%								
Storm Sewer:	95%								
Paving:	85%								
Seeding:	20%								
Utilities:	10%								
Overall Development:	35%								
		I	1	1					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time					
Cumdou	0.00"				Week '				
Sunday:	0.00"	0/04/0000	Double Claude 40/20	40:40					
Monday Tuesday	0.00"	2/24/2020	Partly Cloudy 46/30	10:10 a.m.					
Wednesday	0.00"								
Thursday	0.00"								
Friday	0.00"								
Saturday	0.00"								
- Catal adj	0.00				Week 2				
Sunday:	0.00"								
Monday	0.02"								
Tuesday	0.01"								
Wednesday	0.00"								
Thursday	0.00"								
Friday	0.00"								
Saturday	0.00"								
					Week 3				
Sunday:	0.00"								
Monday	0.28"	3/9/2020	Rain 56/29	2:20 p.m.					
Tuesday	0.00"								
Wednesday	0.00"	ļ							
Thursday	0.01"								
Friday	0.01"								
Saturday	0.33"								
	None								
	1.2								
Complaints:									
Construction Sequencing:									

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site: Grading commenced (11/8/18). Grading temporarily ceased due to winter conditions (3/5/19). Entire site: Grading resumed (4/9/19). Major grading complete, minor grading at a later date (4/23/19). Grading along future location of N. Allen Street (6/17/19). Excavation for storm sewer installation in the southern portion of the site (7/15/19). Minor grading in the southern portion of the site (8/12/19). Excavation for water main installation in the northern portion of the site (11/18/19). Grading complete north of N. Allen Street (12/02/19). Regrading of the slope in the southeast corner of the site, minor grading around the area inlets at the north end of the site (1/27/20). Minor grading north of SB A, slope in the northwest corner of the site (1/27/20).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire Site: Grading commenced (11/8/18), Grading temporarily ceased due to winter conditions (3/5/19), Entire site: Grading resumed (4/9/19), Major grading complete, minor grading at a later date (4/23/19). Grading along future location of N. Allen Street (6/17/19). Excavation for storm sewer installation in the southern portion of the site (7/15/19). Minor grading in the southern portion of the site (8/12/19). Excavation for water main installation in the northern portion of the site (11/18/19). Grading complete north of N. Allen Street (12/02/19). Regrading of the slope in the southeast corner of the site, minor grading around the area inlets at the north end of the site (1/13/20). Minor grading north of SB A, slope in the northwest corner of the site (1/27/20).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/8/18). Negus & Son's Construction seeded the flat area and seeded/matted the slope north of N. Allen Street (12/02/19).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

No - See BMP Section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion

Yes

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No - See BMP and Findings Sections

Create Corrective Action?
No - See BMP Section

s dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

Site was active during the last inspection. Not all BMPs could be properly observed during the last inspection due to winter conditions.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) The t-posts along the entire run of perimeter silt fence needs to be spaced properly. They are currently too wide. Negus & Son's Construction was informed to complete by 11/29/18. Not done as of the last inspection. Mikhail with Negus & Son's Construction was reminded on-site on 7/15/19. Negus & Son's Construction was reminded on 12/19/18, 1/23/19, 3/16/19, 3/29/19, 4/24/19, 5/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19, 8/27/19, 9/11/19, 9/27/19, 10/04/19, 11/04/19, 11/19/19, 12/23/19, 1/29/20. Ryan Schwarz and Negus & Son's Construction were reminded on 2/11/20. As of the inspection on 3/09/20, most of the original silt fence with improperly spaced t-posts have been removed. Specific sections needing additional tposts will now be identified in the BMP section.
- 3.) The portable toilet on site was moved to a location near CE 1 (Y9). The portable toilet should be staked down. Negus & Son's Construction was informed to complete by 8/12/19. Not done as of the last inspection. Negus & Son's Construction was reminded on 8/27/19, 9/11/19, 9/27/19, 10/4/19, 11/04/19, 11/19/19, 12/23/19, 1/29/20. Ryan Schwarz and Negus & Son's Construction were reminded on 2/11/20. Negus & Son's Construction removed the portable toilet from the site prior to the inspection on 3/09/20.
- 4.) The concrete washout waste at the north end of the site should be cleaned up. Ryan Schwarz and Negus & Son's Construction were informed to complete by 2/17/20. Not done as of the last inspection. Ryan Schwarz and Negus & Son's Construction were reminded on 3/10/20.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
	Stabilized Construction					
CE 1	Entrance	N Molley Street (EE11)		Removed		
Current Condition:	Removed - The former co	nstruction entrance was p	aved prior to the inspection	on on 11/04/19.		
	Stabilized Construction					
CE 2	Entrance	N 2nd Street (B24)		Removed		
Current Condition:	Removed - The former construction entrance was paved prior to the inspection on 11/04/19.					
CW 1	Concrete Washout Site 11/15/2018 Pending Yes					
Current Condition:	Pending - Concrete washout waste was observed on-site on 2/10/20. A lined concrete washout pit should be installed. Ryan Schwarz and Negus & Son's Construction were informed to complete by 2/17/20. Not done as of the last inspection. Ryan Schwarz and Negus & Son's Construction were reminded on 3/10/20.					
	Temporary Diversion	/ - /				
D1	Ditch	(Z17-II17)	12/25/2018	Pending	Yes	

Current Condition:	Pending -					
	The diversion needs to be	installed				
	Negus & Son's Construction was informed to complete by 12/25/18. Not done as of the last inspection. Mikha & Son's Construction was reminded on-site on 7/15/19. Negus & Son's Construction was reminded on 3/16/19.					
	4/24/19, 5/20/19, 6/06/19,		<u> </u>		the state of the s	
	12/23/19, 1/29/20. Ryan S	<mark>chwarz and Negus & Sor</mark>	n's Construction were rem	inded on 2/11/20, 3/1	0/20	
D2	Temporary Diversion Ditch	(F25-P21)	12/25/2018	Pending	Yes	
Current Condition:	Pending -			-		
	The diversion needs to be	installed.				
	Negus & Son's Construction & Son's Construction was					
	4/24/19, 5/20/19, 6/06/19,	<mark>6/18/19, 6/24/19, 7/24/1</mark> 9	9, 8/05/19, 8/27/19, 9/11/1	9, 9/27/19, 10/04/19, ¹	11/04/19, 11/19/19,	
	12/23/19, 1/29/20. Ryan Service Temporary Diversion	chwarz and Negus & Sor	n's Construction were rem	inded on 2/11/20 , 3/1	0/20	
D3	Ditch	(P21-R20)	12/25/2018	Pending	Yes	
Current Condition:	Pending -			<u> </u>		
	The diversion needs to be	installed.				
	Negus & Son's Construction & Son's Construction was					
	4/24/19, 5/20/19, 6/06/19,	<mark>6/18/19, 6/24/19, 7/24/1</mark> 9	9, 8/05/19, 8/27/19, 9/11/1	9, 9/27/19, 10/04/19, ¹	11/04/19, 11/19/19,	
	12/23/19, 1/29/20. Ryan S	chwarz and Negus & Sor	n's Construction were rem	inded on 2/11/20, 3/1	0/20	
D4	Temporary Diversion Ditch	(B26-D26)	12/25/2018	Pending	Yes	
Current Condition:	Pending -	,	<u> </u>	-		
	The diversion needs to be installed.					
	Negus & Son's Construction was informed to complete by 12/25/18. Not done as of the last inspection. Mikhail with Negus					
	& Son's Construction was reminded on-site on 7/15/19. Negus & Son's Construction was reminded on 3/16/19, 3/29/19,					
	4/24/19, 5/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19, 8/27/19, 9/11/19, 9/27/19, 10/04/19, 11/04/19, 11/19/19, 12/23/19, 1/29/20. Ryan Schwarz and Negus & Son's Construction were reminded on 2/11/20, 3/10/20					
EM 1	Erosion Control Matting	(C22-DD11)	12/2/2019	Active	No	
Current Condition:	Good Condition - Negus &					
FT 1	Fuel Tank	W11	5/20/2019	Active	No	
Current Condition:	Good Condition - A white f section). The fuel tank had					
	monitor.	appropriate secondary t	Containment as or last ms	Dection. Ear inspecto	i will continue to	
IF 1	Inlet Filter	II14	9/9/2019	Active	Yes	
Current Condition:	Fair Condition - Negus & S 9/09/19. The area around					
	cleaned out around the inle					
	Construction removed the	damaged silt fence wrap				
	the inspection on 12/02/19.					
	The new silt fence wrap should be properly trenched-in.					
	Negus & Son's Construction	on was informed to comp	elete by 12/09/19. Not done	e as of the last inspec	tion. Negus & Son's	
	Construction was reminded on 12/23/19, 1/29/20. Ryan Schwarz and Negus & Son's Construction were reminded on					
IF 2	2/11/20, 3/10/20 Inlet Filter	II11	9/9/2019	Active	Yes	
Current Condition:	Fair Condition - Negus & S	Son's Construction install	ed a silt fence wrap aroun	d the storm sewer inle	et prior to inspection on	
	9/10/19. The area around the include			O .		
	cleaned out around the inlet and removed the silt fence wrap prior to the inspection on 11/18/19. Negus & Son's Construction removed the damaged silt fence wrap material and installed a new silt fence wrap around the inlet prior to					
	the inspection on 12/02/19					
	The new silt fence wrap sh	ould be properly trenche	ed-in.			
	Negus & Son's Construction	· ·			•	
	Construction was reminde	d on 12/23/19, 1/29/20. F	Ryan Schwarz and Negus	& Son's Construction	were reminded on	
IF 3	2/11/20, 3/10/20 Inlet Filter	HH15	1/27/2020	Active	Yes	

Current Condition:	Fair Condition - Negus & 1/27/20.	Son's Construction installe	ed two big red inlet filters	in the curb inlet prior t	to the inspection on		
	1. The damaged inlet filter should be repaired. 2. The inlet filters should be cleaned out.						
		ruction was informed to cor struction were reminded on		one as of the last inspe	ction. Ryan Schwarz		
	2. Negus & Son's Cons	truction and Ryan Schwa	arz were informed to co	omplete by 3/16/20.			
IF 4	Inlet Filter	HH13	1/27/2020	Active	Yes		
Current Condition:	1/27/20. 1. The damaged inlet filte 2. The inlet filters should	 The damaged inlet filter should be repaired. The inlet filters should be repositioned to fully protect the inlet. Negus & Son's Construction was informed to complete by 2/03/20. Not done as of the last inspection. Ryan Schwarz 					
		ruction was informed to cor		one as of the last inspe	ction. Ryan Schwarz		
		struction were reminded on			·		
IF 5	Inlet Filter	AA17	1/27/2020	Active	Yes		
Current Condition:	1/27/20.	Son's Construction install		in the curb inlet prior t	o the inspection on		
		e repositioned to fully block us & Son's Construction wa		ov 2/17/20. Not done a	s of the last		
		arz and Negus & Son's C					
IF 6	Inlet Filter	Y17	1/27/2020	Active	No		
Current Condition:	Good Condition - Negus 1/27/20.	& Son's Construction insta	illed two big red inlet filte	rs in the curb inlet prior	to the inspection on		
IF 7	Inlet Filter	E25	1/27/2020	Active	No		
Current Condition:	1/27/20.	& Son's Construction insta	_	•	to the inspection on		
IF 8	Inlet Filter	GG15	2/10/2020	Active	No		
Current Condition:	2/10/20.	& Son's Construction insta	_				
IF 9	Inlet Filter	GG13	2/10/2020	Active	No		
Current Condition:	2/10/20.	& Son's Construction insta	<u> </u>				
IF 10	Inlet Filter	DD17	2/10/2020	Active	No		
Current Condition:	2/10/20.	& Son's Construction insta	-				
IF 11	Inlet Filter	X17	2/10/2020	Active	No		
Current Condition:	2/10/20.	& Son's Construction insta	illed two big red inlet filte	rs in the curb inlet prior	to the inspection on		
IF 12	Inlet Filter	R19	2/10/2020	Active	No		
Current Condition:	2/10/20.	& Son's Construction insta					
IF 13 Current Condition:	Inlet Filter Good Condition - Negus 2/10/20.	& Son's Construction insta	2/10/2020 Illed two big red inlet filte	Active rs in the curb inlet prior	No r to the inspection on		
IF 14	Inlet Filter	G23	2/10/2020	Active	Yes		
Current Condition:	Fair Condition - Negus &	Son's Construction install	ed two big red inlet filters	in the curb inlet prior t	o the inspection on		
	 2/10/20. The damaged inlet filter should be repaired or replaced. The inlet filters should be cleaned out. Ryan Schwarz and Negus & Son's Construction was informed to complete by 2/17/20. Not done as of the last inspection. Ryan Schwarz and Negus & Son's Construction were reminded on 3/10/20. Ryan Schwarz and Negus & Son's Construction were informed to complete by 3/09/20. 						
IF 15	Inlet Filter	F24	2/10/2020	Active	No		
Current Condition:		& Son's Construction insta					
Lot 11	Individual Lot	GG15	12/30/2019	Active	No		
				•			

Current Condition:		n LLC excavated the lot pri ent. The E&A inspector will			tively flat and on the		
Lot 12	Individual Lot	FF15	2/10/2020	Active	No		
Current Condition:	Active - Viking Homes e. development, the E&A ir	xcavated the lot prior to the nspector will monitor the ne owever excavation was act	e inspection on 2/10/20. The dirt pile was a single of the	Γhe lot is fairly flat and was observed in the R	on the interior of the OW during the		
Lot 73	Individual Lot	AA18	3/16/2020	Pending	Yes		
Current Condition:	Pending - An unknown builder excavated the lot prior to the inspection on 3/09/20. Silt fence should be installed along the back side of the lot. The E&A inspector will attempt to identify the builder and inform them to complete by 3/16/20.						
Lot 74	Individual Lot	BB18	1/6/2020	Pending	Yes		
Current Condition:	Silt fence should be insta	tion LLC excavated the lot particular along the back side or the same as informed to complete as	f the lot.	5/20. Not done as of th	ne last inspection.		
Lot 75	Individual Lot	BB18	2/17/2020	Pending	Yes		
	 The portable toilet sho Viking Homes was inf Viking Homes was inf 	Pending - Viking Homes excavated the lot prior to the inspection on 2/10/20. 1. Silt fence should be installed along the back side of the lot. 2. The portable toilet should be secured 50 feet from any inlets. 1. Viking Homes was informed to complete by 2/17/20. Not done as of the last inspection. 2. Viking Homes was informed to complete by 2/17/20. Not done as of the last inspection.					
Lot 77	Individual Lot	DD18	2/17/2020	Pending	Yes		
	Viking Homes was inform	alled along the back side o). Not done as of the la	<u> </u>			
Lot 83	Individual Lot	HH18	1/6/2020	Pending	Yes		
Current Condition: SB A	Pending - LIM Construction LLC excavated the lot prior to the inspection on 12/30/19. Silt fence should be installed along the north and east sides of the lot. LIM Construction LLC was informed to complete as conditions allow by 1/06/20. Not done as of the last inspection.						
Current Condition:	Sediment Basin	D26	11/15/2018	Pending	Yes		
	Fair Condition - 60 % filled - Negus & Son's Construction partially installed the riser in the basin prior to inspection on 9/19/19. The E&A inspector will monitor and determine if all elements of the basin have been correctly installed when work is completed. Negus & Son's Construction backfilled and compacted dirt around the riser and the portion of the outlet pipe within the wall of the basin prior to the inspection on 12/16/19. Negus & Son's Construction partially dug out and reshaped the sediment basin prior to the inspection on 12/16/19. Negus & Son's Construction backfilled and compacted along the outlet pipe prior to the inspection on 1/27/20. 1. The Preformed Scour Holes should be installed at the outfall to both risers per the SWPPP (previously included under the general recommendation to complete installation of the basin per the SWPPP; previous complete-by and reminder dates still apply). 2. The sediment basin should be cleaned out. 1. Negus & Son's Construction was informed to complete by 12/25/18. Not done as of the last inspection. Mikhail with Negus & Son's Construction was reminded on-site on 7/15/19. Negus & Son's Construction was reminded on 3/16/19, 3/29/19, 4/24/19, 5/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19, 8/27/19, 9/11/19, 9/27/19, 10/04/19, 12/23/19, 1/29/20. Ryan Schwarz and Negus & Son's Construction were reminded on 2/11/20, 3/10/20 2. Ryan Schwarz (The Developer) was informed to complete by 10/29/19. Not done as of the last inspection. Ryan						
	2. The sediment basin si 1. Negus & Son's Constructure 3/29/19, 4/24/19, 5/20/19 1/29/20. Ryan Schwarz a	ruction was informed to cor ction was reminded on-site 9, 6/06/19, 6/18/19, 6/24/19 and Negus & Son's Constru	on 7/15/19. Negus & Soi 0, 7/24/19, 8/05/19, 8/27/ uction were reminded on	n's Construction was r 19, 9/11/19, 9/27/19, 1 2/11/20, <mark>3/10/20</mark>	eminded on 3/16/19, 10/04/19, 12/23/19,		
SB B	2. The sediment basin si 1. Negus & Son's Constructure 3/29/19, 4/24/19, 5/20/19 1/29/20. Ryan Schwarz a	ruction was informed to coretion was reminded on-site 9, 6/06/19, 6/18/19, 6/24/19 and Negus & Son's Constru Developer) was informed to	on 7/15/19. Negus & Soi 0, 7/24/19, 8/05/19, 8/27/ uction were reminded on	n's Construction was r 19, 9/11/19, 9/27/19, 1 2/11/20, <mark>3/10/20</mark>	eminded on 3/16/19, 10/04/19, 12/23/19,		

Current Condition:	will monitor and determin	n's Construction installed on the if all elements of the bas led the second riser in the	in have been correctly inst	talled when work is con	npleted. Negus &	
	installed below both outfallength of the pipe.	alls, and open area around	the original riser pipe need	ds to be backfilled and	compacted along the	
		Holes should be installed a stion to complete installation to description ould be cleaned out.				
	Negus & Son's Construct 3/29/19, 4/24/19, 5/20/19 1/29/20. Ryan Schwarz (Ryan Schwarz and Negu	uction was informed to contion was reminded on-site of 6,6/06/19, 6/18/19, 6/24/19 The Developer) was informs & Son's Construction were eveloper) was informed to a 2/11/20 3/10/20	on 7/15/19. Negus & Son's , 7/24/19, 8/05/19, 8/27/19 ned to complete ASAP on re reminded on 2/11/20, 3/	Construction was rem 9, 9/11/19, 9/27/19, 10/0 10/23/19. Not done as o 10/20	olinded on 3/16/19, 04/19, 12/23/19, of the last inspection.	
SF 1	Silt fence	(A25-II18)	11/8/2018	Active	Yes	
	Fair Condition - Negus & Son's Construction installed the silt fence prior to the inspection on 11/8/18. Negus & Son's Construction installed new runs of silt fence along the north side of SB B and the north and south sides of silt prior to the inspection on 3/09/20. 1.) The north end of the silt fence should be trenched in. 2.) The old run of silt fence behind the standing silt fence should be removed. 3.) The silt fence near SB A should be cleaned out and repaired/reinstalled. 4.) The silt fence should be repaired/reinstalled east of SB B. 5.) The new run of silt fence south of the future location of SB B should be cleaned out / repaired. 6.) The silt fence should be repaired/reinstalled where partially removed north of SB B. 7.) The new run of silt fence along the southeast corner of SB A should have t-posts added and should be real. 8.) The new run of silt fence along the northeast side of SB A should be properly trenched-in. 1.) Negus & Son's Construction was informed to complete by 4/2/19. Not done as of the last inspection. Mikhail with Negus & Son's Construction was reminded on-site on 7/15/19. Negus & Son's Construction was reminded on 4/24/15/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19, 8/27/19, 9/11/19, 9/27/19, 10/04/19, 11/04/19, 11/19/19, 12/23/11/29/20. Ryan Schwarz and Negus & Son's Construction were reminded on 2/11/20, 3/10/20 2.) Negus & Son's Construction was informed to complete by 4/2/19. Not done as of the last inspection. Mikhail with Negus & Son's Construction was reminded on-site on 7/15/19. Negus & Son's Construction was reminded on 4/24/15/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19, 8/27/19, 9/11/19, 9/27/19, 10/04/19, 11/04/19, 11/04/19, 11/29/19, 12/23/11/29/20. Ryan Schwarz and Negus & Son's Construction were reminded on 2/11/20, 3/10/20 3.) Negus & Son's Construction was reminded on-site on 7/15/19. Negus & Son's Construction was reminded on 4/24/11/29/20. Ryan Schwarz and Negus & Son's Construction were reminded on 2/11/20, 3/10/20 4.) Negus & Son's Construction					
	Construction was reminded on 9/27/19, 10/04/19, 11/04/19, 11/19/19, 12/23/19, 1/29/20. Ryan Schwarz and Negus & Son's Construction were reminded on 2/11/20, 3/10/20 6.) Negus & Son's Construction were informed to complete by 12/03/19. Not done as of the last inspection. Negus & Son's Construction was reminded on 12/23/19, 1/29/20. Ryan Schwarz and Negus & Son's Construction were reminded on 2/11/20, 3/10/20 7.) Negus & Son's Construction and Ryan Schwarz were informed to complete by 3/16/20.					
05.0	, ,	struction and Ryan Schw		•	Va	
SF 2 Current Condition:	Silt fence Pending -	II18	11/29/2018	Pending	Yes	
Carrent Continuon.	The silt fence needs to be Negus & Son's Construct & Son's Construction was 3/16/19, 3/29/19, 4/24/19 11/04/19, 11/19/19, 12/23	e installed to cover the adjation was informed to comples reminded on-site on 7/15, 5/20/19, 6/06/19, 6/18/19, 3/19, 1/29/20. Ryan Schwa	ete by 11/29/18. Not done /19. Negus & Son's Const , 6/24/19, 7/24/19, 8/05/19	ruction was reminded o , 8/27/19, 9/11/19, 9/27	on 12/19/18, 1/23/19, 7/19, 10/04/19,	
05.0	3/10/20	1147	44/00/00/2	D. "		
SF 3	Silt fence	II17	11/29/2018	Pending	Yes	

Current Condition:	Pending -					
	The silt fence needs to be installed to cover the adjacent waterway.					
	& Son's Construction was 3/16/19, 3/29/19, 4/24/19, 11/04/19, 11/19/19, 12/23	ion was informed to comple reminded on-site on 7/15/ 5/20/19, 6/06/19, 6/18/19, 1/19, 1/29/20. Ryan Schwar	19. Negus & Son's Cons 6/24/19, 7/24/19, 8/05/1	truction was reminded 9, 8/27/19, 9/11/19, 9/	d on 12/19/18, 1/23/19, /27/19, 10/04/19,	
05.4	3/10/20	(DD4 DD44)	44/0/0040	A ations	V	
SF 4 Current Condition:	Silt fence	(DD1-DD14) Son's Construction installe	11/8/2018	Active	Yes	
	Not done as of the last ins Son's Construction was re	ion will be informed to com spection. Mikhail with Negu eminded on 3/16/19, 3/29/1 , 10/04/19, 11/04/19, 11/19	us & Son's Construction v 9, 4/24/19, 5/20/19, 6/06	was reminded on-site 6/19, 6/18/19, 6/24/19,	on 7/15/19. Negus & 7/24/19, 8/05/19,	
STR	Streets	Site	11/8/2018	Active	Yes	
Current Condition:	Fair Condition - Negus & Son's Construction cleaned up the trackout on the adjacent streets prior to inspection on 8/05/19. The condition of the streets could not be fully determined during the inspection on 12/16/19 due to snow and ice cover. The adjacent streets were free of trackout during the inspection on 1/13/20. Negus & Son's Construction cleaned the trackout off North Molley Street prior to the inspection on 2/10/20. The interior streets should be cleaned. Negus & Son's Construction was informed to complete by 12/03/19. Not done as of the last inspection. Negus & Son's Construction was reminded on 12/23/19, 1/29/20. Ryan Schwarz and Negus & Son's Construction were reminded on 2/11/20, 3/10/20					
SWPPP Sign	Misc/Other	At CE1, end N. Molley St.	12/17/2018	Active	No	
Current Condition:	Good Condition- The inspector installed the sign during the inspection on 12/17/18. The SWPPP sign had been removed prior to the inspection on 12/30/19. The E&A inspector reinstalled the SWPPP sign during the inspection on 12/30/19.					
Inspector Signature:	Son			Reviewed By:	8-to S. 1.)	