E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC				Fuelmossine Ana	
Environmental Services Dept. N		A D0044 400 000		Engineering Ans	vers
	E&	A- P2011.160.006			
Inspector: Rhett DeLay					Stage
		Ridgeview Apart	ments		
			1		
Project Name:		CSW-2021060	7 11		
For Week Ending:		12/10/2022)		68048
Project Location:	211 S 23	RD ST - Plattsmouth, N			
1 Toject Location:	211 0 23	IND OT - Flattsilloutil, I	iL (Gass Gounty)		
Grading:	40%				
Sanitary Sewer:	0%				
Storm Sewer:	0%				
Paving:	0%				
Seeding:	0%				
Utilities:	0%				
Overall Development:	5%				
		1			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"	12/7/2022	Sunny 25/37	1:25 PM	
Thursday:	0.00"				
Friday:	0.00"				
Saturday:	0.82"				
	None				
Complaints:					
Construction Sequencing:					
	of the site have had a temporary or permanent cessa	tion of grading, earthwork,	or ground disturbance in the las	t 14 days?	
E&A hired as SWPPP inspector (11/21/22). Entire site active for grading as of	(11/23/2022). Removal	of concrete at entrance (11	/30/22).	
Which portion(s) (i.e. drainage basins)	of the site do not have grading, earthwork, or ground	d disturbance scheduled in t	he next 14 days?		
	11/21/22). Entire site active for grading as of			/30/22)	
Lax mica as own in inspector (The fire site delive for grading as or	(11/25/2022). Nemovar	or concrete at entrance (1)	100/22].	
	tion measures listed in this section are being implen	nented?			
Existing vegetation (11/23/2022).					
Checklist Questions:					
Are receiving waters ediscent to	a the preject free of any cignificant cigns	of oronion or codimon	t that would be seesalete	d with the construction	n ootivity?
Yes	o the project free of any significant signs	or erosion or sediment	tinat would be associate	a with the construction	n activity?
Create Corrective Action?					
N/A					
	ded or otherwise stabilized as required? I	list inactive portions o	t the project and it stabili	zation measure are a	lequate or needed
to prevent erosion. Yes					
Create Corrective Action?					
N/A					
Are weets metarials (see suct	and the state of t		2		
No	construction material, hazardous, etc.) be	ing managed properly	<u> </u>		
Create Corrective Action?					
No, See BMP Section					
And a constitute of the consti	I adia ant stoata halo o o alotalo a l	- tale 0			
Are construction entrances and	d adjacent streets being maintained adequ	iately?			
Create Corrective Action?					
No, See BMP Section					
In death and a late of the state of	atmost an antidox and a second as the second				
Is dust associated with the con Yes	struction activity adequately controlled or	n the site?			
Create Corrective Action?					

- Comments:
 1.) Site was active during the current inspection.
 2.) E&A hired as SWPPP inspector as of 11/21/22.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date): 1.) Some maintenance in BMP Section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 01	Construction Entrance	North East Corner	12/1/2022	Pending	Yes		
Current Condition:	Pending -	North East Come	12/1/2022	r criding	103		
	A construction entrance should be installed.						
	The Calabretto Building Group was inform		2. Not done as of last inspe				
MS 01	Material Storage	Near CE 01	11/23/2022	Active	No		
Current Condition:	Active - The Calabretto Building Group is	storing building materials of	n site.				
PB 01	Material Storage	Near CE 01	11/30/2022	Active	Yes		
Current Condition:	Fair Condition - The Calabretto Building G	Froup installed a portable to	ilet on site prior to the insp	ection on 11/30/22.			
	Portable toilet should be secured. The Calabretto Building Group was inform	ned to complete by 12/7/22	Not done as of last insp	ection.			
SF 01	Silt Fence	East perimeter	9/9/2022	Active	Yes		
Current Condition:					103		
Current Containon.	Fair Condition - The Calabretto Building Group installed silt fence prior to the inspection on 11/23/22.						
	The silt fence needs to be repaired and extended along the eastern perimeter.						
	The sit tence needs to be repaired and extended along the easiern perimeter.						
	The Calabretto Building Group was informed to complete by 11/30/22. Not done as of last inspection.						
SF 02	Silt Fence	Eastern Slope	12/1/2022	Pending	Yes		
Current Condition:	Pending -			- U			
	Silt fence should be installed once grading in the area is complete.						
	The Calabretto Building Group was inform	ned to complete by 11/30/22	2. Not done as of last inspe	ection.			
STR	Streets	ADJ and Internal Streets	10/31/2022	Active	No		
Current Condition:	Good Condition- No major signs of track of		T				
SWPPP Sign	SWPPP Signs	Adjacent to CE 1	9/30/2022	Active	No		
Current Condition:	Good Condition- E&A inspector installe	ed the SWPPP sign on the	e north east corner of the	site during the in	spection on 12/7/		
WO 01	Concrete Washout	On site	12/1/2022	Pending	No		
Current Condition:	Pending - A concrete washout will be insta		12/1/2022	rending	INU		
WS 01	Waste Storage Area	On site	12/7/2022	Pending	No		
Current Condition:	Pending - The waste storage area will be		12/1/2022	1 01141119			
WT 01	Wattle	North East Corner	11/30/2022	Pendina	Yes		
WT 01 Current Condition:		North East Corner	11/30/2022	Pending	Yes		
	Wattle Pending -	North East Corner	11/30/2022	Pending	Yes		
			11/30/2022	Pending	Yes		
	Pending -		11/30/2022	Pending	Yes		
	Pending -	nage area.		<u> </u>	Yes		
Current Condition:	Pending - Wattles should be installed in front of drain The Calabretto Building Group was inform	nage area. ned to complete by 11/30/2:	2. Not done as of last inspe	ection.			
	Pending - Wattles should be installed in front of drain The Calabretto Building Group was inform "I certify, under penalty of law, that this do	nage area. ned to complete by 11/30/2: cument and all attachment	2. Not done as of last inspe	ection. direction or superv	ision in accordanc		
Current Condition:	Pending - Wattles should be installed in front of drain The Calabretto Building Group was inform "I certify, under penalty of law, that this do with a system designed to assure that quarters."	nage area. ned to complete by 11/30/2: cument and all attachment	2. Not done as of last inspensions were prepared under my athered and evaluated the	ection. direction or supervinformation submit	ision in accordanc		
Current Condition:	Pending - Wattles should be installed in front of drain. The Calabretto Building Group was inform. "I certify, under penalty of law, that this do with a system designed to assure that que inquiry of the person or persons who man	nage area. ned to complete by 11/30/2: cument and all attachment alified personnel properly grage the system or those per	2. Not done as of last inspensions were prepared under my athered and evaluated the ersons directly responsible	ection. direction or supervinformation submit for gathering the in	ision in accordanc ted. Based on my formation, the		
Current Condition:	Pending - Wattles should be installed in front of drain. The Calabretto Building Group was inform. "I certify, under penalty of law, that this do with a system designed to assure that que inquiry of the person or persons who man information submitted is, to the best of my	nage area. ned to complete by 11/30/2: cument and all attachment alfiled personnel properly ga age the system or those per knowledge and belief, true	2. Not done as of last inspers s were prepared under my athered and evaluated the ersons directly responsible to accurate, and complete.	ection. direction or superv information submit for gathering the in	ision in accordanc ted. Based on my formation, the ere are significant		
Current Condition:	Pending - Wattles should be installed in front of drain. The Calabretto Building Group was inform. "I certify, under penalty of law, that this do with a system designed to assure that que inquiry of the person or persons who man	nage area. ned to complete by 11/30/2: cument and all attachment alfiled personnel properly ga age the system or those per knowledge and belief, true	2. Not done as of last inspers s were prepared under my athered and evaluated the ersons directly responsible to accurate, and complete.	ection. direction or superv information submit for gathering the in	ision in accordance ted. Based on my formation, the ere are significant		
Current Condition:	Pending - Wattles should be installed in front of drain. The Calabretto Building Group was inform. "I certify, under penalty of law, that this do with a system designed to assure that que inquiry of the person or persons who man information submitted is, to the best of my	nage area. ned to complete by 11/30/2: cument and all attachment alfiled personnel properly ga age the system or those per knowledge and belief, true	2. Not done as of last inspers s were prepared under my athered and evaluated the ersons directly responsible to accurate, and complete.	ection. direction or superv information submit for gathering the in	ision in accordanc ted. Based on my formation, the ere are significant		
Current Condition:	Pending - Wattles should be installed in front of drain. The Calabretto Building Group was inform. "I certify, under penalty of law, that this do with a system designed to assure that que inquiry of the person or persons who man information submitted is, to the best of my	nage area. ned to complete by 11/30/2: cument and all attachment alfiled personnel properly ga age the system or those per knowledge and belief, true	2. Not done as of last inspers s were prepared under my athered and evaluated the ersons directly responsible to accurate, and complete.	direction. direction or supervinformation submit for gathering the in I am aware that the knowing violations."	ision in accordanc ted. Based on my formation, the ere are significant		