E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Enaineerina Answers

Zachary A. Jilek, CPESC, CISEC

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager Environmental Services Dept. Manager								
Environmental Services Dept. W	ianager	E&A- P.201	5 767 003					
nspector: Chase Wickard		20/4 1 .2014	0.1 01 1000			Stage		
		Tokama	ah Medical	Clinic		510.95		
				_		2		
Project Name:		CSW-201702196						
For Week Ending:		1/27/2018						
Project Location:		Hwy 32 and K St Tekamah, NE (Burt County)						
Crodings	<u> </u>	750/				T		
Grading: Sanitary Sewer:	-	75% 0%						
Storm Sewer:		0%						
Paving:		0%						
Seeding:		0%						
Utilities:		0%						
Overall Development:		10%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weathe	r Conditions	1			
RAIN FALL AMOUNTS	Amount in tentis	Date Inspected	vveatne	Conditions		Week		
Sunday:	0.00"					- Treck		
Monday	0.00"	01/15/	/18 1	4/-2 Clear				
Tuesday	0.00"							
Wednesday	0.00"							
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
Outline	0.400					Week		
Sunday:	0.12" 0.68"							
Monday Tuesday	0.00"	01/23/	/18 CI	oudy 28/14				
Wednesday	0.00"	01/23/	16 CI	oudy 20/14				
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
						Week		
Sunday:	NA							
Monday	NA							
Tuesday	NA							
Wednesday	NA NA							
Thursday Friday	NA NA							
Saturday	NA NA							
outu. uuy	101	ļ.	!			!		
	None							
Complaints:								
0								
Construction Sequencing: Which portion(s) (i.e. drainage basins) of	of the site have had a temp	rany or normanout of	secation of grading	earthwork or ar	ound disturbance in	ho last 14 days?		
willing portion(s) (i.e. dramage basins) (or the site have had a tempt	rary or permanent ce	ssation of grading,	earthwork, or give	ound distarbance in	ne last 14 days:		
Grading began on the entire site (12/20/17)							
						T		
(
		ng earthwork or are	und disturbance se	heduled in the n	ext 14 days?			
Which portion(s) (i.e. drainage basins) of	of the site do not have grad	ng, earthwork, or gro	ound disturbance so	cheduled in the n	ext 14 days? :			
	of the site do not have grad	ing, earthwork, or gro	ound disturbance so	cheduled in the n	ext 14 days? :			
Which portion(s) (i.e. drainage basins) of	of the site do not have grad	ng, earthwork, or gro	ound disturbance so	cheduled in the n	ext 14 days? :			
Which portion(s) (i.e. drainage basins) of	of the site do not have grad			cheduled in the n	ext 14 days? :			

SUMMARY QUESTIONS:
Are approved entrances and adjacent streets being maintained adequately?
Yes
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?
Yes
CHECKLIST QUESTIONS:
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?
Yes
Is dust associated with the construction activity adequately controlled on the site?
Yes

Comments:

Comments:

Grading began on the site prior to the inspection on 12/20/17. The site is now active.

An existing outlet was not identified on the SWPPP but is present on site. The inspector has recommended silt fence to filter the water before leaving the site to ensure silt does not not migrate to the adjacent waterway.

Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):

1) No maintenance is required in the BMP section.

No r to the inspection							
r to the inspection							
r to the inspection							
No							
-ti 10/00/47							
ction on 12/20/17.							
No							
Silt Fence South of A1 12/20/2017 Pending No Pending - The silt fence is currently not necessary. The inspector will continue to monitor.							
No							
ction on 12/20/17.							
No							
Silt Fence Southern Perimeter 12/20/2017 Active No Good Condition - McCarthy Building Companies installed the silt fence prior to the inspection on 12/20/17.							
No No							
Good Condition - McCarthy Building Companies installed the silt fence prior to the inspection on 12/20/17.							
No							
Silt Fence South East side of site 12/20/2017 Active No Good Condition - McCarthy Building Companies installed the silt fence prior to the inspection on 12/20/17.							
Yes							
The silt fence needs installed around the existing outlet.							
McCarthy Building Companies was informed to complete by 12/27/17. Not done so of the last inspection							
McCarthy Building Companies was informed to complete by 12/27/17. Not done as of the last inspection.							
No							
Good Condition- No major signs of track off.							
No							

Current Condition:	Good Condition - The i	inspector installed the sign during the 1/3/18 inspection.				
Inspector Signature:	e auleed		Reviewed By:	Coto Sul		