E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599

www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A - P202	0.235.001			
nspector: Joe Manning					Stage	
Project Name:	Те	2				
For Week Ending:		CSW-202004897 10/23/2021				
Project Location:	112 N 13th Street - Tekamah, NE (Burt County)					
		1			_	
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	95%					
Utilities:	100%					
Overall Development:	98%					
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Time		
Numerica de la constantina della constantina del	0.00"				Wee	
Sunday:						
Monday	0.00"					
Tuesday	0.00"					
Vednesday	0.39"					
Thursday	0.00"	10/14/2021	Sunny 65/39	10:45 AM		
Friday	0.00"					
Saturday	0.00"					
					Wee	
Sunday:	0.00"					
Monday	0.00"					
Гuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
•	0.00"				+	
Saturday	0.00				Wee	
Sunday:	N/A					
Monday	N/A					
Гuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
Jaturuay	IN/A	I .	<u> </u>	<u> </u>		
Complaints:						
Construction Sequencing:						

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Major grading complete (12/08/20). Storm sewer work began (12/08/20). Minor grading to be completed at a later date (3/08/21). Fine grading throughout site (8/31/21).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Major grading complete (12/08/20). Storm sewer work began (12/08/20). Minor grading to be completed at a later date (3/08/21). Fine grading throughout site (8/31/21).

What temporary or permanent stabilization measures listed in this section are being implemented?

Minor existing perimeter vegetation (12/08/20). Seeding/matting in the southern half of the site, landscaping in parking lot medians (9/30/21). Sod throughout the site (10/14/2021)

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Create Corrective Action?

No - See Findings Section.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

No - See BMP Section (FT and PT)

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

No - See BMP Section (Str).

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

Comments:

Comments:

The site was active during the most recent inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) The site should be stabilized or straw wattles should be installed along the curb lines throughout the site. Hausmann Construction was informed to complete by 9/20/21. Hausmann Construction seeded and matted the site south of 'M' Street prior to the inspection on 9/30/21. Hausmann Construction sodded the majority of the site prior to the inspection on 10/14/21.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 01	Construction Entrance	K13		Removed		
Current Condition:	Removed - Hausmann paved the construction entrance prior to the inspection on 1/11/21.					
CE 02	Construction Entrance	M8		Removed		
Current Condition:	Removed - Hausmann Construction paved the construction entrance prior to the inspection on 7/30/21.					
CE 03	Construction Entrance	H10		Removed		
Current Condition:	Removed - Hausmann C	onstruction paved the	construction entrance pri	or to the inspection on 6/26/	21.	
CE 04	Construction Entrance	H10		Removed		
Current Condition:	Removed - Hausmann C	onstruction fully pave	d M Street prior to the ins	pection on 2/09/21.		
CE 05	Construction Entrance	N4		Removed		
Current Condition:	Removed - Hausmann C	onstruction paved the	e construction entrance pri	or to the inspection on 7/30/	21.	
CE 06	Construction Entrance	R13		Removed		
Current Condition:	Removed - Hausmann Construction paved the area near the construction entrance prior to the inspection on 8/13/21.					
FT	Fuel Tank	On Site	12/8/2020	Active	Yes	
	Fair Condition - Hausmann Construction placed a double-walled fuel tank on site prior to the first inspection on 12/08/20. E&A inspector will monitor and recommend additional containment as needed. Hausmann Construction placed one of the diesel tanks in secondary containment and cleaned up spills from the site prior to the inspection on 6/09/21. Secondary containment should be installed around the diesel tank on the western side of the site (at least 110% capacity of the tank). Hausmann Construction was informed to complete by 1/04/21. Not done as of the last inspection. Hausmann Construction was reminded on-site on 1/11/21, 3/09/21, 4/10/21, 4/20/21 (on-site), 5/21/21, 6/10/21, 6/26/21, 8/03/21, 8/13/21, 9/13/21					
IF 01	Inlet Protection	S14	12/8/2020	Active	Yes	

Current Condition:	Fair Condition - Existing curb inlet along Highway 75. Hausmann Construction installed inlet protection prior to the inspection on 4/7/21. E&A inspector repositioned the inlet protection during the inspection on 5/19/21.				
	The inlet protection should be cleaned off.				
	Hausmann Construction was informed to complete by 7/03/21. Not done as of the last inspection. Hausmann Construction was reminded on 8/03/21, 8/13/21, 9/13/21				
IF 02	Inlet Protection	H13	12/8/2020	Active	No
Current Condition:				hway 75 prior to the first ins	
				spection on 1/11/21. Hausn	
			•	/15/21. Hausmann Construc	
	the inlet protection prior		•		
IF 03	Inlet Protection	H12		Removed	
Current Condition:			rotection will no longer b	e recommended as of the	10/14/21
Guirent Gonation.	inspection.	stabilization, infet pr	otection will no longer b	or the	10/14/21
IF 04	Inlet Protection	K11	12/17/2020	Active	No
Current Condition:				the first inspection on 12/08	
Guirent Gondition.				. Hausmann Construction re	
				Hausmann Construction rein	
				paired the inlet protection pr	
	inspection on 5/19/21.	spection on 2/09/21.1	lausilianiii Constituction rep	Janea the inlet protection pr	ioi to tile
	mapoolion on or larz I.				
IF 05	Inlet Protection	J11	12/17/2020	Active	No
Current Condition:	Good Condition - Hausm	ann Construction inst	alled the curb inlet prior to	the first inspection on 12/08	3/20. Hausmann
				. Hausmann Construction re	
	protection due to paving	in the area prior to the	e inspection on 12/28/20. H	Hausmann Construction rep	laced the inlet
	protection prior to the ins	spection on 1/11/21. F	lausmann Construction cle	eaned out the inlet protection	n prior to the
	inspection on 5/27/21.				
IF 06	Inlet Protection	H10		Removed	
Current Condition:	Removed - Due to site	stabilization, inlet pr	otection will no longer b	e recommended as of the	10/14/21
	inspection.		ı		
IF 07	Inlet Protection	R8		Removed	
Current Condition:			the area around the inle	et and removed the inlet pr	rotection prior
	to the inspection on 10			· · · · · · · · · · · · · · · · · · ·	
IF 08	Inlet Protection	R7		Domovad	I
				Removed	retection major
Current Condition:	to the inspection on 10		the area around the inie	et and removed the inlet pr	rotection prior
IF 09	'	P7		Domested	
Current Condition:	Inlet Protection		rotoction will no longer b	Removed e recommended as of the	10/14/21
Current Condition.	inspection.	stabilization, illiet pr	otection will no longer be	e recommended as of the	10/14/21
17.10	<u> </u>		10101000		
IF 10	Inlet Protection	M2	12/8/2020	Active	No
Current Condition:				to the first inspection on 12/	
	1	•	•	n prior to the inspection on 5	
	Hausmann Construction	cleaned out and repo	sitioned the inlet protection	n prior to the inspection on 9	9/27/21.
IF 11	Inlet Protection	N2	12/8/2020	Active	No
Current Condition:	Good Condition - Hausm	ann Construction inst	alled inlet protection prior	to the first inspection on 12/	
				n prior to the inspection on 5	
	Hausmann Construction	cleaned out and repo	sitioned the inlet protection	n prior to the inspection on 9	9/27/21.
MS 01	Material Storage	On Site	12/8/2020	Pending	No
Current Condition:	Pending - The material s				<u> </u>
	Sanitary Waste				
PB	Management	On Site	12/8/2020	Active	Yes
Current Condition:				ble toilets on site prior to the	
				portable toilets prior to the	
				e job trailer prior to the inspe	
				orior to the inspection on 8/2	6/21. Hausmann
	Construction secured on	e of five portable toile	ets on site prior to the inspe	ection on 9/27/21.	
	AU				
	All portable toilets on site	should be resecured			
	Hausmann Caratrustica	was informed to some	ploto by 4/46/24. Not do	as of the last increation 11	ou cmars
				as of the last inspection. Ha	
	Construction was remind	leu 011 4/20/21 (0n-site	5), 3/21/21, 6/10/21, 6/26/2	21, 8/03/21, 8/13/21, 9/13/21	
OF 04	C:# T-::	C40 D44	1	D'	I
SF 01	Silt Fence	S12 - R14	the gilt force and fire	Removed	L cotion ar
Current Condition:		onstruction removed	trie slit tence and fine grad	ded the area prior to the insp	bection on
	8/31/21.				
SF 02	Silt Fence	R14 - K14	12/8/2020	Pending	No
	Illandina Duatananina				
Current Condition:	inspector will monitor.	and the grade in the	area, silt fence will not be r	recommended at this time. T	Γhe E&A

SF 03	Silt Fence	J13 - H14	12/8/2020	Pending	No	
Current Condition:	Pending - Due to paving inspector will monitor.	and the grade in the	area, silt fence will not be	e recommended at this time.	The E&A	
SF 04	Silt Fence	M2 - F13		Removed		
Current Condition:	Removed - Hausmann Construction removed the western check prior to the inspection on 9/27/21. Hausmann Construction seeded and matted the area prior to the inspection on 9/30/21.					
SF 05	Silt Fence	K6 - J10	12/8/2020	Pending	No	
Current Condition:	Pending - Due to paving and the grade in the area, silt fence will not be recommended at this time. The E&A inspector will monitor.					
SF 06	Silt Fence	L8 - J13	12/8/2020	Pending	No	
Current Condition:	Pending - Due to paving and the grade in the area, silt fence will not be recommended at this time. The E&A inspector will monitor.					
STR	Streets	On Site	12/8/2020 ned the streets prior to the	Active	Yes	
CW/DDD Civi	Construction was remine	ded on 6/10/21, 6/26/2	21, 7/30/21 (on-site), 8/03			
SWPPP Sign Current Condition:	SWPPP Signs	South of Building	12/17/2020	Pending	Yes	
	Pending- The E&A inspector installed the SWPPP sign during the inspection on 12/17/20. Hausmann Construction moved the SWPPP sign prior to the inspection on 2/09/21. Hausmann Construction reinstalled the SWPPP sign prior to the inspection on 2/22/21. Hausmann Construction removed the site fence the SWPPP sign was secured on prior to the inspection on 7/30/21. The SWPPP sign should be reinstalled. Hausmann Construction was informed to complete by 8/06/21 (on-site). Not done as of the last inspection. Hausmann Construction was reminded on 8/03/21, 8/13/21, 9/13/21					
WO 01	Concrete Washout	On Site		Removed		
Current Condition:	Removed - Hausmann Construction removed all concrete waste and the washout from the site prior to the inspection on 9/27/21.					
WS 01	Waste Storage Area	On Site	12/8/2020	Pending	No	
Current Condition:	Pending - The waste sto	rage area will be insta	alled as necessary.			
Inspector Signature:	Je lin		Reviewed By:	Get Su		