E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager

**Engineering Answers** 

		E&A- P2005.03	0.000		Stage	
Inspector: Sam Fletcher						
		Th	e Heritage		3	
Project Name:			ER110495			
For Week Ending:	Fact of 4ECth C	8/13/2016				
Draiget Legation	East of 156th St	East of 156th Street and North and South of Rainwood Road- Bennington, NE				
Project Location:	(Douglas County)					
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%	, D				
Seeding:	100%					
Utilities:	100%					
Overall Development:	40%	D				
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions			
					Week	
Sunday:	0.00"					
Monday	1.65"	07/10/16	0.1/0.1			
Tuesday	0.01"	07/12/16	84/64 sunny			
Wednesday	0.17"					
Thursday Friday	0.00" 0.04"					
Saturday	0.00"					
Saturday	0.00				Week	
Sunday:	0.01"				Week	
Monday	0.73"	07/18/16	83/68 cloudy			
Tuesday	0.32"	01710710				
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
		-			Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
		·			Week	
Sunday:	0.03"					
Monday	0.00"					
Tuesday	0.26"					
Wednesday	0.00"					
Thursday	0.03"					
Friday	0.00"					
Saturday	0.00"					
Oran data	0.00"				Week	
Sunday:	0.00"					
Monday Tuesday	0.00"					
Wednesday	0.00 <sup>*</sup>					
Thursday	0.22"					
Friday	0.08"					
	0.04"	1		1		

	None					
Complaints:						
			-			
Construction Sequencing:	have bed a tanaa aaaa		and the second second second	and distant second in the last	44.4	
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?						
Entire site, grading completed 7/2006 and	site seeded 9/5/06.		1	1		
$\mathbf{W}$ (high position (a) (i.e. drain and heating) of the side	de net heve medine les		ence echeduled in the ne	ut 11 days 2 :		
Which portion(s) (i.e. drainage basins) of the site Entire site, grading completed 7/2006 and		arthwork, or ground disturt	bance scheduled in the he	xt 14 days? :		
Entire site, grading completed 1/2000 and						
What temporary or permanent stabilization meas	ures listed in this sectio	n are being implemented?				
Wetlands Mitigation Seeding (5/31/06), Slopes Seeded/Matted (8/30/06), Temp. Seeded (9/5/06), Re-Seeded 5/21/07, Re-Seeded ROW on 9/5/07 & 11/14/07, Erosion seeded in various areas (4/09), Old Basin 5 was seeded and matted (5/2/12)						
SUMMARY QUESTIONS:						
Are approved entrances and adjacent streets bei	ng maintained adequate	ly?				
Yes						
Are receiving waters adjacent to the project free	of any significant signs	of erosion or sediment that	would be associated with	the construction activity?		
Yes						
CHECKLIST QUESTIONS:						
Are waste materials (concrete, construction materials) Yes	erial, hazardous, etc.) be	ing managed properly?				
Is dust associated with the construction activity	adoquately controlled or	a tha sita?				
Yes	adequately controlled of	T the Site :				
Comments:	1		L			
Comments:						
Multiple houses are being built in the deve	lopment.					
Findings / Corrective Actions (Date):						
Tindings / Corrective Actions (Date).						
<ol> <li>The old inlet filter in front of lot 2 needs to be cleaned up. Regency Homes was informed to complete by 8/26/15. Not done as of last inspection. Regency Homes was reminded on 2/23/16, 3/30/16, 5/5/16, 7/8/16.</li> <li>Lots 149 and lot 147 needs to be stabilized due to construction on lot 148. The Home Company was informed to complete by 3/8/16. Not done as of last inspection. The Home Company was reminded on 3/30/16, 5/5/16, 7/8/16.</li> <li>Concrete debris on lot 159 needs to be cleaned up. The inspector is attempting to determine who is responsible for the debris as of the 3/29/16 inspection. The inspector will update.</li> <li>Lot 142 needs to be stabilized due to construction on lot 141. G. Lee Homes was informed to complete by 7/18/16. Not done as of last inspection.</li> <li>Lot 142 needs to be stabilized due to construction on lot 145. Sherwood Homes was informed to complete by 7/18/16. Not done as of last inspection.</li> </ol>						
inspection.						
			Projected Install			
Unique Name	Туре	Location	Date	Status	Maintenance	
CW 1	Concrete Washout	Lot 20		Removed		
Current Condition:	Removed - Boyer Ye	oung cleaned out and re	emoved the concrete v	vashout prior to the 9/2		
					6/15 inspection.	
CW 2			1		6/15 inspection.	
Current Condition:	Concrete Washout	Lot 162		Removed		
		Lot 162 oung cleaned out and re	emoved the concrete v			
Lot 2	Removed - Boyer Yo	oung cleaned out and re	emoved the concrete v	vashout prior to the 9/2		
Lot 2 Current Condition:	Removed - Boyer Yo Silt Fence	oung cleaned out and re		vashout prior to the 9/2 Removed		
Current Condition:	Removed - Boyer Yo Silt Fence Removed - Regenco	Lot 2 y Homes seeded the lot		vashout prior to the 9/2 Removed spection.		
	Removed - Boyer Yo Silt Fence Removed - Regenco Silt Fence	oung cleaned out and re	prior to the 7/16/15 in	vashout prior to the 9/2 Removed spection. Removed		
Current Condition: Lot 7 Replat 2 Current Condition:	Removed - Boyer Yo Silt Fence Removed - Regency Silt Fence Removed - John Sh	Lot 2 Lot 2 Homes seeded the lot Lot 7 Replat 2 elburne sodded the lot	prior to the 7/16/15 in:	vashout prior to the 9/2 Removed spection. Removed pection.	6/15 inspection.	
Current Condition: Lot 7 Replat 2 Current Condition: Lot 39	Removed - Boyer Yo Silt Fence Removed - Regency Silt Fence Removed - John Sh Individual Lot	Lot 2 Lot 2 Y Homes seeded the lot Lot 7 Replat 2 elburne sodded the lot Lot 39	prior to the 7/16/15 in: prior to the 6/23/16 ins 6/23/2016	vashout prior to the 9/2 Removed spection. Removed pection. Active	6/15 inspection. Yes	
Current Condition: Lot 7 Replat 2 Current Condition:	Removed - Boyer Yo Silt Fence Removed - Regency Silt Fence Removed - John Sh Individual Lot	Lot 2 y Homes seeded the lot Lot 7 Replat 2 elburne sodded the lot Lot 39 Company is building on	prior to the 7/16/15 in: prior to the 6/23/16 ins 6/23/2016	vashout prior to the 9/2 Removed spection. Removed pection. Active	6/15 inspection. Yes	
Current Condition: Lot 7 Replat 2 Current Condition: Lot 39 Current Condition: Lot 51	Removed - Boyer Yo Silt Fence Removed - Regenco Silt Fence Removed - John Sh Individual Lot Active - The Home O needed. The inspec Individual Lot	Lot 2 y Homes seeded the lot Lot 7 Replat 2 elburne sodded the lot Lot 39 Company is building on ctor will monitor.	prior to the 7/16/15 in: prior to the 6/23/16 ins 6/23/2016 the lot as of the 6/23/1	Removed spection. Removed pection. Active 6 inspection. The lot is Removed	6/15 inspection. Yes	
Current Condition: Lot 7 Replat 2 Current Condition: Lot 39 Current Condition:	Removed - Boyer Yo Silt Fence Removed - Regenco Silt Fence Removed - John Sh Individual Lot Active - The Home O needed. The inspec Individual Lot	Lot 2 y Homes seeded the lot Lot 7 Replat 2 elburne sodded the lot Lot 39 Company is building on ctor will monitor.	prior to the 7/16/15 in: prior to the 6/23/16 ins 6/23/2016 the lot as of the 6/23/1	Removed spection. Removed pection. Active 6 inspection. The lot is Removed	6/15 inspection. Yes	
Current Condition: Lot 7 Replat 2 Current Condition: Lot 39 Current Condition: Lot 51 Current Condition:	Removed - Boyer Yo Silt Fence Removed - Regency Silt Fence Removed - John Sh Individual Lot Active - The Home Oneeded. The Inspece Individual Lot Removed - The Hor	Lot 2 y Homes seeded the lot Lot 7 Replat 2 elburne sodded the lot Lot 39 Company is building on ctor will monitor. Lot 51 ne Company sodded th	prior to the 7/16/15 in: prior to the 6/23/16 ins 6/23/2016 the lot as of the 6/23/1	Removed spection. Removed pection. Active 6 inspection. The lot is Removed 6 inspection.	6/15 inspection. Yes	
Current Condition: Lot 7 Replat 2 Current Condition: Lot 39 Current Condition: Lot 51	Removed - Boyer Yo Silt Fence Removed - Regenc Silt Fence Removed - John Sh Individual Lot Active - The Home O needed. The inspec Individual Lot Removed - The Hor Silt Fence	Lot 2 y Homes seeded the lot Lot 7 Replat 2 elburne sodded the lot Lot 39 Company is building on ctor will monitor.	prior to the 7/16/15 in: prior to the 6/23/16 ins 6/23/2016 the lot as of the 6/23/1 e lot prior to the 4/21/1	Removed spection. Removed pection. Active 6 inspection. The lot is Removed 6 inspection.	6/15 inspection. Yes	

		1.110	T		1		
Lot 113 Current Condition:	Individual Lot	Lot 113	lot prior to the 7/1/16 in	Removed			
Current Condition.	Removed - Sherwood Homes sodded the lot prior to the 7/4/16 inspection.						
Lot 114	Silt Fence	Lot 114	10/24/2015	Active	No		
Current Condition:		Good Condition - Sherwood Homes installed silt fence on lot 114 to protect adjacent lots prior to the					
	3/29/16 inspection.						
Lot 122	Wattle	Lot 122	11/19/2015	Active	No		
Current Condition:	Good Condition - Regency Homes installed gator guards on the back of the lot to protect the sod on lot 123 prior to the 11/19/15 inspection.						
Lot 124	Silt Fence	Lot 124	3/29/2016	Active	Yes		
Current Condition:	Fair Condition						
	The silt fence on th	e back of the lot needs	to be cleaned out.				
	Regency Homes was informed to complete by 5/31/16. Not done as of last inspection. Regency Home was reminded on 7/8/16.						
Lot 126	Silt Fence	Lot 126	12/17/2014	Active	Yes		
Current Condition:	Fair Condition						
	The silt fence on the back of the lot needs to be cleaned out. Regency Homes was informed to complete by 8/26/15. Not done as of last inspection. Regency Home was reminded on 9/1/15, 9/28/15, 2/23/16, 3/30/16, 5/5/16, 5/25/16, 7/8/16.						
Lot 127	Silt Fence	Lot 127		Removed			
Current Condition:		y Homes sodded the lo	t prior to the 12/16/15		1		
Lot 128	Silt Fence	Lot 128		Removed			
Current Condition:	Removed - Regend	cy Homes sodded the lo	ot prior to the 7/16/15 in	ispection.			
Lot 129	Silt Fence	Lot 129		Removed			
Current Condition:	Removed - Regend	Removed - Regency Homes sodded the lot prior to the 11/13/15 inspection.					
	0.11. 5						
Lot 1 Replat 2 Current Condition:	Silt Fence	Lot 1 Replat 2 was sodded prior to the	11/21/14 inspection	Removed			
Current Condition.	Itemoved - The lot	was source prior to the	= 1/21/14 inspection.				
Lot 135	Silt Fence	Lot 135		Removed			
Current Condition:	Removed - Sherwo	od Homes sodded the	lot prior to the 11/13/15	5 inspection.	•		
Lot 136	Silt Fence	Lot 136		Removed			
Current Condition:		d Homes sodded the lo t of construction on lot 1		inspection. The remain nspection.	ing silt fence w		
Lot 137	Silt Fence	Lot 137		Removed			
Current Condition:	Removed - Legacy	Homes sodded the lot	prior to the 5/6/15 insp	ection.			
Lot 138	Silt Fence	Lot 138	6/30/2016	Pending	Yes		
Current Condition:	Pending						
	Silt fence needs to be installed on the side and front of the lot.						
	Legacy Homes was informed to complete by 6/30/16. Not done as of last inspection. Legacy Homes was reminded on 7/8/16.						
Lot 139	Silt Fence	Lot 139		Removed			
Current Condition:	Removed - Sherwo	od Homes sodded the	lot prior to the 8/19/15	inspection.			
Lot 140	Silt Fence	Lot 140		Removed			
Current Condition:	Removed - Sherwo	od Homes sodded the	lot prior to the 6/12/15	inspection.			
Lot 141	Silt Fence	Lot 141	11/13/2015	Active	Yes		
	•	•		•			

Current Condition:	Fair Condition - She	Fair Condition - Sherwood Homes cleaned out the silt fence prior to the 5/24/16 inspection.					
	The silt fence on the side of the lot needs to be cleaned out and repaired.						
	Sherwood Homes was informed to complete by 5/31/16. Not done as of last inspection. She Homes was reminded on 7/8/16.						
Lot 143	Silt Fence	Lot 143		Removed			
Current Condition:		lomes sodded the lot pr	ior to the 6/23/16 inspe				
		1	1				
Lot 145	Silt Fence	Lot 145		Removed			
Current Condition:	Removed - Sherwood Homes sodded the lot prior to the 6/23/16 inspection.						
	0111 5			- ·			
Lot 144 Current Condition:	Silt Fence	Lot 144 Homes sodded the lot	prior to the 7/16/15 inc	Removed			
Current Condition.	Removed - Dynasty			pection.			
Lot 146	Silt Fence	Lot 146	7/18/2016	Active	No		
Current Condition:	Good Condition - Cł	harleston Homes installe	ed silt fence on the sid	e and front of the lot	prior to the 7/18/16		
	inspection.						
Lot 147	Individual Lot	Lot 147		Removed			
Current Condition:	Removed - The Hor	me Company sodded th	e lot prior to the 12/16/	15 inspection.			
Lot 148	Silt Fence	Lot 148		Removed			
Current Condition:	Removed - The Hor	ne Company sodded th	e lot prior to the 7/16/1	5 inspection.	I		
	011 5	1.454					
Lot 151 Current Condition:	Silt Fence	Lot 151 od Homes sodded the lo	t prior to the 8/19/15 i	Removed			
				-			
Lot 152 Current Condition:	Silt Fence	Lot 152 Homes sodded the lot	prior to the 6/12/15 ins	Removed			
Current Condition.	Kelhoved - Freihier						
Lot 153	Individual Lot	Lot 153		Removed			
Current Condition:		was sodded prior to the	12/17/14 inspection.				
Lot 154 Current Condition:	Wattle	Lot 154 y Homes sodded the lot	prior to the 7/16/15 in	Removed			
				•			
Lot 155 Current Condition:	Silt Fence	Lot 155 Interprise sodded the lot	t prior to the 11/13/15 i	Removed			
Lot 162	Individual Lot	Lot 162		Removed			
Current Condition:		Removed - Legacy Homes sodded the lot prior to the 12/16/15 inspection. Legacy Homes Removed t					
		ebris prior to the 2/23/1	6 inspection.				
Lot 164	Individual Lot	Lot 164	a lat prior to the 0/26/1	Removed			
Current Condition: Lot 165	Silt Fence	me Company sodded th Lot 165		Removed			
Current Condition:		ne Company sodded th	e lot prior to the 7/16/1	5 inspection.	•		
Lot 166	Silt Fence	Lot 166		Removed			
Current Condition: Lot 167	Silt Fence	Homes sodded the lot p Lot 167	prior to the 7/4/16 inspe	Removed			
Current Condition:		od Homes sodded the lo	ot prior to the 4/21/16 i				
Lot 168	Silt Fence	Lot 168		Removed			
Current Condition:	- · ·	Homes sodded the lot p	prior to the 6/2/14 inspe				
Lot 170 Current Condition:	Individual Lot	Lot 170 ton Homes sodded the	at prior to the 10/17/1	Removed			
				-	-		
Lot 181 Current Condition:	Individual Lot Removed - Dreams	Lot 181 cape sodded the lot prid	to the 7/16/15 inspec	Removed			
Lot 182	Silt Fence	Lot 182		Removed			
Current Condition:	Removed - Change			Derrorial			
Lot 183 Current Condition:	Silt Fence Removed - Sherwoo	Lot 183 od Homes sodded the lo	t prior to the 4/29/16 i	Removed			
Lot 184	Silt Fence	Lot 184		Removed			
Current Condition:		od Homes sodded the lo	ot prior to the 11/13/15				
Lot 195 Current Condition:	Silt Fence	Lot 195	r to the 6/4/14 increases	Removed			
Current Condition:	Prodition: Removed - The silt fence was removed prior to the 6/4/14 inspection.						
		South of Wild Indigo					
SB 3	Sediment Basin	St and Prairie Star St.	11/14/2005	Active	No		

Current Condition:	Good Condition- 20% Filled					
	Cleanout 9/24/07 by Dave Hausman					
		South of 149th Dead				
SB 4	Sediment Basin	End	11/14/2005	Active	No	
Current Condition:	Good Condition- 35% Filled - Roth Enterprise cleaned off the risers prior to the 7/7/16 inspection.					
		Southwest corner of				
		Rosewater Pkwy and				
		North H.W.S				
SB 5	Sediment Basin	Cleveland Blvd	11/2/2005	Active	No	
Current Condition:	Good Condition-26% Filled					
	Outlet Pipe recompacted by Sudbeck due to undermining- 4/2006					
STR	Street Cleaning	Entire Site	2/26/2007	Active	No	
Current Condition:	Good Condition - No major track out. The Home Company cleaned the street in front of lot 149 prior to the 6/23/16 inspection.					
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No	
Current Condition:	Good Condition: 156th and Cleveland Blvd					
Inspector Signature: Reviewed By:				1)		