E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager

Engineering Answers

Erosion Control Specialist- Man	ager			angineering missi	
		E&A- P2005.030	0.000		
Inspector: Nick Jenkins		Stage			
•	The Heritage				
Project Name:		NE	R110495		
For Week Ending:		3	/11/2017		
. c. rroom <u></u>	East of 156th S		d South of Rainwood Ro	ad- Bennington, NE	68007
Project Location:	2401 01 100111 0		uglas County)	aa Bonnington, 112	00007
1 Tojou Zoodiom	L	(50.	agiao oounty,	<u> </u>	
Grading:	1009	6			
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	1009		- 		
Seeding:	1009				
Utilities:	1009				
Overall Development:	40%		+		
Overall Development.	407	⁷⁰			
<u> </u>		1			
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions		
					Week 1
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
,					Week 2
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.33"				
Friday	0.01"				
Saturday	0.00"				
outui uuy	0.00		<u> </u>		Week
Sunday:	0.00"		1		WCCK
Monday	0.00"				
Tuesday	0.02"				
Wednesday	0.02"				
Thursday	0.00"	03/02/17	Sunny 42/22	+	
Friday	0.00"	33/0Z/17	Outilly 72/22		
Saturday	0.00"			+	
	10.00				Week 4
Sunday:	0.00"				- Week 4
Monday	0.22"	+			
Tuesday	0.00"	1			
Wednesday	0.00"	+			
Thursday	0.00"	+			
Friday	0.00"	3/10/2017			
Saturday	0.00"	3/10/2017			
Jaturuay	Jυ.υυ				Week 5
Cundou	N/A				- week :
Sunday:	N/A	+			
Monday	N/A	1			
Tuesday	N/A				
Wednesday	N/A				
Thursday	N/A				
Friday	N/A				
Saturday	N/A				

	None							
Complaints:								
	1							
Construction Sequencing:		•	•	•				
Which portion(s) (i.e. drainage basins) of the site	have had a temporary of	or permanent cessation of g	rading, earthwork, or grou	und disturbance in the last	14 days?			
Entire site, grading completed 7/2006 and	site seeded 9/5/06.							
Which portion(s) (i.e. drainage basins) of the site	do not have grading, ea	arthwork, or ground disturb	ance scheduled in the nex	t 14 days? :				
Entire site, grading completed 7/2006 and	site seeded 9/5/06.							
What temporary or permanent stabilization meas	ures listed in this section	n are being implemented?	•	•	•			

Wetlands Mitigation Seeding (5/31/06), Slopes Seeded/Matted (8/30/06), Temp. Seeded (9/5/06), Re-Seeded 5/21/07, Re-Seeded ROW on 9/5/07 & 11/14/07, Erosion seeded in various areas (4/09), Old Basin 5 was seeded and matted (5/2/12). The areas that were disturbed when SB 3 and 5 were closed has been seeded (9/10/16/).

SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

Yes

Yes

CHECKLIST QUESTIONS:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No, See Findings Section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Multiple houses are being built in the development.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) See BMP section for required maintenance.
- 2) Concrete debris on lot 159 needs to be cleaned up. The inspector is attempting to determine who is responsible for the debris as of the 3/29/16 inspection. The inspector will update.
- 3) Silt fence behind lot 114 needs to be removed. Sherwood Homes was informed to complete by 1/4/17. Not done as of the last inspection.

Sherwood was reminded on 3/3/2017.

			Projected Install			
Unique Name	Type	Location	Date	Status	Maintenance	
CW 1	Concrete Washout	Lot 20		Removed		
Current Condition:	Removed - Boyer Y	oung cleaned out and r	emoved the concrete	washout prior to the 9/	26/15 inspection.	
CW 2	Concrete Washout	Lot 162		Removed		
Current Condition:	Removed - Boyer Young cleaned out and removed the concrete washout prior to the 9/26/15 inspection.					
		Rosewater Prky and				
IF 1	Inlet Filter	Chicory St.	8/24/2016	Active	Yes	
	Fair Condition - The inspector attempted to remove the inlet filter but it is frozen to the ground as of the 12/27/16 inspection. The inlet filter needs to be removed due to work on the basin being complete. The inspector will remove the inlet filter during the next inspection. Not done as of the last inspection					
Lot 2	Silt Fence	Lot 2		Removed		
	Removed - Regency Homes seeded the lot prior to the 7/16/15 inspection.					
Current Condition:	Removed - Regenc	y Homes seeded the lo	t prior to the 7/16/15 ir	ispection.		

Current Condition:	Pending- Silt fence is needed on the front of the lot and the inlet filter needs to be removed in the circle. MJ Design was informed to complete by 1/4/17. Not done as of the last inspection. MJ Design were reminded on 3/3/2017.					
Lot 2 Replat 2	Silt Fence	Lot 2 Replat 2	12/27/2016	Active	No	
Current Condition:	Good Condition - Le inspection.	egacy Homes installed	silt fence on the back	of the lot prior to the	12/27/16	
Lot 7 Replat 2	Silt Fence	Lot 7 Replat 2		Removed	T	
Current Condition:	Removed - John Sh	elburne sodded the lot	prior to the 6/23/16 in	spection.	-	
Lot 40	Individual Lot	Lot 40	6/23/2016	Active	Yes	
Current Condition:		Company is building or pector will monitor. Ch			ot is flat so no bmp	
Lot 48	Individual Lot	Lot 48		Removed		
Current Condition:	Removed - Charles	ton Homes sodded the	lot prior to the 10/21/1	6 inspection.	•	
Lot 51	Individual Lot	Lot 51		Removed		
Current Condition:		ne Company sodded th	ne lot prior to the 4/21/			
Lot 67	Silt Fence	Lot 67		Removed		
Current Condition: Lot 112	Silt Fence	od Homes sodded the Lot 112	ot prior to the 7/4/16 in 9/17/2016	Active	Yes	
Current Condition:						
	Fair Condition - Silt fence was installed on the front and back of the lot prior to the 9/17/16 inspection. The builder is unknown. 1.) The silt fence needs to be repaired on the front of the lot. 2.) The silt fence in the rear needs to be repaired.					
	1.) Legacy Homes was informed to complete by 10/4/16. Not done as of last inspection. Legacy Homes was reminded on 11/2/16, 11/27/2016, 1/5/17, 3/3/2017. 2.) Legacy Homes was informed to complete by 11/30/2016. Not done as of last inspection. Legacy					
	Homes was reminde	ed on 1/5/17, 3/3/2017.				
Lot 113	Individual Lot	Lot 113		Removed		
Current Condition:		od Homes sodded the I	ot prior to the 7/4/16 ir			
Lot 114 Current Condition:	Silt Fence	Lot 114 d Homes sodded the lo	t prior to 11/22/2016	Removed		
Lot 122	Wattle	Lot 122	1/4/2017	Pending	Yes	
Current Condition:	Pending	1011111	., .,	· onanig		
	Silt fence needs to be installed on the back of the lot. Charleston Homes was informed to complete by 1/4/17. Not done as of the last inspection. Charlesto Homes was reminded on 3/3/2017.					
Lot 124 Current Condition:	Silt Fence	Lot 124 er Homes sodded the le	t prior to 11/23/2016	Removed		
Lot 126	Silt Fence	Lot 126	1 1/20/2010.	Removed		
Current Condition:	Removed-Regency	Homes sodded the lot	prior to 11/23/2016.		1	
Lot 127 Current Condition:	Silt Fence	Lot 127 y Homes sodded the lo	t prior to the 12/16/15	Removed	1	
Lot 128	Silt Fence	Lot 128	. prior to tric 12/10/13	Removed	1	
Current Condition:		y Homes sodded the lo	t prior to the 7/16/15 in		1	
Lot 129	Silt Fence	Lot 129		Removed		
Current Condition:		y Homes sodded the lo	t prior to the 11/13/15	inspection.	1	
Lot 1 Replat 2	Silt Fence	Lot 1 Replat 2	•	Removed		
Current Condition:	Removed - The lot	was sodded prior to the				
Lot 134	Silt Fence	Lot 134	1/27/2017	Active	No	
Current Condition:		evated prior to 3/2/2017 E&A will continue to mo	, , ,	oue to the lot being fla	it, no BMPs are	
Lot 135	Silt Fence	Lot 135		Removed		
Current Condition:		od Homes sodded the	ot prior to the 11/13/15			
Lot 136	Silt Fence	Lot 136		Removed		
Current Condition:		d Homes sodded the lo			aining silt fence	
1		part of construction on	lot 135 as of the 4/21/			
Lot 137	Silt Fence	Lot 137		Removed		
Current Condition:		Homes sodded the lot	prior to the 5/6/15 insp I		T	
Lot 138	Silt Fence	Lot 138 Homes sodded the lot	prior to the 10/21/16 in	Removed	1	
Current Condition:	rcemoved - Legacy	nomes souded the lot	prior to the 10/21/16 in	speciion.		

Lot 139	Silt Fence	Lot 139		Removed	
Current Condition:	Removed - Sherwo	od Homes sodded the	ot prior to the 8/19/15	inspection.	
Lot 140	Silt Fence	Lot 140		Removed	
Current Condition:	Removed - Sherwor	od Homes sodded the	ot prior to the 6/12/15	inspection.	
Lot 141	Silt Fence	Lot 141		Removed	
Current Condition:		od Homes sodded the	ot prior to the 8/24/16		
Lot 142	Silt Fence	Lot 142	8/31/2016	Active	No
				front prior to 3/2/2017.	
Current Condition:	Good Condition- Si	ierwood nomes repaire	a the silt lence on the	110111 p1101 to 3/2/2017.	
Lot 143	Silt Fence	Lot 143		Removed	
Current Condition:		lomes sodded the lot p	rior to the 6/23/16 inst	pection	
Lot 145	Silt Fence	Lot 145	1	Removed	
Current Condition:		od Homes sodded the	ot prior to the 6/22/16		
Lot 144	Silt Fence	Lot 144	T	Removed	
Current Condition:		Homes sodded the lot	prior to the 7/16/15 in		
Lot 146	Silt Fence	Lot 146		Removed	
Current Condition:		on Homes sodded the I	ot prior to 11/23/2016.		
Lot 147	Individual Lot	Lot 147		Removed	
Current Condition:	Removed - The Hor	me Company sodded tl	ne lot prior to the 12/16	6/15 inspection.	
Lot 148	Silt Fence	Lot 148		Removed	
Current Condition:	Removed - The Hor	me Company sodded tl	ne lot prior to the 7/16/	15 inspection.	
Lot 149	Silt Fence	Lot 149	1/27/2017	Active	Yes
Current Condition:	Fair Condition-				
	1) Now wattles are	needed along the curb	line and the DD needs	s to be staked down	
	2.) Portable tollet v	was added to the driv	eway. Tollet needs m	oved and staked dow	n.
	1.) Charleston Hom	es was informed to cor	nplete by 3/9/2017.		
	2.) Charleston Hon	nes was informed to o	complete by 3/17/17.		
Lot 151	Silt Fence	Lot 151		Removed	
Current Condition:		od Homes sodded the	ot prior to the 8/19/15		
Lot 152	Silt Fence	Lot 152	1	Removed	
			maion to the C/10/15 in		
Current Condition:		Homes sodded the lot	prior to the 6/12/13 in		
Lot 153	Individual Lot	Lot 153		Removed	
Current Condition:		was sodded prior to the	2 12/17/14 inspection.		
Lot 154	Wattle	Lot 154		Removed	
Current Condition:	Removed - Regenc	y Homes sodded the lo	t prior to the 7/16/15 in		
Lot 155	Silt Fence	Lot 155		Removed	
Current Condition:	Removed - Home E	nterprise sodded the lo	ot prior to the 11/13/15	inspection.	
Lot 162	Individual Lot	Lot 162		Removed	
Current Condition:	Removed - Legacy	Homes sodded the lot	prior to the 12/16/15 ir	nspection. Legacy Hon	nes Removed the
		lebris prior to the 2/23/		.opeo.com Logacyo	
Lot 164	Individual Lot	Lot 164	То птороскоти.	Removed	
			- 1-4		
Current Condition:		me Company sodded to	ie ioi prior to the 9/26/		
Lot 165	Silt Fence	Lot 165	1 1 1 1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Removed	
Current Condition:		me Company sodded tl	ne lot prior to the 7/16/		
Lot 166	Silt Fence	Lot 166	L	Removed	
Current Condition:		Homes sodded the lot	prior to the 7/4/16 insp		
Lot 167	Silt Fence	Lot 167		Removed	
Current Condition:	Removed - Sherwood	od Homes sodded the	ot prior to the 4/21/16		
Lot 168	Silt Fence	Lot 168		Removed	
Current Condition:	Removed - Legacy	Homes sodded the lot	prior to the 6/2/14 insp	pection.	
Lot 170	Individual Lot	Lot 170	<u>'</u>	Removed	
Lot 180	Silt Fence	Lot 180	3/10/2017	Active	No
Current Condition:				10/17. Silt fence was	
Current Condition:					
		by Pacesetter Homes	s. Note: Silt tence ma	y need extended arou	ind the stockpile
0 10 ""	near the road.	tan Hamas - 11 12	1-4 maio n 4- 11 - 4011-11	(4 !	
Current Condition:	Removed - Charles	ton Homes sodded the	iot prior to the 12/17/1	14 inspection.	
Lot 181	Individual Lot	Lot 181		Removed	
Current Condition:		cape sodded the lot pr	or to the 7/16/15 inspe		
	4			Removed	
101782	Silt Fence	(nt 182			
Lot 182	Silt Fence Removed - Change	Lot 182		rtemoved	
Current Condition:	Removed - Change	d to Lot 7 Replat 2.			
Current Condition: Lot 183	Removed - Change Silt Fence	d to Lot 7 Replat 2. Lot 183	let prior to the 4/20/40	Removed	
Current Condition: Lot 183 Current Condition:	Removed - Change Silt Fence Removed - Sherwoo	d to Lot 7 Replat 2. Lot 183 od Homes sodded the	ot prior to the 4/29/16	Removed inspection.	
Current Condition: Lot 183 Current Condition: Lot 184	Removed - Change Silt Fence Removed - Sherwood Silt Fence	d to Lot 7 Replat 2. Lot 183 od Homes sodded the Lot 184		Removed inspection.	
Current Condition: Lot 183 Current Condition: Lot 184 Current Condition:	Removed - Change Silt Fence Removed - Sherwoo Silt Fence Removed - Sherwoo	d to Lot 7 Replat 2. Lot 183 od Homes sodded the Lot 184 od Homes sodded the	ot prior to the 11/13/1	Removed inspection. Removed 5 inspection.	
Current Condition: Lot 183 Current Condition: Lot 184	Removed - Change Silt Fence Removed - Sherwood Silt Fence	d to Lot 7 Replat 2. Lot 183 od Homes sodded the Lot 184		Removed inspection.	Yes

Current Condition:	Fair Condition						
	The silt fence on the back of the lot needs to be repaired in several areas.						
	Sherwood Homes was informed to complete by 1/4/17. Not done as of the last inspection. Sherwood						
	was reminded on 3			· ·			
Lot 195	Silt Fence	Lot 195		Removed			
Current Condition:	Removed - The silt	fence was removed pri	or to the 6/4/14 inspec	tion.			
SF 6	Silt Fence	SB 5	8/24/2016	Active	No		
Current Condition:	Good Condition - T	he contractor that close	d SB 5 installed silt fer	nce prior to the 8/24/16	inspection.		
SF 7	Silt Fence	SB 3	9/27/2016	Active	No		
Current Condition:	Good Condition- Le	gacy Homes repaired the	ne silt fence prior to 3/	3/2017.			
SF 8	Silt Fence	Rainwood Road	11/23/2016	Active	No		
Current Condition:	Good Condition - B	oyer Young installed a s	silt fence check in fron	t of Rainwood Road pr	ior to		
	11/23/2016.			·			
		South of Wild Indigo					
SB 3	Sediment Basin	St and Prairie Star St.		Removed			
Current Condition:	Removed - The bas	Removed - The basin was closed prior to the 8/24/16 inspection.					
		South of 149th Dead	·				
SB 4	Sediment Basin	End	11/14/2005	Active	No		
Current Condition:	Good Condition- 35	Good Condition- 35% Filled - Roth Enterprise cleaned off the risers prior to the 7/7/16 inspection.					
		Southwest corner of					
		Rosewater Pkwy and					
		North H.W.S					
SB 5	Sediment Basin	Cleveland Blvd		Removed			
Current Condition:	Removed - The basin was closed prior to the 8/24/16 inspection.						
STR	Street Cleaning	Entire Site	2/26/2007	Active	No		
Current Condition:	Good Condition- St	reets were scraped in fr	ont of lot 149 by Char	leston Homes prior to	1/27/2017.		
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No		
Current Condition:	Good Condition: 156th and Clevelan	nd Blvd					
G.A.	Se			0 01			
Inspector Signature:			Reviewed By:	Brancen Stevens			
mopeotor orginature.		_	INCTIONED Dy.				