E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

**Engineering Answers** 

Erosion Control Specialist- Man		er Engineering Answers					
		E&A- P2005.030.	000				
Inspector: Aaron Tulley					Stage		
-		The	Heritage		2		
Project Name:			R110495				
For Week Ending:			12/2018				
FOI Week Eliding.	East of 156th St	reet and North and	South of Rainwood Ro	ad- Bennington, NE	68007		
Project Location:			glas County)	- '			
Grading:	100%						
Sanitary Sewer:	100%						
Storm Sewer:	100%						
Paving:	100%						
Seeding:	100%						
Utilities:	100%						
Overall Development:	50%						
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions				
NAINT ALL AMOUNTS	A WHOULK IN MONES	Date inspected	Weather Conditions		Week		
Sunday (4/15):	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.04"						
Thursday	0.16"						
Friday	0.00"						
Saturday	0.01"						
	<u> </u>				Week		
Sunday:	0.00"						
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.43"	05/11/18	Tstorm 68/47				
Saturday	0.02"				West		
Conde	NA				Week		
Sunday:	NA NA						
Monday Tuesday	NA						
Wednesday	NA NA						
Thursday	NA NA						
Friday	NA NA						
Saturday	NA						
		1		1			
	None						
Complaints:							
Construction Sequencing:							
Which portion(s) (i.e. drainage basins) or	f the site have had a temporary or	permanent cessation of	grading, earthwork, or groun	d disturbance in the last 14 da	iys?		
Entire site, grading completed 7/20	006 and site seeded 9/5/06. G	rading began on old	school site east of Star of	rass Road (11/9/17).			
, 5 5 1 2		J J		, , , ,			
	<u> </u>			1			

## Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire site, grading completed 7/2006 and site seeded 9/5/06. Grading began on old school site east of Stargrass Road (11/9/17).

# What temporary or permanent stabilization measures listed in this section are being implemented?

Wetlands Mitigation Seeding (5/31/06), Slopes Seeded/Matted (8/30/06), Temp. Seeded (9/5/06), Re-Seeded 5/21/07, Re-Seeded ROW on 9/5/07 & 11/14/07, Erosion seeded in various areas (4/09), Old Basin 5 was seeded and matted (5/2/12). The areas that were disturbed when SB 3 and 5 were closed has been seeded (9/10/16/).

## SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

Vac

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Ves

#### **CHECKLIST QUESTIONS:**

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

s dust associated with the construction activity adequately controlled on the site?

Yes

#### Comments:

## Comments:

- 1. Multiple houses are being built in the development.
- 2. SB 4 is being partially closed to accommodate the dirt from the grading of the new area as of 11/9/17. The inspector will continue to monitor its effectiveness. The surrounding area is primarily built out so the remaining basin can accommodate the flow coming from the adjacent lots.

#### Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

1) See BMP section for required maintenance.

Unique Name	Tune	Location	Projected Install Date	Status	Maintenance	
Unique Name	Туре					
CE 1	Construction Entrance	Intersection of Rosewood and	11/21/2017	Pending	No	
	Entrance	Rainwood Road				
Current Condition:	Pending - The inspec	ctor will recommend an	entrance if it becomes ne	ecessary.		
CW 1	Concrete Washout	Lot 20		Removed		
Current Condition:	Removed - Boyer Yo	oung cleaned out and re	moved the concrete wasl	nout prior to the 9/2	6/15 inspection.	
CW 2	Concrete Washout	Lot 162		Removed		
Current Condition:	Removed - Boyer Yo	oung cleaned out and re	noved the concrete wash	nout prior to the 9/2	6/15 inspection.	
		Rosewater Prky and				
IF 1	Inlet Filter	Chicory St.		Removed		
Current Condition:	Removed - E&A insp	ector removed the inlet	filter during inspection or	n 4/15/17.	•	
Lot 2	Silt Fence	Lot 2		Removed		
Current Condition:	Removed - Regency	Homes seeded the lot	prior to the 7/16/15 inspe	ction.		
Lot 1 Replat 1	Silt Fence	Lot 1 Replat 1		Removed		
Current Condition:	Removed - MJ Desig	n sodded the lot prior to	the last inspection on 6	/7/17.		
Lot 2 Replat 1	Individual Lot	Lot 2 Replat 1		Removed		
Current Condition:	Removed - Legacy H	lomes sodded the lot pr	or to the inspection on 9	/19/17.		
Lot 2 Replat 2	Silt Fence	Lot 2 Replat 2		Removed		
Current Condition:	Removed - Legacy H	lomes sodded the lot pr	or to inspection on 5/17/	17	'	
Lot 5	Individual Lot	Lot 5	4/19/2017	Active	Yes	
Current Condition:	Fair Condition - The	lot was previously labele	ed lot 3 replat 2. The insp	ector has re-name	the lot 5 per the	
	SWPPP. Silt fence was installed at the back of the lot as of the 3/24/18 inspection. The Home Company removed the dirt pile from the ROW prior to the inspection on 4/5/18.					
	Silt Fence is down in	the back of the lot and	needs to be removed or	repaired.		
	The Home Company	was informed to compl	ete by 5/4/18. <b>Not done</b>	as of last inspecti	on.	
	Individual Lot	Lot 6	5/11/2018	Active	Yes	

Current Condition:	Fair Condition -						
	Silt fence is down in the corner of the lot and needs to be repaired						
	The Home Company was informed to complete by 5/18/18.						
Lot 2 Replat 3	Individual Lot	Lot 4 Replat 2		Removed			
Current Condition:	Removed - Paceset	ter Homes sodded the I	ot prior to the inspection	n on 12/4/17.			
Lot 7 Replat 2	Silt Fence	Lot 7 Replat 2		Removed			
Current Condition:		elburne sodded the lot	prior to the 6/23/16 insp				
Lot 19	Silt Fence	Lot 19	8/17/2017	Active	No		
Current Condition:	Good Condition - Pa 3/12/18.	acesetter Homes installe	ed silt fence on the from	t of the lot prior to the in	spection on		
Lot 21	Silt Fence	Lot 21	8/17/2017	Active	Yes		
Current Condition:	Fair Condition - The	Home Company instal	led silt fence prior to the	e inspection on 4/5/18.			
		k in the corner of the		ed/retied			
Lot 26	Individual Lot	Lot 26	4/13/2018	Active	No		
Current Condition:	Active- CBS Homes	began construction price	or to inspection on 4/13	/18.			
Lot 27	Silt Fence	Lot 27		Removed			
Current Condition:	Removed - Sherwoo	od Homes sodded the lo	ot prior to the inspection	on 12/18/17.			
Lot 33	Silt Fence	Lot 33	3/24/2018	Active	Yes		
Current Condition:	Fair Condition - The Home Company began construction on the lot prior to the inspection on 11/9/17. Silt fence was installed at the rear of the lot as of the 3/24/18 inspection. The inspector will continue to monitor.  Silt fence needs to be reinstalled in the SE corner of lot						
	The Home Compar	ny was informed to co	mplete by 5/18/18				
Lot 36	Individual Lot	Lot 36	4/5/2018	Active	No		
Current Condition:	Riverstone Construc		behind the lot prior to ir	the lot prior to the insp espection on 4/13/18. Th			
Lot 40	Individual Lot	Lot 40		Removed			
Current Condition:	Removed- The hom	e company sodded the	lot prior to the inspection	on on 5/17/17			
Lot 41	Individual Lot	Lot 41	12/4/2017	Active	Yes		
Current Condition:	The silt fence should Brookstone Homes/	d be repaired on the sid	e of the lot.				
Lot 42	Silt Fence	Lot 42	2/26/2018	Active	No		
Current Condition:		was removed from the		e lot prior to the inspect on on 5/11/18.	ion on 4/5/18.		
Lot 47	Silt Fence	Lot 47		Removed			
Current Condition:	Removed - Richland	Homes sodded the lot	prior to the inspection of	on 12/4/17.			
Lot 48	Individual Lot	Lot 48		Removed			
Current Condition:		on Homes sodded the I	ot prior to the 10/21/16				
Lot 49	Individual Lot	Lot 49	and dead the state of the	Removed			
Current Condition:	Removed - Marc D	avid Custom Homes s	soaded the lot prior to	inspection on 5/11/18			
Lot 51	Individual Lot	Lot 51		Removed			
Current Condition:		ne Company sodded the	e lot prior to the 4/21/16				
Lot 57	Silt Fence	Lot 57	ot prior to the inenestica	Removed			
Current Condition:		od Homes sodded the lo	or brior to the inspection				
Lot 67	Silt Fence	Lot 67		Removed			

Current Condition:	Removed - Sherwoo	od Homes sodded the lo	t prior to the 7/4/16 ins	spection		
Lot 70	Silt Fence	Lot 70	8/17/2017	Active	Yes	
Current Condition:	Fair Condition - Leg	acv Homes installed silt	fence on the back of t	the lot prior to the inspe	ction on 4/5/18. Silt	
	Fair Condition - Legacy Homes installed silt fence on the back of the lot prior to the inspection on 4/5/18. Silt fence on back of lot was removed prior to inspection on 5/11/18.  1. Another big red needs installed to make the inlet protection effective.  2. Silt fence needs to be reinstalled OR the lot should be stabilized.  1. Legacy Homes was informed to complete by 3/19/18. Not done as of the last inspection. Legacy Homes was reminded on 4/30/18, 5/15/18.					
		was informed to compl		1 1		
Lot 72	Silt Fence	Lot 71	8/17/2017	Active	Yes	
Current Condition:	Fair Condition - Legacy Homes installed silt fence on the back of the lot prior to the inspection on 4/5/18.  The portable toilet needs secured.  Legacy Homes was informed to complete by 3/5/18. Not done as of the last inspection. Legacy Homes was reminded on 4/30/18.					
Lot 112	Silt Fence	Lot 112		Removed		
Current Condition:		Homes sodded the lot pr	ior to the inspection o			
Lot 113	Individual Lot	Lot 113		Removed		
Current Condition:		od Homes sodded the lo	t prior to the 7/4/16 ins		1	
Lot 114	Silt Fence	Lot 114		Removed		
Current Condition:		Homes sodded the lot	prior to 11/23/2016.	T 5 .	1	
Lot 121	Individual Lot	Lot 121		Removed		
Current Condition:		c. sodded the lot prior to	the inspection on 11/			
Lot 122	Wattle	Lot 122		Removed		
Current Condition:		on Homes sodded the lo	t prior to inspection or		1	
Lot 124	Silt Fence	Lot 124		Removed		
Current Condition: Lot 126	Removed-Pacesette Silt Fence	er Homes sodded the lot Lot 126	prior to 11/23/2016.	Removed	1	
		Homes sodded the lot p	rior to 11/22/2016	Removed		
Current Condition: Lot 127	Silt Fence	Lot 127	101 10 1 1/23/2016.	Removed	1	
Current Condition:		y Homes sodded the lot	prior to the 12/16/15 is			
Lot 128	Silt Fence	Lot 128		Removed	1	
Current Condition:		y Homes sodded the lot	prior to the 7/16/15 ins			
Lot 129	Silt Fence	Lot 129		Removed		
Current Condition:	Removed - Regenc	y Homes sodded the lot	prior to the 11/13/15 in	nspection.		
Lot 1 Replat 2	Silt Fence	Lot 1 Replat 2		Removed		
Current Condition:	Removed - The lot v	was sodded prior to the	11/21/14 inspection.			
Lot 133	Individual Lot	Lot 133		Removed		
Current Condition:	Removed - Sherwoo	od Homes sodded the lo	t prior to the inspectio	n on 12/4/17.	•	
Lot 134	Silt Fence	Lot 134		Removed		
Current Condition:	Removed - Legacy	Homes sodded the lot p	ior to the inspection o	n 8/17/17.	1	
Lot 135	Silt Fence	Lot 135		Removed		
Current Condition:		od Homes sodded the lo	t prior to the 11/13/15		1	
Lot 136	Silt Fence	Lot 136		Removed		
Current Condition:		d Homes sodded the lot construction on lot 135 a			ng silt fence will be	
Lot 137	Silt Fence	Lot 137	5 51 616 4/21/15 IIISPE	Removed	1	
		Homes sodded the lot pi	ior to the 5/6/15 inche			
Current Condition: Lot 138	Silt Fence	Lot 138		Removed	1	
Current Condition:		Homes sodded the lot p	ior to the 10/21/16 ins			
Lot 139	Silt Fence	Lot 139	.5. 10 110 10/2 1/10 1116	Removed		
Current Condition:		od Homes sodded the lo	t prior to the 8/19/15 in			
Lot 140	Silt Fence	Lot 140		Removed		
Current Condition:	Removed - Sherwoo	od Homes sodded the lo	t prior to the 6/12/15 in	nspection.	1	
Lot 141	Silt Fence	Lot 141	<u> </u>	Removed		
Current Condition:		od Homes sodded the lo	t prior to the 8/24/16 in	nspection.		
Lot 142	Silt Fence	Lot 142		Removed		
Current Condition:	Removed - Sherwoo	od Homes sodded the lo	t prior to the inspectio	n on 7/27/17.		
Lot 143	Silt Fence	Lot 143		Removed		
Current Condition:	Removed - G Lee H	lomes sodded the lot pri	or to the 6/23/16 inspe	ection.		

Lot 145	Silt Fence	Lot 145		Removed	
Current Condition:	Removed - Sherwoo	d Homes sodded the lo	t prior to the 6/23/16 in	spection.	
Lot 144	Silt Fence	Lot 144		Removed	
Current Condition:	Removed - Dynasty	Homes sodded the lot p	rior to the 7/16/15 insp	ection	
Lot 146	Silt Fence	Lot 146		Removed	
		n Homes sodded the lot		rtemoved	
Current Condition:			prior to 11/23/2016.		
Lot 147	Individual Lot	Lot 147		Removed	
Current Condition:		ne Company sodded the	ot prior to the 12/16/1		
Lot 148	Silt Fence	Lot 148		Removed	
Current Condition:	Removed - The Hon	ne Company sodded the	lot prior to the 7/16/15	inspection.	
Lot 149	Silt Fence	Lot 149	1/27/2017	Removed	No
Current Condition:	Removed- Charlesto	on Homes sodded the lo	t prior to inspection on	4/19/17	
Lot 150	Silt Fence	Lot 150	9/19/2017	Active	No
Current Condition:					
Current Condition:		rrance Butler began cor	istruction on the lot, an	d iristalled slit leftce of	i the side and real
	· ·	inspection on 9/19/17.			
Lot 151	Silt Fence	Lot 151		Removed	
Current Condition:	Removed - Sherwoo	d Homes sodded the lo	t prior to the 8/19/15 in	spection.	
Lot 152	Silt Fence	Lot 152		Removed	
Current Condition:	Removed - Premier	Homes sodded the lot p	rior to the 6/12/15 inco	ection	
Lot 153	Individual Lot	Lot 153		Removed	T
			10/17/14 :	Removed	
Current Condition:		vas sodded prior to the	12/11/14 Inspection.	Dam:	
Lot 154	Wattle	Lot 154		Removed	
Current Condition:		Homes sodded the lot	prior to the 7/16/15 ins		
Lot 155	Silt Fence	Lot 155		Removed	
Current Condition:	Removed - Home E	nterprise sodded the lot	prior to the 11/13/15 in	spection.	
Lot 157	Individual Lot	Lot 157		Removed	
Current Condition:	Removed - Homes	by Premier sodded the	e lot prior to inspecti		
our ent condition.	Tremoved - Homes	by I refiner souded the	e lot prior to mapecin	JII 011 3/1 1/10	
= -		<u> </u>	1	1	
Lot 158	Individual Lot	Lot 158	11/9/2017	Active	No
Current Condition:	Active -Pinecrest Ho	mes began construction	on the lot prior to the	inspection on 11/9/17.	Due to the grade
	of the lot and a vege	tative buffer strip in the	back no BMP's are cur	rently needed. The ins	pector will monitor.
1 -4 450	La alla dale e al 1 a 4	1 -4 450	0/40/0047	A -4!	T N-
Lot 159	Individual Lot	Lot 159	9/19/2017	Active	No
Current Condition:		akovic began constructi			7. Currently no
	BMP's are needed d	ue to the grade of the lo	t. The inspector will mo	onitor.	
1 1 100	1 1 1 1 1 1	1 1 100	1/07/0040	1 A (	T 1
Lot 160	Individual Lot	Lot 160	4/27/2018	Active	No
Current Condition:	Active - The Home (	Company began constru	ction prior to inspection	n on 4/27/18. Currently	no BMP's are
	needed due to the g	rade of the lot. The insp	ector will monitor.		
Lot 161	Individual Lot	Lot 161	11/9/2017	Active	No
Current Condition:		Trademark Homes bega			
		ot and a vegetative buffe	er strip in the rear of the	olot no BMP's are need	ded. Silt fence
	was installed in SV	V corner.			
Lot 162	Individual Lot	Lot 162		Removed	
Current Condition:	Removed - Legacy I	Homes sodded the lot pr	rior to the 12/16/15 insp	pection. Legacy Home	s Removed the
		ebris prior to the 2/23/16		- •	
Lot 163	Silt Fence	Lot 162	3/24/2018	Active	No
Current Condition:	Good Condition - Sil	verstone Building begar	construction on the lo	t prior to the inspection	on 12/18/17.
		are needed. Silt fence w			
	inspection.				0/2 1/ 10
1 1101	1 2 1 1 4	1 1 101	I		
Lot 164	Individual Lot	Lot 164	l	Removed	
Current Condition:		ne Company sodded the	lot prior to the 9/26/15		
Lot 165	Silt Fence	Lot 165		Removed	
Current Condition:	Removed - The Hon	ne Company sodded the	e lot prior to the 7/16/15	inspection.	
Lot 166	Silt Fence	Lot 166		Removed	
Current Condition:	Removed - Legacy F	Homes sodded the lot pr	ior to the 7/4/16 inspec		•
Lot 167	Silt Fence	Lot 167	15 1.15 1.7 17 10 1110 000	Removed	
		00/	1	1	i l
Current Conditions		d Homes soddod the la	t prior to the 1/21/16 in	enection	
Current Condition:	Removed - Sherwoo	od Homes sodded the lo	t prior to the 4/21/16 in:		
Lot 168	Removed - Sherwood Silt Fence	Lot 168		Removed	
Lot 168  Current Condition:	Removed - Sherwood Silt Fence Removed - Legacy I	Lot 168 Homes sodded the lot pr		Removed tion.	
Lot 168  Current Condition: Lot 170	Removed - Sherwood Silt Fence Removed - Legacy H Individual Lot	Lot 168 Homes sodded the lot pr Lot 170	ior to the 6/2/14 inspec	Removed ction.	
Lot 168  Current Condition:	Removed - Sherwood Silt Fence Removed - Legacy H Individual Lot	Lot 168 Homes sodded the lot pr	ior to the 6/2/14 inspec	Removed ction.	

Lot 171	Individual Lot	Lot 171		Removed		
Current Condition:		ter Homes sodded the lo	I of prior to the inspection			
Lot 179	Silt Fence	Lot 179	11/9/2017	Active	Yes	
Lot 179						
Current Condition:	4/5/18. Silt fence w Silt Fence needs to	acy Homes installed silt as removed prior to in	spection on 5/11/18. hould be stabilized.	eter of the lot prior to tl	ne inspection on	
Lot 180	Silt Fence	s informed to complete Lot 180	<mark>э ру 5/18/18.</mark> Г	Removed	T	
Current Condition:		ter Homes sodded the lo	t prior to the inequation			
Current Condition:		on Homes sodded the lo				
Lot 181	Individual Lot	Lot 181	profito the 12/17/14	Removed		
Current Condition:	Removed - Dreams	cape sodded the lot prio	r to the 7/16/15 inspect	ion.	1	
Lot 182	Silt Fence	Lot 182		Removed		
Current Condition:	Removed - Change	d to Lot 7 Replat 2.	•			
Lot 183	Silt Fence	Lot 183		Removed		
Current Condition:	Removed - Sherwoo	od Homes sodded the lo	t prior to the 4/29/16 in	spection.		
Lot 184	Silt Fence	Lot 184		Removed		
Current Condition:		od Homes sodded the lo	t prior to the 11/13/15 in			
Lot 185	Wattle	Lot 185		Removed		
Current Condition:		d Homes sodded the lot				
Lot 186 Current Condition:	Individual Lot	Lot 186 cesetter Homes began	5/11/2018	Active	Yes	
		be removed from the R				
Lot 187	Silt Fence	Lot 187		Removed		
Current Condition:	Removed - Sherwood Homes sodded the lot prior to the inspection on 11/9/17.					
Lot 188	Individual Lot	Lot 188	5/11/2018	Active	Yes	
Lot 188 Current Condition:	Fair Condition - Th 5/11/18. Dirt Pile needs to b	Lot 188 e Home Company beg be removed from the R my was informed to con	an construction on th			
Current Condition:  Lot 189	Fair Condition - Th 5/11/18.  Dirt Pile needs to b The Home Compar Individual Lot	e Home Company beg be removed from the R ny was informed to cor Lot 189	an construction on the COW mplete by 5/18/18.	e lot prior to the ins Pending	pection on Yes	
Current Condition:	Fair Condition - The 5/11/18.  Dirt Pile needs to be The Home Compar Individual Lot Pending - The Home 1. Silt fence needs in 2. Straw Wattles should be supported by the Home Company was remired.	be removed from the R  ny was informed to cor  Lot 189  e Company began const  nestalled in the rear of the build be placed in above  any was informed to con	an construction on the construction on the lot prior of the curb inlet to protect applete by 2/5/18. Not do	Pending to the inspection on 1/	Yes 29/18. g off the lot ection. The Home	
Current Condition:  Lot 189	Fair Condition - The 5/11/18.  Dirt Pile needs to be The Home Compar Individual Lot Pending - The Home 1. Silt fence needs in 2. Straw Wattles should be supported by the Home Company was remired.	be removed from the R  my was informed to cor  Lot 189  e Company began const  mstalled in the rear of the bould be placed in above  any was informed to con ided on 2/27/18.	an construction on the construction on the lot prior of the curb inlet to protect applete by 2/5/18. Not do	Pending to the inspection on 1/	Yes 29/18. g off the lot ection. The Home	
Current Condition:  Lot 189  Current Condition:	Fair Condition - The 5/11/18.  Dirt Pile needs to be The Home Compar Individual Lot Pending - The Home 1. Silt fence needs in 2. Straw Wattles should 1. The Home Company was remir 2. The Home Company was remir 2. The Home Company was observed on the was observed on the 1. Silt Fence should 2. Dirt Pile should be 1. Pinecrest Homes	be removed from the R  my was informed to cor  Lot 189  e Company began const  metalled in the rear of the bould be placed in above  any was informed to con ided on 2/27/18.  any was informed to con	an construction on the COW  mplete by 5/18/18.  1/29/2018 ruction on the lot prior is a lot. the curb inlet to protect inplete by 2/5/18. Not do inplete by 5/4/18. Not do inplete by 5/4/18. Not do instruction on the lot prior in the inspection on 4/5/18 ack of lot.	Pending to the inspection on 1/ from sediment comin one as of the last inspection as of last inspection on 1/ Active or to the inspection on 1/ as as of last inspection on 1/	Yes 29/18. g off the lot ection. The Home tion. Yes 4/5/18. Silt fence	
Lot 189 Current Condition:  Lot 190  Current Condition:	Fair Condition - The 5/11/18.  Dirt Pile needs to be The Home Compar Individual Lot Pending - The Home 1. Silt fence needs in 2. Straw Wattles should 1. The Home Compar Company was remir 2. The Home Compar Silt Fence  Fair Condition - Pine was observed on the 1. Silt Fence should 2. Dirt Pile should be 1. Pinecrest Homes 2. Pinecrest Homes	Lot 190  Lot 190	an construction on the COW  mplete by 5/18/18.  1/29/2018 ruction on the lot prior is a lot. the curb inlet to protect inplete by 2/5/18. Not do inplete by 5/4/18. Not do inplete by 5/4/18. Not do instruction on the lot prior in the inspection on 4/5/18 ack of lot.	Pending to the inspection on 1/ from sediment comin one as of the last inspection Active  Active  To to the inspection on 1/ a sea of last inspection on 1/ one as of last inspection on 1/ one as of last inspection.	Yes 29/18. g off the lot ection. The Home tion. Yes 4/5/18. Silt fence	
Lot 189 Current Condition:  Lot 190 Current Condition:  Lot 190 Lot 190	Fair Condition - The 5/11/18.  Dirt Pile needs to be The Home Compar Individual Lot Pending - The Home 1. Silt fence needs in 2. Straw Wattles should 1. The Home Company was remir 2. The Home Company was remir 2. The Home Company was observed on the was observed on the 1. Silt Fence should 2. Dirt Pile should be 1. Pinecrest Homes 2. Pinecrest Homes Silt Fence	Lot 190	an construction on the COW  mplete by 5/18/18.  1/29/2018 ruction on the lot prior of the Curb inlet to protect in plete by 2/5/18. Not do not be inspection on the lot prior of the inspection on the lot prior of the inspection on 4/5/18 ack of lot.  ete by 4/20/18. Not done the by 4/20/18. Not done in the lot prior of the inspection on 4/5/18 ack of lot.	Pending to the inspection on 1/ from sediment comin one as of the last inspection as of last inspection on 1/ Active  Active  a so of last inspection on 1/ a as of last inspection. Removed	Yes 29/18. g off the lot ection. The Home tion. Yes 4/5/18. Silt fence	
Lot 189 Current Condition:  Lot 190  Current Condition:	Fair Condition - The 5/11/18.  Dirt Pile needs to be The Home Compar Individual Lot Pending - The Home 1. Silt fence needs in 2. Straw Wattles should 1. The Home Company was remir 2. The Home Company was remir 2. The Home Company was observed on the was observed on the 1. Silt Fence should 2. Dirt Pile should be 1. Pinecrest Homes 2. Pinecrest Homes Silt Fence	Lot 190  Lot 190	an construction on the COW  mplete by 5/18/18.  1/29/2018 ruction on the lot prior of the Curb inlet to protect in plete by 2/5/18. Not do not be inspection on the lot prior of the inspection on the lot prior of the inspection on 4/5/18 ack of lot.  ete by 4/20/18. Not done the by 4/20/18. Not done in the lot prior of the inspection on 4/5/18 ack of lot.	Pending to the inspection on 1/ from sediment comin one as of the last inspection as of last inspection on 1/ Active  Active  a so of last inspection on 1/ a as of last inspection. Removed	Yes 29/18. g off the lot ection. The Home tion. Yes 4/5/18. Silt fence	

Current Condition:	Fair Condition - The	Fair Condition - The contractor that closed SB 5 installed silt fence prior to the 8/24/16 inspection.					
	The silt fence needs to be repaired in the southeast corner of the lot.  The inspector will attempt to re-tie the silt fence during the next inspection. Not done as of the last inspection.						
SF 7	Silt Fence	SB 3	9/27/2016	Removed	Yes		
Current Condition:	Removed - SF 7 ch	nanged to lot level item	(lots 5 and 6) as of 5/	15/18.			
SF 8	Silt Fence	Rainwood Road	11/23/2016	Active	No		
Current Condition:	Good Condition - Bo	oyer Young installed a sil	t fence check in front o	f Rainwood Road prior	to 11/23/2016.		
SF 9	Silt Fence	The perimeter of the newly graded area	11/21/2017	Active	No		
Current Condition:	section of the silt fer around the existing	Good Condition - The silt fence was repaired by Commercial Seeding prior to the inspection on 4/5/18. A section of the silt fence was not repairable due to standing water. Commercial Seeding installed silt fence around the existing dirt stock pile prior to the inspection on 3/5/18. The silt fence in the SE corner was repaired prior to inspection on 4/27/18.					
SB 3	Sediment Basin	South of Wild Indigo St and Prairie Star St.		Removed			
Current Condition:		in was closed prior to the	e 8/24/16 inspection.	Removed			
SB 4	Sediment Basin	South of 149th Dead End	11/14/2005	Active	Yes		
Current Condition:		Filled - Roth Enterprise					
	<ol> <li>Dirt needs to be r</li> <li>Dusty Roth has b monitor. Dusty Roth</li> </ol>	er was damaged by Leik removed from around risc seen contacted as of 12/1 a was reminded on 2/26/1 contacted 4/11/18. Not do	2/17 in order to remove 8, 3/28/18.	ain properly.	inspector will		
CD E	Sediment Basin	Southwest corner of Rosewater Pkwy and North H.W.S Cleveland Blvd		Domested			
SB 5 Current Condition:			0.0/24/16 in an antic :	Removed			
STR	Street Cleaning	in was closed prior to the Entire Site	2/26/2007	Active	No		
Current Condition:	Good Condition - no				<u> </u>		
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No		
Current Condition:	Good Condition: 156th and Benningt	<u> </u>					
spector Signature:	$\mathcal{I}_{\gamma}$		Reviewed By:	The Sur			