E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept, Manager

Enaineerina Answers

Environmental Services Dept. Manager Engineering Answers						
Inspector: Luke Antholz		E&A- P2005.03	30.000		Stage	
		Tha	Heritage			
			-		2	
Project Name:			R110495			
For Week Ending:		7/2	27/2019			
	East of 156th	East of 156th Street, North and South of Rainwood Road - Bennington, NE				
Project Location:		(Doug	las County)		68007	
Grading:		100%				
Sanitary Sewer:		100%				
Storm Sewer:		100%				
Paving:		100%				
Seeding:		100%				
Utilities:		100%				
Overall Development:		70%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.77"	7/16/2019	Tstorm 88/71			
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	0.53"					
Monday	0.00"	7/22/2019	1			
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.01"					
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday Friday	0.00"				+	
Saturday	0.00"				+	
outuruuy	10.00					
	None					
Complaints:						
Construction Sequencing:	I		1	1		
	s) of the site have had a temporary c	or permanent cessation of	grading, earthwork, or ground distur	bance in the last 14 da	iys?	
Entire site, grading completed 7	7/2006 and site seeded 9/5/06. 0	Frading began on old s	chool site east of Stargrass Poo	nd (11/9/17)		
	s) of the site do not have grading, ea					
	7/2006 and site seeded 9/5/06. C lization measures listed in this section			iu (11/9/17).		
	/31/06), Slopes Seeded/Matted			Re-Seeded ROW	on 9/5/07 & 11/14/07	
Erosion seeded in various area	s (4/09), Old Basin 5 was seede nding SB#4 has been seeded (5	d and matted (5/2/12).				
	- (*	•				

Summary Questions: Are approved entrances and adjacent streets being maintained adequately? Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes

Checklist Questions:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments: Comments:

 Site is active for home building.
SB 4 is being partially closed to accommodate the dirt from the grading of the new area as of 11/9/17. The inspector will continue to monitor its effectiveness. The surrounding area is primarily built out so the remaining basin can accommodate the flow coming from the adjacent lots. The basin was working effectively as of the 8/13/18 inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) No maintenance is required at this time

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
		Intersection of			
05.4		Rosewood and		.	
CE 1	Construction Entrance	Rainwood Road	11/21/2017	Pending	No
Current Condition:	Pending - The inspector will I		If it becomes necessary as		Inspection.
CW 1	Concrete Washout	Lot 20		Removed	
Current Condition:	Removed - Boyer Young clea	1	ne concrete washout prior to		ction.
CW 2	Concrete Washout	Lot 162		Removed	
Current Condition:	Removed - Boyer Young cleaned out and removed the concrete washout prior to the 9/26/15 inspection.				
IF 1	Inlet Filter	Rosewater Prky and Chicory St.		Removed	
Current Condition:	Removed - E&A inspector re	,	ing inspection on 4/15/17	Removed	
Lot 5	Individual Lot	Lot 5		Removed	
Current Condition:	Removed - The Home Comp		to inspection on 5/22/18	rtoniovou	
L of 6	Individual Lot	Lot 6		Removed	
Current Condition:	Removed - The Home Comp		emoved the silt fence prior		 ection
Lot 6 Replat 2	Silt Fence	Lot 6 Replat 2		Removed	
Current Condition:	Removed - Sherwood Home		the 12/18/18 inspection	Removed	1
Lot 18	Silt Fence	Lot 18	5/7/2019	Active	No
Current Condition:	Active - Homeowner Gene B		****		
Current Condition:	recommended at this time, d			19 inspection, no E	smes are
Lot 19	Silt Fence	Lot 19		Removed	
Current Condition:	Removed - Pacesetter Homes installed silt fence on the front of the lot prior to the inspection on 3/12/18. Pacesetter Homes sodded the lot and removed the silt fence prior to the 7/18/18 inspection.				
Lot 20	Individual Lot	Lot 20		Removed	
Current Condition:	Removed - Lot is currently in	active, Lot 20 will be re-	added when construction be	egins.	1
Lot 21	Silt Fence	Lot 21		Removed	
Current Condition:	Removed - The Home Company installed silt fence prior to the inspection on 4/5/18. The Home Company sodded t and removed the silt fence prior to the inspection on 7/18/18.				mpany sodded th
Lot 22	Individual Lot	Lot 22		Removed	1
Current Condition:	Removed - Lot is currently in		I added when construction be		
Lot 26	Individual Lot	Lot 26		Removed	1
Current Condition:	Removed- CBS Homes sodd		/20/18 inspection		
Lot 33	Silt Fence	Lot 33		Removed	
Current Condition:	Removed - The Home Comp		to inspection on 6/2/18	. tonio i ou	
L of 36	Individual Lot	Lot 36		Removed	1
Current Condition:	Removed- River Stone Custo		I ot prior to the 6/24/19 inspec		
Lot 38	Individual Lot	Lot 38		Removed	
Current Condition:	Removed- D&E Custom Buil	ding and Design sodded	the lot prior to the 6/24/19	inspection.	
Lot 39	Individual Lot	Lot 39		Removed	
Current Condition:	Removed- D&E Custom Buil	ding and Design sodded	the lot prior to the 6/24/19	inspection.	
Lot 41	Individual Lot	Lot 41		Removed	
Current Condition:	Removed - Brookstone Hom	es sodded the lot prior to	inspection on 6/12/18.		
Lot 42	Silt Fence	Lot 42		Removed	
Current Condition:	Removed - Legacy Homes s		inspection on 8/21/18.	<u> </u>	1
	Individual Lot	Lot 43		Removed	
Lot 43	inuividual Lot	LOL 45		rtoniovou	

Lot 44	Individual Lot	Lot 44	7/16/2019	Active	No
Current Condition:	Active - Brookstone Develop BMP's are recommended a				mostly flat, no
Lat 49			tor will continue to monit		1
Lot 48	Individual Lot	Lot 48		Removed	
Current Condition:	Removed - Marc David Cust		T prior to inspection on 5/1	Removed	1
Lot 58 Current Condition:	Silt Fence	Lot 58	- 7/0/40 in an action	Removed	
	Removed - Dynasty Homes	· · · · · · · · · · · · · · · · · · ·			1
Lot 60	Individual Lot	Lot 60	5/7/40 :	Removed	
Current Condition:	Removed - Legacy Homes s	1	5/7/19 Inspection.		1
Lot 61	Individual Lot	Lot 61	5/7/40 :	Removed	
Current Condition:	Removed - Legacy Homes s			A .::	
Lot 65	Individual Lot	Lot 65	7/16/2019	Active	No
Current Condition:	Active - Hunnington Homes ROW, since excavating was to monitor.	actively going on no ma		is needed. E&A ins	
Lot 66	Individual Lot	Lot 66		Removed	
Current Condition:	Removed - Legacy Homes s		5/7/19 inspection.		
Lot 70	Silt Fence	Lot 70		Removed	
Current Condition:	Removed - Legacy Homes s		pection on 6/12/18.		
Lot 72	Silt Fence	Lot 72		Removed	
Current Condition:	Removed - Legacy Homes s		· · · · · · · · · · · · · · · · · · ·		
Lot 150	Silt Fence	Lot 150	9/19/2017	Removed	
Current Condition:	Removed - Terrance Butler	sodded the lot and remov	ed the silt fence prior to the		۱.
Lot 157	Individual Lot	Lot 157		Removed	
Current Condition:	Removed - Homes by Premi	er sodded the lot prior to	inspection on 5/11/18		
Lot 158	Individual Lot	Lot 158	11/9/2017	Removed	
Current Condition:	Removed - Pinecrest Homes	s sodded the lot and rem	oved the silt fence prior to t	he 7/18/18 inspecti	on.
Lot 159	Individual Lot	Lot 159		Removed	
Current Condition:	Removed - Ljubissa Milakov	ic sodded the lot prior to	inspection on 6/12/18.		
Lot 160	Individual Lot	Lot 160		Removed	
Current Condition:	Removed - The Home Comp	pany sodded the lot prior	to the 9/18/18 inspection.		
Lot 161	Individual Lot	Lot 161		Removed	
Current Condition:	Removed - Trademark Hom	es sodded the lot prior to	inspection on 6/2/18.		
Lot 163	Silt Fence	Lot 163		Removed	
Current Condition:	Removed - Silverstone Build		e lot prior to inspection on 6		
Lot 179	Silt Fence	Lot 179		Removed	
Current Condition: Lot 186	Removed - Legacy Homes s Individual Lot	Lot 186	pection on 6/12/18.	Removed	1
Current Condition:	Removed - Pacesetter Home		the 10/0/18 inspection	Removed	
Lot 188	Individual Lot	Lot 188		Removed	
Current Condition:	Removed - The Home Comp		to the 10/0/19 increation	Removed	
Lot 189	Individual Lot	Lot 189		Removed	
Current Condition:			to the increation on 9/21/1/		
Lot 190	Removed - The Home Comp Silt Fence	Lot 190		8. Removed	
Current Condition:	Removed - Pinecrest Homes		he 5/7/19 inspection	ITEIHOVEU	
Current Condition:	Removed - Fillecrest nomes				
Lot 191	Individual Lot	Lot 191		Removed	
Current Condition:	Removed - David Thomas C	Construction sodded the I	ot prior to the 4/23/19 inspe	ction.	-
Lot 192	Individual Lot	Lot 192		Removed	
Current Condition:	Removed - Brookstone Deve		prior to the 7/8/19 inspectio		1
1 - 1 - 100		1 -+ 100		Dama	1
Lot 193	Individual Lot	Lot 193		Removed	1
Current Condition:	Removed- Proline Homes so	baded the lot prior to the	6/24/19 inspection.		
SF 6	Silt Fence	SB 5		Removed	
Current Condition:	Removed - Commercial See	ding removed the silt fer	ce prior to the 10/9/18 insp	ection.	-
SF 7	Silt Fence	SB 3		Removed	
Current Condition:	Removed - SF 7 changed to	lot level item (lots 5 and	6) as of 5/15/18.		
SF 8	Silt Fence	Rainwood Road		Removed	
Current Condition:	Removed - Boyer Young ins repaired prior to the 8/13/18	talled a silt fence check i		prior to 11/23/2016.	
SF 9	Silt Fence	The perimeter of the newly graded area	11/21/2017	Active	No
				•	•

Current Condition:	Good Condition - The silt fe silt fence was not repairabl pile prior to the inspection of Inspector was informed tha 7/30/18. Silt fence was rep Commercial Seeding repair undermined in the northeas remedy during the next insp backfilled and repaired the	e due to standing water. C on 3/5/18. The silt fence in t the silt fence would be th aired and sediment was cl red and cleaned out the sil stern section as of the 3/26 pection. Inspector backfille	ommercial Seeding instal the SE corner was repair e highest priority for Com leaned up from adjacent I t fence prior to the 11/6/1 //19 inspection, inspector ed the silt fence during the	led silt fence around ed prior to inspection mercial Seeding duri ots prior to the 8/13/1 8 inspection. Silt fen will continue to monit	the existing dirt stock on 4/27/18. The ng the week of 8 inspection. ce is becoming for and attempt to	
SB 3	Sediment Basin	South of Wild Indigo St and Prairie Star St.		Removed		
Current Condition:	Removed - The basin was	closed prior to the 8/24/16	inspection.		-	
SB 4	Sediment Basin	South of 149th Dead End	11/14/2005	Active	No	
Current Condition:	Good Condition- 40% Filled - Roth Enterprise cleaned off the risers prior to the 7/7/16 inspection. Dustin Roth removed southern riser and removed dirt to restore drainage prior to inspection on 7/2/18.					
SB 5	Sediment Basin	Southwest corner of Rosewater Pkwy and North H.W.S Cleveland Blvd		Removed		
Current Condition:	Removed - The basin was closed prior to the 8/24/16 inspection.					
STR	Street Cleaning	Entire Site	2/26/2007	Active	No	
Current Condition:	Good Condition - CBS Homes cleaned the streets in front of Lot 26 prior to inspection on 6/20/18. Streets were clean during the 9/18/18 inspection. Street was cleaned in front of lot 38 prior to the 10/23/18 inspection. Streets were covered in snow during the 2/19/19 inspection, street cleaning recommendations will remain on the report until the inspector can verify if any street cleaning activities have occurred. Minor street cleaning was performed in front of lots 60, 61, and 66 by plowing activities or by Legacy Homes prior to the 3/5/19 inspection, sediment is still present along the curb line. Legacy Homes cleaned the curb line prior to the 5/7/19 inspection, minor sediment is present in front of lots 38 and 39, inspector will continue to monitor.					
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No	
Current Condition:	Good Condition: 156th and Bennington Blvd					
ector Signature:	Luce arthralp			Reviewed By:	But Sul	