E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Ma

Engineering Answers

		E&A- P2005.030.00	0		
Inspector: Hannah Herzfeld			Stage		
Project Name:		2			
For Week Ending:					
Project Location:	East of 156th Stre	68007			
		ı		1	
Grading:	100%				
Sanitary Sewer:	100%				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	98%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	

RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week
Sunday:	0.00*				
Monday	0.00*				
Tuesday	0.00*				
Wednesday	0.00*				
Thursday	0.03"	1/14/2021	Cloudy 48/32	12:40 PM	
Friday	0.00*				
Saturday	0.00*				
					Week
Sunday:	0.00*				
Monday:	0.00*				
Tuesday:	0.00*				
Wednesday:	0.00*				
Thursday:	0.00*				
Friday:	0.00*				
Saturday:	0.00"				
					Week
Sunday:	N/A				
Monday	N/A				
Tuesday	N/A				
Wednesday	N/A				
Thursday	N/A				
Friday	N/A				
Saturday	N/A				
	None				
Complaints:					
	1	1	I	1	1

Construction Sequencing:
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site, grading completed 7/2006 and site seeded 95/06. Grading began on old school site east of Stargrass Road (11/6/17), Grading activity on site ide (96/20).

That supporary or personnel stabilization measures lated in this section are bring implemented?

Wellmards Mitigation Seeding (65/3106, Spees Seededdiffuethe (68/3006), Temp. Seededd (95/06), Re-Seeded 95/107, Re-Seeded ROW on 95/07 & 11/14/07,
Erosion seeded in various areas (40/9), Old Basin 5 was seeded and matted (56/21/2). The areas that were disturbed when SB 3 and 5 were closed has been seeded (91/01/6), Area surrounding 948H has been seededd (91/21/6). Well well seed the seeded (91/01/6) will well seed the seeded (91/01/6). Well stress teeded and matted (98/20/5).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the co

res Create Corrective Action?

as been seeded or otherwise stabilized as required? List inactive portions of the project and if sta

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?
No - See BMP Section (Lot 22)

ve construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

reate Corrective Action?

Comments:

1. Site is active for home building.

2. Site is being partially closed to accommodate the drift from the grading of the new area as of 11/9/17. The inspector will continue to monitor its effectiveness. The surrounding area is primarily built out so the remaining basin can accommodate the flow coming from the adjacent lots. The basin was working effectively as of the 19/18 if inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

Some maintenance is required in the BMP section.

Unique Name

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
		Intersection of					
		Rosewood and					
CE 1	Construction Entrance	Rainwood Road	11/21/2017	Pending	No		
Current Condition:	Pending - The inspector will	recommend an entrance	if it becomes necessary as	of the 11/21/2017	inspection.		
CW 1	Concrete Washout	Lot 20		Removed			
Current Condition:	Removed - Boyer Young clea	Removed - Boyer Young cleaned out and removed the concrete washout prior to the 9/26/15 inspection.					
CW 2	Concrete Washout	Lot 162		Removed			
Current Condition:	Removed - Boyer Young clea	Removed - Boyer Young cleaned out and removed the concrete washout prior to the 9/26/15 inspection.					
		Rosewater Prky and					
IF 1	Inlet Filter	Chicory St.		Removed			
Current Condition:	Removed - E&A inspector re						
Lot 17 Current Condition:	Individual Lot Fair Condition - Metro Home	Lot 17	5/12/2020	Active	Yes		
	The silt fence on both sides of		m the lot prior to the inspec red where damaged OR re				
	The silt fence on both sides of Metro Homes was informed to 9/10/20, 10/7/20, 10/27/20, 1	of the lot should be repair to complete by 8/4/20. N	red where damaged OR re	moved.	s reminded on		
Lot 18	Metro Homes was informed t	of the lot should be repair to complete by 8/4/20. N	red where damaged OR re	moved.	s reminded on		
Lot 18 Current Condition:	Metro Homes was informed t 9/10/20, 10/7/20, 10/27/20, 1	of the lot should be repart to complete by 8/4/20. N 2/22/20	red where damaged OR re	moved. n. Metro Homes wa	s reminded on		
Current Condition: Lot 20	Metro Homes was informed to 9/10/20, 10/7/20, 10/27/20, 1: Silt Fence Removed - Gene Bramhill so Individual Lot	of the lot should be repa to complete by 8/4/20. N 2/22/20 Lot 18 idded the lot prior to the Lot 20	red where damaged OR re to done as of last inspection inspection on 6/19/20. 10/12/2020	n. Metro Homes wa Removed Active	Yes		
Current Condition:	Metro Homes was informed t 9/10/20, 10/7/20, 10/27/20, 13 Silt Fence Removed - Gene Bramhill so	of the lot should be repa to complete by 8/4/20. N 2/22/20 Lot 18 dodded the lot prior to the Lot 20 installed silt fence and n excavating the lot prior the inspection on 11/1/0/2 the lot should be remo- es of the lot should be re- dd to complete by 11/2/2	red where damaged QR re tot done as of last inspection inspection on 6/19/20. 10/12/2020 wattles on the sides and fire to the inspection on 10/26/ 20. eed or repositioned and res- paired/cleaned out. 0. Not done as of last inspec-	n. Metro Homes wa Removed Active not of the lot prior to 20. Story Homes research.	Yes the inspection on emoved the dirt/sa		

Airport for weather/RQs: Blair

Closure Information: Applicant Business Name/Project Name Representative's Email Address Phone Number Representatives Name Address Project # Assigned by Applicant

3-Jan

Current Condition:	during the 11/24/20 inspection	Active - Metro Homes began excavating the lot prior to the 11/24/20 inspection. A dirt pile was observed in the ROW during the 11/24/20 inspection. Due to the lot being mostly flat during the 11/24/20 inspection no BMP recommendation is needed at this time. E&A inspector will continue to monitor for BMP installation.						
		Dirt pile should be removed from the ROW. Concrete waste on the lot should be cleaned up.						
	Metro Homes was informed to complete by 12/28/20. Not done as of last inspection. Metro Homes was informed to complete by 12/28/20. Not done as of last inspection.							
Lot 24	Individual Lot	Lot 24	10/12/2020	Active	No			
Current Condition:	Good Condition - Story Home							
	Homes installed a portable portable toilet is secured.	toilet on the southeas	t corner of the lot prior to	o the inspection o	n 1/14/21, the			
Lot 25	Individual Lot	Lot 25	5/12/2020	Active	Yes			
Current Condition:	Fair Condition - Metro Home the owner of the lot during th removed the dirt pile and cor fence on the front corners of	e 5/27/20 inspection. And acrete waste from the RC	y maintenance for the lot w DW prior to the inspection of	ill now be sent to th on 6/10/20. Metro H	em. Metro Homes omes installed silt			
	the lot prior to the inspection	fence on the front corners of the fox prior to the inspection on 6/19/20. Metro Homes repaired the silt fence on the side of the fox prior to the inspection on 8/11/20. The silt fence on both sides of the lot should be repaired or removed.						
	Metro Homes was informed t	to complete by 11/2/20.	Not done as of last inspecti	on. Metro Homes w	as reminded on			
Lot 62	Individual Lot	Lot 62		Removed				
Current Condition:	Removed - Huntington Home		the inspection on 4/28/20.	removed	l .			
Lot 65	Individual Lot	Lot 65		Removed				
Current Condition:	Removed - Huntington Home	1	the inspection on 4/28/20.					
SF 6	Silt Fence	SB 5		Removed				
Current Condition:	Removed - Commercial See	ding removed the silt fen	ce prior to the 10/9/18 insp	ection.				
SF 7	Silt Fence	SB 3		Removed				
Current Condition: SF 8	Removed - SF 7 changed to Silt Fence	Rainwood Road	6) as of 5/15/18.	Removed				
Current Condition:	Removed - Boyer Young inst		n front of Rainwood Road o		Silt Fence was			
	repaired prior to the 8/13/18	inspection. Boyer Young	removed the silt fence pri	or to the 10/23/18 in	spection.			
SF 9	Silt Fence	The perimeter of the newly graded area	11/21/2017	Active	Yes			
Current Condition:	Fair Condition - The silt fen Seeding installed silt fence a	ce was repaired by Com	mercial Seeding prior to th	e inspection on 4/5/	18. Commercial			
	retied the ailt fence where it was damaged during the 81/21/9 Impaction. Jerry Banks repaired/cleaned outtrenched in the ailt fince in multiple locations prior to the inspection on 81/10/20. Centennial Enterprises trenched in and backfilled the undermined ailt fence prior to the inspection on 81/10/20. Sitt fence is damaged in multiple locations along the run and should be repaired/teled. Jerry Banks and Centennial Enterprises will be informed to complete when weather conditions allow.							
	Jerry Banks and Centennial I	Enterprises will be inforn	ned to complete when weat	ther conditions allow	V.			
SB 3	Sediment Basin	South of Wild Indigo St and Prairie Star St.		Removed				
Current Condition:	Removed - The basin was cl	osed prior to the 8/24/16	inspection.	removed	1			
SB 4	Sediment Basin	South of 149th Dead End	11/14/2005	Active	No			
Current Condition:	Good Condition- 40% Filled	- Roth Enterprise cleane	d off the risers prior to the	7/7/16 inspection. D	ustin Roth removed			
	southern riser and removed of	Southwest corner of Rosewater Pkwy and	rior to inspection on 7/2/18	1				
SB 5	Sediment Basin	North H.W.S Cleveland Blvd		Removed				
Current Condition:	Removed - The basin was cl		inspection.	Kellioved				
STR	Street Cleaning	Entire Site	2/26/2007	Active	Yes			
Current Condition:	Fair Condition - CBS Homes	cleaned the streets in fr	ont of Lot 26 prior to inspec	ction on 6/20/18. St	reets were clean			
	during the 91818 inspection. Street was cleared in front of lot 35 prior to the 10/2318 inspection. Streets were covered in sow during the 2/1919 inspection, street cleaning recommendations will remain on the report until the inspector can wrify if any street cleaning activities have occurred. Minor street cleaning was performed in front of lot 50, 61, and 66 by plowing activities or by Leaga-y Homes prior to the 3/3710 inspection, sediment is still present along the cut hill. Leaga-y Homes cleaned the cut-hillien prior to the 5/7719 inspection, minor sediment is present in front of lot 53 38 and 39, inspection will continue to mortice. Recokatene Development cleaned the street in front of lot 10 38 and 39 inspection. Metro Homes cleaned the street in front of Lot 17 prior to the inspection on 5/27/20. Metro Homes cleaned the street in front of Lot 17 prior to the inspection on 5/11/20. Metro Homes cleaned the street in front of Lot 17 prior to the inspection on 5/11/20.							
	1.) The street in front of lot 20 should be cleaned. 2.) The street in front of lot 25 should be cleaned. 3.) The street in front of lot 22 should be cleaned. 4.) The street in front of lot 17 should be cleaned. 4.) The street in front of lot 17 should be cleaned. 4.) Story Homes was informed to complete by 1027/20. Not done as of last inspection. Story Homes was reminded on 1222/20. 2.) Metro Homes was informed to complete by 1222/20. Not done as of last inspection. 3.) Metro Homes was informed to complete by 1222/20. Not done as of last inspection. 4.) Metro Homes was informed to complete by 1222/20. Not done as of last inspection.							
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No			
SWEET SIGH	Signs							
Current Condition:	Good Condition:				140			
Current Condition:	Good Condition: 156th and Bennington Blvd	-			NO			

CO Status: Good, unknown cleanout elevation.

Website Sticker = www.EACG.com