E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers Environmental Services Dept. Manager E&A- P2005.030.000 Stage Inspector: Hannah Herzfeld The Heritage 2 **NER110495** Project Name: 4/10/2021 For Week Ending: East of 156th Street, North and South of Rainwood Road - Bennington, NE 68007 Project Location: (Douglas County) Grading: 100% 100% Sanitary Sewer: Storm Sewer: 100% Paving: 100% Seeding: 100% **Utilities:** 100% Overall Development: 98% **RAIN FALL AMOUNTS** Amount in tenths Date inspected Weather Conditions Time Week 1 Sunday: 0.00" 0.00" Monday **Tuesday** 0.00" Wednesday 0.00" Thursday 0.00" Friday 0.00" 0.00" Saturday Week 2 Sunday: 0.00" 0.00" Monday: Tuesday: 0.00" Wednesday: 0.00" 4/7/2021 Cloudy 65/46 12:10 PM Thursday: 0.00" Friday: 0.00" 4/9/2021 Cloudy 56/0 10:45 AM 0.00 Saturday: Week 3 Sunday: N/A Monday N/A N/A Tuesday N/A Wednesday N/A **Thursday** Friday N/A N/A Saturday None Complaints:

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site, grading completed 7/2006 and site seeded 9/5/06. Grading began on old school site east of Stargrass Road (11/9/17). Grading activity on site idle

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site, grading completed 7/2006 and site seeded 9/5/06. Grading began on old school site east of Stargrass Road (11/9/17). Grading activity on site idle

What temporary or permanent stabilization measures listed in this section are being implemented?

Wetlands Mitigation Seeding (5/31/06), Slopes Seeded/Matted (8/30/06), Temp. Seeded (9/5/06), Re-Seeded 5/21/07, Re-Seeded ROW on 9/5/07 & 11/14/07, Erosion seeded in various areas (4/09), Old Basin 5 was seeded and matted (5/2/12). The areas that were disturbed when SB 3 and 5 were closed has been seeded (9/10/16/). Area surrounding SB#4 has been seeded (5/22/18). Stub road at the end of N 149th Street seeded and matted (9/8/20).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Nο

Create Corrective Action?

No - See BMP Section (Lot 22)

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMP section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

- 1. Site is active for home building.
- 2. SB 4 is being partially closed to accommodate the dirt from the grading of the new area as of 11/9/17. The inspector will continue to monitor its effectiveness. The surrounding area is primarily built out so the remaining basin can accommodate the flow coming from the adjacent lots. The basin was working effectively as of the 8/13/18 inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
		Intersection of					
		Rosewood and					
CE 1	Construction Entrance	Rainwood Road	11/21/2017	Pending	No		
Current Condition:	Pending - The inspector will	Pending - The inspector will recommend an entrance if it becomes necessary as of the 11/21/2017 inspection.					
CW 1	Concrete Washout	Lot 20		Removed			
Current Condition:	Removed - Boyer Young cle	aned out and removed t	the concrete washout prior	to the 9/26/15 insp	ection.		
CW 2	Concrete Washout	Lot 162		Removed			
Current Condition:	Removed - Boyer Young cle	Removed - Boyer Young cleaned out and removed the concrete washout prior to the 9/26/15 inspection.					
		Rosewater Prky and					
IF 1	Inlet Filter	Chicory St.		Removed			
Current Condition:	Removed - E&A inspector removed the inlet filter during inspection on 4/15/17.						
Lot 17	Individual Lot	Lot 17	5/12/2020	Active	Yes		
	as the owner of the lot during the 5/27/20 inspection. Any maintenance for the lot will now be sent to them. Metro Homes removed dirt pile from the ROW prior to the inspection on 6/10/20. Metro Homes installed silt fence on the front corners of the lot prior to the inspection on 6/19/20. Metro Homes installed a portable toilet on the lot prior to the inspection on 7/28/20. Metro Homes removed the portable toilet from the lot prior to the inspection on 11/10/20. The driveway and sidewalk was paved prior to the 4/7/21 inspection. 1.) The silt fence on both sides of the lot should be repaired where damaged OR removed. 2.) The sidewalk should be cleaned off. 1.) Metro Homes was informed to complete by 8/4/20. Not done as of last inspection. Metro Homes was reminded or 9/10/20, 10/7/20, 10/27/20, 12/22/20, 1/29/21, 3/2/21, 3/26/21, 4/7/21 2.) Metro Homes was informed to complete by 4/14/21. Not done as of last inspection.						
Lot 18	Silt Fence	Lot 18		Removed			
Lot 18 Current Condition:	Silt Fence Removed - Gene Bramhill so		e inspection on 6/19/20.	Removed			

Current Condition:	Fair Condition - Story Homes installed silt fence and wattles on the sides and front of the lot prior to the inspection on 10/12/20. Story Homes began excavating the lot prior to the inspection on 10/26/20. Story Homes removed the dirt/sand piles from the ROW prior to the inspection on 11/10/20. 1.) The wattles on the front of the lot should be removed or repositioned and resecured. 2.) The silt fence on both sides of the lot should be repaired/cleaned out. 1.) Story Homes was informed to complete by 11/2/20. Not done as of last inspection. Story Homes was reminded on 12/22/20, 1/29/21, 3/2/21, 3/26/21, 4/7/21 2.) Story Homes was informed to complete by 11/2/20. Not done as of last inspection. Story Homes was reminded on 12/22/20, 1/29/21, 3/2/21, 3/26/21, 4/7/21						
Lot 22	Individual Lot	Lot 22	11/24/2020	Active	Yes		
Current Condition:	Active - Metro Homes begar						
current condition.	during the 11/24/20 inspection recommendation is needed a removed the dirt pile from the Dirt pile should be removed.	on. Due to the lot being at this time. E&A inspecte ROW, and the concre	mostly flat during the 11/24 tor will continue to monitor	I/20 inspection no E for BMP installation	BMP		
	Metro Homes was informed	to complete by 4/14/21.	Not done as of last insp	ection.			
Lot 24	Individual Lot	Lot 24	10/12/2020	Active	Yes		
Current Condition:	Fair Condition - Story Home	s installed silt fence on t	he sides of the lot prior to	the inspection on 10	0/12/20. Story		
Lot 25 Current Condition:	toilet is secured. Story Homes removed the portable toilet from the lot prior to the inspection on 2/15/21. Story Homes placed a portable toilet on the lot prior to the inspection on 3/1/21. 1.) The silt fence on the south side of the lot should be repaired. 2.) The portable toilet should be secured. 3.) The silt fence on the north side of the lot should be cleaned out/repaired. 4.) Dirt piles should be removed from the ROW. 1.) Story Homes was informed to complete by 2/4/21. Story Homes was reminded on 3/2/21, 3/26/21, 4/721 2.) Story Homes was informed to complete by 3/8/21. Not done as of the last inspection. Story Homes was reminded on 3/26/21, 4/7/21 3.) Story Homes was informed to complete by 4/14/21. Not done as of last inspection. 4.) Story Homes was informed to complete by 4/14/21. Not done as of last inspection. Individual Lot Lot 25 5/12/2020 Active Yes Fair Condition - Metro Homes began excavating the lot prior to the inspection on 5/12/20. Metro Homes was identified as the owner of the lot during the 5/27/20 inspection. Any maintenance for the lot will now be sent to them. Metro Homes removed the dirt pile and concrete waste from the ROW prior to the inspection on 6/10/20. Metro Homes installed silt fence on the front corners of the lot prior to the inspection on 6/19/20. Metro Homes repaired the silt fence on the side of the lot prior to the inspection on 8/11/20. The sidewalk was paved in front of the lot prior to the 4/7/21 inspection.						
	The silt fence on both sides of the lot should be repaired or removed. Metro Homes was informed to complete by 11/2/20. Not done as of last inspection. Metro Homes was reminded on 12/22/20, 1/29/21, 3/2/21, 3/26/21, 4/7/21						
Lot 62	Individual Lot	Lot 62		Removed			
Current Condition:	Removed - Huntington Hom	1	the inspection on 4/28/20				
Lot 65	Individual Lot	Lot 65	a di atau di atau	Removed			
Current Condition:	Removed - Huntington Hom	es sodded the lot prior to	o the inspection on 4/28/20).			
SF 6							
Command Canadida	Silt Fence	SB 5	000 prior to the 40/0/40 '	Removed			
Current Condition:	Removed - Commercial See	eding removed the silt fe	nce prior to the 10/9/18 ins	pection.			
SF 7	Removed - Commercial See Silt Fence	eding removed the silt fe	·				
	Removed - Commercial See	eding removed the silt fe	·	pection. Removed			
SF 7 Current Condition:	Removed - Commercial See Silt Fence Removed - SF 7 changed to	SB 3 lot level item (lots 5 and Rainwood Road	d 6) as of 5/15/18.	pection. Removed Removed	5. Silt Fence was		
SF 7 Current Condition: SF 8	Removed - Commercial See Silt Fence Removed - SF 7 changed to Silt Fence	SB 3 lot level item (lots 5 and Rainwood Road	d 6) as of 5/15/18. in front of Rainwood Road	Removed Removed prior to 11/23/2016			

Current Condition:	Fair Condition - The silt fence was repaired by Commercial Seeding prior to the inspection on 4/5/18. Commercial Seeding installed silt fence around the existing dirt stock pile prior to the inspection on 3/5/18. The silt fence in the SE corner was repaired prior to inspection on 4/27/18. Silt fence was repaired and sediment was cleaned up from adjacent lots prior to the 8/13/18 inspection. Commercial Seeding repaired and cleaned out the silt fence prior to the 11/6/18 inspection. Commercial Seeding backfilled and repaired the silt fence prior to the 6/24/19 inspection. E&A inspector retied the silt fence where it was damaged during the 8/12/19 inspection. Jerry Banks repaired/cleaned out/trenched in the silt fence in multiple locations prior to the inspection on 6/10/20. Centennial Enterprises trenched in and backfilled the undermined silt fence prior to the inspection on 8/11/20. Silt fence is damaged in multiple locations along the run and should be repaired/retied. Jerry Banks and Centennial Enterprises will be informed to complete when weather conditions allow. Mark Hopkins was informed to complete as weather conditions allow 3/5/21. Not done as of the last inspection.						
00.0	Out the set Davis	South of Wild Indigo		D			
SB 3	Sediment Basin	St and Prairie Star St.	C in an action	Removed			
Current Condition:	Removed - The basin was c	South of 149th Dead	6 inspection.	<u> </u>	1		
SB 4	Sediment Basin	End	11/14/2005	Active	No		
Current Condition:	Good Condition- 41% Filled						
Ca. Sit Condition	removed southern riser and	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	The second secon			
SB 5	Sediment Basin	Southwest corner of Rosewater Pkwy and North H.W.S Cleveland Blvd		Removed			
Current Condition:	Removed - The basin was c	l	L 6 inspection.	1	<u> </u>		
STR	Street Cleaning	Entire Site	2/26/2007	Active	Yes		
	during the 9/18/18 inspection. Street was cleaned in front of lot 38 prior to the 10/23/18 inspection. Streets were covered in snow during the 2/19/19 inspection, street cleaning recommendations will remain on the report until the inspector can verify if any street cleaning activities have occurred. Minor street cleaning was performed in front of lots 60, 61, and 66 by plowing activities or by Legacy Homes prior to the 3/5/19 inspection, sediment is still present along the curb line. Legacy Homes cleaned the curb line prior to the 5/7/19 inspection, minor sediment is present in front of lots 38 and 39, inspector will continue to monitor. Brookstone Development cleaned the street in front of lot 44 prior to the 10/22/19 inspection. Metro Homes cleaned the street in front of Lots 17 and 25 prior to the inspection on 5/27/20. Metro Homes cleaned the street in front of Lot 17 prior to the inspection on 8/11/20. Metro Homes cleaned the street in front of lot 17 prior to the inspection on 11/10/20. 1.) The street in front of lot 20 should be cleaned. 2.) The street in front of lot 22 should be cleaned. 3.) The street in front of lot 17 should be cleaned. 4.) The street in front of lot 17 should be cleaned. 1.) Story Homes was informed to complete by 10/27/20. Not done as of last inspection. Story Homes was reminded on 1/29/21, 3/29/21, 3/26/21, 4/7/21 2.) Metro Homes was informed to complete by 12/22/20. Not done as of last inspection. Metro Homes was reminded on 1/29/21, 3/2/21, 3/26/21, 4/7/21 3.) Metro Homes was informed to complete by 12/22/20. Not done as of last inspection. Metro Homes was reminded on 1/29/21, 3/2/21, 3/26/21, 4/7/21						
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No		
Current Condition:	Good Condition:	1 3 2 2	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1	1		
Janoni Jonation.	156th and Bennington Blvd						
spector Signature:	meh Heyburl			Reviewed By:	Get Su		