E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Manager

Engineering Answers

		E&A- P200					
		Lot 195 P200	05.030.0	024			
Inspector: Bryce Wright						Stage	
		TI	he Her	ritage		2	
Project Name:		N	IER11	0495		2	
For Week Ending:	6/12/2021						
	East of 156th S	East of 156th Street, North and South of Rainwood Road - Bennington, NE					
Project Location:	(Douglas County)					68007	
Grading:	10	00%		<u> </u>	<u> </u>		
Sanitary Sewer:		00%					
Storm Sewer:		00%					
Paving:		00%					
Seeding:		00%					
Utilities:		00%					
Overall Development:		98%					
	1	<u> </u>		<u></u>	T		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected		Weather Conditions	Time		
Sunday:	0.00"					Week 1	
Monday	0.07"	5/24/2	2021	Sunny 81	2:30 PM		
Tuesday	0.00"	3/24/2	2021	Sullily 61	2.30 F W		
Wednesday	0.00"						
Thursday	1.11"	5/27/2	2021	Overcast 62	7:45 AM		
Friday	0.00"	3/2//2	2021	Overcast 62	7.45 AW		
Saturday	0.00"					Week	
Sunday:	0.01"					Week	
Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.00"						
Thursday:	0.00"						
Friday:	0.00"						
Saturday:	0.00"						
Sunday:	0.00"					Week	
Monday	0.00"	6/7/2	021	Sunny 85	1:45 PM		
Tuesday	0.00"	0/1/2	021	Julily 63	1.43 FW		
Wednesday	0.00"						
Thursday	0.00"						
Friday	0.65"	6/11/2	2021	Partly Cloudy 73	2:25 PM		
Saturday	0.00"	5,11/2		rainy cloudy 10	2.20		
- Catal day	10.00	I		1	ı		
	None						

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site, grading completed 7/2006 and site seeded 9/5/06. Grading began on old school site east of Stargrass Road (11/9/17). Grading activity on site idle (9/9/20).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site, grading completed 7/2006 and site seeded 9/5/06. Grading began on old school site east of Stargrass Road (11/9/17). Grading activity on site idle (9/9/20).

What temporary or permanent stabilization measures listed in this section are being implemented?

Wetlands Mitigation Seeding (5/31/06), Slopes Seeded/Matted (8/30/06), Temp. Seeded (9/5/06), Re-Seeded 5/21/07, Re-Seeded ROW on 9/5/07 & 11/14/07, Erosion seeded in various areas (4/09), Old Basin 5 was seeded and matted (5/2/12). The areas that were disturbed when SB 3 and 5 were closed has been seeded (9/10/16/). Area surrounding SB#4 has been seeded (5/22/18). Stub road at the end of N 149th Street seeded and matted (9/8/20).

Checklist Questions

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Nο

Create Corrective Action?

No - See BMP Section (Lot 22)

Are construction entrances and adjacent streets being maintained adequately?

No

Create Corrective Action?

No - See BMP section

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

1. Site is active for home building.

2. SB 4 is being partially closed to accommodate the dirt from the grading of the new area as of 11/9/17. The inspector will continue to monitor its effectiveness. The surrounding area is primarily built out so the remaining basin can accommodate the flow coming from the adjacent lots. The basin was working effectively as of the 8/13/18 inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

Some maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
		Intersection of					
		Rosewood and					
CE 1	Construction Entrance	Rainwood Road	11/21/2017	Pending	No		
Current Condition:	Pending - The inspector will	Pending - The inspector will recommend an entrance if it becomes necessary as of the 11/21/2017 inspection.					
CW 1	Concrete Washout	Lot 20	Removed				
Current Condition:	Removed - Boyer Young clea	aned out and removed	the concrete washout prior	to the 9/26/15 insp	ection.		
CW 2	Concrete Washout	Lot 162		Removed			
Current Condition:	Removed - Boyer Young clea	aned out and removed	the concrete washout prior	to the 9/26/15 insp	ection.		
		Rosewater Prky and					
IF 1	Inlet Filter	Chicory St.		Removed			
Current Condition:	Removed - E&A inspector re	Removed - E&A inspector removed the inlet filter during inspection on 4/15/17.					
Lot 17	Individual Lot	Lot 17		Removed			
Current Condition:	Removed - Metro Homes s	Removed - Metro Homes sodded the lot prior to the inspection on 6/11/21.					
Lot 18	Silt Fence	Lot 18		Removed			
Current Condition:	Removed - Gene Bramhill so	Removed - Gene Bramhill sodded the lot prior to the inspection on 6/19/20.					
Lot 20	Individual Lot	Lot 20	10/12/2020	Active	No		
Current Condition:	Fair Condition - Story Homes installed silt fence and wattles on the sides and front of the lot prior to the inspection on 10/12/20. Story Homes began excavating the lot prior to the inspection on 10/26/20. Story Homes removed the dirt/sand piles from the ROW prior to the inspection on 11/10/20. Story Homes removed all BMPs on the lot prior to the inspection on 5/3/21. Due to the grade of the lot no BMPs are needed at this time. E&A inspector will continue to monitor.						
Lot 22	Individual Lot	Lot 22	11/24/2020	Active	No		
Current Condition:	Active - Metro Homes began excavating the lot prior to the 11/24/20 inspection. A dirt pile was observed in the ROW during the 11/24/20 inspection. Due to the lot being mostly flat during the 11/24/20 inspection no BMP recommendation is needed at this time. E&A inspector will continue to monitor for BMP installation. Metro Homes removed the dirt pile from the ROW, and the concrete waste prior to the inspection on 1/28/21. Metro Homes removed the dirt pile from the ROW prior to the inspection on 4/19/21.						
	u p	non to the mopeothern on	·/ · · · · ·				

Current Condition:	Fair Condition - Story Homes installed silt fence on the sides of the lot prior to the inspection on 10/12/20. Story Homes installed a portable toilet on the southeast corner of the lot prior to the inspection on 1/14/21, the portable toilet is secured. Story Homes removed the portable toilet from the lot prior to the inspection on 2/15/21. Story Homes placed a portable toilet on the lot prior to the inspection on 3/1/21. Story Homes removed the dirt pile from the ROW prior to the inspection on 4/19/21. 1.) The silt fence on the south side of the lot should be reinstalled . 2.) The portable toilet should be secured. 3.) The silt fence on the north side of the lot should be cleaned out/repaired. 1.) Story Homes was informed to complete by 2/4/21. Not done as of the last inspection. Story Homes was reminded on 3/2/21, 3/26/21, 4/7/21, 6/12/21 2.) Story Homes was informed to complete by 3/8/21. Not done as of the last inspection. Story Homes was reminded on 3/26/21, 4/7/21, 6/12/21 3.) Story Homes was informed to complete by 4/14/21. Not done as of last inspection. Story Homes was reminded					
Lot 25	on 6/12/21 Individual Lot	Lot 25		Removed		
Current Condition:	Removed - Metro Homes s		the inspection on 6/11/2		l	
			· · · · · · · · · · · · · · · · · · ·			
Lot 62	Individual Lot	Lot 62		Removed		
Current Condition: Lot 65	Removed - Huntington Home Individual Lot	es sodded the lot prior t	o the inspection on 4/28/20 I	Removed		
Current Condition:	Removed - Huntington Home		the inspection on 4/28/20			
	ĭ	· ·	o and mapedaon on 4/20/20			
SF 6	Silt Fence	SB 5		Removed		
Current Condition:	Removed - Commercial See		nce prior to the 10/9/18 ins	•		
SF 7	Silt Fence Removed - SF 7 changed to	SB 3	d C) F (4 F (4 C	Removed		
Current Condition: SF 8	Ů.	,	a 6) as of 5/15/18.	Damaria		
Current Condition:	Silt Fence	Rainwood Road	in front of Doinwood Dood	Removed	6 Cilt Fanca was	
Current Condition:	Removed - Boyer Young installed a silt fence check in front of Rainwood Road prior to 11/23/2016. Silt Fence was repaired prior to the 8/13/18 inspection. Boyer Young removed the silt fence prior to the 10/23/18 inspection.					
SF 9 Current Condition:	The perimeter of the newly graded area Fair Condition - The silt fence was repaired by Commercial Seeding prior to the inspection on 4/5/18. Commercial Seeding installed silt fence around the existing dirt stock pile prior to the inspection on 3/5/18. The silt fence in the SE corner was repaired prior to inspection on 4/27/18. Silt fence was repaired and sediment was cleaned up from adjacent lots prior to the 8/13/18 inspection. Commercial Seeding repaired and cleaned out the silt fence prior to the 11/6/18 inspection. Commercial Seeding backfilled and repaired the silt fence prior to the 6/24/19 inspection. E&A inspector retied the silt fence where it was damaged during the 8/12/19 inspection. Jerry Banks repaired/cleaned out/trenched in the silt fence in multiple locations prior to the inspection on 6/10/20. Centennial Enterprises trenched in and backfilled the undermined silt fence prior to the inspection on 8/11/20. 1.) Silt fence is damaged in multiple locations along the run and should be repaired/retied. 2.) The northern run of this silt fence needs to be reinstalled. 1.) Jerry Banks and Centennial Enterprises will be informed to complete when weather conditions allow. Mark Hopkins was informed to complete as weather conditions allow 3/5/21. Not done as of the last inspection. JBG was informed					
	to complete by 6/14/21. 2.) JBG was informed to complete by 6/14/21.					
		South of Wild Indigo				
SB 3	Sediment Basin	St and Prairie Star St.		Removed		
Current Condition:	Removed - The basin was cl	losed prior to the 8/24/1	6 inspection.		•	
	0.11.	South of 149th Dead	44/44/			
SB 4	Sediment Basin	End Enterprise class	11/14/2005	Active	No Duetie Deth	
Current Condition:	Good Condition- 41% Filled - Roth Enterprise cleaned off the risers prior to the 7/7/16 inspection. Dustin Roth removed southern riser and removed dirt to restore drainage prior to inspection on 7/2/18.					
SB 5	Sediment Basin	Southwest corner of Rosewater Pkwy and North H.W.S Cleveland Blvd		Removed		
Current Condition:	Removed - The basin was cl	losed prior to the 8/24/1	6 inspection.			
STR	Street Cleaning	Entire Site	2/26/2007	Active	Yes	
	<u> </u>					

Current Condition:

Fair Condition - CBS Homes cleaned the streets in front of Lot 26 prior to inspection on 6/20/18. Streets were clean during the 9/18/18 inspection. Street was cleaned in front of lot 38 prior to the 10/23/18 inspection. Streets were covered in snow during the 2/19/19 inspection, street cleaning recommendations will remain on the report until the inspector can verify if any street cleaning activities have occurred. Minor street cleaning was performed in front of lots 60, 61, and 66 by plowing activities or by Legacy Homes prior to the 3/5/19 inspection, sediment is still present along the curb line. Legacy Homes cleaned the curb line prior to the 5/7/19 inspection, minor sediment is present in front of lots 38 and 39, inspector will continue to monitor. Brookstone Development cleaned the street in front of lot 44 prior to the 10/22/19 inspection. Metro Homes cleaned the street in front of Lot 17 prior to the inspection on 5/27/20. Metro Homes cleaned the street in front of Lot 17 prior to the inspection on 11/10/20.

- 1.) The street in front of lot 20 should be cleaned.
- 2.) The street in front of lot 25 should be cleaned.
- 3.) The street in front of lot 22 should be cleaned.
- 4.) The street in front of lot 17 should be cleaned.
- 5.) The street in front of lot 24 should be cleaned.
- 1.) Story Homes was informed to complete by 10/27/20. Not done as of last inspection. Story Homes was reminded on 12/22/20, 1/29/21, 3/2/21, 3/26/21, 4/7/21
- 2.) Metro Homes was informed to complete by 12/22/20. Not done as of last inspection. Metro Homes was reminded on 1/29/21, 3/2/21, 3/26/21, 4/7/21
- 3.) Metro Homes was informed to complete by 12/22/20. Not done as of last inspection. Metro Homes was reminded on 1/29/21, 3/2/21, 3/2/21, 4/7/21
- 4.) Metro Homes was informed to complete by 12/22/20. Not done as of last inspection. Metro Homes was reminded on 1/29/21, 3/2/21, 3/2/21, 4/7/21
- 5.) Story Homes was informed to complete by 4/26/21. Not done as of last inspection.

		Replat 6				
CE 1	Construction Entrance	East edge of site	5/27/2021	Pending	Yes	
Current Condition:	Pending-					
	Construction entrance need JBG was informed to com		e southwest corner of	the site.		
D 1	Diversion Ditch	South of SB 4	5/27/2021	Pending	No	
Current Condition:	Pending- Diversion will be installed during grading.					
SF 1	Silt Fence	East edge of site	5/27/2021	Active	No	
Current Condition:	Good Condition- Mark Hopkins installed prior to the inspection on 5/27/21.					
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No	
Current Condition:	Good Condition: 156th and Bennington Blvd			•	•	
Inspector Signature:	Braga M Waght			Reviewed By:	St Se	