E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Mana	ager			Engineering An	swers		
-		E&A- P2017.41	1.001				
Inspector: Patrick Sechser					Stage		
Project Name:	The Villas at Piney Creek OMA-20160711-03678 CSW-201600546			1			
For Week Ending:	5/26/2018						
Project Location:	202nd Street and Blondo Parkway, Omaha, NE (Douglas County) 68022						
Crading	80%	1		1 1			
Grading: Sanitary Sewer:	50%						
Storm Sewer:	50%						
Paving:	50%						
Seeding:	82%						
Utilities:	50%						
Overall Development:	20%						
	1	1	1				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions				
					Week 1		
Sunday:	0.08"						
Monday	0.00"						
Tuesday	0.47"	05/22/18	84/60 Cloudy				
Wednesday	0.01"						
Thursday	0.00"						
Friday	0.00"						
Saturday	0.00						
Complaints:		T		T			
CONSTRUCTION SEQUENCING:							
Which portion(s) (i.e. drainage basins) of the	ne site have had a temporar	y or permanent cessation	on of grading, earthwork, or gro	ound disturbance in the la	st 14 days?		
Grading activities began in the Summer/Fall of 2016 by Ruff Grading. Major grading activities have ceased in the Summer of 2017 on site.  Minor grading to be completed at a later time in drainage areas A1-A0.2 due to lot level construction (10/2/2017).  Drainage basins A0.3, A2, A0.4 and B1 were inactive (10/2/2017).							
Which portion(s) (i.e. drainage basins) of the	ne site do not have grading,	earthwork, or ground of	disturbance scheduled in the ne	ext 14 days?			
Grading activities began in the Summer/Fall of 2016 by Ruff Grading. Major grading activities have ceased in the Summer of 2017 on site.  Minor grading to be completed at a later time in drainage areas A1-A0.2 due to lot level construction (10/2/2017).  Drainage basins A0.3, A2, A0.4 and B1 were inactive (10/2/2017).							
W	P. C. A. C.		11.10				
What temporary or permanent stabilization measures listed in this section are being implemented?  Existing Vegetation (2016); Both sides of project were seeded and erosion control blanket installed (2017); Right-of Ways were seeded on west side of project (10/2/2017); NW slope was re-matted and seeded due to erosion (10/19/2017).							
SUMMARY QUESTIONS:							
Are approved entrances and adjacent streets being maintained adequately?							
No. See BMPs  Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?							
Yes	or moo or any organicant org				· ·		
CHECKLIST QUESTIONS:							
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?							
Yes Is dust associated with the construction activity adequately controlled on the site?							
Yes	adoquatery controlled	. c the one:					
Comments:	•	•	•				
Comments:							
East side of the site remains idle. Home construction is continuing on the west side of the project.							

Findings / Corrective Actions (Da	ate):						
Findings / Corrective Actions (Date	•						
1.) Some maintenance is required i							
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CD1-14	Wattles	Site	9/7/2016	Active	No		
Current Condition:			&A will verify other wattles	and necessity as v	vork progresses.		
	CD 1-10 are presently	not needed based on lo	t level construction.				
		T					
CE-1 Current Condition:	Entrance	Blondo Parkway		Removed			
Current Condition:	Removed- Entrance w	as removed and paved	prior to 10/2/2017 inspection	on.			
CE-2	Entrance	Blondo Parkway-East	9/7/2016	Active	No		
Current Condition:			as installed prior to 10/2/20				
	Entrance remains inac		<b>,</b>	.,	<b>.</b>		
CW-1	Concrete washout	West side of project		Removed			
Current Condition:	Removed- Washout p	it was removed prior to	10/2/2017.				
CW 2	Concrete weekent	Foot side of project	E/1/0010	Donding	No		
CW-2 Current Condition:	Concrete washout	East side of project	5/1/2018 ern phase prior to road pav	Pending ing operations	No		
Current Condition.	Pending- washout wii	i de ilistalleu ili tile east	em phase phor to road pav	ing operations.			
Diversion Ditches 1-24	Diversion Ditches	Site	9/7/2016	Active	No		
Current Condition:			installed prior to the inspec				
			ation is mowed back. DD1,				
	during the first inspect	ion by E&A. E&A will co	ntinue to monitor. Other div	ersion ditches wer	e removed for lot		
	level construction.						
		000 - 1 01 1 000 - 1					
Inlet Filters	Inlet Filters	202nd Street, 202nd Avenue	10/25/2017	Active	Yes		
Current Condition:	Fair Condition-	Avenue	10/23/2017	Active	165		
Surront Sonation.	r dir Gorialdion						
	Inlet filters need to b	e cleaned and pulled o	ut of the curb inlets.				
	Terri Krasne was info	ormed to complete by	5/29/2018.				
1 -+ 20	0:14 =====	000-4 044	40/05/0047	A =41:=	N.		
Lot 30  Current Condition:	Silt Fence	202nd Street	10/25/2017 x prior to 10/25/2017. Lot i	Active	No RA will continue to		
ourient condition.		ence installation on the fr	•	s presently flat. Lt	XA WIII CONTINUE TO		
	Informed flood for our fo	moo motaliation on the h	one.				
Lot 31	Silt Fence	202nd Street	3/15/2018	Active	No		
Current Condition:	Active- Lot was excava	ated by Steve Champou	x prior to 3/15/2018. Lot is	presently flat. E&	A will continue to		
	monitor need for silt fe	nce installation on the fr	ont. Dirt was removed from	the ROW prior to	4/12/2018.		
Lot 33	Silt Fence	202nd Avenue	10/9/2017	Active	Yes		
Current Condition:	Active-	Zozna / Wenae	10/0/2017	7101170	103		
	7 10.17 0						
	Due to the lot being fine graded, the lot can be sodded.						
			lete by 5/9/2018. Not done	as of the last inspe	ection. Developer		
	Terri Krasne was remi	nded on 5/16/2018 on s	ite.				
Lot 43	Silt Fence	Miami Circle		Removed			
Current Condition:		ne sodded the lot prior	to 5/22/2018.	110.110104			
Lot 44	Silt Fence	Miami Circle		Removed			
Current Condition:		ne sodded the lot prior	to 5/22/2018.	TOMOVOU			
Lot 45	Silt Fence	Miami Circle	1. 5100100.11	Removed			
Current Condition:	Removed-Terri Krası	ne sodded the lot prior	to 5/22/2018.				
Lot 46	Silt Fence	Miami Circle	3/15/2018	Active	No		
Current Condition:			x prior to 3/15/2018. Lot is ont. Dirt was removed from				
	Informor fieed for sill le	moo motaliation on the H	one pur was removed fioli	NOVV PITOT LO	., 12,2010.		

	Stream Outlet Rip							
RR-1-2	Rap	Drainage way	9/7/2016	Active	No			
Current Condition:	pending once outfall is	Good Condition- Rip rap 1 was installed prior to 10/2/2017 inspection. E&A will continue to monitor. RR 2 is pending once outfall is installed from outfall #3.						
RW-1-8	Rock Weirs	Site	9/7/2016	Active	No			
Current Condition:	5 have been removed	·	or to 10/2/2017 inspection n 10/2/2017. RW 6-8 will					
EOD 4.45	Erosion Control	0.11	0/7/0040	A . C				
ECB-1-15 Current Condition:	Blanket	Site	9/7/2016	Active	No No Povolonor Stove			
	Champoux.	·						
Silt Fence 1-4 Current Condition:	Silt Fence	West side of project	9/7/2016  n the west side & repaired	Active	Yes			
Silt Fence 5-10 Current Condition:  Sediment Basin 1 Current Condition:	202nd Avenue on lot 8 by the Developer Steve 3/2/2018. SF #2 from to segretation and silt fence Silt fence checks need Terri Krasne was information of the segretation of the segretatio	Replat 1; Silt fence #4 e Champoux. E&A inspethe SWPPP sign to the roce checks #4 were repaired to be added by the substitution of the complete by Substitutio	9/7/2016 talled by Developer Steve 11/29/2017. E&A inspecto 9/7/2016 ex device was installed pr	e to undercutting SF to the posts during to moved due to the enamercial Seeding proof on 2012nd Ave.  Active Champoux prior to per retied the silt fencion of the control o	prior to 10/19/2017 he inspection on stablishment of ior to 4/12/2018.  No 10/19/2017. SF 10 he to the posts durin			
		npoux. SRR 4-6 are in p	lace on the slopes. Riser					
Sediment Basin 2	Sediment Basin	East side-Central	9/7/2016	Active	No			
Current Condition:	Developer Steve Char	Good Condition- 28% full- Basin and Anti-vortex device was installed prior to 10/2/2017 inspection by Developer Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, and repaired where it was undermined prior to 5/11/2018.						
Sediment Basin 3	Sediment Basin	East side	9/7/2016	Active	Yes			
Current Condition:	to 10/2/2017.  Sediment Basin needs  Developer Steve Char  Developer Steve Char  Krasne was reminded	to be installed per plan npoux was informed to on npoux was reminded on on 3/28/2018, 4/3/18, 5/		ex device, outfall and ot done as of the las 11/21/2017, 1/30/20	d rip rap per plan. st inspection. 018, 2/27/2018. Ter			
Sediment Trap 1	Sediment Trap	SW corner	9/7/2016	Active	No			
Current Condition:	Good Condition-20% f SRR 1 & 2 are in place		orior to 10/2/2017 inspecti	on by Developer Ste	eve Champoux.			
Sediment Traps 2-8	Sediment Trap	Site	9/7/2016	Active	No			
Current Condition:		•	en removed for developminspection on 10/2/2017.					
SRR-1-12	Slope Outlet Rip Rap	Site	9/7/2016	Active	Yes			
Current Condition:	Fair Condition- Rip rap currently missing or ne SRR 12 needs to be in	p. 1,2, 4-8, 10-11 were in: eed to be verified. estalled per City's prior re	equest.	inspection. Rip rap	3, 9 and 12 are			
	done as of last inspect	ion. Terri Krasne was re	2018, specifically when grain and a specifically when grain are specifically are s	18.	<u> </u>			
STR	Streets	Site	9/7/2016	Active	Yes			

Current Condition:	Fair Condition-	Fair Condition-				
	Streets need to be cl	Streets need to be cleaned on the west side of the project.				
	Terri Krasne was info	Terri Krasne was informed to complete by 5/23/2018.				
SWPPP Sign	Misc./Other	Blondo Parkway	10/9/2017	Active	No	
Current Condition:	Good Condition- 2 SW	Good Condition- 2 SWPPP signs were installed by the entrances prior to 10/19/2017 by E&A.				
Inspector Signature:	Get Sur			Reviewed By:	Pette SVain	