E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. Man	ager			Engineering An	swers		
		E&A- P2017.41	1.001		_		
Inspector: Patrick Sechser					Stage		
Project Name:	The Villas at Piney Creek OMA-20160711-03678 CSW-201600546				1		
For Week Ending:							
Project Location:	202nd Stre	County)	68022				
Grading:	80%	<u> </u>					
Sanitary Sewer:	50%						
Storm Sewer:	50%						
Paving:	50%						
Seeding:	82%						
Utilities:	50%						
Overall Development:	20%						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions				
	0.000				Week 1		
Sunday: Monday	0.03" 0.00"						
Tuesday	0.04"						
Wednesday	0.00"	8/29/2018	Partly Sunny 76/62				
Thursday	0.00"	0/23/2010	1 artiy Guilly 7 G/G2				
Friday	0.03"						
Saturday	0.26"						
CONSTRUCTION SEQUENCING: Which portion(s) (i.e. drainage basins) of the	ne site have had a temporar	y or permanent cessation	on of grading, earthwork, or grou	nd disturbance in the la	st 14 days?		
Grading activities began in the Summer/Fall of Minor grading to be completed at a later time in Drainage basins A0.3, A2, A0.4 and B1 were in	n drainage areas A1-A0.2 due	•		e.			
Which portion(s) (i.e. drainage basins) of the	ne site do not have grading,	earthwork, or ground d	listurbance scheduled in the next	14 days?			
Grading activities began in the Summer/Fall of 2016 by Ruff Grading. Major grading activities have ceased in the Summer of 2017 on site.  Minor grading to be completed at a later time in drainage areas A1-A0.2 due to lot level construction (10/2/2017).  Drainage basins A0.3, A2, A0.4 and B1 were inactive (10/2/2017).							
What temporary or permanent stabilization	measures listed in this sec	tion are being impleme	nted?	1			
Existing Vegetation (2016); Both sides of proje was re-matted and seeded due to erosion (10/		control blanket installed (2	017); Right-of Ways were seeded o	n west side of project (10	/2/2017); NW slope		
OLIMARY OUESTICALS					·		
SUMMARY QUESTIONS: Are approved entrances and adjacent stree	ate heing maintained adequa	ately?					
No	Joing mannamed adequa	y .					
Are receiving waters adjacent to the project	ct free of any significant sig	ns of erosion or sedime	ent that would be associated with	the construction activi	ty?		
Yes		<u> </u>		<del></del>			
CHECKLIST QUESTIONS:		l					
Are waste materials (concrete, construction	n material, hazardous, etc.)	being managed properl	v?				
Yes		gagea propert	<i>y</i> :				
Is dust associated with the construction activity adequately controlled on the site?							
Yes		1					
0							
Comments:							
Comments:		uniona and the construction					
East side of the site remains idle. Hor	he construction is contin	iuirig on the west side	e or the project.				

- Findings / Corrective Actions (Date):
  Findings / Corrective Actions (Date):
  1.) Some maintenance is required in the BMP section.
- 2.) City Inspection Report #7916 was received and forwarded to Developer Terri Krasne on 7/31/2018. (See BMP section for additional details). CIR 8037 was received on 8/21/2018 and forwarded to Developer Terri Krasne on 8/22/2018 for continued compliance.

Unique Name	Type	Location	Projected Install Date	Status	Mainten		
CD1-14	Wattles	Site	9/7/2016	Active	No		
Current Condition:		I is in place currently. E not needed based on lo	E&A will verify other wattles of level construction.	and necessity as v	ork progres		
CE-1	Entrance	Blondo Parkway		Removed			
Current Condition:	Removed- Entrance was removed and paved prior to 10/2/2017 inspection.						
CE-2	Entrance	Blondo Parkway-East		Active	No		
Current Condition:	Good Condition-70% functioning- Entrance was installed prior to 10/2/2017 inspection by Ruff Grading. Entrance remains inactive as of 3/16/2018.						
CW-1	Concrete washout	West side of project		Removed			
Current Condition:	Removed- Washout p	it was removed prior to	10/2/2017.				
CW-2	Concrete washout	East side of project	5/1/2018	Pending	No		
Current Condition:			ern phase prior to road pav		INO		
Diversion Ditches 1-24	Diversion Ditches	Site	9/7/2016	Active	No		
Current Condition:	E&A will continue to ve	erify ditches once vegeta	installed prior to the inspectation is mowed back. DD1, intinue to monitor. Other div	part of DD2, DD1	3-DD24 were		
Inlet Filters	Inlet Filters	202nd Street, 202nd Avenue	10/25/2017	Active	Yes		
Current Condition:		ters were cleaned out by filters prior to 7/28/2018	y Commercial Seeding prior	r to 5/30/2018. Cor	nmercial Sec		
		med to complete by 6/13 8, 7/10/2018, 7/31/2018	3/2018. Not done as of the 8/22/2018.	last inspection. Tel	ri Krasne wa		
Lot 7	Silt Fence	North 202nd Avenue		Active	No		
Current Condition:	Active- Lot was excavated by Terri Krasne prior to 8/1/2018. Lot is presently flat. E&A will continue to moneed for silt fence installation on the front.						
Lot 8	Silt Fence	North 202nd Avenue	8/15/2018	Active	Yes		
Current Condition:	Active- Lot was excavated by Terri Krasne prior to 8/15/2018. Lot is presently flat. E&A will continue to meed for silt fence installation on the front.						
	Dirt needs to be removed from the ROW.						
	Developer Terri Krasne was informed to complete by 9/5/2018.						
1 ct 00	0:4.5	200-4 04 4		Demand			
Lot 30 Current Condition:	Silt Fence Removed- Terri Krasn	202nd Street e sodded the lot prior to	7/19/2018 and cleaned the	Removed curb line.			
Lot 31	Silt Fence	202nd Street	3/15/2018	Active	No		
Current Condition:			x prior to 3/15/2018. Lot is ront. Dirt was removed from				
Lot 32	Silt Eanga	202nd Avenue		Pomovod			
Lot 33  Current Condition:	Silt Fence Removed- Terri Krasn	e sodded the lot prior to	7/19/2018.	Removed	1		
		1					
Lot 34	Individual Lot	202nd Avenue	6/2/2018	Active	No		
	ii luiviuuai LUl	ZUZIIU AVEIIUE	5/2/2010	/JOHNE	INO		

Current Condition:		ated by Terri Krasne pric	or to 6/2/2018. Due to the longe to monitor.	ot being mostly flat,	E&A will monitor		
Lot 43	Silt Fence	Miami Circle		Removed			
Current Condition:		e sodded the lot prior to	5/22/2018.				
		· · · · · · · · · · · · · · · · · · ·	T	1	ı		
Lot 44	Silt Fence	Miami Circle		Removed			
Current Condition:	Removed-Terri Krasno	e sodded the lot prior to	5/22/2018.				
Lot 45	Silt Fence	Miami Circle	1	Removed	I		
Current Condition:		e sodded the lot prior to	5/22/2018	Removed			
Current Condition.	Removed-Terri Klasii	s souded the lot phor to	5/22/2016.				
Lot 46	Silt Fence	Miami Circle	3/15/2018	Active	No		
Current Condition:			x prior to 3/15/2018. Lot is	presently flat. E&	A will continue to		
			ront. Dirt was removed from				
		T	1	1			
Lot 47	Silt Fence	Miami Circle	5/30/2018	Active	Yes		
Current Condition:	Fair Condition-						
	Damaged silt fence in	the rear needs to be rep	paired.				
	Developer Terri Krasn	e was informed to comp	lete by 8/7/2018. Not done	as of the last inspe	ection. Devleoper		
	Terri Krasne was remi	inded on 8/22/2018					
			1		I		
				_			
Lot 48	Silt Fence	Miami Circle	5/30/2018	Active	No		
Current Condition:	Good Condition- Lot w	vas excavated by Terri K	Trasne prior to 5/30/2018. [	Oue to silt fence in	the rear for		
	perimeter controls, E8	A will continue to monito	or need for additional silt fe	nce.			
			T				
1 - 1 40	0:11 5	Min of Ottal	7/10/0010	A . C .	N		
Lot 49	Silt Fence	Miami Circle	7/19/2018	Active	No		
Current Condition:			or to 7/19/2018. Due to a b				
	continue to monitor ne	ed for additional silt fend	ce. Dirt was removed from	the ROW by Terri I	Krasne prior to		
	8/8/2018. Due to the le	ot being flat and backing	to a basin, BMPs are pres	ently not needed.	E&A will monitor.		
		9 9	, , , , , , , , , , , , , , , , , , , ,	,			
	Stream Outlet Rip						
RR-1-2	Rap	Drainage way	9/7/2016	Active	No		
Current Condition:	Good Condition- Rip r	ap 1 was installed prior t	to 10/2/2017 inspection. Ea	&A will continue to	monitor. RR 2 is		
	pending once outfall is	s installed from outfall #3	3.				
DW 4.0	Daali Maire	0:4-	0/7/0040	Λ -4:	l M-		
RW-1-8	Rock Weirs	Site	9/7/2016	Active	No		
Current Condition:		· ·	ior to 10/2/2017 inspection.				
	5 have been removed	prior to the inspection or	n 10/2/2017. RW 6-8 will b	e verified during the	e next inspection		
			1	1	1		
	Erosion Control						
ECB-1-15	Blanket	Site	9/7/2016	Active	No		
Current Condition:	Good Condition- Eros	ion Control Blanket has I	been installed on the site p	rior to 10/2/2017 by	y Developer Stev		
	Champoux.						
Silt Fonce 1 4	Silt Fence	West side of project	0/7/2016	Activo	No		
Silt Fence 1-4		West side of project	9/7/2016	Active	No		
Current Condition:			on the west side & repaired	•	•		
	reinstalled by SB 1; SF #2 and #3 was reinstalled to the east of lot 39; Silt fence was entrenched to the north						
	202nd Avenue on lot 8, Replat 1; Silt fence #4 by RR1 was repaired due to undercutting SF prior to 10/19/20						
	by the Developer Steve Champoux. E&A inspector retied the silt fence to the posts during the inspection on						
	3/2/2018. SF #2 from the SWPPP sign to the main drainageway was removed due to the establishment of						
	vegetation and silt fence checks #4 were repaired and extended by Commercial Seeding prior to 4/12/2018. S						
	_	·	walk to capture runoff on 2				
		•	west SWPPP sign to the we		•		
	_		on prior to 6/2/2018. Silt fen	-	-		
	prior to 8/8/2018 by Co	_	III prior to orzizo io. Ont ich	So diving Zuzilia AV	chac was repair		
	prior to 6/6/2016 by Co	Jimilercial Seeuling					
Silt Fence 5-10	Silt Fence	East side of project	9/7/2016	Active	No		
		<u> </u>					
Current Condition:		inspector retied the silt fe	ence to the posts along Blo	nuo Parkway durin	y the inspection		
	7/26/2018.						
Sediment Pasin 1	Sediment Pasin	West side entrance	0/7/2016	Activo	No		
Sediment Basin 1	Sediment Basin	West side-entrance	9/7/2016	Active	No No Povole		
Current Condition:			ex device was installed pric		•		
			e slopes. Riser is beginning	, to become underr	nıned. E&A will		
	continue to monitor as	ot 3/15/2018.					
0 "		T =	1		T		
Sediment Basin 2	Sediment Basin	East side-Central	9/7/2016	Active	No		

Current Condition:	Good Condition- 31% full- Basin and Anti-vortex device was installed prior to 10/2/2017 inspection by Developer Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, and repaired where it was undermined prior to 5/11/2018.					
Sediment Basin 3	Sediment Basin	East side	9/7/2016	Active	No	
Current Condition:	to 10/2/2017. Sedimen rip rap per plan. Develo functioning as a sediment	t Basin still needs to be oper Terri Krasne was re	ne slopes, although SRR 1. installed per plan, includin eminded to complete once and area is heavily vegetaea.	g riser, anti-vortex grading begins in	device, outfall and area. Basin is	
Sediment Trap 1	Sediment Trap	SW corner	9/7/2016	Active	No	
Current Condition:	Good Condition-20% full- Trap was installed prior to 10/2/2017 inspection by Developer Steve Champoux. SRR 1 & 2 are in place on the slopes.					
Sediment Traps 2-8	Sediment Trap	Site	9/7/2016	Active	No	
Current Condition:	Good Condition- Sediment Traps 2-5 have been removed for development on the west side. ST 6-8 have been installed prior by Steve Champoux prior to the inspection on 10/2/2017. E&A will monitor area due to extensive vegetation.					
SRR-1-12	Slope Outlet Rip Rap	Site	9/7/2016	Active	No	
Current Condition:	Fair Condition- Rip rap 1,2, 4-8, 10-11 were installed prior to 10/2/2017 inspection. Rip rap 3, 9 and 12 are currently missing or need to be verified. SRR 12 needs to be installed per City's prior request. Developer Terri Krasne was reminded to complete rip rap once grading begins in area. Basin is functioning as a sediment trap as of 7/27/2018 and area is heavily vegetated. BMP will be monitored and added as needing maintenance once work begins area.					
STR	Streets	Site	9/7/2016	Active	Yes	
Current Condition:	Fair Condition- Street cleaning is needed around North 202nd Avenue.  Terri Krasne was informed to complete by 8/23/2018. Not done as of the last inspection					
SWPPP Sign	Misc./Other	Blondo Parkway	10/9/2017	Active	No	
Current Condition:			ed by the entrances prior to			
Inspector Signature:	Got Su			Reviewed By:	Act Vien	