E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tell 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers Environmental Services Dept. Manager E&A- P2017.411.001 Inspector: Patrick Sechser Stage The Villas at Piney Creek OMA-20160711-03678 Project Name: 1 CSW-201600546 11/10/2018 For Week Ending: 68022 **Project Location:** 202nd Street and Blondo Parkway, Omaha, NE (Douglas County) Grading: Sanitary Sewer: 50% 50% Storm Sewer: Paving: 50% Seeding: 82% **Utilities**: 50% Overall Development: 20% RAIN FALL AMOUNTS Amount in tenths Date inspected Weather Conditions Week Sunday: 0.06" Monday 0.12" Tuesday 0.00" 11/08/18 Partly Sunny 36/28 Wednesday 0.00" Thursday 0.00" Friday 0.00' 0.00" Saturday Complaints: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Grading activities began in the Summer/Fall of 2016 by Ruff Grading. Major grading activities have ceased in the Summer of 2017 on site. Minor grading to be completed at a later time in drainage areas A1-A0.2 due to lot level construction (10/2/2017). Drainage basins A0.3, A2, A0.4 and B1 were inactive (10/2/2017). Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturba Grading activities began in the Summer/Fall of 2016 by Ruff Grading. Major grading activities have ceased in the Summer of 2017 on site. Minor grading to be completed at a later time in drainage areas A1-A0.2 due to lot level construction (10/2/2017). Drainage basins A0.3, A2, A0.4 and B1 were inactive (10/2/2017). What temporary or permanent stabilization measures listed in this section are being implemented? Existing Vegetation (2016); Both sides of project were seeded and erosion control blanket installed (2017); Right-of Ways were seeded on west side of project (10/2/2017); NW slope was re-matted and seeded due to erosion (10/19/2017). SUMMARY QUESTIONS Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? CHECKLIST QUESTIONS: rete, construction material, hazardous, etc.) being managed properly? Yes Yes Comments

East side of the site remains idle. Home construction is continuing on the west side of the project.

- Findings / Corrective Actions (Date):
 Findings / Corrective Actions (Date):
 1.) Some maintenance is required in the BMP section.
 2.) CIR # 8420 was received and reviewed on 10/23/2018. CIR was forwarded to Developer Terri Krasne for additional compliance.

Unique Name	Туре	Location	Projected Install Date	Status	Maintena		
CD1-14	Wattles	Site	9/7/2016	Active	No		
Current Condition:	Good Condition-CD 14 is in place currently. E&A will verify other wattles and necessity as work progresse 1-10 are presently not needed based on lot level construction.						
CE-1	Entrance	Blondo Parkway		Removed			
Current Condition:	Removed- Entrance was removed and paved prior to 10/2/2017 inspection.						
CE-2	Entrance	Blondo Parkway-East		Active	No		
Current Condition:	Good Condition-70% functioning- Entrance was installed prior to 10/2/2017 inspection by Ruff Grading. Entremains inactive as of 3/16/2018.						
CW-1	Concrete washout	West side of project		Removed			
Current Condition:		it was removed prior to 1	10/2/2017.	removed	1		
CW 2	Concrete weekent	Fact side of project	F/4/0049	Dandina	No		
CW-2 Current Condition:	Concrete washout Pending- Washout will	East side of project be installed in the easte	5/1/2018 ern phase prior to road pavir	Pending ng operations.	No		
Diversion Ditches 1-24	Diversion Ditches	Site	9/7/2016	Active	No		
Current Condition:	E&A will continue to ve during the first inspect	erify ditches once vegeta ion by E&A. E&A will con 1 has been removed for	installed prior to the inspect ation is mowed back. DD1, intinue to monitor. Other diver construction as of 9/13/201	part of DD2, DD13 ersion ditches wer	3-DD24 were		
Inlet Filters	Inlet Filters	202nd Street, 202nd Avenue	10/25/2017	Active	No		
Current Condition:	Good Condition- Inlet filters were cleaned out by Commercial Seeding prior to 5/30/2018. Commercial Seed cleaned out a few inlet filters and reset them prior to 10/17/2018.						
Lot 7	Silt Fence	North 202nd Avenue	8/1/2018	Active	No		
Current Condition:	Active- Lot was excava	•	or to 8/1/2018. Lot is presen	tly flat. E&A will o	continue to mo		
Lot 8	Silt Fence	North 202nd Avenue	8/15/2018	Active	No		
Current Condition:	Active- Lot was excava	ated by Terri Krasne pric	or to 8/15/2018. Lot is prese was removed from the ROV	ntly flat. E&A will	continue to m		
Lot 9	Silt Fence	North 202nd Avenue	9/13/2018	Active	No		
Current Condition:			or to 9/13/2018. Lot is prese				
	need for silt fence installation on the front.						
Lot 12, Replat 1	Silt Fence	North 202nd Avenue	11/1/2018	Active	Yes		
Current Condition:		at. E&A will monitor nee					
	Dirt needs to be removed from the ROW.						
	Terri Krasne was informed to remove the dirt by 11/8/2018. Not done as of the last inspection.						
Lot 29	Silt Fence	202nd Street	11/1/2018	Active	Yes		
Current Condition:	Active- Lot is mostly fla	at. E&A will monitor nee	ed for BMPs.				
	Dirt needs to be removed from the ROW.						
	Terri Krasne was informed to remove the dirt by 11/8/2018. Not done as of the last inspection.						
				_			
Lot 30 Current Condition:	Silt Fence Removed- Terri Krasn	202nd Street e sodded the lot prior to	7/19/2018 and cleaned the	Removed curb line.			
		to					

Current Condition:			ont. Dirt was removed from				
Lot 32	Silt Fence	North 202nd Street	9/13/2018	Active	No		
Current Condition:			r to 9/13/2018. Lot is preshout debris and the curb				
Lot 33	Silt Fence	202nd Avenue		Removed			
Current Condition:		ne sodded the lot prior to	7/19/2018.				
Lot 34	Individual Lot	202nd Avenue	6/2/2018	Active	No		
Current Condition:	Active- Lot was excav		r to 6/2/2018. Due to the lue to monitor.		E&A will monitor		
Lot 25	Silt Fence	North 202nd Avenue	11/1/2019	Activo	Voc		
Lot 35 Current Condition:		North 202nd Avenue at. E&A will monitor nee	11/1/2018 d for BMPs.	Active	Yes		
	Dirt needs to be removed from the ROW.						
	Terri Krasne was info	rmed to remove the dirt b	y 11/8/2018. Not done as	s of the last inspecti	on.		
Lot 36	Silt Fence	North 202nd Avenue	11/1/2018	Active	Yes		
Current Condition:	Active- Lot is mostly fl	at. E&A will monitor nee	d for BMPs.				
	Dirt needs to be removed from the ROW.						
	Terri Krasne was info	rmed to remove the dirt b	y 11/8/2018. Not done as	s of the last inspecti	on.		
Lot 43	Silt Fence	Miami Circle	10010040	Removed			
Current Condition:		e sodded the lot prior to 5	0/22/2016.	Domested			
Lot 44 Current Condition:	Silt Fence Removed-Terri Krasn	Miami Circle e sodded the lot prior to 5	5/22/2018.	Removed			
Lot 45	Silt Fence	Miami Circle		Removed			
Current Condition:	Removed-Terri Krasn	e sodded the lot prior to 5	5/22/2018.				
Lot 46	Silt Fence	Miami Circle	3/15/2018	Active	Yes		
Current Condition:			ear for sod install by Terri				
	The lot needs to be sodded once fine graded. Developer Terri Krasne was informed to complete by 11/8/2018. Not done as of the last inspection.						
				I I			
Lot 47 Current Condition:	Silt Fence Fair Condition- Silt fer	Miami Circle nce was removed in the re	5/30/2018 ear for sod install by Terri	Active Krasne prior to 11/7/	Yes 2018.		
	The lot needs to be s	sodded once fine grade	d				
	The lot needs to be sodded once fine graded. Developer Terri Krasne was informed to complete by 11/8/2018. Not done as of the last inspection.						
Lot 48	Silt Fence	Miami Circle	5/30/2018	Active	Yes		
Current Condition:			ear for sod install by Terri				
	The lot needs to be s	sodded once fine grade	d.				
	Developer Terri Krasne was informed to complete by 11/8/2018. Not done as of the last inspection.						
	Developer Terri Krasn	ne was informed to compi	ete by 11/8/2018. Not do	ne as of the last ins	pection.		
Lot 49	Silt Fence	Miami Circle	7/19/2018	Active	No		
Current Condition:	Active- Lot was excav	ated by Terri Krasne prio	r to 7/19/2018. Due to a l	basin in the rear of th	e lot, E&A will		
			e. Dirt was removed from to a basin, BMPs are pre	•	•		
t-	*						

RR-1-2	Stream Outlet Rip Rap	Drainage way	9/7/2016	Active	No
Current Condition:	Good Condition- Rip ra		o 10/2/2017 inspection. E		
RW-1-8	Rock Weirs	Site	9/7/2016	Active	No
Current Condition:			or to 10/2/2017 inspection 10/2/2017. RW 6-8 will be		
	Erosion Control	1			
ECB-1-15	Blanket	Site	9/7/2016	Active	No
Current Condition:	Good Condition- Erosi Champoux.	on Control Blanket has b	peen installed on the site p	prior to 10/2/2017 by I	Developer Ste
Silt Fence 1-4 Current Condition:	Silt Fence	West side of project	9/7/2016 n the west side & repaired	Active	No
Silt Fence 5-10 Current Condition:	202nd Avenue on lot 8 by the Developer Steve 3/2/2018. SF #2 from to vegetation and silt fence was repaired and Commercial Seeding, due to the establishme 8/8/2018 by Commercial Installation of sod by Silt Fence	Replat 1; Silt fence #4 e Champoux. E&A inspe the SWPPP sign to the n ce checks #4 were repair d reinstalled by the sidev and silt fence from the w ent of vegetation prior to 0 ial Seeding. Silt fence w Terri Krasne. East side of project Inspector retied the silt fe	ed to the east of lot 39; Si by RR1 was repaired due extor retied the silt fence to read and extended by Comwalk to capture runoff on 2 lest SWPPP sign to the w 6/2/2018. Silt fence along vas removed behind lots 9/7/2016 ence to the posts along Bloomer to the post	to undercutting SF p to the posts during the moved due to the est mercial Seeding prio 202nd Avenue prior to est along Blondo Par 202nd Avenue was r 46-48 prior to 11/7/	rior to 10/19/20 inspection on ablishment of r to 4/12/2018. b 5/30/2018 by rkway was rem repaired prior to 2018 for
Sediment Basin 1	Sediment Basin	West side-entrance	9/7/2016	Active	No
Current Condition:		R 4-6 are in place on the	ex device was installed pri slopes. Riser is beginning		
Sediment Basin 2	Sediment Basin	East side-Central	9/7/2016	Active	No
Current Condition:	Steve Champoux. SR undermined prior to 5/	R 7 & 8 are in place on t 11/2018.	ex device was installed pri the slopes. Riser was bacl	kfilled, and repaired v	vhere it was
Sediment Basin 3	Sediment Basin	East side	9/7/2016	Active	No
Current Condition:	10/2/2017. Sediment E rap per plan. Develope functioning as a sedim	Basin still needs to be inser Terri Krasne was remin	, although SRR 12 is miss stalled per plan, including nded to complete once gr. and area is heavily veget a.	riser, anti-vortex devi ading begins in area.	ce, outfall and Basin is
Cadimant T 4	Sediment Trap	SW corner	9/7/2016	Active	No
Sediment Trap 1	0 10 111 000/ 6	III Tara area in stall and a	rior to 10/2/2017 increastic	n by Developer Stev	
Current Condition:	SRR 1 & 2 are in place		nor to 10/2/2017 inspection	2, 2010.000. 0.01	
<u> </u>			9/7/2016	Active	
Current Condition:	SRR 1 & 2 are in place Sediment Trap Good Condition- Sedir	e on the slopes. Site nent Traps 2-5 have bee		Active ent on the west side.	e Champoux. No ST 6-8 have b
Current Condition: Sediment Traps 2-8	SRR 1 & 2 are in place Sediment Trap Good Condition- Sedin installed prior by Steve vegetation. Slope Outlet Rip Rap	s on the slopes. Site ment Traps 2-5 have bee to Champoux prior to the i	9/7/2016 en removed for developme inspection on 10/2/2017. I	Active ent on the west side. E&A will monitor area	e Champoux. No ST 6-8 have b due to extens No
Current Condition: Sediment Traps 2-8 Current Condition:	SRR 1 & 2 are in place Sediment Trap Good Condition- Sedin installed prior by Steve vegetation. Slope Outlet Rip Rap Good Condition- Rip ra currently missing or ne Krasne was reminded	Site ment Traps 2-5 have bee e Champoux prior to the i Site ap 1,2, 4-8, 10-11 were in ted to be verified. SRR 1 to complete rip rap once	9/7/2016 en removed for developme inspection on 10/2/2017. I	Active ent on the west side. E&A will monitor area Active Inspection. Rip rap 3 er City's prior request Basin is functioning a	No ST 6-8 have b a due to extens No 3, 9 and 12 are be sediment to
Current Condition: Sediment Traps 2-8 Current Condition: SRR-1-12	SRR 1 & 2 are in place Sediment Trap Good Condition- Sedin installed prior by Steve vegetation. Slope Outlet Rip Rap Good Condition- Rip racurrently missing or ne Krasne was reminded as of 7/27/2018 and ar	Site ment Traps 2-5 have bee e Champoux prior to the i Site ap 1,2, 4-8, 10-11 were in ted to be verified. SRR 1 to complete rip rap once	9/7/2016 en removed for developme inspection on 10/2/2017. If 9/7/2016 enstalled prior to 10/2/2017 12 needs to be installed prior grading begins in area. If	Active ent on the west side. E&A will monitor area Active Inspection. Rip rap 3 er City's prior request Basin is functioning a	No ST 6-8 have b a due to extens No 3, 9 and 12 are be sediment to
Current Condition: Sediment Traps 2-8 Current Condition: SRR-1-12 Current Condition:	SRR 1 & 2 are in place Sediment Trap Good Condition- Sedin installed prior by Steve vegetation. Slope Outlet Rip Rap Good Condition- Rip racurrently missing or ne Krasne was reminded as of 7/27/2018 and ar work begins area. Streets Good Condition-Street	Site ment Traps 2-5 have bee to Champoux prior to the interpretable of the page 1,2, 4-8, 10-11 were interpretable of the page 1,2, 4-8, 10-11 were interpretable of the complete rip rap once the interpretable of the page 1,2, 4-8, 10-11 were interpretable of t	9/7/2016 en removed for developme inspection on 10/2/2017. It 9/7/2016 enstalled prior to 10/2/2017 a needs to be installed prior grading begins in area. It BMP will be monitored an 9/7/2016 bund the project. Minor st	Active ent on the west side. E&A will monitor area Active inspection. Rip rap 3 er City's prior request Basin is functioning a d added as needing Active	No ST 6-8 have be detected by the second of
Sediment Traps 2-8 Current Condition: SRR-1-12 Current Condition:	SRR 1 & 2 are in place Sediment Trap Good Condition- Sedin installed prior by Steve vegetation. Slope Outlet Rip Rap Good Condition- Rip racurrently missing or ne Krasne was reminded as of 7/27/2018 and ar work begins area. Streets Good Condition-Street	Site ment Traps 2-5 have bee to Champoux prior to the interest of the interest	9/7/2016 en removed for developme inspection on 10/2/2017. It 9/7/2016 enstalled prior to 10/2/2017 a needs to be installed prior grading begins in area. It BMP will be monitored an 9/7/2016 bund the project. Minor st	Active ent on the west side. E&A will monitor area Active inspection. Rip rap 3 er City's prior request Basin is functioning a d added as needing Active	No ST 6-8 have be a due to extens No 3, 9 and 12 are. Developer Tes a sediment to maintenance co
Sediment Traps 2-8 Current Condition: SRR-1-12 Current Condition: STR Current Condition:	SRR 1 & 2 are in place Sediment Trap Good Condition- Sedin installed prior by Steve vegetation. Slope Outlet Rip Rap Good Condition- Rip racurrently missing or ne Krasne was reminded as of 7/27/2018 and ar work begins area. Streets Good Condition-Street Avenue, but there are in Misc./Other	Site ment Traps 2-5 have bee to Champoux prior to the interpretable of the prior to the interpretable of the prior to the interpretable of the prior to complete rip rap once the prior to the prior	9/7/2016 en removed for developme inspection on 10/2/2017. It 9/7/2016 nstalled prior to 10/2/2017 12 needs to be installed prior grading begins in area. It BMP will be monitored an 9/7/2016 pund the project. Minor st of 9/5/2018.	Active ent on the west side. E&A will monitor area Active inspection. Rip rap 3 er City's prior request Basin is functioning a d added as needing Active reet cleaning is need Active	No ST 6-8 have be a due to extens No 3, 9 and 12 are. Developer Tess a sediment to maintenance commended to the sediment of the sed off North 20 No