E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tell 402.895.4700 fax 402.895.3599 www.eacg.com



A .lilek CPESC. CISEC

	ironmental Services Dept. Manager Engin				eering Answers	
		E&A- P2017.4	11.001			
Inspector: Patrick Sechser					Stage	
Project Name:		The Villas at Piney Creek OMA-20160711-03678 CSW-201600546			1	
For Week Ending:		Δ <i>l</i>	27/2019			
Project Location:	202nd Str	202nd Street and Blondo Parkway, Omaha, NE (Douglas County)				
				ao ooaniy,	68022	
Grading:	80%)				
Sanitary Sewer:	50%)				
Storm Sewer:	50%)				
Paving:	50%					
Seeding:	82%					
Utilities:	50%					
Overall Development:	27%)				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
					Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"	04/23/19	Sunny 74/46			
Wednesday	0.00"					
Thursday	0.00"					
Friday Saturday	0.00" 0.60"	04/27/19	Cloudy 57/39			
Complaints:						
CONSTRUCTION SEQUENCING	3:	•	•	•	•	
Which portion(s) (i.e. drainage basins)	of the site have had a temporar	y or permanent cessation	on of grading, earthwork, or gro	ound disturbance in the la	ast 14 days?	
Grading activities began in the Summer/F Minor grading to be completed at a later t Drainage basins A0.3, A2, A0.4 and B1 w	time in drainage areas A1-A0.2 due vere inactive (10/2/2017).	to lot level construction	(10/2/2017).			
Which portion(s) (i.e. drainage basins)				•		
Grading activities began in the Summer/F Minor grading to be completed at a later t Drainage basins A0.3, A2, A0.4 and B1 w	time in drainage areas A1-A0.2 due			site.		
What temporary or permanent stabilizate Existing Vegetation (2016); Both sides of re-matted and seeded due to erosion (10.	project were seeded and erosion of	control blanket installed (2	2017); Right-of Ways were seeded			
CUMMARY OUTSTIONS:						
SUMMARY QUESTIONS: Are approved entrances and adjacent	streets being maintained adequa	ately?				
Yes	oncote being maintained adequ	atory:				
Are receiving waters adjacent to the p	project free of any significant sig	ns of erosion or sedime	ent that would be associated wi	th the construction activ	itv?	
Yes	,		The second secon		•	
CHECKLIST QUESTIONS:						
Are waste materials (concrete, constru	uction material, hazardous, etc.)	being managed proper	ly?			

Comments:

No. See findings section

Is dust associated with the construction activity adequately controlled on the site?

Comments:

East side of the site remains idle. Home construction is continuing on the west side of the project.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) CIR # 8612 was received and reviewed on 11/20/2018. CIR was forwarded to Developer Terri Krasne for additional compliance on 11/20/2018, including sod installation of lots and removal of dirt piles from ROW.
- NOTE: Due to spot dumping of concrete, E&A will recommend either a washout pit or that the concrete residue gets removed as soon as its deposited. E&A will contact Terri Krasne and update the report accordingly.

 3.) CIR #9288 was received and forwarded to Developer Terri Krasne on 4/2/2019 for continued compliance.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenanc		
CD1-14	Wattles	Site	9/7/2016	Active	No		
Current Condition:			A will verify other wattles a	nd necessity as wo	ork progresses. (
	1-10 are presently not	needed based on lot leve	el construction.				
CE-1	Entrance	Blondo Parkway		Removed			
Current Condition:			rior to 10/2/2017 inspection		1		
CE-2	Entrance	Blondo Parkway-East		Active	No		
Current Condition:	Good Condition-70%		stalled prior to 10/2/2017 in	spection by Ruff G	Grading, Entrance		
	remains inactive as of			, ,			
CW-1	Concrete washout	West side of project	1	Removed	1		
Current Condition:		it was removed prior to 10	7/2/2017	Removed	ļ		
CW-2	Concrete washout		5/1/2018	Pending	No		
Current Condition:			rn phase prior to road pavin		NO		
Diversion Ditches 1-24	Diversion Ditches	Site	9/7/2016	Active	No		
			nstalled prior to the inspecti				
Current Condition:							
			mowed back. DD1, part o				
			monitor. Other diversion d	itches were remov	ed for lot level		
	construction. DD 1 has	s been removed for const	ruction as of 9/13/2018.				
		202nd Street, 202nd			1		
Inlet Filters	Inlet Filters	Avenue	10/25/2017	Active	No		
Current Condition:	Good Condition- Inlet	filters were cleaned out a	nd adjusted by Commercial	Seeding prior to 3	3/24/2019.		
Lot 7	Silt Fence	North 202nd Avenue	8/1/2018	Active	No		
Current Condition:	Active- Lot was excav	ated by Terri Krasne prior	to 8/1/2018. Lot is present	tly flat. E&A will co	ontinue to monito		
	need for silt fence inst	allation on the front.	•				
Lot 8	Silt Fence	North 202nd Avenue	8/15/2018	Active	No		
Current Condition:			to 8/15/2018. Lot is presen				
Current Condition.			was removed from the ROV				
	need for slit ferice inst			v prior to 9/13/2016	0.		
Lot 9	Silt Fence	North 202nd Avenue	9/13/2018	Active	No		
Current Condition:	Active- Lot was excav	ated by Terri Krasne prior	to 9/13/2018. Lot is presen	ntly flat. E&A will o	continue to monit		
	need for silt fence inst	allation on the front.					
Lot 11, Replat 1	Silt Fence	202nd Street	12/18/2018	Active	No		
Current Condition:	1	Active - Lot is mostly flat. Dirt was removed from the ROW by Terri Krasne prior to 1/22/2019. E&A will monito					
	need for BMPs.						
Lot 12, Replat 1	Silt Fence	North 202nd Avenue	11/1/2018	Active	No		
Current Condition:			for BMPs. Dirt was remove	ed from the ROW	by Terri Krasne r		
	to 11/26/2018.	a 200 t tim titotimos titot			.,		
Lot 28	Silt Fence	202nd Street	12/18/2018	Active	No		
Current Condition:		iat. Dirt was removed iror	n the ROW by Terri Krasne	prior to 1/22/2019	. E&A WIII MONII		
	need for BMPs.						
Lot 29	Silt Fence	202nd Street	11/1/2018	Active	No		
Current Condition:			n the ROW by Terri Krasne				
Guitelli Collultion.	need for BMPs.	iat. Diit was removed nor	ii iiic i tovv by i ciii ftiasiic	prior to 1/22/2019	. Lan will illollin		
1-400		1 000		D '	ı		
Lot 30	Silt Fence	202nd Street	7/40/0040	Removed			
Current Condition:			7/19/2018 and cleaned the		T		
	Silt Fence	202nd Street		Removed			
Lot 31	D	dded by Terri Krasne prio					
Current Condition:							
	Silt Fence	North 202nd Street	9/13/2018	Active	No		
Current Condition:	Silt Fence	North 202nd Street	9/13/2018 to 9/13/2018. Lot is prese				
Current Condition: Lot 32	Silt Fence Active- Lot was excav	North 202nd Street ated by Terri Krasne prior		ntly flat. E&A will o	continue to monit		
Current Condition: Lot 32	Silt Fence Active- Lot was excav	North 202nd Street ated by Terri Krasne prior	to 9/13/2018. Lot is prese	ntly flat. E&A will o	continue to monit		
Current Condition: Lot 32 Current Condition:	Silt Fence Active- Lot was excav need for silt fence inst	North 202nd Street ated by Terri Krasne prior allation on the front. Was	to 9/13/2018. Lot is prese	ntly flat. E&A will one was cleaned up	continue to monit		
Current Condition: Lot 32 Current Condition: Lot 33	Silt Fence Active- Lot was excav need for silt fence inst Silt Fence	North 202nd Street ated by Terri Krasne prior allation on the front. Was 202nd Avenue	to 9/13/2018. Lot is present to the curb lin	ntly flat. E&A will o	continue to monit		
Current Condition: Lot 32 Current Condition:	Silt Fence Active- Lot was excav need for silt fence inst Silt Fence	North 202nd Street ated by Terri Krasne prior allation on the front. Was	to 9/13/2018. Lot is present to the curb lin	ntly flat. E&A will one was cleaned up	continue to monit		

Current Condition: Active- Lot is mostly flat. E&A will monitor need for BMPs. Dirt was removed from the ROW to 11/26/2018. Lot 36 Silt Fence North 202nd Avenue 11/1/2018 Active Current Condition: Active- Lot is mostly flat. E&A will monitor need for BMPs. Dirt was removed from the ROW to 11/26/2018. Lot 43 Silt Fence Miami Circle Removed Current Condition: Removed-Terri Krasne sodded the lot prior to 5/22/2018. Lot 44 Silt Fence Miami Circle Removed	No				
to 11/26/2018. Lot 36 Silt Fence North 202nd Avenue 11/1/2018 Active Current Condition: Active-Lot is mostly flat. E&A will monitor need for BMPs. Dirt was removed from the ROW to 11/26/2018. Lot 43 Silt Fence Miami Circle Removed Current Condition: Removed-Terri Krasne sodded the lot prior to 5/22/2018. Lot 44 Silt Fence Miami Circle Removed					
Current Condition: Active- Lot is mostly flat. E&A will monitor need for BMPs. Dirt was removed from the ROW to 11/26/2018. Lot 43 Silt Fence Miami Circle Removed Current Condition: Removed-Terri Krasne sodded the lot prior to 5/22/2018. Lot 44 Silt Fence Miami Circle Removed	by Terri Krasne prior				
to 11/26/2018. Lot 43 Silt Fence Miami Circle Removed	No				
Current Condition: Removed-Terri Krasne sodded the lot prior to 5/22/2018. Lot 44 Silt Fence Miami Circle Removed	by Terri Krasne prior				
Lot 44 Silt Fence Miami Circle Removed					
Current Condition: Removed-Terri Krasne sodded the lot prior to 5/22/2018.					
Lot 45 Silt Fence Miami Circle Removed					
Current Condition: Removed-Terri Krasne sodded the lot prior to 5/22/2018. Lot 46 Silt Fence Miami Circle Removed					
Current Condition: Removed- Lot was sodded by Terri Krasne prior to 11/20/2018. Lot 47 Silt Fence Miami Circle Removed					
Current Condition: Removed- Lot was sodded by Terri Krasne prior to 11/26/2018.	-				
Lot 48 Silt Fence Miami Circle Removed					
Current Condition: Removed- Lot was sodded by Terri Krasne prior to 11/26/2018.	-				
Lot 49 Silt Fence Miami Circle Removed					
Current Condition: Removed- Lot was sodded by Terri Krasne prior to 11/26/2018.					
Stream Outlet Rip					
RR-1-2 Rap Drainage way 9/7/2016 Active	No				
Current Condition: Good Condition- Rip rap 1 was installed prior to 10/2/2017 inspection. E&A will continue to	monitor. RR 2 is				
pending once outfall is installed from outfall #3.					
RW-1-8 Rock Weirs Site 9/7/2016 Active	No				
Current Condition: Good Condition- Rock Weir 1 was installed prior to 10/2/2017 inspection. E&A will continue	to monitor. RW 2-5				
have been removed prior to the inspection on 10/2/2017. RW 6-8 will be verified during the					
Erosion Control ECB-1-15 Blanket Site 9/7/2016 Active	No				
Current Condition: Good Condition- Erosion Control Blanket has been installed on the site prior to 10/2/2017 b					
Champoux.	,				
Silt Fence 1-4 Silt Fence West side of project 9/7/2016 Active Current Condition: Good Condition- Silt Fence #1 was removed on the west side & repaired along Blondo Park	No				
202nd Avenue on lot 8, Replat 1; Silt fence #4 by RR1 was repaired due to undercutting SF by the Developer Steve Champoux. E&A inspector retied the silt fence to the posts during the 3/2/2018. SF #2 from the SWPPP sign to the main drainage way was removed due to the expectation and silt fence checks #4 were repaired and extended by Commercial Seeding properties of the sidewalk to capture runoff on 202nd Avenue prior Commercial Seeding, and silt fence from the west SWPPP sign to the west along Blondo Podue to the establishment of vegetation prior to 6/2/2018. Silt fence along 202nd Avenue was	Good Condition- Silt Fence #1 was removed on the west side & repaired along Blondo Parkway; SF #2 was reinstalled by SB 1; SF #2 and #3 was reinstalled to the east of lot 39; Silt fence was entrenched to the north of 202nd Avenue on lot 8, Replat 1; Silt fence #4 by RR1 was repaired due to undercutting SF prior to 10/19/2017 by the Developer Steve Champoux. E&A inspector retied the silt fence to the posts during the inspection on 3/2/2018. SF #2 from the SWPPP sign to the main drainage way was removed due to the establishment of vegetation and silt fence checks #4 were repaired and extended by Commercial Seeding prior to 4/12/2018. Silt fence was repaired and reinstalled by the sidewalk to capture runoff on 202nd Avenue prior to 5/30/2018 by Commercial Seeding, and silt fence from the west SWPPP sign to the west along Blondo Parkway was removed due to the establishment of vegetation prior to 6/2/2018. Silt fence along 202nd Avenue was repaired prior to 8/8/2018 by Commercial Seeding. Silt fence was removed behind lots 46-48 prior to 11/7/2018 for installation of				
	NI-				
	No				
Current Condition: Good Condition- Silt fence along Blondo Parkway was repaired and tied back to the p Inspector prior to 4/23/2019.					
Sediment Basin 1 Sediment Basin West side-entrance 9/7/2016 Active	No				
Current Condition: Good Condition- 44% full- Basin and Anti-vortex device was installed prior to 10/2/2017 insp					
Steve Champoux. SRR 4-6 are in place on the slopes. Riser is beginning to become underr continue to monitor as of 3/15/2018.	No				
Steve Champoux. SRR 4-6 are in place on the slopes. Riser is beginning to become under continue to monitor as of 3/15/2018.	spection by				
Steve Champoux. SRR 4-6 are in place on the slopes. Riser is beginning to become under continue to monitor as of 3/15/2018. Sediment Basin 2 Sediment Basin East side-Central 9/7/2016 Active					
Steve Champoux. SRR 4-6 are in place on the slopes. Riser is beginning to become under continue to monitor as of 3/15/2018. Sediment Basin 2 Sediment Basin East side-Central 9/7/2016 Active Current Condition: Good Condition- 36% full- Basin and Anti-vortex device was installed prior to 10/2/2017 in Developer Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, a was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019.	·				
Steve Champoux. SRR 4-6 are in place on the slopes. Riser is beginning to become under continue to monitor as of 3/15/2018. Sediment Basin 2 Sediment Basin East side-Central 9/7/2016 Active Current Condition: Good Condition- 36% full- Basin and Anti-vortex device was installed prior to 10/2/2017 in Developer Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, a was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin 3 Sediment Basin East side 9/7/2016 Active	No				
Steve Champoux. SRR 4-6 are in place on the slopes. Riser is beginning to become under continue to monitor as of 3/15/2018. Sediment Basin 2 Sediment Basin East side-Central 9/7/2016 Active Current Condition: Good Condition- 36% full- Basin and Anti-vortex device was installed prior to 10/2/2017 in Developer Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, a was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin 3 Sediment Basin East side 9/7/2016 Active Current Condition: Active-SRR 10 & 11 are in place on the slopes, although SRR 12 is missing. Basin has bee 10/2/2017. Sediment Basin still needs to be installed per plan, including riser, anti-vortex de rap per plan. Developer Terri Krasne was reminded to complete once grading begins in are: functioning as a sediment trap as of 7/27/2018 and area is heavily vegetated. BMP will be mas needing maintenance once work begins area.	No n dug prior to vice, outfall and rip a. Basin is nonitored and added				
Steve Champoux. SRR 4-6 are in place on the slopes. Riser is beginning to become under continue to monitor as of 3/15/2018. Sediment Basin 2 Sediment Basin East side-Central 9/7/2016 Active Current Condition: Good Condition- 36% full- Basin and Anti-vortex device was installed prior to 10/2/2017 in Developer Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, at was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin 3 Sediment Basin East side 9/7/2016 Active Active-SRR 10 & 11 are in place on the slopes, although SRR 12 is missing. Basin has bee 10/2/2017. Sediment Basin still needs to be installed per plan, including riser, anti-vortex de rap per plan. Developer Terri Krasne was reminded to complete once grading begins in area functioning as a sediment trap as of 7/27/2018 and area is heavily vegetated. BMP will be mas needing maintenance once work begins area. Sediment Trap 1 Sediment Trap SW corner 9/7/2016 Active	No n dug prior to vice, outfall and rip a. Basin is nonitored and added				
Steve Champoux. SRR 4-6 are in place on the slopes. Riser is beginning to become under continue to monitor as of 3/15/2018. Sediment Basin 2 Sediment Basin East side-Central 9/7/2016 Active Current Condition: Good Condition-36% full- Basin and Anti-vortex device was installed prior to 10/2/2017 in Developer Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, a was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin 3 Sediment Basin East side 9/7/2016 Active Current Condition: Active-SRR 10 & 11 are in place on the slopes, although SRR 12 is missing. Basin has bee 10/2/2017. Sediment Basin still needs to be installed per plan, including riser, anti-vortex de rap per plan. Developer Terri Krasne was reminded to complete once grading begins in area functioning as a sediment trap as of 7/27/2018 and area is heavily vegetated. BMP will be mas needing maintenance once work begins area.	No n dug prior to vice, outfall and rip a. Basin is nonitored and added				

Current Condition:			n removed for development espection on 10/2/2017. E8		
SRR-1-12	Slope Outlet Rip Rap	Site	9/7/2016	Active	No
Current Condition:	currently missing or nee Krasne was reminded t	ed to be verified. SRR 12 o complete rip rap once o	stalled prior to 10/2/2017 ir 2 needs to be installed per grading begins in area. Ba P will be monitored and add	City's prior request sin is functioning a	. Developer Terri s a sediment trap as
STR	Streets	Site	9/7/2016	Active	No
Current Condition:	Good Condition- Street present.	s were scraped up by Co	mmercial Seeding prior to	3/24/2019. No sign	s of trackout were
SWPPP Sign	Misc./Other	Blondo Parkway	10/9/2017	Active	No
Current Condition:	Good Condition- 2 SWI	PPP signs were installed	by the entrances prior to 1	0/19/2017 by E&A.	
Inspector Signature:	Got Sol			Reviewed By:	Hittes Vann