E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tell 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Environmental Services Dept. N	lanager			Engineering A	nswers
		E&A- P2017.4	11.001		
Inspector: Patrick Sechser					Stage
Project Name:	The Villas at Piney Creek OMA-20160711-03678				1
-		CSW-201600546			
For Week Ending:		5/	11/2019		
Project Location:	202nd Street and Blondo Parkway, Omaha, NE (Douglas County)				
Grading:	80°	0/6			
Sanitary Sewer:	50				
Storm Sewer:	50				_
Paving:	50'	_			1
Seeding:	829	%			
Utilities:	509	%			
Overall Development:	27	%			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		
					Week
Sunday:	0.01"				
Monday	0.30"				
Tuesday	0.10"				
Wednesday	1.08"	5/8/2019	Rain 52/40		
Thursday	0.00"				
Friday	0.01"				
Saturday	0.24"				
O-markatara					
Complaints:					1
CONSTRUCTION SEQUENCING	<u></u>				
Which portion(s) (i.e. drainage basins)		ary or normanent cossat	on of grading earthwork or gro	und disturbance in the l	aet 14 daye?
Times pertien(s) (i.e. dramage basins)	or the one have had a tempore	ny or permanent occour	on or grading, cardinorit, or gro	and distarbance in the i	ust 14 days.
Grading activities began in the Summer/F	all of 2016 by Ruff Grading. Maj	or grading activities have	ceased in the Summer of 2017 on s	site.	
Minor grading to be completed at a later ti		ue to lot level construction	(10/2/2017).		
Drainage basins A0.3, A2, A0.4 and B1 w	ere inactive (10/2/2017).				
Which portion(s) (i.e. drainage basins)	of the site do not have grading	g, earthwork, or ground	disturbance scheduled in the ne	xt 14 days?	
Grading activities began in the Summer/F	all of 2016 by Ruff Grading. Maj	or grading activities have	ceased in the Summer of 2017 on s	site.	
Minor grading to be completed at a later ti		ue to lot level construction	(10/2/2017).		
Drainage basins A0.3, A2, A0.4 and B1 w					
What temporary or permanent stabiliza					
Existing Vegetation (2016); Both sides of re-matted and seeded due to erosion (10/ applied to the NW slope where the erosion	19/2017); Erosion control matting	g and seed were installed			
SUMMARY QUESTIONS:					
Are approved entrances and adjacent s	streets being maintained adeq	uately?			
Yes					
Are receiving waters adjacent to the p	roject free of any significant s	igns of erosion or sedim	ent that would be associated wi	th the construction activ	rity?
Yes					
OUTOW IOT OUTOTION					
CHECKLIST QUESTIONS:					

Comments:

No. See findings section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Is dust associated with the construction activity adequately controlled on the site?

Comments:

East side of the site remains idle. Home construction is continuing on the west side of the project.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) No maintenance is required in the BMP section.
- 2.) CIR # 9472 was received and reviewed on 5/1/2019. CIR was forwarded to Developer Terri Krasne for additional compliance on 5/1/2019, including street cleaning.
- NOTE: Due to spot dumping of concrete, E&A will recommend either a washout pit or that the concrete residue gets removed as soon as its deposited. E&A will contact Terri Krasne and update the report accordingly.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CD1-14	Wattles	Site	9/7/2016	Active	No
Current Condition:			A will verify other wattles a	nd necessity as wo	ork progresses. CD
		needed based on lot leve	er construction.		
CE-1	Entrance	Blondo Parkway		Removed	
Current Condition:			rior to 10/2/2017 inspection		l NI-
CE-2	Entrance	Blondo Parkway-East	9/7/2016	Active	No
Current Condition:	remains inactive as of		stalled prior to 10/2/2017 ir	ispection by Ruil G	rading. Entrance
CW-1	Concrete washout	West side of project		Removed	
Current Condition:		t was removed prior to 10		Daniella a	l N-
CW-2	Concrete washout	East side of project	5/1/2018	Pending	No
Current Condition: Diversion Ditches 1-24	Diversion Ditches	Site	n phase prior to road pavin 9/7/2016	Active	No
Current Condition:			nstalled prior to the inspect		
Current Condition.	will continue to verify d	itches once vegetation is	mowed back DD1 part of	f DD2 DD13-DD2	y ixuii Grauing. L&A 1 were noted during
	will continue to verify ditches once vegetation is mowed back. DD1, part of DD2, DD13-DD24 were noted during the first inspection by E&A. E&A will continue to monitor. Other diversion ditches were removed for lot level				
		been removed for const			04 101 101 1010.
			1	ı	1
		202nd Street, 202nd		l	
Inlet Filters	Inlet Filters	Avenue	10/25/2017	Active	No
Current Condition:	Good Condition- Inlet f	ilters were cleaned out a	nd adjusted by Commercial	Seeding prior to 3	/24/2019.
-					
Lot 7	Silt Fence	North 202nd Avenue		Removed	
Current Condition:	Removed-Terri Krasne	sodded the lot prior to 5	/1/2019.		
Lot 8	Silt Fence	North 202nd Avenue		Removed	
Current Condition:	Removed-Terri Krasne	sodded the lot prior to 5	/1/2019.		
Lot 9	Silt Fence	North 202nd Avenue	9/13/2018	Active	No
Current Condition:			to 9/13/2018. Lot is prese	ntly flat. E&A will o	continue to monitor
	need for silt fence insta	allation on the front.			
Lot 11, Replat 1	Silt Fence	202nd Street	12/18/2018	Active	No
Current Condition:	Active - Lot is mostly fl	at. Dirt was removed fron	n the ROW by Terri Krasne	prior to 1/22/2019	. E&A will monitor
	need for BMPs.		•	•	
Lot 12, Replat 1	Silt Fence	North 202nd Avenue	11/1/2018	Active	No
Current Condition:			I for BMPs. Dirt was remov		
Current Condition.	to 11/26/2018.	it. Lan will mornion need	TIOI DIVII 3. DIIT WAS TEINOV	ed from the NOW i	by Telli Masile piloi
Lot 28	Silt Fence	202nd Street	12/18/2018	Active	No
Current Condition:			n the ROW by Terri Krasne		
ourient condition.	need for BMPs.	at. Dirt was removed from	II alo INOW by I cill INIASIIC	, p. 101 to 1/22/2019	. Lart will illorinol
Lot 29	Silt Fence	202nd Street	11/1/2018	Active	No No
Current Condition:		at. Dirt was removed fron	n the ROW by Terri Krasne	e prior to 1/22/2019	. ∟&A will monitor
	need for BMPs.		T		1
Lot 30	Silt Fence	202nd Street	7/40/0040	Removed	
Current Condition:			7/19/2018 and cleaned the		1
Lot 31	Silt Fence	202nd Street Ided by Terri Krasne prio	r to 11/20/2019	Removed	
Current Condition: Lot 32	Silt Fence	North 202nd Street	9/13/2018	Active	No
Current Condition:					
Current Condition.		Active- Lot was excavated by Terri Krasne prior to 9/13/2018. Lot is presently flat. E&A will continue to monitor need for silt fence installation on the front. Washout debris and the curb line was cleaned up prior to 10/17/2018.			
	Thood for our reflect files	manon on the none. Was	ioat aobiio ana mo ourb iin	o mas oleaned up	51151 10 10/11/2010.
1 5 + 00	0:14 =====	20254 4	Γ	Dam	1
Lot 33	Silt Fence	202nd Avenue	7/40/2040	Removed	<u> </u>
Current Condition: Lot 34	Removed- Terri Krasno Individual Lot	e sodded the lot prior to 7 202nd Avenue	/ 19/2018.	Removed	
Current Condition:	_	e sodded the lot prior t	o 5/8/2019	Removed	
Current Condition:	Kemoved-Terri Krasn	e souded the lot prior t	0 3/8/2019.		

1.105	0.11.5	
Lot 35		No .
Current Condition:	Active- Lot is mostly flat. E&A will monitor need for BMPs. Dirt was removed from the ROW by Terri Kr	rasne prior
	to 11/26/2018.	
Lot 36		No
Current Condition:	Active- Lot is mostly flat. E&A will monitor need for BMPs. Dirt was removed from the ROW by Terri Kr	rasne prior
	to 11/26/2018.	
Lot 43	Silt Fence Miami Circle Removed	
Current Condition:	Removed-Terri Krasne sodded the lot prior to 5/22/2018.	
Lot 44	Silt Fence Miami Circle Removed	
Current Condition:	Removed-Terri Krasne sodded the lot prior to 5/22/2018.	
Lot 45	Silt Fence Miami Circle Removed	
Current Condition:	Removed-Terri Krasne sodded the lot prior to 5/22/2018.	
Lot 46	Silt Fence Miami Circle Removed	
Current Condition:	Removed- Lot was sodded by Terri Krasne prior to 11/20/2018.	
Lot 47	Silt Fence Miami Circle Removed	
Current Condition:	Removed- Lot was sodded by Terri Krasne prior to 11/26/2018.	
Lot 48	Silt Fence Miami Circle Removed	
Current Condition:	Removed- Lot was sodded by Terri Krasne prior to 11/26/2018.	
Lot 49	Silt Fence Miami Circle Removed	
Current Condition:	Removed- Lot was sodded by Terri Krasne prior to 11/26/2018.	
	Stream Outlet Rip	
RR-1-2		No
Current Condition:	Good Condition- Rip rap 1 was installed prior to 10/2/2017 inspection. E&A will continue to monitor. Ri	R 2 is
	pending once outfall is installed from outfall #3.	
RW-1-8	Rock Weirs Site 9/7/2016 Active	No
Current Condition:	Good Condition- Rock Weir 1 was installed prior to 10/2/2017 inspection. E&A will continue to monitor.	
	have been removed prior to the inspection on 10/2/2017. RW 6-8 will be verified during the next inspect	tions
FOR 4.45	Erosion Control	
ECB-1-15		No
Current Condition:	Good Condition- Erosion Control Blanket has been installed on the site prior to 10/2/2017 by Developer	Steve
	Champoux.	
Silt Fence 1-4	Silt Fence West side of project 9/7/2016 Active	No
Current Condition:	Good Condition- Silt Fence #1 was removed on the west side & repaired along Blondo Parkway; SF #2	was
	reinstalled by SB 1; SF #2 and #3 was reinstalled to the east of lot 39; Silt fence was entrenched to the	north of
	202nd Avenue on lot 8, Replat 1; Silt fence #4 by RR1 was repaired due to undercutting SF prior to 10/	19/2017
	by the Developer Steve Champoux. E&A inspector retied the silt fence to the posts during the inspectio	
	3/2/2018. SF #2 from the SWPPP sign to the main drainage way was removed due to the establishmer	
	vegetation and silt fence checks #4 were repaired and extended by Commercial Seeding prior to 4/12/2	
	fence was repaired and reinstalled by the sidewalk to capture runoff on 202nd Avenue prior to 5/30/201	
	Commercial Seeding, and silt fence from the west SWPPP sign to the west along Blondo Parkway was	
	due to the establishment of vegetation prior to 6/2/2018. Silt fence along 202nd Avenue was repaired p	
	8/8/2018 by Commercial Seeding. Silt fence was removed behind lots 46-48 prior to 11/7/2018 for insta	
	sod by Terri Krasne.	
Oilt Famas F 40		NI-
Silt Fence 5-10		No .
Current Condition:	Good Condition- Silt fence along Blondo Parkway was repaired and tied back to the posts by E&A Inspection	ector prior
	to 4/23/2019.	
Sediment Basin 1	Sediment Basin West side-entrance 9/7/2016 Active	
Current Condition:	Good Condition- 44% full- Basin and Anti-vortex device was installed prior to 10/2/2017 inspection by D	No
	Steve Champoux. SRR 4-6 are in place on the slopes. Riser is beginning to become undermined. E&A	
1	Oteve Champoux. Of the 4-6 are in place of the slopes. The is beginning to become undernined. Ear	eveloper
	continue to monitor as of 3/15/2018.	eveloper
Sediment Basin 2	continue to monitor as of 3/15/2018.	eveloper A will
Sediment Basin 2	continue to monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active	Developer A will No
Sediment Basin 2 Current Condition:	continue to monitor as of 3/15/2018. Sediment Basin	Developer A will No Developer
	continue to monitor as of 3/15/2018. Sediment Basin	Developer A will No Developer
	continue to monitor as of 3/15/2018. Sediment Basin	Developer A will No Developer
Current Condition:	continue to monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active 1 Good Condition- 36% full- Basin and Anti-vortex device was installed prior to 10/2/2017 inspection by D Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, and repaired where it was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019.	Developer A will No Developer as
Current Condition: Sediment Basin 3	continue to monitor as of 3/15/2018. Sediment Basin	Developer A will No Developer as
Current Condition:	continue to monitor as of 3/15/2018. Sediment Basin	No Developer as No to
Current Condition: Sediment Basin 3	continue to monitor as of 3/15/2018. Sediment Basin	No Developer as No to
Current Condition: Sediment Basin 3	continue to monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active I Good Condition- 36% full- Basin and Anti-vortex device was installed prior to 10/2/2017 inspection by D Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, and repaired where it was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin East side 9/7/2016 Active I Active-SRR 10 & 11 are in place on the slopes, although SRR 12 is missing. Basin has been dug prior 10/2/2017. Sediment Basin still needs to be installed per plan, including riser, anti-vortex device, outfall rap per plan. Developer Terri Krasne was reminded to complete once grading begins in area. Basin is	No Developer as No Developer as No and rip
Current Condition: Sediment Basin 3	continue to monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active Monitor as of 3/15/2018. Good Condition- 36% full- Basin and Anti-vortex device was installed prior to 10/2/2017 inspection by D Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, and repaired where it was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin East side 9/7/2016 Active Mactive-SRR 10 & 11 are in place on the slopes, although SRR 12 is missing. Basin has been dug prior 10/2/2017. Sediment Basin still needs to be installed per plan, including riser, anti-vortex device, outfall rap per plan. Developer Terri Krasne was reminded to complete once grading begins in area. Basin is functioning as a sediment trap as of 7/27/2018 and area is heavily vegetated. BMP will be monitored ar	No Developer as No Developer as No and rip
Current Condition: Sediment Basin 3 Current Condition:	continue to monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active Monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active Monitor as of 5/11/2018 Basin and Anti-vortex device was installed prior to 10/2/2017 inspection by D Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, and repaired where it was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin East side 9/7/2016 Active Monitor Active-SRR 10 & 11 are in place on the slopes, although SRR 12 is missing. Basin has been dug prior 10/2/2017. Sediment Basin still needs to be installed per plan, including riser, anti-vortex device, outfall rap per plan. Developer Terri Krasne was reminded to complete once grading begins in area. Basin is functioning as a sediment trap as of 7/27/2018 and area is heavily vegetated. BMP will be monitored area needing maintenance once work begins area.	No Developer as No Developer as No to and rip
Sediment Basin 3 Current Condition: Sediment Trap 1	continue to monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active Moderate Sediment Basin East side-Central 9/7/2016 Active Moderate Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, and repaired where it was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin East side 9/7/2016 Active Moderate Active-SRR 10 & 11 are in place on the slopes, although SRR 12 is missing. Basin has been dug prior 10/2/2017. Sediment Basin still needs to be installed per plan, including riser, anti-vortex device, outfall rap per plan. Developer Terri Krasne was reminded to complete once grading begins in area. Basin is functioning as a sediment trap as of 7/27/2018 and area is heavily vegetated. BMP will be monitored are as needing maintenance once work begins area. Sediment Trap SW corner 9/7/2016 Active Moderate Sediment Trap SW corner 9/7/2016 Active Moderate Sediment Trap SW corner 9/7/2016 Active Moderate Sediment Moderate Sediment Moderate Moderate Sediment Trap SW corner 9/7/2016 Active Moderate Sediment Moderate Sediment Moderate Sediment Moderate Sediment Moderate Sediment Trap SW corner 9/7/2016 Active Moderate Sediment	No Developer as No To and rip and added
Current Condition: Sediment Basin 3 Current Condition:	continue to monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active Moderate Active Moderate Active Moderate Active Moderate Mod	No Developer as No To and rip and added
Sediment Basin 3 Current Condition: Sediment Trap 1	continue to monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active Moderate Sediment Basin East side-Central 9/7/2016 Active Moderate Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, and repaired where it was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin East side 9/7/2016 Active Moderate Active-SRR 10 & 11 are in place on the slopes, although SRR 12 is missing. Basin has been dug prior 10/2/2017. Sediment Basin still needs to be installed per plan, including riser, anti-vortex device, outfall rap per plan. Developer Terri Krasne was reminded to complete once grading begins in area. Basin is functioning as a sediment trap as of 7/27/2018 and area is heavily vegetated. BMP will be monitored are as needing maintenance once work begins area. Sediment Trap SW corner 9/7/2016 Active Moderate Sediment Trap SW corner 9/7/2016 Active Moderate Sediment Trap SW corner 9/7/2016 Active Moderate Sediment Moderate Sediment Moderate Moderate Sediment Trap SW corner 9/7/2016 Active Moderate Sediment Moderate Sediment Moderate Sediment Moderate Sediment Moderate Sediment Trap SW corner 9/7/2016 Active Moderate Sediment	No Developer as No To and rip and added
Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition:	continue to monitor as of 3/15/2018. Sediment Basin	No Developer as No and rip and added No Doux. SRR
Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Trap 2-8	continue to monitor as of 3/15/2018. Sediment Basin	No Developer as No Total and rip and added No Doux. SRR
Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition:	continue to monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active Moderate Sediment Basin East side-Central 9/7/2016 Active Moderate Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, and repaired where it was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin East side 9/7/2016 Active Moderate Active-SRR 10 & 11 are in place on the slopes, although SRR 12 is missing. Basin has been dug prior 10/2/2017. Sediment Basin still needs to be installed per plan, including riser, anti-vortex device, outfall rap per plan. Developer Terri Krasne was reminded to complete once grading begins in area. Basin is functioning as a sediment trap as of 7/27/2018 and area is heavily vegetated. BMP will be monitored are as needing maintenance once work begins area. Sediment Trap SW corner 9/7/2016 Active Moderate Sediment Trap was installed prior to 10/2/2017 inspection by Developer Steve Champor 1 & 2 are in place on the slopes. Sediment Trap Site 9/7/2016 Active Moderate Sediment Trap Site 9/7/2016 Active Moderate	No Developer as No Toto and rip and added No Developer as No
Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Trap 2-8	continue to monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active 1 Good Condition- 36% full- Basin and Anti-vortex device was installed prior to 10/2/2017 inspection by D Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, and repaired where it was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin East side 9/7/2016 Active 1 Active-SRR 10 & 11 are in place on the slopes, although SRR 12 is missing. Basin has been dug prior 10/2/2017. Sediment Basin still needs to be installed per plan, including riser, anti-vortex device, outfall rap per plan. Developer Terri Krasne was reminded to complete once grading begins in area. Basin is functioning as a sediment trap as of 7/27/2018 and area is heavily vegetated. BMP will be monitored are as needing maintenance once work begins area. Sediment Trap SW corner 9/7/2016 Active 1 Good Condition-20% full- Trap was installed prior to 10/2/2017 inspection by Developer Steve Champot 1 & 2 are in place on the slopes. Sediment Trap Site 9/7/2016 Active Good Condition-Sediment Traps 2-5 have been removed for development on the west side. ST 6-8 has installed prior by Steve Champoux prior to the inspection on 10/2/2017. E&A will monitor area due to expend the slope of the slopes.	No Developer as No Toto and rip and added No Developer as No
Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Trap 2-8	continue to monitor as of 3/15/2018. Sediment Basin East side-Central 9/7/2016 Active Moderate Sediment Basin East side-Central 9/7/2016 Active Moderate Steve Champoux. SRR 7 & 8 are in place on the slopes. Riser was backfilled, and repaired where it was undermined prior to 5/11/2018. Riser was backfilled again on 4/23/2019. Sediment Basin East side 9/7/2016 Active Moderate Active-SRR 10 & 11 are in place on the slopes, although SRR 12 is missing. Basin has been dug prior 10/2/2017. Sediment Basin still needs to be installed per plan, including riser, anti-vortex device, outfall rap per plan. Developer Terri Krasne was reminded to complete once grading begins in area. Basin is functioning as a sediment trap as of 7/27/2018 and area is heavily vegetated. BMP will be monitored are as needing maintenance once work begins area. Sediment Trap SW corner 9/7/2016 Active Moderate Sediment Trap was installed prior to 10/2/2017 inspection by Developer Steve Champor 1 & 2 are in place on the slopes. Sediment Trap Site 9/7/2016 Active Moderate Sediment Trap Site 9/7/2016 Active Moderate	No Developer as No Toto and rip and added No Developer as No
Sediment Basin 3 Current Condition: Sediment Trap 1 Current Condition: Sediment Trap 2-8	continue to monitor as of 3/15/2018. Sediment Basin	No Developer as No Toto and rip and added No Developer as No

Current Condition:	currently missing or ne Krasne was reminded t	ed to be verified. SRR 12 to complete rip rap once	stalled prior to 10/2/2017 ir 2 needs to be installed per grading begins in area. Ba P will be monitored and add	City's prior request sin is functioning a	. Developer Terri s a sediment trap as
STR	Streets	Site	9/7/2016	Active	No
Current Condition:	Good Condition- Streets were scraped up by Commercial Seeding prior to 3/24/2019. No signs of trackout were present.				
SWPPP Sign	Misc./Other	Blondo Parkway	10/9/2017	Active	No
Current Condition:	Good Condition- 2 SWPPP signs were installed by the entrances prior to 10/19/2017 by E&A.				
Inspector Signature:	Sto See			Reviewed By:	Auto Van