E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

E&A CONSULTING GROUP, INC.

Zachary A. Jilek, CPESC, CISEC
Erosion Control Specialist- Manager

ENGINEERING • PLANNING • FIELD SERVICES

Erosion Control Specialist- Manager ENGINEERING • PLANNING • FIELD SERVICE						
	E&A - I	2001.059.00	0			
					Stage	
	Walnut Creek Hills				3	
96th a	and Gold	Coast Road- P	apillion, NE (Sarpy C	county)	68046	
	1000/					
	85%					
Amount in inches	Date	e inspected				
0.04"					Week 1	
0.57"						
0.01"						
0.01"						
0.00"						
0.011			<u> </u>		Week 2	
0.28"						
					Week 3	
0.02"						
0.00					Week 4	
0.01"						
0.04"						
0.18"						
0.01"						
0.04"					Week 5	
0.03"					- Week 5	
	- 					
0.00"	2/9	/2011				
0.01"						
0.00"						
0.00"						
	Amount in inches 0.04" 0.57" 0.01" 0.01" 0.01" 0.01" 0.01" 0.01" 0.01" 0.01" 0.01" 0.04" 0.01" 0.04" 0.01" 0.00"	## Section	E&A - P2001.059.00 Walnut Cr NER11 2/12/2 96th and Gold Coast Road- P 100% 100% 100% 100% 100% 100% 100% 10	E&A - P2001.059.000 Walnut Creek Hills NER110517 2/12/2011 96th and Gold Coast Road- Papillion, NE (Sarpy Coast Road-Papillion, Ne (Sarpy Coast Road-Papilli	E&A - P2001.059.000 Walnut Creek Hills	

	None				
Complaints:					
•	1				
Construction Sequencing:	•		Į.	Į.	Į.
Which portion(s) (i.e. drainage basins) of the	e site have had a temporary or pe	rmanent cessation of gradi	ng, earthwork, or ground o	listurbance in the last	14 days?
. , , , , ,		_			•
Entire site; grading completed and si	te seeded prior to 2005.				
3 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
Which portion(s) (i.e. drainage basins) of the	e site do not have grading, earthy	vork, or ground disturbance	scheduled in the next 14	days?:	
Entire site; grading completed and si	te seeded prior to 2005.				
7 3 3 1	·				
What temporary or permanent stabilization	measures listed in this section ar	e being implemented?		I	I.
Paving, dense vegetation and landso		<u> </u>			
li aving, dense vegetation and landsc	aping installed prior to 2005.				

Comments:

Comments:

Site is currently idle. Inspection was a drive thru inspection due to large amount of snow on the property. This project went over on days between inspections to avoid inspecting during winter and/or dangerous driving conditions.

Inspection was not conducted on 1/10/11 due to winter weather and dangerous driving conditions.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) No required maintenance in the BMP section.

			Projected Install		Maintenance
Unique Name	Туре	Location	Date	Status	Scheduled
		N41d00m00s			
CE 1	Construction Entrance	W96d00m00s		Removed	
Current Condition:	Entrance paved.				
		N41d00m00s			
CE 2	Construction Entrance	W96d00m00s		Removed	
Current Condition:	Entrance paved.				
		N41d00m00s			
SB 1	Sediment Basin	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition - 30% Full				
		N41d00m00s			
SB 2	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed				
		N41d00m00s			
SB 3	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed December 2005 b	, ,	e to drainage area devel	opment.	
		N41d00m00s			
SB 4	Sediment Basin	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition - 32% Full -		d		
		N41d00m00s			
SB 5	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed				
		N41d00m00s			
SF 1	Silt Fence	W96d00m00s		Active	
Current Condition:	Removed; area vegetated.				
		N41d00m00s			
SF 2	Silt Fence	W96d00m00s		Active	
Current Condition:	Removed; area vegetated.				
		N41d00m00s			
SF 3	Silt Fence	W96d00m00s		Removed	
Current Condition:	Removed				
		N41d00m00s			
STR	Streets	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition - No major	signs of track off			

SWPPP Sign	Signs	3 Signs	8-19-08	Active	No
Current Condition:	Good Condition -90th and Fenwick, 90th and Gold Coast, 96th and Gold Coast				
Inspector Signature:		Reviewed By:	Zadnany K. Yil	ldc	