E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager Engineering Answers

	E	&A - P2001.059.0				
Inspector: Aaron Tulley					Stage	
Project Name:			3			
For Week Ending:	Walnut Creek Hills 10/12/2019					
Project Location:	96th and Gold Coast Road- Papillion, NE (Sarpy County)					
		<i>y</i> /	68046			
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding: Utilities:	100%					
Overall Development:	92%		-			
overali Development.	5270					
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions			
					Week 1	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	1.87"					
Friday	0.00"	09/20/19	Scattered Clouds 88/72			
Saturday	1.52"					
					Week	
Sunday:	0.64"					
Monday	0.00"	09/23/19	Clear 83/55			
Tuesday	0.51"					
Wednesday	0.00"	09/25/19	Scattered Clouds 75/58			
Thursday	0.00"					
Friday	0.04"					
Saturday	0.28"					
					Week	
Sunday:	0.78"					
Monday	0.00"	09/30/19	Scattered Clouds 91/75			
Tuesday	2.15"					
Wednesday	0.09"	10/02/19	Rain 57/49			
Thursday	0.00"					
Friday	0.07"					
Saturday	0.94"					
Cara au					Week	
Sunday:	0.00"					
Monday	0.00"	10/07/19	Clear 74/40			
Tuesday	0.00"					
Wednesday	0.02"					
Thursday	1.93"					
Friday	0.00"	10/11/19	Partly Cloudy 42/32			
Saturday	0.00"	10/11/13				
					Week	
Sunday:	N/A				WEEK	
Monday	N/A N/A					
Monday Tuesday	N/A N/A					
Wednesday	N/A N/A		+			
wednesday Thursday	N/A N/A		+			
Friday	N/A					
Saturday	N/A					
	None					
Complaints:						
oompianto.						
	I			[]		

Construction Sequencing:							
Which portion(s) (i.e. drainage basins) of	f the site have had a temporary or pern	nanent cessation of grading	g, earthwork, or ground disturbance	e in the last 14 days?			
Entire site; grading completed and	site seeded prior to 2005.						
Which portion(s) (i.e. drainage basins) of	f the site do not have grading, earthwo	rk, or ground disturbance s	cheduled in the next 14 days? :				
Entire site; grading completed and							
What temporary or permanent stabilizati							
Paving, dense vegetation and land	scaping installed prior to 2005. Va	acant lots 1, 2, and 3 re	plat 20 have been seeded (4/	27/19).			
					-		
Summary Questions:							
Are approved entrances and adjacent str	reets being maintained adequately?						
Yes Are receiving waters adjacent to the proj	is at free of our circuitie out circus of our		d he appendiated with the appendix of	en estivitud			
Yes	ject free of any significant signs of eros	sion or sediment that would	d be associated with the constructi	on activity?			
Checklist Questions:							
Are waste materials (concrete, construct	tion material, hazardous, etc.) being ma	anaged properly?					
Yes							
Is dust associated with the construction	activity adequately controlled on the s	ite?					
Yes							
Comments:							
Comments: Grading has begun for Trinity Luthor inspect SB 1. Grading for storm se							
Findings / Corrective Actions (D	ate):						
Findings / Corrective Actions (D. 1) No required maintenance in the 2) TD2 will be informed to attempt appears the vacant Lots 1, 2, and 3	BMP section. to prevent sediment going into SE				t inspection. It		
					Maintenance		
Unique Name	Туре	Location	Projected Install Date	Status	Scheduled		
· · · · · ·		41°08'23.73"N					
SB 1	Sediment Basin	96°03'19.85"W	In Place	Active	No		
Current Condition:	Good Condition - 49% Full. SB 1 was cleared of vegetation prior to inspection on 2/22/18. The basin is filling with sediment from the adjacent unstabilized Lots 1, 2, and 3 Replat 20 associated with the Trinity Lutheran Church project being managed by TD2. Due to basin being closed in the near future, E&A will not be recommending cleanout at this time. E&A will continue to monitor.						
		41°08'17.47"N					
STR	Streets	96°03'13.01"W	In Place	Active	No		
Current Condition:	Good Condition - No signs o						
	Swppp Sign Signs 3 Signs Removed						
Current Condition:	Ŭ		ble to be located as of 12/20/ umes a new sign will be order	0	installed due to		
Inspector Signature:	L Zz		Reviewed By:	to Van	~		

Inspector Signature:

Reviewed By:

Hettes Van