E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Enaineerina Answers

Environmental Services Dept	. Manager			ingineering ni	1511 (15			
		E&A- P2021.	065.002		Stage			
Inspector: Joe Manning								
Project Name:		Westridge Estates CSW-202106214						
For Week Ending:		68073						
Project Location:	Highw	1/7/2023 Highway 77 West of Eagle Drive - Yutan, NE (Saunders County)						
Tojou Location.	i iigiiiii	ay 11 Woot of Lagio B	Tivo Tatan, NE (Oddina	oro county,				
Grading:	Q	9%			1			
Sanitary Sewer:		0%						
Storm Sewer:		0%						
Paving:		5%						
Seeding:		5%						
Utilities:		0%						
Overall Development:		0%						
C torum 2 otoropinomi		0.0						
RAIN FALL AMOUNTS	Amount in tenths	Data increated	Masthar Canditions	Time				
RAIN FALL AWOUNTS	Amount in tentins	Date inspected	Weather Conditions	Time	Week 1			
Sunday:	0.00"				vveek 1			
Monday:	0.31"							
Tuesday:	0.19"							
Wednesday:	0.00"	1/4/2023	Cloudy 31	1:45 PM				
Thursday:	0.00"	1/4/2023	Cloudy 31	1.45 F W				
Friday:	0.00"							
Saturday:	0.00"							
Saturday.	0.00							
Complaints:	None							
Construction Someonium								
Construction Sequencing: Which portion(s) (i.e. drainage basin	ns) of the site have had a tem	norary or normanent cossa	tion of grading parthwork or	around disturbance in the	last 14 days?			
Viner pertion(s) (i.e. drainage basin	is of the site have had a tem	porary or permanent cesse	ition or grading, cartimork, or	ground disturbunce in the	last 14 days i			
Stripping and grading began (5/	/17/2022).							
Which portion(s) (i.e. drainage basin	ns) of the site do not have gra	ding, earthwork, or ground	d disturbance scheduled in th	e next 14 days?				
Stripping and grading began (5/	/17/2022).							
What temporary or permanent stabil	lization measures listed in thi	is section are being implen	nented?					
Existing vegetation (5/17/2022).	. Seeding/matting near th	e construction entrance	e (9/14/2022). Seeding ald	ong ROWs (11/16/2022	).			
Checklist Questions:								
Are receiving waters adjacent construction activity?	t to the project free of a	ny significant signs o	f erosion or sediment th	at would be associate	ed with the			
Yes								
Create Corrective Action?								
N/A								

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

No

## **Create Corrective Action?**

No - See Findings section

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

**Create Corrective Action?** 

N/A

Are construction entrances and adjacent streets being maintained adequately?

NΙα

**Create Corrective Action?** 

No - See BMP Section.

Is dust associated with the construction activity adequately controlled on the site?

Yes

**Create Corrective Action?** 

N/A

## Comments:

## Comments:

Site was inactive during the last inspection.

Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) Inactive portions of the site should be stabilized. Summit Development was informed to complete by 8/16/22. Not done as of last inspection. Summit Development was reminded on 9/14/22, 11/9/22. Summit Development seeded the ROWs prior to the inspection on 11/16/22. E&A inspector will monitor for vegetative establishment.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenan	
CE 01	Construction Entrance	H16		Removed		
<b>Current Condition:</b>	Removed - Summit Development paved the construction entrance prior to the inspection on 8/9/22.					
D 01	Diversion	J11 to H9	6/7/2022	Pending	No	
Current Condition:	Pending - The diversion will be installed once grading in the area requires. E&A inspector will continue to mo					
D 02	Diversion	J11 to I13	6/7/2022	Pending	No	
Current Condition:	Pending - The diversion	on will be installed onc	e grading in the area require	es. E&A inspector w	vill continue to m	
D 03	Diversion	J10 to I7		Removed		
D 03  Current Condition:	Removed - The grade	* . *	n prior to the first inspection lue to grading activity.		version has beer	
	Removed - The grade	r installed the diversio	•		version has beer	
Current Condition:	Removed - The grade removed prior to the ir	r installed the diversionspection on 7/19/22 of	lue to grading activity. 6/7/2022	on 5/17/22. The di		
Current Condition:  MS 01	Removed - The grade removed prior to the ir Material Storage	r installed the diversionspection on 7/19/22 of	lue to grading activity. 6/7/2022	on 5/17/22. The di		
Current Condition:  MS 01  Current Condition:	Removed - The grade removed prior to the ir  Material Storage Pending - The materia  Portable Toilet	r installed the diversionspection on 7/19/22 of On Site al storage will be instal	lue to grading activity. 6/7/2022	on 5/17/22. The diversity Pending  Removed	No	
Current Condition:  MS 01  Current Condition:  PT 01	Removed - The grade removed prior to the ir  Material Storage Pending - The materia  Portable Toilet	r installed the diversionspection on 7/19/22 of On Site al storage will be instal	lue to grading activity.  6/7/2022  led as necessary.	on 5/17/22. The diversity Pending  Removed	No	
MS 01  Current Condition:  PT 01  Current Condition:	Removed - The grade removed prior to the ir  Material Storage Pending - The material Portable Toilet Removed - Summit De	on Site On Site On Site On Site H6 to G8	lue to grading activity.  6/7/2022  led as necessary.	Pending  Removed e inspection on 9/28 Removed	No No 1/22.	

STR	Streets	ADJ and Internal Streets	5/17/2022	Active	Yes			
Current Condition:	Fair Condition -							
	Track off from the site and the internal streets should be cleaned.							
	Summit Development was informed to complete by 9/15/22. Not done as of the last inspection. Summit Development was reminded on 11/9/22, 1/06/23							
SWPPP Sign 01	SWPPP Signs	Adjacent to CE 1	6/7/2022	Active	No			
Current Condition:	Good Condition - E&A	inspector installed the S	SWPPP sign during the ir	nspection on 6/6/22.				
W 01	Straw Wattles	H16	9/14/2022	Active	No			
Current Condition:	Good Condition - Sum	Good Condition - Summit Development installed the straw wattles prior to the inspection on 9/14/22.						
W 02	Straw Wattles	H16	9/14/2022	Active	No			
Current Condition:	Good Condition - Sum	Good Condition - Summit Development installed the straw wattles prior to the inspection on 9/14/22.						
W 03 - 05	Straw Wattles	East side of internal streets	11/16/2022	Active	No			
Current Condition:		Good Condition - Summit Development installed straw wattles along the east side of the street prior to the inspection on 11/16/22.						
WO 01	Concrete Washout	On site		Removed				
Current Condition:	Removed - Summit Development removed the concrete washout prior to the inspection on 8/9/22.							
WO 02	Concrete Washout	On site		Removed				
Current Condition:	Removed - Summit Development removed the concrete washout prior to the inspection on 9/14/22.							
WS 01	Waste Storage Area	On site		Removed				
Current Condition:	Removed - Summit Development removed the waste storage prior to the inspection on 8/22/22.							
Certification Statement:	I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility							
Inspector Signature:	of fines and imprisonn	nent for knowing violatio	ns.	Reviewed By:	Put Sol			