E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager **Engineering Answers**

E&A - P2017.483.001 Bill SID as of 10/27/20 P2017.483.000

		BIII SID as of 10/	27/20 P2017.463.000				
Inspector: Bryce Wright					Stage		
		Wi	ndsor East				
		1					
		'					
Project Name:		CSW-201904190					
For Week Ending:		1/28/2023					
Project Location:		180th & Giles R	oad (NE), Sarpy County, NE				
Grading:		90%	T		I		
Sanitary Sewer:		90%					
Storm Sewer:		90%					
Paving:		95%					
Seeding:		50%					
Utilities:		85%					
Overall Development:		35%					
			T T		T		
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time			
					Week		
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.00"						
Wednesday:	0.00"	1/25/2023	Overcast 26	10:15 AM			
Thursday:	0.00"						
Friday:	0.00"						
Saturday:	0.00"						
	I						
Complaints:	None						
1							

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began in the eastern portion of the site (4/27/20). Grading began over all portions of the site (7/13/20). Grading on site has ceased due to winter conditions (2/9/21). Paving began all portions of site (4/15/21). Paving completed (6/2/21). Grading and excavation on large western slope (6/24/21). Utility installation began (9/14/21). Home excavation began (12/28/21).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began in the eastern portion of the site (4/27/20). Grading began over all portions of the site (7/13/20). Grading on site has ceased due to winter conditions (2/9/21). Paving began all portions of site (4/15/21). Paving completed (6/2/21). Grading and excavation on large western slope (6/24/21). Utility installation began (9/14/21). Home excavation began (12/28/21).

on measures listed in this section are being implemented?

Existing vegetation (4/27/20). EM 1, 2, 3, and 4 installed (9/22/20). Western portion of GN 9 seeded/matted along Giles Road (9/22/20). Entire site was drill seeded (4/6/22).

Checklist Questions

No

No, see BMP section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

N/A

No

No, See BMP section

Are construction entrances and adjacent streets being maintained adequately?

No

No, See BMP section Is dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action? N/A

Comments:

Comments:

Site was active for home construction during the most recent inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is recommended in the BMP section of this report.
 2) SF-1 for SAR-20200507-5452-GP2 (Giles Road/180th Street Improvements) was installed along the east side of EM 3 prior to the 8/2/21 inspection. The SF will not be included in this report and is part of the road improvement project. The SF has been marked on the SWPPP map to indicate its location within the temporary road project. This is also consistent with the silt fence wraps installed at ~K12 and the fuel tank at AA12.

CE 2 Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Construction Entrance Removed - Hawkins Const Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Excar section of the diversion do	Giles Road (BB14) truction paved the entran	ce prior to the inspection on 9 ce prior to the inspection on 9 ce prior to the inspection on 9 sion is no longer necessary as 1 sion is no longer necessary as 1	Removed						
CE 2 Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Construction Entrance Removed - Hawkins Const Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Excar section of the diversion do	Giles Road (BB14) truction paved the entran	ce prior to the inspection on 9 sion is no longer necessary assion is no longer necessary assion is no longer necessary assion is no longer necessary as	Removed						
Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Removed - Hawkins Const Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Excasection of the diversion do	ruction paved the entran E of SB A onstruction starting divers SE of SB A onstruction starting divers S of SB A onstruction starting divers W of SB A	sion is no longer necessary a sion is no longer necessary a sion is no longer necessary a	9/8/21. Removed s of 5/3/22. Removed						
Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Removed - Hawkins Const Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Excasection of the diversion do	ruction paved the entran E of SB A onstruction starting divers SE of SB A onstruction starting divers S of SB A onstruction starting divers W of SB A	sion is no longer necessary a sion is no longer necessary a sion is no longer necessary a	9/8/21. Removed s of 5/3/22. Removed						
D 1 Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Excar section of the diversion do	E of SB A onstruction starting divers SE of SB A onstruction starting divers S of SB A onstruction starting divers W of SB A	sion is no longer necessary a sion is no longer necessary a sion is no longer necessary a	Removed s of 5/3/22. Removed						
Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Removed - Due to home control Diversion Removed - Due to home control Diversion Removed - Due to home control Diversion Good Condition - JC Excarsection of the diversion do	onstruction starting diver SE of SB A onstruction starting diver S of SB A onstruction starting diver W of SB A	rsion is no longer necessary a	s of 5/3/22. Removed						
D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Exca section of the diversion do	SE of SB A onstruction starting divers S of SB A onstruction starting divers W of SB A	rsion is no longer necessary a	Removed						
D 3 Current Condition: D 4 Current Condition:	Diversion Removed - Due to home c Diversion Good Condition - JC Excar section of the diversion do	S of SB A onstruction starting diver W of SB A		s of 5/3/22	Diversion SE of SB A Removed					
Current Condition: D 4 Current Condition:	Removed - Due to home c Diversion Good Condition - JC Excar section of the diversion do	onstruction starting diver		J J. 010122.						
D 4 Current Condition:	Diversion Good Condition - JC Excar section of the diversion do	W of SB A		Removed						
Current Condition: D 5	Good Condition - JC Excar section of the diversion do		sion is no longer necessary a							
D 5	section of the diversion do	ration installed the seator	9/22/2020	Active	No No					
		oved as part of SAR-202 ted all disturbed areas pr	as of the 9/22/20 inspection, 200507-5452-GP2 for the 1801 rior to the inspection on 11/22	th St. improvements. Ha	wkins repaired the					
Current Condition:	Diversion	East side of site		Removed						
	Removed - Due to the com	pletion of primary civil de	evelopment as of the 8/2/21 ir	spection, the diversion	will not be installed					
ET 1	Erosion Control Terrace	See SWPPP Map	T	Removed						
			evelopment as of the 8/2/21 ir		Il not be installed.					
	Tromovou Buo to the con-	.p.oo., o. pa., o a.	ove.ope do e. d.e e, 2, 2 ·	ioposiion, and terrado in						
EM 1	Erosion Control Matting	See SWPPP Map		Removed						
Current Condition:	Removed - Due to home c	onstruction and the entire	e site being seeded the erosic	in control matting is no l	onger necessary.					
EM 2	Erosion Control Matting	See SWPPP Map		Removed						
Current Condition:	Removed - Due to home c	onstruction and the entire	e site being seeded the erosic	n control matting is no l	onger necessary.					
EM 3	Erosion Control Matting	See SWPPP Map	9/22/2020	Active	No					
İ	install storm prior to the ins	spection on 6/15/21. Haw /27/21 (see findings sect	ng prior to the 9/22/20 inspect kins installed silt fence at the ion). Hawkins repaired the slo	base of the hill where m	natting was remove					
EM 4	Erosion Control Matting	See SWPPP Map	9/22/2020	Active	No					
			ng prior to the 9/22/20 inspect							
EM 5	Erosion Control Matting	See SWPPP Map		Removed						
Current Condition: FT 1	Fuel Tank	On Site	ppear to be necessary as of th	Removed						
			prior to the 10/28/20 inspection		<u> </u>					
FT 2	Fuel Tank	On Site	2.1.5. 1.5 11.6 10/20/20 1/15PC010	Removed						
			ite prior to the 11/4/20 inspect							
FT 3	Fuel Tank	Adjacent to CE 1		Removed						
Current Condition:	Removed - Swain construction	tion removed the fuel tar	nk prior to the inspection on 6	/29/21.						
FT 4	Fuel Tank	western section of site		Removed						
			nk prior to the inspection on 6		.,					
Lot 1	Individual Lot	Lot 1	11/2/2022 on the lot on 11/2/22. Due to a	Active	Yes					
	BMP installation. Concrete waste should be Legacy Homes was inform	removed from the front o								
	1/4/23 (CIR #18242) Individual Lot	Lot 2	11/8/2022	Active	No					

Lot 4	Individual Lot	Lot 4	10/19/2022	Pending	Yes		
Current Condition:			lot prior to the inspection on 1				
Lot 5 Current Condition:	Silt fence should be install Legacy Homes was inform 12/8/22, 1/4/23 (CIR #1820 Individual Lot	ed along the front of the lined to complete by 11/2/2 42) Lot 5	2. Not done as of the last insp 9/28/2022	pection. Legacy Homes	Yes		
Current Condition:	Pending - Legacy Homes began excavation on the lot prior to the inspection on 9/28/22. SF 1 is already installed behind the lot Legacy Homes removed the dirt piles from the ROW prior to the inspection on 11/22/22. Silt fence should be installed along the front of the lot. Legacy Homes was informed to complete by 11/2/22. Not done as of the last inspection. Legacy Homes was reminded on 12/8/22, 1/4/23 (CIR #18242)						
Lot 6 Current Condition:	Individual Lot	Lot 6	10/19/2022 lot prior to the inspection on 1	Pending	Yes		
Lot 7	Silt fence should be install	ed along the front of the lead to complete by 11/2/2	V prior to the inspection on 11 ot. 2. Not done as of the last inspection of 10/19/2022		was reminded on Yes		
Current Condition:			lot prior to the inspection on 1				
	12/8/22, 1/4/23 (CIR #182	ned to complete by 11/2/2	2. Not done as of the last insp				
Lot 8 Current Condition:	Individual Lot	Lot 8	4/26/2022 n the lot prior to the inspection	Active	Yes		
Lot 9 Current Condition:	Homes installed silt fence along the front downhill corner of the lot prior to the inspection on 9/28/22. Silt fence should be repaired along the front of the lot. Legacy Homes was informed to complete by 11/2/22. Not done as of the last inspection. Legacy Homes was reminded on 12/8/22, 1/4/23 (CIR #18242) Individual Lot						
	12/8/22, 1/4/23 (CIR #182						
Lot 10 Current Condition:	Individual Lot Lot 10 4/26/2022 Active Yes Fair Condition - Legacy Homes began excavation on the lot prior to the inspection on 4/26/22. SF 1 is already installed behind the lot. Legacy Homes removed the dirt pile and concrete waste from the ROW prior to the inspection on 5/26/22. Legacy Homes installed silt fence along the front downhill corner of the lot prior to the inspection on 9/28/22. Silt fence should be repaired along the front of the lot. Legacy Homes was informed to complete by 11/2/22. Not done as of the last inspection. Legacy Homes was reminded on 12/8/22, 1/4/23 (CIR #18242)						
1 150 50		the state of the s	2. Not done as of the last insp	Dection: Legacy Florines	was reminded on		
Lot 52 - 53		the state of the s	4/26/2022	Pending	was reminded on Yes		
Lot 52 - 53 Current Condition:	12/8/22, 1/4/23 (CIR #182- Individual Lot Pending - Legacy Homes needed at this time. E&A i inspection on 8/10/22. Leg Silt fence should be reinsta	Lot 52 - 53 began excavation on the nspector will continue to r pacy Homes removed the alled.	4/26/2022 lot prior to the inspection on 4 monitor. Legacy Homes instal silt fence along the front of th	Pending //26/22. Lot is relatively led silt fence at the fron e lot for paving prior to	Yes flat so no BMPs are t of the lot prior to the the 9/12/22 inspection.		
	12/8/22, 1/4/23 (CIR #182. Individual Lot Pending - Legacy Homes needed at this time. E&A i inspection on 8/10/22. Leg Silt fence should be reinst. Legacy Homes was inform	Lot 52 - 53 began excavation on the nspector will continue to r pacy Homes removed the alled.	4/26/2022 lot prior to the inspection on 4 monitor. Legacy Homes instal silt fence along the front of th	Pending //26/22. Lot is relatively led silt fence at the fron e lot for paving prior to	Yes flat so no BMPs are t of the lot prior to the the 9/12/22 inspection.		

Current Condition:	lition: Pending - Legacy Homes began excavation on the lot prior to the inspection on 3/18/22. Legacy Homes removed the dirt pile from the ROW prior to the inspection on 4/26/22. Legacy Homes installed silt fence at the front of the lot prior to the inspection on 8/10/22. Legacy Homes removed the silt fence along the front of the lot for paving prior to the 9/12/22 inspection. Silt fence should be reinstalled.					
	Legacy Homes was inform 10/28/22, 12/8/22, 1/4/23 (2. Not done as of the last insp	ection. Legacy Homes	was reminded on	
Lot 56 - 57	Individual Lat	Lot EG E7	2/18/2022	Donding	Voc	
Current Condition:	Pending - Legacy Homes began excavation on the lot prior to the inspection on 3/18/22. Legacy Homes removed the dirt from the ROW prior to the inspection on 4/26/22. Legacy Homes installed silt fence at the front of the lot prior to the inspection on 8/10/22. Legacy Homes removed the silt fence along the front of the lot for paving prior to the 9/12/22 inspection. Silt fence should be reinstalled.					
	Legacy Homes was inform 10/28/22, 12/8/22, 1/4/23 (2. Not done as of the last insp	ection. Legacy Homes	was reminded on	
Lot 58 - 59	Individual Lot	Lot 58 - 59	3/18/2022	Pending	Yes	
Current Condition:	Pending - Legacy Homes be from the ROW prior to the on 8/10/22. Legacy Homes Silt fence should be reinsta	pegan excavation on the inspection on 4/26/22. Let removed the silt fence a silled.	lot prior to the inspection on 3, agacy Homes installed silt fend llong the front of the lot for particular to the lot for particular to the lot for particular to the last inspection of the last inspection.	118/22. Legacy Homes ce at the front of the lot ving prior to the 9/12/22	removed the dirt pile prior to the inspection inspection.	
Lot 60 - 61	Individual Lat	Lot 60 - 61	3/18/2022	Donding	Yes	
Current Condition:	Individual Lot		lot prior to the inspection on 3	Pending		
	Silt fence should be reinsta	ulled. ed to complete by 9/19/2	llong the front of the lot for pav			
Lot 62 - 63	Individual Lot	Lot 62 - 63	4/26/2022	Pending	Yes	
Current Condition:	Pending - Legacy Homes began excavation on the lot prior to the inspection on 4/26/22. Legacy Homes installed silt fence at the front of the lot prior to the inspection on 8/10/22. Legacy Homes removed the silt fence along the front of the lot for paving prior to the 9/12/22 inspection. Silt fence should be reinstalled Legacy Homes was informed to complete by 8/24/22. Not done as of the last inspection. Legacy Homes was reminded on 9/9/22, 9/14/22, 10/28/22, 1/4/23 (CIR #18242)					
Lot 64 65	Individual Lot	Lot 64 - 65	4/14/2022	Pending	Voc	
Lot 64 - 65 Current Condition:			4/14/2022		Yes	
Carron Condition.	Pending - Legacy Homes began excavation on the lot prior to the inspection on 4/14/22. Legacy Homes removed the dirt pile from the ROW prior to the inspection on 4/26/22. Legacy Homes installed silt fence at the front of the lot prior to the inspection on 8/10/22. Legacy Homes removed the silt fence along the front of the lot for paving prior to the 9/12/22 inspection. Silt fence should be reinstalled Legacy Homes was informed to complete by 8/24/22. Not done as of the last inspection. Legacy Homes was reminded on 9/9/22, 9/14/22, 10/28/22, 12/8/22, 1/4/23 (CIR #18242)					
Lot 66 - 67	Individual Lot	Lot 66 - 67	4/14/2022	Pending	Yes	
Current Condition:			lot prior to the inspection on 4	/14/22. Legacy Homes	removed the dirt pile	
	from the ROW prior to the on 8/10/22. Legacy Homes Silt fence should be reinsta Legacy Homes was inform 10/28/22, 12/8/22, 1/4/23 (co. 10/28/22, 12/8/22, 1/4/23)	inspection on 4/26/22. Let removed the silt fence a silt	egacy Homes installed silt fend long the front of the lot for par and the front of the lot for par 2. Not done as of the last insp	ce at the front of the lot ving prior to the 9/12/22 dection. Legacy Homes	prior to the inspection inspection.	
Lot 68 - 69	Individual Lot	Lot 68 - 69		Removed		
Current Condition:	Removed - Legacy Homes	sodded the lots prior to t	the inspection on 9/28/22.			
Lot 70 - 71	Individual Lot	Lot 70 - 71		Removed		
Current Condition:	Removed - Legacy Homes		the inspection on 11/17/22.			
Lot 72 - 73	Individual Lot	Lot 72 - 73	12/28/2021	Pending	Yes	
LULIZIO	mulvidual LUL	LUL 12 - 13	1212012021	I renaing	163	

Current Condition:	Pending - Legacy Homes began excavation on the lot prior to the inspection on 12/28/21. Legacy Homes removed the dirt piles from the ROW prior to the inspection on 2/22/22. Legacy Homes installed silt fence along the northwest corner of the lot prior to the inspection on 2/22/22. Legacy Homes reinstalled silt fence at the front of the lot prior to the inspection on 8/10/22. Legacy Homes removed the silt fence along the front of the lot for paving prior to the 9/12/22 inspection.					
	Silt fence should be reinstalled					
	Legacy Homes was inform 9/9/22, 9/14/22, 10/28/22,		22. Not done as of the last insp 3242)	ection. Legacy Homes	was reminded on	
Lot 74 - 75	Individual Lot	Lot 74 - 75	12/28/2021	Pending	Yes	
Current Condition:	Pending - Legacy Homes began excavation on the lot prior to the inspection on 12/28/21. Legacy Homes removed the dirt piles from the ROW prior to the inspection on 2/8/22. Legacy Homes installed silt fence along the northwest corner of the lot prior to the inspection on 3/7/22. Legacy Homes removed the silt fence for utility installation prior to the inspection on 4/14/22. Legacy Homes reinstalled silt fence at the front of the lot prior to the inspection on 8/10/22. Legacy Homes removed the silt fence along the front of the lot for paving prior to the 9/12/22 inspection. Silt fence should be reinstalled.					
	Legacy Homes was informed to complete by 9/19/22. Not done as of the last inspection. Legacy Homes was reminded on 10/28/22, 12/8/22, 1/4/23 (CIR #18242)					
Lot 76 - 77	Individual Lot	Lot 76 - 77	1/4/2022	Pending	Yes	
Current Condition:			lot prior to the inspection on 1.			
	from the ROW prior to the inspection on 2/22/22. Legacy Homes installed silt fence along the northwest corner of the lot prior to the inspection on 3/7/22. Legacy Homes removed the silt fence for utility installation prior to the inspection on 4/14/22. Legacy Homes reinstalled silt fence at the front of the lot prior to the inspection on 8/10/22. Legacy Homes removed the silt fence along the front of the lot for paving prior to the 9/12/22 inspection. Silt fence should be reinstalled. Legacy Homes was informed to complete by 8/24/22. Not done as of the last inspection. Legacy Homes was reminded on 9/9/22, 9/14/22, 10/28/22, 1/4/23 (CIR #18242)					
1 170 70			T	I 5 .	1	
Lot 78 - 79 Current Condition:	Individual Lot	Lot 78 - 79	the inspection on 11/17/22.	Removed		
	<u> </u>		the inspection on 11/1/1/22.		ı	
Lot 80 - 81	Individual Lot	Lot 80 - 81	1	Removed		
Current Condition:	Removed - Legacy Homes	s sodded the lots prior to	the inspection on 11/17/22.			
Lot 82 - 83	Individual Lot	Lot 82 - 83		Removed		
Current Condition:	Removed - Legacy Homes	s sodded the lot prior to t	the inspection on 11/8/22.			
Lot 84 - 85	Individual Lot	Lot 84 - 85	2/8/2022	Active	Yes	
	Fair Condition - Legacy Homes began excavation on the lot prior to the inspection on 2/8/22. Legacy Homes removed the dirt pile from the ROW prior to the inspection on 3/7/22. Legacy Homes installed silt fence along the northern edge of the lot prior to the inspection on 3/29/22. Silt fence should be repaired along the street. Legacy Homes was informed to complete by 6/13/22. Not done as of the last inspection. Legacy Homes was reminded on 7/7/22, 7/27/22, 8/18/22, 9/9/22, 9/14/22, 10/28/22, 12/8/22, 1/4/23 (CIR #18242)					
Lot 86 - 87	Individual Lot	Lot 86 - 87	2/8/2022	Active	Yes	
Current Condition:	Fair Condition - Legacy Homes began excavation on the lot prior to the inspection on 2/8/22. Legacy Homes removed the dirt pile from the ROW prior to the inspection on 3/7/22. Legacy Homes installed silt fence in the northeast corner of the lot prior to the inspection on 3/29/22. Silt fence should be repaired at the front of the lot. Legacy Homes was informed to complete by 9/19/22. Not done as of the last inspection. Legacy Homes was reminded on 10/28/22, 12/8/22, 1/4/23 (CIR #18242)					
Lot 88 - 89	Individual Lot	Lot 88 - 89	2/15/2022	Active	Yes	
Current Condition:	Fair Condition - Legacy Homes began excavation on the lot prior to the inspection on 2/15/22. Legacy Homes removed the dirt pile from the ROW and installed silt fence along the northeast corner of the lot prior to the inspection on 3/29/22. Silt fence should be repaired at the front of the lot. Legacy Homes was informed to complete by 9/19/22. Not done as of the last inspection. Legacy Homes was reminded on 10/28/22, 12/8/22, 1/4/23 (CIR #18242)					
Lot 90 - 91	Individual Lot	Lot 90 - 91	2/15/2022	Active	Yes	
Current Condition:	Fair Condition - Legacy Ho pile from the ROW and ins	omes began excavation of stalled silt fence along the	on the lot prior to the inspection e northeast corner of the lot pri	on 2/15/22. Legacy H	omes removed the dirt	
	Silt fence should be repaired at the front of the lot. Legacy Homes was informed to complete by 9/19/22. Not done as of the last inspection. Legacy Homes was reminded on 10/28/22, 1/8/23 (CIR #18242)					
Lot 92 - 93	Individual Lot	Lot 92 - 93	3/1/2022	Pending	Voc	
LUI 92 - 93	muividuai Lot	LUI 92 - 93	3/ 1/2022	Pending	Yes	

Current Condition:	Pending - Legacy Homes began excavation on the lot prior to the inspection on 3/1/22. A dirt pile was observed in the ROW but due to the lot being actively excavated no recommendations will be made at this time. The E&A inspector will continue to monitor for dirt pile removal. Silt fence should be installed along the front of the lot. Legacy Homes was informed to complete by 9/19/22. Not done as of the last inspection. Legacy Homes was reminded on						
	Legacy Homes was inform 10/28/22, 12/8/22, 1/4/23 (2. Not done as of the last insp	ection. Legacy Homes	was reminded on		
Lot 118 - 119	Individual Lot	Lot 118 - 119	7/18/2022	Active	No		
Current Condition:	Good Condition - Legacy F	lomes began excavation	on the lot prior to the inspection	on on 7/18/22. Due to v	regetative buffer along		
	the back of the lots no BMPs will be recommended at this time. Legacy Homes removed the dirt pile from the ROW prior to the inspection on 8/10/22. Legacy Homes installed silt fence along the front and rear corners of the lot prior to the inspection on 9/28/22.						
Lot 130 - 131	Individual Lot	Lot 130 - 131	10/13/2022	Active	No		
Current Condition:	0 ,	•	t prior to the inspection on 10/ ne. Legacy Homes removed th	•	•		
Lot 148	Individual Lot	Lot 148	5/18/2022	Active	Yes		
Current Condition:	piles from the ROW prior t recommended at this time. 9/28/22. Silt fence along the front of	o the inspection on 7/18/2. Legacy Homes installed f the lot should be repaire	n the lot prior to the inspection 22. Due to the vegetative buffer silt fence along the front and led. 22. Not done as of the last inspection.	er along the back of the rear corners of the lot p	lot no BMPs will be prior to the inspection on		
MS 1	Material Storage	On Site		Removed			
Current Condition:		evelopment is complete a	s of the 8/2/21 inspection. Mas report.		attributed to		
PB X Current Condition:	Portable Bathroom	On Site	2/22/2022 toilet on site prior to the inspec	Active	Yes		
	portable toilet prior to the inspection on 3/7/22. Legacy Homes secured a second portable toilet on site prior to the inspection on 4/6/22. Legacy Homes stood up and secured the portable toilet prior to the 7/13/22 inspection. Portable toilets should be secured. Legacy Homes was informed to complete by 9/14/22. Not done as of the last inspection. Legacy Homes was reminded on 9/14/22, 10/28/22, 1/2/8/22, 1/4/23 (CIR #18242)						
SB A	Sediment Basin	04	10/20/2020	Active	No		
Current Condition:	Good Condition - 0% Filled - The basin was partly dug out prior to the 6/10/20 inspection. The basin was fully dug out and the baffle installed by JC Excavation prior to the 9/22/20 inspection. JC Excavation finished installed the riser prior to the 10/20/20 inspection. The E&A inspector painted the cleanout mark on the riser during the 11/4/20 inspection. Minor erosion was observed at the basin outfall during the 3/31/21 inspection. Damage to the baffle was observed on 6/2/21. KDI Excavating began cleaning out the basin prior to the 11/2/22 inspection. KDI Excavating finished cleaning out the basin prior to the inspection on 11/17/22. KDI Excavating removed the baffle during the cleanout. As of 11/17/22 the baffle will not be recommended to be reinstalled. The E&A inspector repainted the cleanout mark on the riser during the 11/30/22 inspection.						
SF 1	Silt fence	S6-X7	5/6/2020	Active	Yes		
Current Condition:	Fair Condition - JC Excavation installed the silt fence prior to the 5/6/20 inspection. The SB A berm is built up adjacent to the drainage ditch as of the 6/19/20 inspection, extending the silt fence is no longer recommended. JC Excavation partially cleaned out, trenched in, and repaired the silt fence prior to the 7/6/20 inspection, further maintenance is recommended. JC Excavation cleaned out and repaired the silt fence at V7 prior to the 7/13/20 inspection. The silt fence was partially removed at T6 for utility work prior to the 9/22/20 inspection. JC Excavation patched some of the silt fence prior to the 10/9/20 inspection. All silt fence maintenance is being sent to Legacy Homes as of 2/1/22. 1.) The silt fence should be extended around the disturbance behind the basin until the area is stabilized. 2.) Silt fence needs to be reinstalled where removed for infrastructure work. 1.) JC Excavation was informed to complete by 8/25/20. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 9/11/20, 10/9/20, 1/13/21, 3/5/21, 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21, Legacy Homes was reminded on 2/3/22, 2/24/22, 3/17/22, 3/31/22, 4/71/22, 4/21/22, 5/4/22, 5/19/22, 6/7/22, 7/71/22, 7/77/22, 8/18/22, 9/14/22, 10/28/22, 12/8/22, 12/8/22, 1/4/23 (CIR #18242) 2.) JC Excavation/Gene Graves were informed to complete by 3/11/21. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21, Legacy Homes was reminded on 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21, Legacy Homes was reminded on 2/3/22, 2/24/22, 3/17/22, 3/31/22, 4/7/22, 4/21/22, 5/19/22, 6/7/22, 7/7/22, 8/18/22, 9/14/22, 10/28/22, 1/4/23 (CIR #18242)						
SF 2	Silt fence	D13-D7-J4	5/6/2020	Active	No		
Current Condition:	Good Condition - JC Excar	vation installed the silt fer prior to the inspection or	nce prior to the 5/6/20 inspectin 8/9/21. All silt fence mainten	on. Hawkins Construct	ion removed a section of		
SF 3	Silt fence	CC9-X7	5/6/2020	Active	Yes		

	through the silt fence. The	maintenance recommer	ted sediment along the silt to idation will remain until prope during the 4/15/21 inspection	er maintenance is compl			
	1.) The silt fence needs to be cleaned out where full. 2.) Erosion outside of the silt fence should be repaired where silt fence is full. 3.) The silt fence should be repaired on the east side of the run.						
	10/9/20, 1/13/21, 3/5/21, 3/ Homes was reminded on 5 2.) JC was informed to con 9/16/21, 10/20/21, 12/2/21, 9/14/22, 10/28/22, 12/8/22, 3.) JC was informed to con		one as of the last inspection. 6/10/21, 7/9/21, 8/19/21, 9/1/7/22, 7/27/22, 8/18/22, 9/14/9 ene as of the last inspection. 6/10/24 Homes was reminded on 5/10/24 one as of the last inspection. 6/10/24 on 5/19/22, 5/19/22, 6/7/24	6/21, 10/20/21, 12/2/21, 22, 10/28/22, 12/8/22, 1 JC Excavation/Gene Gra 4/22, 5/19/22, 6/7/22, 7/	2/10/22, 3/31/22 Legacy /4/23 (CIR #18242) aves was reminded on /7/22, 7/27/22, 8/18/22, raves was reminded on		
SF 4	Silt fence	Interior Streets	3/21/2022	Active	Yes		
Current Condition:	fence needed to be trenche 3/29/22. Gene Graves exterdamaged areas of silt fence 1.) Silt fence along Robin I. 2.) All interior street silt fence 1.) Legacy Homes was info 7/7/22, 7/27/22, 8/18/22, 9/	ed in as of the inspection ended the silt fence along e prior to the inspection of the should be backfilled ce should be maintained ormed to complete by 6/1/14/22, 10/28/22, 12/8/22	I where undermined 3/22. Not done as of the last	ence was trenched in pri pection on 4/14/22. Lega	or to the inspection on cy Homes repaired all		
STR	Streets	Giles Road	4/27/2020	Active	Yes		
Current Condition:	the inspection on 3/15/22. 3/23/22. Minor sediment with streets during the inspection of active Legacy Homes was inform	Street cleaning is still ned as observed in the ROW action on 5/3/22. lots should be cleaned deducted to complete by 5/4/22	acy Homes as of 2/1/22. Legacessary. Legacy Homes clear during the inspection on 3/2: laily or as often as needed. Not done as of the last insp/9/22, 9/14/22, 10/28/22, 12/	ned all interior streets pi 3/22. Great Plains was i ection. Legacy Homes v	rior to the inspection on n the process of cleaning was reminded on		
SWPPP Sign	Misc./Other	Giles Road	7/13/2020	Pending	No		
Current Condition:		uring the 10/28/20 inspec	PP sign at Q13 during the 7/ ction. SWPPP sign was remo sign on 8/20/21.				
WO 1	Concrete Washout	On Site	3/21/22.	Active	Yes		
Current Condition:	out the concrete washout p Concrete waste should be Legacy Homes was inform	orior to the inspection on cleaned up. ed to complete by 3/22/2	washout on site prior to the interest of the interest of the last ins 2, 7/7/22, 7/27/22, 8/18/22, 9/27/22, 8/18/22, 9/27/22, 7/27/22, 8/18/22, 9/27/22, 8/18/22, 9/27/22, 8/27/22/22, 8/27/22/22, 8/27/22/22, 8/2	pection. Legacy Homes	was reminded to		
WO 2	Concrete Washout	On Site		Removed			
Current Condition:			ut prior to the inspection on 6		T		
WS 1	Waste Storage	On Site	o of the 0/0/04 in an artist iii	Removed	waste staron I		
Current Condition:	Removed - Primary civil de lot basis.	evelopment is complete a	s of the 8/2/21 inspection, th	e irispector will monitor	waste storage on a lot by		
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
Inspector Signature:	Brya M Wazht			Reviewed By:	St Su		

Fair Condition - JC Excavation installed the silt fence prior to the 5/6/20 inspection. The silt fence was partially cleaned out prior

Current Condition: