E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

E&A - P2017.483.001 Bill SID as of 10/27/20 P2017.483.000

	Bill SID as of 10/2	7/20 P2017.483.000			
	Stage				
	1				
	2/25/2023				
	180th & Giles Roa	d (NE), Sarpy County, NE			
90	0%		T	T	
90	0%				
90)%				
95	5%				
85	5%				
35	5%				
Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time	
				Week	
0.00"					
0.00"					
0.00"					
0.00"	2/22/2023	Overcast 28	11:35 AM		
0.00"					
0.00"					
0.00"					
None					
TOTIC					
	90 90 95 50 85 35 Amount in tenths	Wind SAR-2019 CSW- 2/2 180th & Giles Roa 90% 90% 90% 90% 90% 95% 50% 85% 35% Amount in tenths Date inspected 0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.00"	180th & Giles Road (NE), Sarpy County, NE 90% 90% 90% 95% 50% 85% 35%	Windsor East SAR-20191014-5177-GP1 CSW-201904190 2/25/2023 180th & Giles Road (NE), Sarpy County, NE 90% 90% 90% 95% 50% 85% 35% 35%	

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began in the eastern portion of the site (4/27/20). Grading began over all portions of the site (7/13/20). Grading on site has ceased due to winter conditions (2/9/21). Paving began all portions of site (4/15/21). Paving completed (6/2/21). Grading and excavation on large western slope (6/24/21). Utility installation began (9/14/21). Home excavation began (12/28/21).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began in the eastern portion of the site (4/27/20). Grading began over all portions of the site (7/13/20). Grading on site has ceased due to winter conditions (2/9/21). Paving began all portions of site (4/15/21). Paving completed (6/2/21). Grading and excavation on large western slope (6/24/21). Utility installation began (9/14/21). Home excavation began (12/28/21).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (4/27/20). EM 1, 2, 3, and 4 installed (9/22/20). Western portion of GN 9 seeded/matted along Giles Road (9/22/20). Entire site was drill seeded (4/6/22).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No

Create Corrective Action?

No, see BMP section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No

NO Create Corrective Action?

No, See BMP section

Are construction entrances and adjacent streets being maintained adequately

No

Create Corrective Action?

No, See BMP section Is dust associated with the construction activity adequately controlled on the site? Yes Create Corrective Action? N/A

Comments:

Comments:

Site was active for home construction during the most recent inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is recommended in the BMP section of this report.
 2) SF-1 for SAR-20200507-5452-GP2 (Giles Road/180th Street Improvements) was installed along the east side of EM 3 prior to the 8/2/21 inspection. The SF will not be included in this report and is part of the road improvement project. The SF has been marked on the SWPPP map to indicate its location within the temporary road project. This is also consistent with the silt fence wraps installed at ~K12 and the fuel tank at AA12.

CE 2 Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Construction Entrance Removed - Hawkins Const Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Excar section of the diversion do	Giles Road (BB14) truction paved the entran	ce prior to the inspection on 9 ce prior to the inspection on 9 ce prior to the inspection on 9 sion is no longer necessary as 1 sion is no longer necessary as 1	Removed							
CE 2 Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Construction Entrance Removed - Hawkins Const Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Excar section of the diversion do	Giles Road (BB14) truction paved the entran	ce prior to the inspection on 9 sion is no longer necessary assion is no longer necessary assion is no longer necessary assion is no longer necessary as	Removed							
Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Removed - Hawkins Const Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Excasection of the diversion do	ruction paved the entran E of SB A onstruction starting divers SE of SB A onstruction starting divers S of SB A onstruction starting divers W of SB A	sion is no longer necessary a sion is no longer necessary a sion is no longer necessary a	9/8/21. Removed s of 5/3/22. Removed							
Current Condition: D 1 Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Removed - Hawkins Const Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Excasection of the diversion do	ruction paved the entran E of SB A onstruction starting divers SE of SB A onstruction starting divers S of SB A onstruction starting divers W of SB A	sion is no longer necessary a sion is no longer necessary a sion is no longer necessary a	9/8/21. Removed s of 5/3/22. Removed							
D 1 Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Excar section of the diversion do	E of SB A onstruction starting divers SE of SB A onstruction starting divers S of SB A onstruction starting divers W of SB A	sion is no longer necessary a sion is no longer necessary a sion is no longer necessary a	Removed s of 5/3/22. Removed							
Current Condition: D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Removed - Due to home control Diversion Removed - Due to home control Diversion Removed - Due to home control Diversion Good Condition - JC Excarsection of the diversion do	onstruction starting diver SE of SB A onstruction starting diver S of SB A onstruction starting diver W of SB A	rsion is no longer necessary a	s of 5/3/22. Removed							
D 2 Current Condition: D 3 Current Condition: D 4 Current Condition:	Diversion Removed - Due to home c Diversion Removed - Due to home c Diversion Good Condition - JC Exca section of the diversion do	SE of SB A onstruction starting divers S of SB A onstruction starting divers W of SB A	rsion is no longer necessary a	Removed							
D 3 Current Condition: D 4 Current Condition:	Diversion Removed - Due to home c Diversion Good Condition - JC Excar section of the diversion do	S of SB A onstruction starting diver W of SB A		s of 5/3/22	Diversion SE of SB A Removed						
Current Condition: D 4 Current Condition:	Removed - Due to home c Diversion Good Condition - JC Excar section of the diversion do	onstruction starting diver		J J. 010122.							
D 4 Current Condition:	Diversion Good Condition - JC Excar section of the diversion do	W of SB A		Removed							
Current Condition: D 5	Good Condition - JC Excar section of the diversion do		sion is no longer necessary a								
D 5	section of the diversion do	ration installed the seator	9/22/2020	Active	No No						
		oved as part of SAR-202 ted all disturbed areas pr	as of the 9/22/20 inspection, 200507-5452-GP2 for the 1801 rior to the inspection on 11/22	th St. improvements. Ha	wkins repaired the						
Current Condition:	Diversion	East side of site		Removed							
	Removed - Due to the com	pletion of primary civil de	evelopment as of the 8/2/21 ir	spection, the diversion	will not be installed						
ET 1	Erosion Control Terrace	See SWPPP Map	I	Removed							
			evelopment as of the 8/2/21 ir		Il not be installed.						
	Tromovou Buo to the con-	.p.oo o. pa. y o a.	ove.ope do e. a.e e, 2, 2 ·	ioposiusii, aio toituos iii							
EM 1	Erosion Control Matting	See SWPPP Map		Removed							
Current Condition:	Removed - Due to home c	onstruction and the entire	e site being seeded the erosic	in control matting is no l	onger necessary.						
EM 2	Erosion Control Matting	See SWPPP Map		Removed							
Current Condition:	Removed - Due to home c	onstruction and the entire	e site being seeded the erosic	n control matting is no l	onger necessary.						
EM 3	Erosion Control Matting	See SWPPP Map	9/22/2020	Active	No						
İ	install storm prior to the ins	spection on 6/15/21. Haw /27/21 (see findings sect	ng prior to the 9/22/20 inspect kins installed silt fence at the ion). Hawkins repaired the slo	base of the hill where m	natting was remove						
EM 4	Erosion Control Matting	See SWPPP Map	9/22/2020	Active	No						
			ng prior to the 9/22/20 inspect								
EM 5	Erosion Control Matting	See SWPPP Map		Removed							
Current Condition: FT 1	Fuel Tank	On Site	ppear to be necessary as of th	Removed							
			prior to the 10/28/20 inspection		<u> </u>						
FT 2	Fuel Tank	On Site	2.1.5. 1.5 11.6 10/20/20 1/15PC010	Removed							
			ite prior to the 11/4/20 inspect								
FT 3	Fuel Tank	Adjacent to CE 1		Removed							
Current Condition:	Removed - Swain construction	tion removed the fuel tar	nk prior to the inspection on 6	/29/21.							
FT 4	Fuel Tank	western section of site		Removed							
			nk prior to the inspection on 6		.,						
Lot 1	Individual Lot	Lot 1	11/2/2022 on the lot on 11/2/22. Due to a	Active	Yes						
	BMP installation. Concrete waste should be Legacy Homes was inform	removed from the front o									
	1/4/23 (CIR #18242) Individual Lot	Lot 2	11/8/2022	Active	No						

Lot 4	Individual Lot	Lot 4	10/19/2022	Pending	Yes				
Current Condition:			lot prior to the inspection on 1 W prior to the inspection on 1		y installed behind the lot.				
	Silt fence should be installed along the front of the lot.								
	Legacy Homes was inform 12/8/22, 1/4/23 (CIR #182		22. Not done as of the last ins	pection. Legacy Homes	was reminded on				
Lot 5	Individual Lot	Lot 5	9/28/2022	Pending	Yes				
Current Condition:			lot prior to the inspection on 9						
	Legacy Homes removed to Silt fence should be install Legacy Homes was inform	Legacy Homes removed the dirt piles from the ROW prior to the inspection on 11/22/22. Silt fence should be installed along the front of the lot. Legacy Homes was informed to complete by 11/2/22. Not done as of the last inspection. Legacy Homes was reminded on 12/8/22, 1/4/23 (CIR #18242)							
Lot 6	Individual Lot	Lot 6	10/19/2022	Pending	Yes				
Current Condition:	Legacy Homes removed to Silt fence should be install	Pending - Legacy Homes began excavation on the lot prior to the inspection on 10/19/22. SF 1 is already installed behind the lot. Legacy Homes removed the dirt piles from the ROW prior to the inspection on 11/22/22. Silt fence should be installed along the front of the lot. Legacy Homes was informed to complete by 11/2/22. Not done as of the last inspection. Legacy Homes was reminded on							
Lot 7	Individual Lot	Lot 7	10/19/2022	Pending	Yes				
Current Condition:	Legacy Homes removed t	Pending - Legacy Homes began excavation on the lot prior to the inspection on 10/19/22. SF 1 is already installed behind the lot. Legacy Homes removed the dirt piles from the ROW prior to the inspection on 11/22/22. Silt fence should be installed along the front of the lot.							
	Legacy Homes was inform 12/8/22, 1/4/23 (CIR #182		22. Not done as of the last ins	pection. Legacy Homes	was reminded on				
Lot 8	Individual Lot	Lot 8	4/26/2022	Active	No				
Current Condition:	the lot. Legacy Homes ren	moved the dirt pile and co along the front downhill o	non the lot prior to the inspect oncrete waste from the ROW porner of the lot prior to the insertion on 2/8/23.	prior to the inspection of	n 5/26/22. Legacy				
Lot 9	Individual Lot	Lot 9	4/26/2022	Active	No				
Current Condition:	the lot. Legacy Homes rer	moved the dirt pile and co along the front downhill o	on the lot prior to the inspect encrete waste from the ROW p corner of the lot prior to the ins aspection on 2/8/23.	prior to the inspection of	n 5/26/22. Legacy				
Lot 10	Individual Lot	Lot 10	4/26/2022	Active	No				
Current Condition:	the lot. Legacy Homes rer	moved the dirt pile and co along the front downhill o	on the lot prior to the inspect encrete waste from the ROW p corner of the lot prior to the ins aspection on 2/8/23.	prior to the inspection of	n 5/26/22. Legacy				
Lot 52 - 53	Individual Lot	Lot 52 - 53	4/26/2022	Active	No				
Current Condition:	Good Condition - Legacy are needed at this time. E the inspection on 8/10/22.	&A inspector will continue. Legacy Homes removed	on the lot prior to the inspect e to monitor. Legacy Homes in I the silt fence along the front long the front of the lot prior to	ion on 4/26/22. Lot is re nstalled silt fence at the of the lot for paving prio	elatively flat so no BMPs front of the lot prior to or to the 9/12/22				
Lot 54 - 55	Individual Lot	Lot 54 - 55	3/18/2022	Active	No				
Current Condition:	pile from the ROW prior to inspection on 8/10/22. Le	o the inspection on 4/26/2 gacy Homes removed the	on the lot prior to the inspect 12. Legacy Homes installed sile silt fence along the front of the nt of the lot prior to the inspec	It fence at the front of the lot for paving prior to	e lot prior to the				
Lot 56 - 57	Individual Lot	Lot 56 - 57	3/18/2022	Active	No				
Current Condition:	Good Condition - Legacy pile from the ROW prior to inspection on 8/10/22. Legacy	Homes began excavation of the inspection on 4/26/2 gacy Homes removed the	on the lot prior to the inspect 2. Legacy Homes installed siles silt fence along the front of the nt of the lot prior to the inspec	It fence at the front of the lot for paving prior to	e lot prior to the				
Lot 58 - 59	Individual Lot	Lot 58 - 59	3/18/2022	Active	No				
Current Condition:	Good Condition - Legacy pile from the ROW prior to inspection on 8/10/22. Legacy	Homes began excavation the inspection on 4/26/2 gacy Homes removed the	on the lot prior to the inspect 22. Legacy Homes installed sil silt fence along the front of the nt of the lot prior to the inspec	ion on 3/18/22. Legacy It fence at the front of the ne lot for paving prior to	Homes removed the dirt e lot prior to the				
Lot 60 - 61	Individual Lot	Lot 60 - 61	3/18/2022	Active	No				
	•	•	•	•	•				

Current Condition:	pile from the ROW prior to inspection on 8/10/22. Leg	the inspection on 4/26/2 acy Homes removed the	on the lot prior to the inspection 2. Legacy Homes installed silt silt fence along the front of the nt of the lot prior to the inspect	fence at the front of the lot for paving prior to	e lot prior to the			
Lot 62 - 63	Individual Lot	Lot 62 - 63	4/26/2022	Active	No			
Current Condition:	fence at the front of the lot	prior to the inspection or	on the lot prior to the inspection 8/10/22. Legacy Homes remotes installed straw wattles along	oved the silt fence alor	g the front of the lot for			
Lot 64 - 65	Individual Lot	Lot 64 - 65	4/14/2022	Active	No			
Current Condition:	pile from the ROW prior to inspection on 8/10/22. Leg	the inspection on 4/26/2 acy Homes removed the	on the lot prior to the inspection the lot prior to the inspection of the silt silt fence along the front of the int of the lot prior to the inspection of the lot prior to the lot prior t	fence at the front of the lot for paving prior to	e lot prior to the			
Lot 66 - 67	Individual Lot	Lot 66 - 67	4/14/2022	Active	No			
Current Condition:	pile from the ROW prior to inspection on 8/10/22. Leg	the inspection on 4/26/2 acy Homes removed the	on the lot prior to the inspectic 2. Legacy Homes installed silt silt fence along the front of the nt of the lot prior to the inspect	fence at the front of the lot for paving prior to	e lot prior to the			
Lot 68 - 69	Individual Lot	Lot 68 - 69		Removed				
Current Condition:	Removed - Legacy Homes	sodded the lots prior to	the inspection on 9/28/22.					
Lot 70 - 71	Individual Lot	Lot 70 - 71		Removed				
Current Condition:	Removed - Legacy Homes	sodded the lots prior to	the inspection on 11/17/22.	•				
Lot 72 - 73	Individual Lot	Lot 72 - 73	12/28/2021	Active	No			
Current Condition:	dirt piles from the ROW pr prior to the inspection on 2	ior to the inspection on 2. 1/22/22. Legacy Homes re ne silt fence along the fro	on the lot prior to the inspection /22/22. Legacy Homes installe sinstalled silt fence at the front int of the lot for paving prior to spection on 2/8/23.	d silt fence along the r of the lot prior to the i	northwest corner of the lonspection on 8/10/22.			
Lot 74 - 75	Individual Lot	Lot 74 - 75	12/28/2021 on the lot prior to the inspection	Active	No			
Lot 76 - 77	prior to the inspection on 3 Legacy Homes reinstalled	1/7/22. Legacy Homes rer silt fence at the front of the lot for paving prior to the	/8/22. Legacy Homes installed moved the silt fence for utility in the lot prior to the inspection or e 9/12/22 inspection. Legacy H	nstallation prior to the in 8/10/22. Legacy Hom	nspection on 4/14/22. les removed the silt			
Current Condition:								
	piles from the ROW prior to prior to the inspection on 3 Legacy Homes reinstalled fence along the front of the the lot prior to the inspection	Good Condition - Legacy Homes began excavation on the lot prior to the inspection on 1/4/22. Legacy Homes removed the dirt piles from the ROW prior to the inspection on 2/22/22. Legacy Homes installed silt fence along the northwest corner of the lot prior to the inspection on 3/7/22. Legacy Homes removed the silt fence for utility installation prior to the inspection on 4/14/22. Legacy Homes reinstalled silt fence at the front of the lot prior to the inspection on 8/10/22. Legacy Homes removed the silt fence along the front of the lot for paving prior to the 9/12/22 inspection. Legacy Homes installed straw wattles along the front of the lot prior to the inspection on 2/8/23.						
Lot 78 - 79	Individual Lot	Lot 78 - 79	th - in	Removed				
Current Condition:	<u> </u>		the inspection on 11/17/22.		1			
Lot 80 - 81 Current Condition:	Individual Lot Removed - Legacy Homes	Lot 80 - 81 s sodded the lots prior to	the inspection on 11/17/22.	Removed				
Lot 82 - 83	Individual Lot	Lot 82 - 83		Removed				
Current Condition:	Removed - Legacy Homes		ne inspection on 11/8/22.	Removed	!			
Lot 84 - 85	Individual Lot	Lot 84 - 85	2/8/2022	Active	Yes			
Current Condition:	Fair Condition - Legacy Hopile from the ROW prior to the inspection on 3/29/22. Silt fence should be repair	the inspection on 3/7/22 and along the street.	n the lot prior to the inspectior Legacy Homes installed silt f	ence along the norther	mes removed the dirt n edge of the lot prior to			
	7/7/22, 7/27/22, 8/18/22, 9	/9/22, 9/14/22, 10/28/22,	12/8/22, 1/4/23 (CIR #18242)		was reminded on			
Lot 86 - 87		<mark>/9/22, 9/14/22, 10/28/22,</mark> Lot 86 - 87	12/8/22, 1/4/23 (CIR #18242) 2/8/2022	Active	Yes			
Lot 86 - 87 Current Condition:	7/7/22, 7/27/22, 8/18/22, 9 Individual Lot Fair Condition - Legacy Ho	Lot 86 - 87 omes began excavation of the inspection on 3/7/22		on 2/8/22. Legacy Ho	Yes mes removed the dirt			
	7/7/22, 7/27/22, 8/18/22, 9 Individual Lot Fair Condition - Legacy Ho pile from the ROW prior to the inspection on 3/29/22. Silt fence should be repair Legacy Homes was inform	Lot 86 - 87 mes began excavation of the inspection on 3/7/22 ed at the front of the lot. led to complete by 9/19/2	2/8/2022 on the lot prior to the inspection	n on 2/8/22. Legacy Ho ence in the northeast o	Yes mes removed the dirt corner of the lot prior to			
	7/7/22, 7/27/22, 8/18/22, 9 Individual Lot Fair Condition - Legacy Hopile from the ROW prior to the inspection on 3/29/22. Silt fence should be repair	Lot 86 - 87 mes began excavation of the inspection on 3/7/22 ed at the front of the lot. led to complete by 9/19/2	2/8/2022 In the lot prior to the inspection Legacy Homes installed silt f	n on 2/8/22. Legacy Ho ence in the northeast o	Yes mes removed the dirt corner of the lot prior to			

Current Condition:	Fair Condition - Legacy Homes began excavation on the lot prior to the inspection on 2/15/22. Legacy Homes removed the dirt pile from the ROW and installed silt fence along the northeast corner of the lot prior to the inspection on 3/29/22. Silt fence should be repaired at the front of the lot.					
	Legacy Homes was inform 10/28/22, 12/8/22, 1/4/23 (2. Not done as of the last insp	ection. Legacy Homes	was reminded on	
Lot 90 - 91	Individual Lot	Lot 90 - 91	2/15/2022	Active	Yes	
Current Condition:			n the lot prior to the inspection		omes removed the dirt	
	pile from the ROW and installed silt fence along the northeast corner of the lot prior to the inspection on 3/29/22. Silt fence should be repaired at the front of the lot. Legacy Homes was informed to complete by 9/19/22. Not done as of the last inspection. Legacy Homes was reminded on 10/28/22, 12/8/22, 1/4/23 (CIR #18242)					
1 100 00			0.440000			
Lot 92 - 93	Individual Lot	Lot 92 - 93	3/1/2022	Pending	Yes	
Current Condition:	Pending - Legacy Homes began excavation on the lot prior to the inspection on 3/1/22. A dirt pile was observed in the ROW but due to the lot being actively excavated no recommendations will be made at this time. The E&A inspector will continue to monitor for dirt pile removal. Silt fence should be installed along the front of the lot. Legacy Homes was informed to complete by 9/19/22. Not done as of the last inspection. Legacy Homes was reminded on					
1 = 1 440 440	10/28/22, 12/8/22, 1/4/23 (7/40/0000	Λ -4:	NI-	
Lot 118 - 119 Current Condition:	Individual Lot	Lot 118 - 119	7/18/2022	Active	No No	
	Good Condition - Legacy Homes began excavation on the lot prior to the inspection on 7/18/22. Due to vegetative buffer along the back of the lots no BMPs will be recommended at this time. Legacy Homes removed the dirt pile from the ROW prior to the inspection on 8/10/22. Legacy Homes installed silt fence along the front and rear corners of the lot prior to the inspection on 9/28/22. Legacy Homes installed straw wattles along the front of the lot prior to the inspection on 2/8/23.					
Lot 130 - 131	Individual Lot	Lot 130 - 131	10/13/2022	Active	No	
Current Condition:	Active - Legacy Homes began excavation on the lot prior to the inspection on 10/13/22. Due to vegetative buffer along the back of the lots no BMPs will be recommended at this time. Legacy Homes removed the dirt piles from the ROW prior to the inspection on 11/22/22.					
Lot 148	Individual Lot	Lot 148	5/18/2022	Active	No	
Current Condition:	Good Condition - Legacy Homes began excavation on the lot prior to the inspection on 5/18/22. Legacy Homes removed the dirt piles from the ROW prior to the inspection on 7/18/22. Due to the vegetative buffer along the back of the lot no BMPs will be recommended at this time. Legacy Homes installed silt fence along the front and rear corners of the lot prior to the inspection on 9/28/22. Legacy Homes installed straw wattles along the front of the lot prior to the inspection on 2/8/23.					
MS 1	Material Storage	On Site		Removed		
Current Condition:			is of the 8/2/21 inspection. Mass report.	aterial storage on site is	s attributed to	
PB X	Portable Bathroom	On Site	2/22/2022	Active	Yes	
Current Condition:	Fair Condition - Legacy homes installed a portable toilet on site prior to the inspection on 2/22/22. Legacy Homes secured the portable toilet prior to the inspection on 3/7/22. Legacy Homes secured a second portable toilet on site prior to the inspection on 4/6/22. Legacy Homes stood up and secured the portable toilet prior to the 7/13/22 inspection. Portable toilets should be secured. Legacy Homes was informed to complete by 9/14/22. Not done as of the last inspection. Legacy Homes was reminded on 9/14/22, 10/28/22, 12/8/22, 1/4/23 (CIR #18242), 2/23/23					
SB A	Sediment Basin	04	10/20/2020	Active	No	
Current Condition:	Good Condition - 0% Filled baffle installed by JC Exca inspection. The E&A inspection. The E&A inspection observed at the basin outfle cleaning out the basin prio 11/17/22. KDI Excavating I	d - The basin was partly of vation prior to the 9/22/20 ector painted the cleanouall during the 3/31/21 insperto to the 11/2/22 inspection removed the baffle during	lug out prior to the 6/10/20 ins 0 inspection. JC Excavation fit t mark on the riser during the bection. Damage to the baffle on. KDI Excavating finished cle g the cleanout. As of 11/17/22 but mark on the riser during the	pection. The basin wa nished installed the ris 11/4/20 inspection. Mi was observed on 6/2/2 aning out the basin pri- the baffle will not be re	s fully dug out and the er prior to the 10/20/20 nor erosion was 1. KDI Excavating began or to the inspection on	
SF 1	Silt fence	S6-X7	5/6/2020	Active	Yes	
L SF I	Silt fence	Ου-λ/	3/0/2020	Active	res	

Current Condition:	Fair Condition - JC Excavation installed the silt fence prior to the 5/6/20 inspection. The SB A berm is built up adjacent to the drainage ditch as of the 6/19/20 inspection, extending the silt fence is no longer recommended. JC Excavation partially cleaned out, trenched in, and repaired the silt fence prior to the 7/6/20 inspection, further maintenance is recommended. JC Excavation cleaned out and repaired the silt fence at V7 prior to the 7/13/20 inspection. The silt fence was partially removed at T6 for utility work prior to the 9/22/20 inspection. JC Excavation patched some of the silt fence prior to the 10/9/20 inspection. All silt fence maintenance is being sent to Legacy Homes as of 2/1/22. 1.) The silt fence should be extended around the disturbance behind the basin until the area is stabilized. 2.) Silt fence needs to be reinstalled where removed for infrastructure work. 1.) JC Excavation was informed to complete by 8/25/20. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 9/11/20, 10/9/20, 1/13/21, 3/5/21, 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21, Legacy Homes was reminded on 2/3/22, 2/24/22, 3/17/22, 3/31/22, 4/71/22, 4/71/22, 5/4/22, 5/19/22, 6/71/22, 7/71/22, 7/71/22, 8/18/22, 9/14/22, 10/28/22, 1/2/8/22, 1/4/23 (CIR #18242) 2.) JC Excavation/Gene Graves were informed to complete by 3/11/21. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, Legacy Homes was					
	10/28/22, 12/8/22, 1/4/23 (CIR #18242)	22, 4/21/22, 5/4/22, 5/19/22, 6			
SF 2 Current Condition:		prior to the inspection or	5/6/2020 ace prior to the 5/6/20 inspect a 8/9/21. All silt fence mainter to the inspection on 4/6/22.			
SF 3	Silt fence	CC9-X7	5/6/2020	Active	Yes	
05.4	to the 3/31/21 inspection. The remaining accumulated sediment along the silt fence needs to be removed to allow water to filter through the silt fence. The maintenance recommendation will remain until proper maintenance is completed. Minor damage was observed to the south end of the silt fence run during the 4/15/21 inspection. 1.) The silt fence needs to be cleaned out where full. 2.) Erosion outside of the silt fence should be repaired where silt fence is full. 3.) The silt fence should be repaired on the east side of the run. 1.) JC was informed to complete by 9/16/20. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 10/9/20, 1/13/21, 3/5/21, 3/16/21, 4/23/21, 5/20/21, 6/10/21, 7/9/21, 8/19/21, 9/16/21, 10/20/21, 12/2/21, 2/10/22, 3/31/22 Legacy Homes was reminded on 5/4/22, 5/19/22, 6/7/22, 7/7/22, 7/27/22, 8/18/22, 9/14/22, 10/28/22, 12/8/22, 1/4/23 (CIR #18242) 2.) JC was informed to complete by 8/24/21. Not done as of the last inspection. JC Excavation/Gene Graves was reminded on 9/16/21, 10/20/21, 12/2/21, 2/10/22, 3/31/22 Legacy Homes was reminded on 5/4/22, 5/19/22, 6/7/22, 7/7/22, 7/27/22, 8/18/22, 9/14/22, 10/28/22, 1/4/23 (CIR #18242) 3.) JC was informed to complete by 10/26/21. Not done as of the last inspection. JC Excavation/Gene Graves was reminded on 12/2/21, 2/10/22, 3/31/22 Legacy Homes was reminded on 5/4/22, 5/19/22, 6/7/22, 7/27/22, 8/18/22, 9/14/23, 10/28/22, 1/4/23 (CIR #18242)					
SF 4	Silt fence	Interior Streets	3/21/2022	Active	Yes	
Current Condition:	fence needed to be trenche 3/29/22. Gene Graves exter damaged areas of silt fence. 1.) Silt fence along Robin E. 2.) All interior street silt fence. 1.) Legacy Homes was infor 7/7/22, 7/27/22, 8/18/22, 9/2.) Legacy Homes was infor 1/4/23 (CIR #18242)	ed in as of the inspection anded the silt fence along a prior to the inspection of the should be backfilled accessored to complete by 6/1 (14/22, 10/28/22, 12/8/22) armed to complete by 12/	where undermined. 3/22. Not done as of the last i, 1/4/23 (CIR #18242) 14/22. Not done as of the last	nce was trenched in pricection on 4/14/22. Legacense in the section on 4/14/22. Legacense inspection. Legacy Homes inspection. Legacy Homes inspection. Legacy Homes inspection.	er to the inspection on cy Homes repaired all less was reminded on mes was reminded on	
STR Current Condition:	Streets Fair Condition - Street class	Giles Road	4/27/2020 cv Homes as of 2/1/22 Legal	Active	Yes	
Current Condition:	Fair Condition - Street cleaning will be sent to Legacy Homes as of 2/1/22. Legacy Homes partially cleaned the streets prior to the inspection on 3/15/22. Street cleaning is still necessary. Legacy Homes cleaned all interior streets prior to the inspection on 3/23/22. Minor sediment was observed in the ROW during the inspection on 3/23/22. Great Plains was in the process of cleaning the streets during the inspection on 5/3/22. Legacy Homes partially cleaned the streets prior to the inspection on 2/1/23. Street cleaning is still needed. All streets in front of active lots should be cleaned daily or as often as needed. Legacy Homes was informed to complete by 5/4/22. Not done as of the last inspection. Legacy Homes was reminded on 5/19/22, 6/7/22, 6/16/22, 7/7/22, 7/27/22, 8/18/22, 9/9/22, 9/14/22, 10/28/22, 1/8/22, 1/4/23 (CIR #18242), 2/23/23					
SWPPP Sign	Misc./Other	Giles Road	7/13/2020	Pending	No	
Current Condition:	Good Condition - E&A ins	pector installed the SWP uring the 10/28/20 inspec	PP sign at Q13 during the 7/1 tion. SWPPP sign was remov	3/20 inspection. The E	&A inspector reinstalled	
WO 1	Concrete Washout	On Site	3/21/22.	Active	Yes	

Current Condition:	Fair Condition - Legacy Homes installed a concrete washout on site prior to the inspection on 4/26/22. Legacy Homes cleaned out the concrete washout prior to the inspection on 12/7/22. Legacy Homes cleaned out the concrete washout prior to the inspection on 2/1/23.					
	Concrete waste should be cleaned up. Legacy Homes was informed to complete by 3/22/22. Not done as of the last inspection. Legacy Homes was reminded to complete on 4/7/22, 4/21/22, 5/4/22, 5/19/22, 6/7/22, 7/7/22, 7/27/22, 8/18/22, 9/14/22, 10/28/22, 12/8/22, 1/4/23 (CIR #18242)					
WO 2	Concrete Washout	On Site		Removed		
Current Condition:	Removed - Swain Constru	ction removed the washo	ut prior to the inspection on 6/	8/21.		
WS 1	Waste Storage	On Site		Removed		
Current Condition:	Removed - Primary civil development is complete as of the 8/2/21 inspection, the inspector will monitor waste storage on a lot by lot basis.					
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
Inspector Signature:	Brega M Wazht			Reviewed By:	G. 6 S. 6)	