E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402A6863:F7009.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

Environmental Services D	ept. Manager			3	9	
		E&A - P20	17.483.002			
		Bill SID - P2	2017.483.010			
Inspector: Bryce Wright		Stage				
epooto.: 2.yee :g		Windsor West GRE-20190812-5114-GP1				
		1				
Project Name:						
For Week Ending:		68136				
Project Location:		7/29/2023 180th & Giles Road (SW), Sarpy County, NE				
•			77 13			
Grading:	90%	ó				
Sanitary Sewer:	75%	ó				
Storm Sewer:	75%	o l				
Paving:	70%					
Seeding:	75%	0				
Utilities:	60%	, 0				
Overall Development:	30%	6				
DAIN FALL AMOUNTS	Amount in tenths	T	I			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time	
					Week	
Sunday:	0.00"					
Monday:	0.17"					
Tuesday:	0.00"					
Wednesday:	0.00"	7/26/2023	Sunny 73	7:10 AM		
Thursday:	0.00"		-			
Friday:	0.02"					
Saturday:	0.00"					
Compleinter						
Complaints:						

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began in drainage area DEV C (7/28/20). Grading began in drainage area DEV C and DEV B (8/3/20). Grading began in DEV A (10/28/20). Grading on site has ceased due to winter conditions (2/9/21). Grading resumed in all drainage areas (4/5/21). Storm and sanitary began installation (7/26/21). Paving began on site (9/21/21). Grading in the southern section began (11/30/21). Grading in southern section resumed (06/01/22). Electric installation began (2/22/23). All grading on site ceased (3/8/23). Sidewalk paving on all interior streets (3/15/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began in drainage area DEV C (7/28/20). Grading began in drainage area DEV C and DEV B (8/3/20). Grading began in DEV A (10/28/20). Grading on site has ceased due to winter conditions (2/9/21). Grading resumed in all drainage areas (4/5/21). Storm and sanitary began installation (7/26/21). Paving began on site (9/21/21). Grading in the southern section began (11/30/21). Grading in southern section resumed (06/01/22). Electric installation began (2/22/23). All grading on site ceased (3/8/23). Sidewalk paving on all interior streets (3/15/23).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (7/28/20). Entire site has volunteer vegetation growing (7/7/21). Seed and matting installed on slope along Meridian Street (12/28/21). Entire site was beginning to be seeded (4/6/22). Seed and mat around all installed sidewalks on site (3/29/23). Entire site was seeded (6/7/23).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No

Create Corrective Action?

No, See BMP section

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion Yes

Create Corrective Action

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action

N/A

Comments:

Site was **in**active during the current inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section of this report.
- 2) SF-1 for SAR-20200507-5452-GP2 (Giles Road/180th Street Improvements) was installed along Giles Road on the west end of the site prior to the 8/9/21 inspection. The SF will not be included in this report and is part of the road improvement project. The SF has been marked on the SWPPP map to indicate its location within the temporary road project. Also applies to silt fence east of river on north side of Giles Rd and the fuel tank located near CE 1. The fuel tank was removed prior to the inspection on 9/19/22. Silt fence checks were installed as part of the road project along Giles Rd. prior to the inspection on

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
CE 1	Construction Entrance	Giles Road (BB3)		Removed	
Current Condition:	Removed - Hawkins Cons	struction paved the Con	struction entrance prior to the	inspection on 5/3/23.	•
CE 2	Construction Entrance	180th Street (DD9)	· · · · · · · · · · · · · · · · · · ·	Removed	
Current Condition:		\ /	ide of the site as of 5/18/22.	Removed	
			Territoria site as of 3/16/22.	 	I
CE 3	Construction Entrance	L3		Removed	
Current Condition:		21. Construction entrand	onstruction entrance, graded to ce will not be recommended to		
D 1	Diversion	N17-E17	8/14/2020	Active	No
Current Condition:			sion prior to the 7/18/22 inspe		
D 2	Diversion	N17-U17	8/14/2020	Active	No
Current Condition:		_	rsion prior to the 7/13/22 inspe		110
D 3		West of SB A	1/13/2021	Active	No
Current Condition:	Diversion		to the 1/13/21 inspection. JC		
D 4	4/5/21 inspection, the insp	pector will monitor as the	e diversion is redefined. JC Exercises Graves reinstalled the divers	xcavation/Gene Grave	s reinstalled the
Current Condition:			rersion prior to the inspection		
	the diversion prior to the i	nspection on 11/22/22.	Gene Graves reinstalled the d	liversion prior to the ins	spection on 4/5/23.
D 5	Diversion	West of SB B	10/13/2022	Active	No
Current Condition:	the diversion prior to the i	nspection on 11/22/22.	rersion prior to the inspection of Gene Graves reinstalled the d	liversion prior to the ins	
D 6	Diversion	SW of SB C	PP as of the 10/6/2020 revision	Removed	
Current Condition: D 7	Diversion	S of SB A	The 10/6/2020 revision	Removed	
Current Condition:	Removed - Due to paving	and the site being vege	etated the diversion is no long	er necessary as of the	
D 8	Diversion	M25-N17	1/20/2021	Active	No
Current Condition:	Good Condition - JC insta	· · · · · · · · · · · · · · · · · · ·	to the 7/26/22 inspection.		
D 9	Diversion	X15-SB B		D 1	
0 10 10				Removed	
Current Condition:	ı ,	and the site being vege	I etated the diversion is no long	er necessary as of the	7/26/22 inspection
D 10	Diversion	and the site being vege		er necessary as of the Removed	7/26/22 inspection
D 10 Current Condition:	Diversion Removed - D10 has been	AA10-AA9 removed from the SWI	etated the diversion is no long PPP as of the 10/6/2020 revis	er necessary as of the Removed ion.	7/26/22 inspection
D 10 Current Condition: D 11	Diversion Removed - D10 has been Diversion	AA10-AA9 removed from the SWI S of SB C	PPP as of the 10/6/2020 revis	Removed ion. Removed	7/26/22 inspection
D 10 Current Condition: D 11 Current Condition:	Diversion Removed - D10 has been Diversion Removed - D11 has been	AA10-AA9 removed from the SWI S of SB C removed from the SWI		Removed ion. Removed ion.	7/26/22 inspection
D 10 Current Condition: D 11 Current Condition: D 12	Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion	AA10-AA9 removed from the SWI S of SB C removed from the SWI E of SB B	PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis	Removed ion. Removed ion. Removed ion. Removed	7/26/22 inspection
D 10 Current Condition: D 11 Current Condition: D 12 Current Condition:	Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves	AA10-AA9 removed from the SWI S of SB C removed from the SWI E of SB B removed the diversion I	PPP as of the 10/6/2020 revis	Removed ion. Removed ion. Removed ion. Removed ion. Removed inspection.	7/26/22 inspection
D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition:	Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves Erosion Control Terrace Removed - Due to paving	AA10-AA9 removed from the SWI S of SB C removed from the SWI E of SB B removed the diversion I See SWPPP Map the terrace is no longer	PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis or paving prior to the 7/26/22	er necessary as of the Removed ion. Removed ion. Removed inspection. Removed	7/26/22 inspection
D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2	Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves Erosion Control Terrace Removed - Due to paving Erosion Control Terrace	AA10-AA9 removed from the SWI S of SB C removed from the SWI E of SB B removed the diversion I See SWPPP Map the terrace is no longer	PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis or paving prior to the 7/26/22 recessary as of 5/18/22.	Removed ion. Removed ion. Removed ion. Removed ion. Removed inspection.	7/26/22 inspection
D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves Erosion Control Terrace Removed - Due to paving Erosion Control Terrace Removed - Due to paving	AA10-AA9 removed from the SWI S of SB C removed from the SWI E of SB B removed the diversion I See SWPPP Map the terrace is no longer	PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis or paving prior to the 7/26/22	er necessary as of the Removed ion. Removed ion. Removed inspection. Removed	7/26/22 inspection
D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2	Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves Erosion Control Terrace Removed - Due to paving Erosion Control Terrace	AA10-AA9 removed from the SWI S of SB C removed from the SWI E of SB B removed the diversion I See SWPPP Map the terrace is no longer	PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis or paving prior to the 7/26/22 recessary as of 5/18/22.	er necessary as of the Removed ion. Removed ion. Removed inspection. Removed	7/26/22 inspection
D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2 Current Condition:	Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves Erosion Control Terrace Removed - Due to paving Erosion Control Terrace Removed - Due to paving	AA10-AA9 removed from the SWI S of SB C removed from the SWI E of SB B removed the diversion I See SWPPP Map the terrace is no longer See SWPPP Map the terrace is no longer See SWPPP Map	PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis for paving prior to the 7/26/22 r necessary as of 5/18/22. r necessary as of 5/18/22. 8/14/2020	Removed ion. Removed ion. Removed ion. Removed ion. Removed inspection. Removed	
D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition:	Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves Erosion Control Terrace Removed - Due to paving Erosion Control Terrace Removed - Due to paving Erosion Control Terrace Removed - Due to paving Control Terrace Removed - Due to paving Control Terrace Good Condition - JC insta	AA10-AA9 removed from the SWI S of SB C removed from the SWI E of SB B removed the diversion I See SWPPP Map the terrace is no longer See SWPPP Map the terrace is no longer See SWPPP Map	PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis or paving prior to the 7/26/22 recessary as of 5/18/22. recessary as of 5/18/22. 8/14/2020 the 7/26/22 inspection.	er necessary as of the Removed ion. Removed ion. Removed inspection. Removed Removed Active	No
D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 2 Current Condition: ET 3	Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves Erosion Control Terrace Removed - Due to paving Erosion Control Terrace Removed - Due to paving Erosion Control Terrace Good Condition - JC insta Erosion Control Matting Pending - The erosion con	AA10-AA9 removed from the SWI S of SB C removed from the SWI E of SB B removed the diversion I See SWPPP Map the terrace is no longer See SWPPP Map the terrace is no longer See SWPPP Map the terrace prior to See SWPPP Map	PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis for paving prior to the 7/26/22 r necessary as of 5/18/22. r necessary as of 5/18/22. 8/14/2020	Removed ion. Removed ion. Removed ion. Removed ion. Removed inspection. Removed Active Pending	No No
D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1 Current Condition: ET 2 Current Condition: ET 3 Current Condition: ET 3 Current Condition:	Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves Erosion Control Terrace Removed - Due to paving Erosion Control Terrace Removed - Due to paving Erosion Control Terrace Good Condition - JC insta	AA10-AA9 removed from the SWI S of SB C removed from the SWI E of SB B removed the diversion to See SWPPP Map the terrace is no longer See SWPPP Map the terrace is no longer See SWPPP Map the terrace prior to See SWPPP Map	PPP as of the 10/6/2020 revis PPP as of the 10/6/2020 revis For paving prior to the 7/26/22 recessary as of 5/18/22. 8/14/2020 the 7/26/22 inspection. 3/5/2021	Removed ion. Removed ion. Removed ion. Removed ion. Removed inspection. Removed Active Pending	No No

EM 3	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No	
Current Condition:	grade.		Illed within the seeding windo			
EM 4	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No	
Current Condition:	grade.	illoi malling will be insta	alled within the seeding window	w when the associated	a area reacries illiai	
EM 5	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No	
Current Condition:	•	ntrol matting will be insta	alled within the seeding window	w when the associated	d area reaches final	
EM 6	grade. Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No	
Current Condition:			illed within the seeding window			
	grade.			T - "		
EM 7 Current Condition:	Pending - The erosion cor	See SWPPP Map	3/5/2021	Pending w when the associated	No Larea reaches final	
ouncin condition.	Pending - The erosion control matting will be installed within the seeding window when the associated area reaches final grade.					
FT X	Fuel Tank	On Site		Removed		
Current Condition:	Removed - Cedar Constru		ank from site prior to the insp	ection on 8/10/22.		
FT Y	Fuel Tank	On Site		Removed		
Current Condition:	Removed - The double wa	Interior Streets curb	ved from the site prior to the i	nspection on 11/30/21		
IF 1-32	Inlet Filters	inlets	5/17/2023	Active	No	
Current Condition:	Good Condition - Comme		let filters in all interior street of	curb inlets prior to the i	inspection on 5/17/23.	
MS 1	Material Storage	On Site	8/14/2020	Active	No	
Current Condition:	Good condition - Sewer pi	pes being stored on site				
PB X	Portable Bathroom	On Site	1/25/2023	Active	No	
Current Condition:	Good Condition - JC Excavation brought a portable toilet on site prior to the 6/8/21 inspection. JC Excavation removed the portable toilet prior to the inspection on 9/8/21. MBC brought a portable toilet on site and secured it prior to the inspection on 10/13/21. MBC removed the portable toilet from the site prior to the inspection on 10/26/21. Cedar Construction installed and secured a portable toilet on site prior to the inspection on 6/29/22. Cedar Construction stood up and secured the portable toilet prior to the 7/13/22 inspection. Cedar Construction removed the portable toilet from the site prior to the inspection on 9/19/22. Nelson Construction installed and secured a portable toilet on site prior to the inspection on 1/25/23.					
SB A	Sediment Basin	M10	1/20/2021	Active	Yes	
Current Condition:			in and installed the baffle prio			
	The second secon		cleaned out. ractor to complete maintenan	ce with the SID on 6/1	/22. Not done as of the	
SB B	last inspection. Sediment Basin	V7	10/28/2020	Active	Yes	
Current Condition:			prior to the 10/28/20 inspecti			
	mark during the 11/4/20 inspection. JC Excavation is doing work on the riser during the 7/20/21 inspection. No recommendations will be made at this time and the E&A inspector will continue to monitor. JC backfilled around the riser prior to the 8/2/21 inspection. JC repaired the erosion around the riser prior to the inspection on 9/15/21. CDS Enterprise began cleaning out the basin during the inspection on 4/6/22. CDS Enterprise completed cleanout of the basin prior to the inspection on 6/29/22. E&A inspector repainted the cleanout mark on the riser during the 8/10/22 inspection. The baffle needs to be installed per the SWPPP. JC Excavation/Gene Graves were informed to complete by 3/22/21. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 3/26/21, 4/16/21, 5/20/21, 6/10/21, 6/25/21, 7/17/21, 8/19/21, 9/2/21, 10/15/21, 11/17/21, 12/2/21,					
	Graves were reminded on	3/26/21, 4/16/21, 5/20/2	21, 6/10/21, 6/25/21, 7/17/21,			
SB C		3/26/21, 4/16/21, 5/20/2	21, 6/10/21, 6/25/21, 7/17/21,			
SB C Current Condition:	Graves were reminded on 2/10/22 3/31/22 6/7/22 1 Sediment Basin	0 3/26/21, 4/16/21, 5/20/2 12/1/22 1/4/23 (CIR #18 Z4	21, 6/10/21, 6/25/21, 7/17/21, 252)	8/19/21, 9/2/21, 10/15 Active	/21, 11/17/21, 12/2/21, Yes	
	Graves were reminded on 2/10/22 3/31/22 6/7/22 1 Sediment Basin Fair Condition - 50% Fille mark during the 11/4/20 in Enterprise was dewatering prior to the inspection on 6 Basin needs to be clean	13/26/21, 4/16/21, 5/20/2 12/1/22 1/4/23 (CIR #18 Z4 d - JC installed the basin respection. CDS Enterpris g the basin into silt fence 6/22/22.	2 <mark>1, 6/10/21, 6/25/21, 7/17/21, 25/2) </mark>	8/19/21, 9/2/21, 10/15 Active ion. The E&A inspects in during the inspection/22. CDS completed	Yes or painted the cleanout on on 4/6/22. CDS cleanout of the basin	
Current Condition:	Graves were reminded on 2/10/22 3/31/22 6/7/22 1 Sediment Basin Fair Condition - 50% Fille mark during the 11/4/20 ir Enterprise was dewatering prior to the inspection on 6 Basin needs to be clean E&A inspector is in the Silt fence	13/26/21, 4/16/21, 5/20/2 12/1/22 1/4/23 (CIR #18 Z4 d - JC installed the basin respection. CDS Enterprise g the basin into silt fence 6/22/22. ed out. Process of lining up a control of Site	21, 6/10/21, 6/25/21, 7/17/21, 25/2) 10/28/2020 10/28/2020 10/28/20 inspect se began cleaning out the base during the inspection on 5/10 contractor to complete main 10/20/2020	Active Active ion. The E&A inspection during the inspection of t	Yes or painted the cleanout on on 4/6/22. CDS cleanout of the basin O on 7/26/23. No	
Current Condition:	Graves were reminded on 2/10/22 3/31/22 6/7/22 4 Sediment Basin Fair Condition - 50% Fille mark during the 11/4/20 ir Enterprise was dewatering prior to the inspection on 6 Basin needs to be clean E&A inspector is in the Silt fence Good Condition - JC instates B to install storm. E&A inspection on 4/19/22. Gree 4/19/22. Gene Graves extremoved a portion of the silt fence.	a 3/26/21, 4/16/21, 5/20/2 12/1/22 1/4/23 (CIR #18 Z4 d - JC installed the basin respection. CDS Enterprise go the basin into silt fence 6/22/22. ed out. process of lining up a company of the silt fence prior to the inspector will continue the silt fence from silt fence prior to the inspector to the inspector to the inspector to the inspector silt fence prior silt fence prior to the inspector silt fence prior	21, 6/10/21, 6/25/21, 7/17/21, 25/2) 10/28/2020 n prior to the 10/28/20 inspect se began cleaning out the base during the inspection on 5/10	Active ion. The E&A inspection. The E&A inspection of the inspecti	Yes or painted the cleanout on on 4/6/22. CDS cleanout of the basin O on 7/26/23. No a small section north of creek prior to the to the inspection on inknown contractor epaired the silt fence	
Current Condition:	Graves were reminded on 2/10/22 3/31/22 6/7/22 4 Sediment Basin Fair Condition - 50% Fille mark during the 11/4/20 ir Enterprise was dewatering prior to the inspection on 6 Basin needs to be clean E&A inspector is in the Silt fence Good Condition - JC insta SB B to install storm. E&A inspection on 4/19/22. Gre 4/19/22. Gene Graves extremoved a portion of the sprior to the inspection on 4/19/25.	a 3/26/21, 4/16/21, 5/20/2 12/1/22 1/4/23 (CIR #18 Z4 d - JC installed the basin respection. CDS Enterprise go the basin into silt fence 6/22/22. ed out. process of lining up a continue to the silt fence prior to the inspector will continue to the silt fence from silt fence from silt fence prior to the inspector to the inspec	21, 6/10/21, 6/25/21, 7/17/21, 25/21 10/28/2020 10/28/2020 se began cleaning out the base during the inspection on 5/10 contractor to complete main 10/20/2020 the 10/20/20 inspection. JC to monitor. Great Plains instal paired, and extended the silt fin SB B to SB A prior to the 7/pection on 11/22/22. Gene Gra	Active ion. The E&A inspection. The E&A inspection of the inspecti	Yes or painted the cleanout on on 4/6/22. CDS cleanout of the basin O on 7/26/23. No a small section north of creek prior to the to the inspection on inknown contractor epaired the silt fence	

Current Condition:	Removed - Crops are out of the ground as of the 10/20/20 inspection, silt fence below grading activities will be included under SF 1.					
SF 3	Silt fence	N of Giles Road	10/20/2020	Active	No	
Current Condition:	Good Condition - JC installed the silt fence prior to the 10/20/20 inspection. Hawkins Construction removed a portion of this silt fence, graded the area, and installed their own silt fence prior to the inspection on 8/17/21. E&A inspector will continue to monitor. Great Plains repaired the entire run of silt fence prior to the inspection on 4/19/22.					
SF 4	Silt fence	NE Corner Across RR		Active	No	
Current Condition:	Good Condition - Dave Doll installed some of the silt fence prior to the 1/28/2021 inspection. The undermined portion of the silt fence was backfilled prior to the 3/31/21 inspection. West end of drainage is fully vegetated so silt fence is no longer recommended on 6/8/21. Hawkins Construction removed the northern run of silt fence, graded the area, and installed their own silt fence prior to the inspection on 8/17/21. Gene Graves cleaned out the silt fence and extended the silt fence around the west end of the dirt piles prior to the inspection on 4/26/22.					
SF 5	Silt fence	Interior streets	6/13/2022	Active	Yes	
Current Condition:	Fair Condition - Gene Graves installed silt fence along Meridian Street to the 7/13/22 inspection. Gene Graves installed silt fence along all interior street corners prior to the inspection on 7/18/22. Gene Graves reinstalled multiple sections of silt fence along Portal street that were removed for utility installation prior to the inspection on 9/28/22. Gene Graves removed multiple sections of silt fence prior to the inspection on 11/22/22. Reinstallation will not be recommended at this time. E&A inspector will continue to monitor. Gene Graves repaired the silt fence prior to the inspection on 4/5/23. Interior street silt fence should be reinstalled and repaired once site is overseeded. Gene Graves was informed to complete by 5/3/23. Not done as of the last inspection. Peter Katt was reminded on 7/6/23					
STR	Streets	Giles Road/180th	7/28/2020	Active	Yes	
Current Condition:		Street	Enterprise cleaned the streets			
	6/29/22. Street cleaning was in progress by OPPD during the inspection on 3/1/23. Gene Graves Development cleaned the street prior to the inspection on 5/3/23. Interior streets should be cleaned. Peter Katt was informed to complete by 7/6/23. Not done as of the last inspection.					
SWPPP Sign	Misc./Other	S 148th Ave & Meridian St.	8/10/2020	Active	No	
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign at Y3 during the 8/10/20 inspection. E&A inspector reinstalled the SWPPP sign during the inspection on 2/22/22. E&A inspector reinstalled the SWPPP sign at S 148th Ave and Meridian St. during the inspection on 10/19/22. E&A inspector reinstalled the SWPPP sign during the inspection on 11/30/22. E&A inspector moved the SWPPP sign to the entrance on 182nd and Giles prior to the inspection on 6/7/23.					
WO 1	Concrete Washout	On Site	3/5/2021	Pending	No	
Current Condition:	Pending - A concrete was					
WS 1	Waste Storage	On Site	3/5/2021	Pending	No	
Current Condition:	Pending - Waste will be contained on site and in proper containment vessels.					
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."					
Inspector Signature:	Broga M Waght			Reviewed By:	St Sil	