E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402A6863:F7009.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Engineering Answers

Environmental Services Dept. Manager							
		E&A - P2	017.483.002				
		Bill SID - P	2017.483.010				
Inspector: Bryce Wright		Stage					
	Windsor West						
	GRE-20190812-5114-GP1						
Project Name:	CSW-201903993						
For Week Ending:		,	9/9/2023		68136		
Project Location:		180th & Giles Road (SW), Sarpy County, NE					
Grading:		90%					
Sanitary Sewer:		75%					
Storm Sewer:		75%					
Paving:		70%					
Seeding:		75%					
Utilities:		60%					
Overall Development:							
	1						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm event time		
					Week 1		
Sunday:	0.00"						
Monday:	0.00"						
Tuesday:	0.01"						
Wednesday:	0.00"	9/6/2023	Overcast 63	10:35 AM			
Thursday:	0.00"						
Friday:	0.00"						
Saturday:	0.00"						
Complaints:					•		

Construction Sequencing:

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Rough grading began in drainage area DEV C (7/28/20). Grading began in drainage area DEV C and DEV B (8/3/20). Grading began in DEV A (10/28/20). Grading on site has ceased due to winter conditions (2/9/21). Grading resumed in all drainage areas (4/5/21). Storm and sanitary began installation (7/26/21). Paving began on site (9/21/21). Grading in the southern section began (11/30/21). Grading in southern section resumed (06/01/22). Electric installation began (2/22/23). All grading on site ceased (3/8/23). Sidewalk paving on all interior streets (3/15/23). Storm sewer installation began on the southern section of the site (8/9/23).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Rough grading began in drainage area DEV C (7/28/20). Grading began in drainage area DEV C and DEV B (8/3/20). Grading began in DEV A (10/28/20). Grading on site has ceased due to winter conditions (2/9/21). Grading resumed in all drainage areas (4/5/21). Storm and sanitary began installation (7/26/21). Paving began on site (9/21/21). Grading in the southern section began (11/30/21). Grading in southern section resumed (06/01/22). Electric installation began (2/22/23). All grading on site ceased (3/8/23). Sidewalk paving on all interior streets (3/15/23). Storm sewer installation began on the southern section of the site (8/9/23).

Existing vegetation (7/28/20). Entire site has volunteer vegetation growing (7/7/21). Seed and matting installed on slope along Meridian Street (12/28/21). Entire site was beginning to be seeded (4/6/22). Seed and mat around all installed sidewalks on site (3/29/23). Entire site was seeded (6/7/23).

Checklist Questions:

cent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? No

No, See BMP section

Yes

N/A

Yes
Create Corrective Action?
N/A
Are construction entrances and adjacent streets being maintained adequately?
Yes
Create Corrective Action?
N/A
Is dust associated with the construction activity adequately controlled on the site?
Yes
Create Corrective Action?
N/A
Comments:
Comments:
Site was inactive during the current inspection.
Findings (Ones Antino Antino (Date)

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some maintenance is required in the BMP section of this report.

2) SF-1 for SAR-20200507-5452-GP2 (Giles Road/180th Street Improvements) was installed along Giles Road on the west end of the site prior to the 8/9/21 inspection. The SF will not be included in this report and is part of the road improvement project. The SF has been marked on the SWPPP map to indicate its location within the temporary road project. Also applies to silt fence east of river on north side of Giles Rd and the fuel tank located near CE 1. The fuel tank was removed prior to the inspection on 9/19/22. Silt fence checks were installed as part of the road project along Giles Rd. prior to the inspection on 9/19/22.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
CE 1	Construction Entrance	Giles Road (BB3)		Removed			
Current Condition:	Removed - Hawkins Construction paved the Construction entrance prior to the inspection on 5/3/23.						
CE 2	Construction Entrance	180th Street (DD9)		Removed			
Current Condition:	Removed - All entrances are paved on the east side of the site as of 5/18/22.						
CE 3	Construction Entrance	L3		Removed			
Current Condition:		Construction entrance w	istruction entrance, graded the ill not be recommended to be re				
CE 4	Construction Entrance	Southern section	8/9/2023	Active	No		
Current Condition:	Good Condition - 90% Effe	ective - TAB Construction	n installed a rock construction e	ntrance prior to the ir	spection on 8/9/23		
D 1	Diversion	N17-E17	8/14/2020	Active	No		
Current Condition:	Good Condition - Gene Gr	aves installed the diversi	ion prior to the 7/18/22 inspection	on.			
D 2	Diversion	N17-U17	8/14/2020	Active	No		
Current Condition:	Good Condition - Gene Gr	aves installed the diversi	ion prior to the 7/13/22 inspection	on.			
D 3	Diversion	West of SB A	1/13/2021	Active	No		
Current Condition:	4/5/21 inspection, the inspection	ector will monitor as the	the 1/13/21 inspection. JC par diversion is redefined. JC Exca nstalled the diversion prior to the	vation/Gene Graves	reinstalled the divers		
D 4	Diversion	East of SB A	10/13/2022	Active	No		
	diversion prior to the inepa		rsion prior to the inspection on		an an AIEIOO		
D 5	diversion prior to the inspe		Graves reinstalled the diversio		on on 4/5/23.		
D 5 Current Condition:	Diversion Good Condition - Gene Gr	ction on 11/22/22. Gene West of SB B aves reinstalled the dive	Graves reinstalled the diversio	n prior to the inspecti Active 10/13/22. An unknow	No n contractor remove		
	Diversion Good Condition - Gene Gr diversion prior to the inspe	West of SB B aves reinstalled the divection on 11/22/22. Gene SW of SB C	Graves reinstalled the diversio 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversio	n prior to the inspecti Active 10/13/22. An unknow	No n contractor remove		
Current Condition: D 6 Current Condition:	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C	Graves reinstalled the diversio 10/13/2022 rsion prior to the inspection on	Active Active 10/13/22. An unknow n prior to the inspecti	No n contractor remove		
Current Condition: D 6 Current Condition: D 7	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A	Graves reinstalled the diversio 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversio P as of the 10/6/2020 revision.	Active 10/13/22. An unknown prior to the inspecti Removed Removed	No n contractor remove on on 4/5/23.		
Current Condition: D 6 Current Condition:	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A	Graves reinstalled the diversio 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversio	Active 10/13/22. An unknown prior to the inspecti Removed Removed	No n contractor remove on on 4/5/23.		
Current Condition: D 6 Current Condition: D 7	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving a	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta	Graves reinstalled the diversio 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversio P as of the 10/6/2020 revision. ated the diversion is no longer r	Active 10/13/22. An unknown prior to the inspecti Removed Removed	No n contractor remove on on 4/5/23.		
D 6 Current Condition: D 7 Current Condition:	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta	Graves reinstalled the diversio 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversio P as of the 10/6/2020 revision. ated the diversion is no longer r	Active 10/13/22. An unknown prior to the inspecti Removed Removed necessary as of the 7.	No n contractor remove on on 4/5/23.		
D 6 Current Condition: D 7 Current Condition: D 8	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving Diversion Good Condition - JC instal Diversion	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B	Graves reinstalled the diversio 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversio P as of the 10/6/2020 revision. ated the diversion is no longer reinstalled the diversion is no longer reinstalled.	Active 10/13/22. An unknown prior to the inspecti Removed Removed necessary as of the 7.	No n contractor remove on on 4/5/23.		
D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition:	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving Diversion Good Condition - JC instal Diversion Removed - Due to paving	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta	Graves reinstalled the diversio 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversio P as of the 10/6/2020 revision. ated the diversion is no longer r	Active 10/13/22. An unknown prior to the inspecti Removed Removed necessary as of the 7. Active Removed necessary as of the 7.	No n contractor remove on on 4/5/23.		
D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition:	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving Diversion Good Condition - JC instal Diversion Removed - Due to paving	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9	Graves reinstalled the diversio 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversio P as of the 10/6/2020 revision. atted the diversion is no longer reinstalled the diversion is no longe	Active 10/13/22. An unknown prior to the inspecti Removed Removed necessary as of the 7. Active Removed	No n contractor remove on on 4/5/23.		
Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition:	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving Diversion Good Condition - JC instal Diversion Removed - Due to paving of the paving	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPPI	Graves reinstalled the diversio 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversio P as of the 10/6/2020 revision. ated the diversion is no longer reinstalled the diversion is no longer reinstalled.	Active 10/13/22. An unknown prior to the inspecti Removed Removed necessary as of the 7. Active Removed Removed Removed Removed Removed Removed	No n contractor remove on on 4/5/23.		
Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving Diversion Good Condition - JC instal Diversion Removed - Due to paving Diversion Removed - Due to paving Diversion Removed - Due to paving Diversion Removed - D10 has been Diversion	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPFI S of SB C	Graves reinstalled the diversion 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversion P as of the 10/6/2020 revision. ated the diversion is no longer reinstalled the diversion.	Active 10/13/22. An unknown prior to the inspecti Removed Removed Active Active Removed Active Removed Removed Removed Removed Removed Removed	No n contractor remove on on 4/5/23.		
Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition:	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving Diversion Good Condition - JC instal Diversion Removed - Due to paving Diversion Removed - Due to paving Removed - Due to paving Diversion Removed - D10 has been Diversion Removed - D11 has been	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF	Graves reinstalled the diversio 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversio P as of the 10/6/2020 revision. atted the diversion is no longer reinstalled the diversion is no longe	Active 10/13/22. An unknown prior to the inspecti Removed Removed necessary as of the 7/ Active Removed necessary as of the 7/ Removed necessary as of the 7/ Removed	No n contractor remove on on 4/5/23.		
Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B	Graves reinstalled the diversion 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversion P as of the 10/6/2020 revision. 1/20/2021 the 7/26/22 inspection. ated the diversion is no longer related the di	Active 10/13/22. An unknown prior to the inspecti Removed Removed necessary as of the 7. Active Removed necessary as of the 7.	No n contractor remove on on 4/5/23.		
Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition:	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion	West of SB B aves reinstalled the dive ction on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPF S of SB C removed from the SWPF E of SB B emoved the diversion for	Graves reinstalled the diversion 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversion P as of the 10/6/2020 revision. ated the diversion is no longer reinstalled the diversion.	Active 10/13/22. An unknown prior to the inspecti Removed Removed necessary as of the 7. Active Removed necessary as of the 7.	No n contractor remove on on 4/5/23.		
Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving a Diversion Good Condition - JC instal Diversion Removed - Due to paving a Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - D11 has been Diversion Removed - D11 has been	West of SB B aves reinstalled the divection on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPPI S of SB C removed from the SWPPI E of SB B emoved the diversion fol See SWPPP Map	Graves reinstalled the diversion 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversion P as of the 10/6/2020 revision. 1/20/2021 the 7/26/22 inspection. ated the diversion is no longer related the 10/6/2020 revision PP as of the 10/6/2020 revision Pr as of the 10/6/2020 revision r paving prior to the 7/26/22 ins	Active 10/13/22. An unknown prior to the inspecti Removed Removed necessary as of the 7. Active Removed necessary as of the 7.	No n contractor remove on on 4/5/23.		
Current Condition: D 6 Current Condition: D 7 Current Condition: D 8 Current Condition: D 9 Current Condition: D 10 Current Condition: D 11 Current Condition: D 12 Current Condition: ET 1	Diversion Good Condition - Gene Gr diversion prior to the inspe Diversion Removed - D6 has been re Diversion Removed - Due to paving Diversion Good Condition - JC instal Diversion Removed - Due to paving Diversion Removed - D10 has been Diversion Removed - D11 has been Diversion Removed - D11 has been Diversion Removed - Gene Graves r Erosion Control Terrace	West of SB B aves reinstalled the divection on 11/22/22. Gene SW of SB C emoved from the SWPPI S of SB A and the site being vegeta M25-N17 led the diversion prior to X15-SB B and the site being vegeta AA10-AA9 removed from the SWPPI S of SB C removed from the SWPPI E of SB B emoved the diversion fol See SWPPP Map	Graves reinstalled the diversion 10/13/2022 rsion prior to the inspection on Graves reinstalled the diversion P as of the 10/6/2020 revision. 1/20/2021 the 7/26/22 inspection. ated the diversion is no longer related the 10/6/2020 revision PP as of the 10/6/2020 revision Pr as of the 10/6/2020 revision r paving prior to the 7/26/22 ins	Active 10/13/22. An unknown prior to the inspecti Removed Removed necessary as of the 7. Active Removed necessary as of the 7.	No n contractor remove on on 4/5/23.		

ET 3 Current Condition:	Erosion Control Terrace Good Condition - JC insta		8/14/2020 e 7/26/22 inspection.	Active	No
EM 1	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No
Current Condition:			ed within the seeding window		
EM 2	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No No
Current Condition:	Pending - The erosion cor	ntroi matting will be install	ed within the seeding window	when the associated a	rea reacnes final grade.
EM 3	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No
Current Condition:	Pending - The erosion cor	ntrol matting will be install	ed within the seeding window	when the associated a	rea reaches final grade.
EM 4	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No
Current Condition:			ed within the seeding window		
		T			
EM 5	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No
Current Condition:	Pending - The erosion cor	ntrol matting will be install	ed within the seeding window	when the associated a	rea reaches final grade.
EM C	Francisco Construct Mattings	C CWDDD M	D 0/5/0004	Donalin a	l N-
EM 6	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No
Current Condition:	Pending - The erosion cor	ntroi matting will be install	ed within the seeding window	when the associated a	rea reacnes final grade.
EM 7	Erosion Control Matting	See SWPPP Map	3/5/2021	Pending	No
Current Condition:			ed within the seeding window		
Current Condition.	r ending - The erosion con	itioi matting will be install	ed within the seeding window	when the associated a	rea reacries illiai grade.
FT X	Fuel Tank	On Site	8/9/2023	Active	No
Current Condition:			ble walled fuel tank on site pri		
			The wanted fact tarm of the pri		J
FT Y	Fuel Tank	On Site	L	Removed	
Current Condition:	Removed - The double wa	alled fuel tank was remov	ed from the site prior to the in	spection on 11/30/21.	
IF 1-32	Inlet Filters	Interior Streets curb	5/17/2023	Active	Yes
		inlets			
Current Condition:	Fair Condition - Commerc	cial Seeding installed inlet	filters in all interior street curb	o inlets prior to the inspe	ection on 5/17/23.
	D R Horton was informed	to complete by 9/6/23. No	ot done as of the last inspec	ction.	
Lot 24	Individual Lot	Lot 24	8/16/2023	Active	Yes
Current Condition:			ot prior to the inspection on 8/		
			or silt fence installed along the		
			ot done as of the last inspec		
Lot 25 Current Condition:	Individual Lot	Lot 25	8/16/2023 ot prior to the inspection on 8/	Active	Yes
	during the inspection on 8 R Horton removed the dirt Straw wattles should be re	v16/23. D R Horton install t piles from the ROW prio	led wattles around the perime r to the inspection on 8/30/23 or silt fence installed along the ot done as of the last inspec	ter of the lot prior to the . estreet.	
Lot 26	Individual Lot	Lot 26	8/23/2023	Active	Yes
Current Condition:		on began excavating the l	ot prior to the inspection on 8/	23/23. D R Horton insta	lled wattles around the
	Horton removed the dirt p Straw wattles should be re	iles from the ROW prior to	 A dirt pile was observed in the inspection on 8/30/23. Silt fence installed along the ot done as of the last inspect 	e street.	spection on 8/23/23. D R
Lot 27	Individual Lot	Lot 27	8/23/2023	Active	Yes
Current Condition:			ot prior to the inspection on 8/		
		0		the ROW during the ins	
	Horton removed the dirt p Straw wattles should be re	iles from the ROW prior to	o the inspection on 8/30/23. or silt fence installed along the ot done as of the last inspect	e street.	spection on 8/23/23. D K
Lot 29	Horton removed the dirt p Straw wattles should be re D R Horton was informed	iles from the ROW prior to	o the inspection on 8/30/23. or silt fence installed along the	e street.	Yes
Lot 29 Current Condition:	Horton removed the dirt p Straw wattles should be re D R Horton was informed Individual Lot Fair Condition - D R Horto perimeter of the lot prior to Horton removed the dirt p Straw wattles should be re	iles from the ROW prior to epositioned and secured of to complete by 9/6/23. No Lot 29 on began excavating the lot the inspection on 8/23/2 illes from the ROW prior to epositioned and secured of the inspection on secured of the inspection of the	o the inspection on 8/30/23. or silt fence installed along the opt done as of the last inspec	e street. Active 23/23. D R Horton instathe ROW during the instance as street.	Yes Illed wattles around the

MS 1	Material Storage	On Site	8/14/2020	Active	No		
Current Condition:	Good condition - Sewer pipes being stored on site.						
PB X	Portable Bathroom	On Site	1/25/2023	Active	No		
Current Condition:	Good Condition - JC Excavation brought a portable toilet on site prior to the 6/8/21 inspection. JC Excavation removed the portable toilet prior to the inspection on 9/8/21. MBC brought a portable toilet on site and secured it prior to the inspection on 10/13/21. MBC removed the portable toilet from the site prior to the inspection on 10/26/21. Cedar Construction installed and secured a portable toilet on site prior to the inspection on 6/29/22. Cedar Construction stood up and secured the portable toilet prior to the 7/13/22 inspection. Cedar Construction removed the portable toilet from the site prior to the inspection on 9/19/22. Nelson Construction installed and secured a portable toilet on site prior to the inspection on 1/25/23. TAB Construction installed and secured a portable toilet on the site prior to the inspection on 8/9/23.						
SB A	Sediment Basin	M10	1/20/2021	Active	No		
Current Condition:	Good Condition - 0% filled - JC excavated the basin and installed the baffle prior to the 1/13/21 inspection. JC Excavation ceased dewatering prior to the inspection on 9/8/21. Kersten Construction was in the process of installing the riser during the inspection on 5/18/22. Kersten Construction installed the riser prior to the inspection on 6/1/22. Hausman cleaned out a portion of the basin prior to the inspection on 7/26/22. E&A inspector painted the cleanout mark during the 8/10/22 inspection. Kenny Digs Dirt began cleaning out the basin prior to the inspection on 8/30/23.						
SB B	Sediment Basin	V7	10/28/2020	Active	Yes		
	Fair Condition - 10% Filled - JC installed the basin prior to the 10/28/20 inspection. The E&A inspector painted the cleanout mark during the 11/4/20 inspection. JC Excavation is doing work on the riser during the 7/20/21 inspection. No recommendation will be made at this time and the E&A inspector will continue to monitor. JC backfilled around the riser prior to the 8/2/21 inspection. JC repaired the erosion around the riser prior to the inspection on 9/15/21. CDS Enterprise began cleaning out the basin during the inspection on 4/6/22. CDS Enterprise completed cleanout of the basin prior to the inspection on 6/29/22. E&A inspector repainted the cleanout mark on the riser during the 8/10/22 inspection. The baffle needs to be installed per the SWPPP. JC Excavation/Gene Graves were informed to complete by 3/22/21. Not done as of the last inspection. JC Excavation/Gene Graves were reminded on 3/26/21, 4/16/21, 5/20/21, 6/10/21, 6/25/21, 7/17/21, 8/19/21, 9/2/21, 10/15/21, 1/11/121, 1/2/2/1,						
SB C	2/10/22, 3/31/22, 6/7/22, 13 Sediment Basin	Z4 Z4	10/28/2020	Active	No		
Current Condition: SF 1	Good Condition - 15% Filled - JC installed the basin prior to the 10/28/20 inspection. The E&A inspector painted the cleanout mark during the 11/4/20 inspection. CDS Enterprise began cleaning out the basin during the inspection on 4/6/22. CDS Enterprise was dewatering the basin into silt fence during the inspection on 5/10/22. CDS completed cleanout of the basin prior to the inspection on 6/22/22. Kenny Digs Dirt began cleaning out the basin prior to the inspection on 8/16/23. Kenny Digs Dirt cleaned out the basin prior to the inspection on 8/30/23. Silt fence N side of Site 10/20/2020 Active No						
Current Condition:	Good Condition - JC installed the silt fence prior to the 10/20/20 inspection. JC Excavation took down a small section north of SI B to install storm. E&A inspector will continue to monitor. Great Plains installed a berm along the creek prior to the inspection or 4/19/22. Great Plains reinstalled, repaired, and extended the silt fence up to SB B prior to the inspection on 4/19/22. Gene Graves extended the silt fence from SB B to SB A prior to the 7/13/22 inspection. An unknown contractor removed a portion of the silt fence prior to the inspection on 11/22/22. Gene Graves reinstalled and repaired the silt fence prior to the inspection on 4/5/23. Commercial Seeding extended the silt fence along the west edge of the site prior to the inspection on 5/17/23.						
SF 2	Silt fence	West End of Meridian Street		Removed			
Current Condition:	Removed - Crops are out of SF 1.	of the ground as of the 10	0/20/20 inspection, silt fence be	elow grading activities	will be included under		
SF 3	Silt fence	N of Giles Road	10/20/2020	Active	No		
Current Condition:	fence, graded the area, an	d installed their own silt f	the 10/20/20 inspection. Hawk ence prior to the inspection on ence prior to the inspection on	8/17/21. E&A inspecto	•		
SF 4	Silt fence	NE Corner Across RR	1/28/2021	Active	No		
Current Condition:	fence was backfilled prior to recommended on 6/8/21. It silt fence prior to the inspe- end of the dirt piles prior to	to the 3/31/21 inspection. Hawkins Construction rerection on 8/17/21. Gene Good the inspection on 4/26/2		vegetated so silt fence ence, graded the area, e and extended the sil	is no longer and installed their own t fence around the west		
SF 5	Silt fence	Interior streets	6/13/2022	Active	No		
Current Condition:	fence along all interior stre along Portal street that we sections of silt fence prior t	et corners prior to the instre removed for utility instructor the inspection on 11/22 Graves repaired the silt for the inspection on 8/9/	along Meridian Street to the 7/1 spection on 7/18/22. Gene Gra allation prior to the inspection of 2/22. Reinstallation will not be fence prior to the inspection on 23.	ves reinstalled multiple on 9/28/22. Gene Grav recommended at this t	e sections of silt fence les removed multiple ime. E&A inspector will		
STR	Streets	Giles Road/180th Street	7/28/2020	Active	Yes		

Current Condition:	Fair Condition - No major signs of track off. CDS Enterprise cleaned the streets around SB B and C prior to the inspection on 6/29/22. Street cleaning was in progress by OPPD during the inspection on 3/1/23. Gene Graves Development cleaned the street prior to the inspection on 5/3/23. Peter Katt cleaned the streets prior to the inspection on 8/9/23. Mud was observed in the street during the 8/16/23 inspection. Streets were cleaned by Kenny Digs Dirt prior to the inspection on 8/30/23. Streets in front of active lots should be cleaned daily or as needed. D R Horton was informed to complete by 8/31/23. Not done as of the last inspection.						
SWPPP Sign	Misc./Other	S 148th Ave & Meridian St.	8/10/2020	Active	No		
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign at Y3 during the 8/10/20 inspection. E&A inspector reinstalled the SWPPP sign during the inspection on 2/22/22. E&A inspector reinstalled the SWPPP sign at S 148th Ave and Meridian St. during the inspection on 10/19/22. E&A inspector reinstalled the SWPPP sign during the inspection on 11/30/22. E&A inspector moved the SWPPP sign to the entrance on 182nd and Giles prior to the inspection on 6/7/23.						
WO 1	Concrete Washout On Site 3/5/2021 Active Yes						
Current Condition:	Fair Condition - D R Horton installed a concrete washout on site prior to the inspection on 8/30/23. Concrete waste outside the washout should be cleaned up. D R Horton was informed to complete by 9/6/23. Not done as of the last inspection.						
WS 1	Waste Storage	On Site	3/5/2021	Pending	No		
Current Condition:	Pending - Waste will be co	ntained on site and in pro	pper containment vessels.				
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."						
Inspector Signature:	Broga M Waght			Reviewed By:	Cut Sur		